



## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

F.6/DFS/MS/Audi/2024/SZ/295 No.

Dated: 10 / 0J /2024

## FIRE SAFETY CERTIFICATE

Certified that the Weightlifting Auditorium located at Jawahar Lal Nehru Sports Complex, Lodhi Road, New Delhi-110003, comprised of two Basements, ground plus one upper floor, was issued Fire Safety Certificate by this office vide letter No. F.6/DFS/MS/Audi/2019/SZ/1237 dated 11/06/2019. The said premise was re-inspected by the officers concerned of this department on 02/05/2024 in the presence of Mr. Sailender Thakur (JE/Elect) and observed that all the fire prevention and fire safety arrangements provided in the premises except two tier basement have deem complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises excluding basements is fit for occupancy class "Assembly" (Group 'D') (stadium) with effect from the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of conditions under 38 of the Delhi Fire Service rules, 2010.

Issued on 10 05 2024 at New Delhi by

DELHI FIRE SERVICE

Copy to: -

1. Assistant Engineer (E), Safdarjung Hospital, Sub-Division (E), CPWD, Jawahar Lal Nehru Sports Complex, Lodhi Road, New Delhi-110003

2. The Administrator, Jawahar Lal Nehru Sports Complex, Lodhi Road, New Delhi-110003

## Conditions for the validity of Fire Safety Certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided therein shall be maintained in good working conditions at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of firefighting system.

4. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.

5. The owner/occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule37] along with a copy of this Certificate, six months prior to its N-25

	INSPECTIO	N REPORT	u marc	5.00		
١.	Name & address of the building	Weightlifting Auditorium, JLN Sports Complex, Lodhi Road, New Delhi-110003				
	Type of Occupancy	Assembly Building (Stadium)				
2.	Building Comprised of	Two Basement,	Two Basement, Ground + 01 Upper Floor.			
3	Building Comprised of	Renewal				
4.	Type of Case	F6/DFS/MS/Audi/2019/SZ/1237 dated				
5.	Details of previous NOC	11/06/2019				
	Fire Safety directives Letter	F.6/DFS/MS/BP/2008/2988 Dt. 31/10/2008				
6.	Fire Safety directives Letter	02/05/2024				
7. 8.	Date of inspection  Name of Inspecting Officer	Manoj Kumar Sharma (DO/SD) and Santosh Kumar (ADO/SJ)				
1	COfficer	Mr. Sailender Thakur (JE/Elect)				
9.	Name and designation of Officer	IVII. Dunion				
	from building side	1982				
10.	Year of Construction Applicant letter / Email dated 29/04/2	024 from ID: ae4	sjhed@gmail.com	1		
11.	Applicant letter / Email dated 2970 172	Requirements	Provided at site	Remark		
S.	Minimum standards on fire prevention and fire safety U/R 33			MR/NM		
No.	Access of building			1.00		
1.	Access of building     Road width	30m	Provided	MR		
	Road width     Gate width	6m	Provided	MR MR		
	Width of internal road	6m	Provided	MK		
2	Number, width, Type & Arrangemen	ts of exits				
2.	a. Number of staircases			1 10		
	Upper floors	10 Nos	10 Nos	MR		
	Basements	NA	NA	NA*		
	b. Width of staircases	sidner		1 10		
	Upper floors	1.5 mtr each	3 Nos= 1.25m each 3 Nos= 1.35m each 4 Nos= 2.20m each	MR (old case)		
	Basements	NA	NA	NA*		
	c. Protection of exits	- 1	Provided	MR		
1	<ul> <li>Fire check door</li> </ul>	Required	Provided	MR		
	<ul> <li>Pressurization</li> </ul>	Required	4 Nos	MR		
	d. No of continuous staircase to terrace	Required	Provided	MR		
1	e. Width of Corridor	Required	1.5m	MR		
	f. Door Size	Required	1.5m	IVIIC		
3	B. Compartmentation	7 1	Provided	MR		
	Fire check door	Required	Provided	MR		
	<ul> <li>Sealing of electrical shafts</li> </ul>	Required	Provided	MR		
	<ul> <li>Fire Rating of shaft door</li> </ul>	Required	EDDER MARK	NA		
	Water Curtain	NA	NA	NA NA		
	Fire Dampers	NA	NA	INA		
	4. Smoke managements System	W. T.	274	NA*		
	Basements	NA	NA ral Provided	MR		
	Upper floors	Mechanical/ Natu	rai Provided	IVIIC		
	5. Fire Extinguishers	10.37	40 Nos	MR		
	Total numbers	40 Nos ABC / CO <sub>2</sub>	ABC & CO <sub>2</sub>	MR		
	• Types	Required	Provided	MR		
	ISI marking	Required				
	6. First-Aid Hose Reels	B2 & B1=06 Nos,	Provided in UFs but	MR*		
	<ul> <li>Total numbers on each floor</li> </ul>	GF=08, FF=04 No	B1, B2 was closed	MR		
ıl I	<ul> <li>Length of hose reel hose</li> </ul>	30m	Provided Provided	MR		

7.	Automatic fire detection and alarmin	ng system  Required	Provided	MR
A11-50	Type of detector	Required	Provided	MR
	Location of Main Panel		Fire Control Room	MR
	Location of Repeater Panel	recquire	Provided	MR
	Alternate source of power	Required	All Area	MR
	Hooters' Location	Staircase	Provided	MR
0	MOEFA/MCPs	Required	Provided	MR
8.	Public Address System	Required	Piovided	
10	Automatic Sprinkler System	NA NA		NA*
10	Basements	NA Required	Provided	MR
	Upper Floors	Required	Provided	MR
	Sprinkler above false ceiling	Required		
11	Internal Hydrants	150 mm	150 mm	MR
	Size of riser/down-comer	B2 & B1=06 Nos	, Provided in UFs but	MR*
	<ul> <li>Number of hydrants per floor</li> </ul>	GF=08, FF-04 No	B1, B2 is closed	MR*
	Hose Box	B2 & B1=06 No	s, Provided in UFs but B1, B2 is closed	IVIIC
		GF=08, FF-04 No	OS D1, D2 15 010000	
12	Yard Hydrants	11 Nos	Provided	MR
Ы,	Total number of hydrants	11 Nos 11 Nos	Provided	MR
	Hose Box	11 NOS	1201201	
13	Pumping Arrangements	171		
	Ground Level	22227774	Provided	MR
	Discharge of main pump	2280 LPM		MR
	➤ Head of main pump	70m	Provided	
	> Number of main pumps	2 Nos	Provided	MR
	> Jockey pump out put	180 LPM	Provided	MR
	> Jockey pump head	70m	Provided	MR
	> Standby Pump out put	2280 LPM	Provided	MR
	> Standby Pump Head	70m	Provided	MR
	> Auto Starting/Manual stopping	Required	Provided	MR
	> Pump House Access	Required	Provided	MR
		Required	TTOVIGCU	1,111
	Terrace level	000 I DM	900 LPM x 2	MD
	<ul><li>Discharge of pump</li><li>Head of the pump</li></ul>	900 LPM 40m		MR
	<ul><li>Head of the pump</li><li>Power supply</li></ul>	Required	Provided Provided	MR
	> Auto starting of pump	Required		MR
14	Captive water Storage for fire fight		Provided	MR
14	Underground tank capacity	50,000 Ltrs	Drovidod	MD
	> Draw of connection	Required	Provided Provided	MR
	> Fire service inlet	Required		MR
	Access to tank	Required	Provided Provided	MR
	Overhead Tank capacity	10,000 Ltrs	Provided	MR
15	Exit Signage	Required	Provided	MR
16.	Provision of Lifts	required	Flovided	MR
	> Pressurization of Lift Shaft	Required	Provided	100
	> Pressurization of lift lobby		22,588	MR
	Communication in lift Car	Required	Provided	MR
		Required	Provided	MR
	a distance of the control of the con	Required	Provided	MF
	➤ Lift Signage	Required	Provided	MF
17.	Standby power supply	Required	Provided	
18.	Refuge Area	- Juliou	TIOVICE	MI
	> Total area	NA	NIA	
	> Location	777777	NA	N/
		NA	NA	NA.



19.	Fire control room			
17.	> Detector system panel	Required	Provided	MR
	> Flow Switch Panel	Required	Provided	MR
	> PA System Panel > Battery backup	Required	Provided	MR
		Required	Provided	MR
	> Building Floor Plans	Required	Provided	MR
	Building Floor Systems for	NA NA	NA	NA
20.	Special Fire Protection Systems for Protection of special Risks, if any;			od Hor

\*Note: The Double Basement under the weightlifting auditorium was closed, Hence, inspection of the basements could not be conducted. We may consider renewal of FSC excluding basement, if approved please.

The fire protection systems provided in the building/premises were checked, tested at random and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the fire safety certificate issued vide letter No. F6/DFS/MS/Audi/2019/SZ/1237 dated 11/06/2019, renewal under rule 37 of Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer Name: Manoj Kumar Sharma

Designation: DO (SD)

Signature of the Inspecting Officer

Name: Santosh Kumar Designation: ADO (SJ)

is putup for your strag. pl