

C 23

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110 001


No.F6/DFS/MS/School/NDZ/2024/ 432

Dated: 16/05/2024

FIRE SAFETY CERTIFICATE

Certified that the **Butler Memorial Girls Sr. Sec. School** located at **17, Boulevard Road, Delhi-06**, comprised of **ground + 01 upper floor only** was granted Fire Safety Certificate by this department vide letter No.- F6/DFS/MS/2019/School/NDZ/63 dated 08.01.2019. The school building was re-inspected by the officer concerned of this department on 03.05.2024 in the presence of Mrs. Mollina (Manager) and found that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with the circular No. F.16/Estate/CC/Fire safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and the building is fit for occupancy of class **Group-B, "Educational Building" Sub-Div. B-1** with effect from16/05/2024 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to conditions under rule 38 of Delhi Fire service Rules, 2010 printed below.

Issued on16/05/2024.....at New Delhi by


(Atul Garg)
Director
Delhi Fire Service
Tel: 011-23414000
o/c
15/5

Copy to:-

1. The Director of Education,
Govt. of NCT of Delhi, Old Secretariat, Delhi.
2. The Principal,
Butler Memorial Girls Sr. Sec. School at 17, Boulevard Road, Delhi-06.

Conditions for the validity of fire safety certificate

1. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form 'J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry
2. All the means of escape shall be kept free of all the type of obstruction all the time.
3. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
4. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
5. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
6. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

- N/B -
INSPECTION REPORT

| | | |
|----|---|--|
| 1 | Name and address of the building: | Butler Memorial Girls Senior Secondary School, 17, Boulevard Road, Delhi - 54. |
| 2 | Type of occupancy with details of floors: | Educational Building (Group-B-1) (Ground + 01 upper floor only) |
| 3 | Type of case: | Renewal |
| 4 | Details of previous FSC: | F6/DFS/MS/2019/School/NDZ/63 dated 08.01.2019 |
| 5 | Fire safety directives no.: | NA |
| 6 | Date of inspection: | 03.05.2024 |
| 7 | Name of the inspecting officer: | Sumit Kumar, ADO (SPM) |
| 8 | Name and designation of the officer from the building side: | Mrs. Molina (Manager) |
| 9 | Year of construction: | 1925 |
| 10 | Reference letter no.: | Outdoor diary no. 264 dated 05.04.2024 |

| S. No | Minimum Standards on fire Prevention and fire safety requirements U/R 33 | As per Education Circular dated 01.03.2011 | Provide at site | Remarks MR/NM R |
|-------|--|--|--|-----------------|
| | | <i>Existing F.S. Arrangement</i> | | |
| 1 | Access to Building | | | |
| A | Road width | 06 mtr. | 09 mtr. ✓ | MR |
| B | Gate width | 3.5 mtr. | 04 mtr. | MR |
| C | Width of internal roads | NA | NA ✓ | NA |
| 2 | Number, Width, Type & Arrangement of Exits | | | |
| A | No. of Staircase: | | | |
| | a) Upper floor | 06 nos. | 06 nos. ✓ | MR |
| | b) Basements | NA | NA | NA |
| B | Width of the Staircase: | | | |
| | a) Upper floor | 1.35 mtrs. & ramp 1.60 mtr. | 03 Nos.-1.20 mtr. 02 Nos.-1 mtr. & ↑ 01 Nos.- 2 mtr. ✓ | MR |
| | b) Basements | NA | NA | NA |
| C | Protection of Exits | | | |
| | a) Fire check door | NA | NA | NA |
| | b) Pressurization | NA | NA | NA |
| D | No. of continuous staircase to terrace: | NA | NA | NA |
| F | Width of the corridor | NA | NA | NA |
| E | Door size | 1.0 mtr. | 1.0 mtr. ✓ | MR |
| 3 | Compartmentation: | | | |
| A | Fire check doors | NA | NA | NA |
| B | Sealing of electrical shafts | NA | NA | NA |
| C | Fire rating of shaft doors | NA | NA | NA |
| D | Water curtain | NA | NA | NA |
| E | Fire dampers | NA | NA | NA |
| 4 | Smoke management System: | | | |
| A | Basements | NA | NA | NA |
| B | Upper floors | NA | NA | NA |
| 5 | Fire extinguishers | | | |
| A | Total numbers | 10 nos. | 10 nos. ✓ | MR |
| B | Types | Co2 & ABC | Co2 & ABC & W. Co2 | MR |
| C | ISI marking | Required | Provided | MR |

| | | | | | |
|-----------|---|-----------------------------------|----------|----------|----|
| 6 | First Aid Hose reel | | | | |
| | A | Total no. at each floor | NA | NA | NA |
| | B | Length of Hose Reel | NA | NA | NA |
| | C | Nozzle diameter | NA | NA | NA |
| 7 | Automatic Fire Detection and Alarm System (ADAS) | | | | |
| | A | Type of Detectors | NA | NA | NA |
| | B | Location of main Panel | NA | NA | NA |
| | C | Location of Repeater Panel | NA | NA | NA |
| | D | Alternate power Source | NA | NA | NA |
| | E | Hooter's location | NA | NA | NA |
| 8 | MOEFA | | NA | NA | NA |
| 9 | Public Address System | | NA | NA | NA |
| 10 | Automatic Sprinkler System | | | | |
| | A | Basement | NA | NA | NA |
| | B | Upper Floor | NA | NA | NA |
| | C | Sprinklers above false ceiling | NA | NA | NA |
| 11 | Internal hydrants | | | | |
| | A | Size of the riser/down comer | NA | NA | NA |
| | B | No. Of hydrants per floor | NA | NA | NA |
| | C | Hose box | NA | NA | NA |
| 12 | Yard Hydrants | | | | |
| | A | Total no. of hydrants | NA | NA | NA |
| | B | Hose box | NA | NA | NA |
| 13 | Pumping arrangements | | | | |
| | A | Ground Level | | | |
| | | a) Discharge of main pump | NA | NA | NA |
| | | b) Head of main pump | NA | NA | NA |
| | | c) Number of main pump | NA | NA | NA |
| | | d) Discharge of jockey pump | NA | NA | NA |
| | | e) Head of jockey pump | NA | NA | NA |
| | | f) Discharge of Standby pump | NA | NA | NA |
| | | g) Head of Standby pump | NA | NA | NA |
| | | h) Auto starting/ manual stopping | NA | NA | NA |
| | B | Terrace Level | | | |
| | | a) Discharge of terrace pump | NA | NA | NA |
| | | b) Head of terrace pump | NA | NA | NA |
| | | c) Alternate power supply | NA | NA | NA |
| | | d) Auto starting of pump | NA | NA | NA |
| 14 | Captive Water Storage for Fire Fighting | | | | |
| | A | Underground tank capacity | NA | NA | NA |
| | B | Draw off connection | NA | NA | NA |
| | C | Fire Service Inlet | NA | NA | NA |
| | E | Access to tank | NA | NA | NA |
| | D | Overhead tank capacity | NA | NA | NA |
| 15 | Exit Signage | | Required | Provided | MR |
| 16 | Provision of lift | | | | |
| | A | Pressurization of lift shaft | NA | NA | NA |
| | B | Pressurization of lift lobby | NA | NA | NA |
| | C | Communication in lift car | NA | NA | NA |
| | D | Fireman switch | NA | NA | NA |
| | E | Lift signage | NA | NA | NA |
| 17 | Standby Power Supply | | NA | NA | NA |

| | | | | |
|-----------|---|----|----|----|
| 18 | Refuge Area | | | |
| A | location | NA | NA | NA |
| B | Total area | NA | NA | NA |
| 19 | Fire Control Room | | | |
| A | Fire Detection System panel | NA | NA | NA |
| B | Flow switch panel | NA | NA | NA |
| C | P A system panel | NA | NA | NA |
| D | Battery backup | NA | NA | NA |
| E | Building floor plan | NA | NA | NA |
| 20 | Special Fire Protection for special risk if any: | | | NA |

The Fire Protection System provided in the school were tested, checked and random and found functional at the time of inspection.

Shortcomings communicated vide letter No.F6/DFS/MS/NDZ/School/2023/548 dated 15/11/2023 has been rectified.

Keeping in view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter No. F6/DFS/MS/2019/School/NDZ/63 dated 08.01.2019 is recommended to be renewed under Rule 35 of the Delhi Fire Service Rules 2010.

*Sir, no other file is pending with me, before disposal of this file.

Sumit Kumar
03/05/2024

Signature of the Inspecting Officer
Name Sumit Kumar
Designation ADO (SPM)

~~DO (CD)~~

~~DO~~
31/5/24

~~Dy. C.F.O. (NDZ)~~

~~ADP~~
06/05/24

~~C.F.O.~~
8/5/2024

~~Director~~
9/5/24

~~ADP/SPM~~

F.T. letter is put up for signature, please.

~~Director (DFS)~~
15/5/24

Sumit Kumar
15/05/2024