GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001**

No.F6/DFS/MS/2024/ School/ 437

Dated: 17/05/2024

FIRE SAFETY CERTIFICATE

Certified that the Govt. Girls Ser. Sec. School located at Quresh Nagar, Idgah Road, Delhi comprises of Ground + 03 Upper floor owned/occupied by Govt. Girls Ser. Sec. School was earlier granted FSC by this department vide letter No. F6/DFS/MS/2020/School/387 dated 30/09/20 & Corrigendum letter no. F6/DFS/MSGH/NDZ/2020/789 Dated 22.12.2020. Now, the premises was re-inspected by the officer concerned of this department on 08/05/24 in the presence of the Seema Maini (Vice Principal) and found that school have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Sevice Rules, 2010 and the premises is fit for occupancy of class Group B "Educational Building" Sub-Div. B-I with effect from1.7.1.0.5...2024 for a period of three years subject to compliance of the conditions mentioned below:

Issued on ... 17.105.1202.4... at New Delhi by.

elhi Eire Service

Copy to:-

1. Director of Education, Govt. of NCT, Delhi.

2. The Principal, Govt. Girls Ser. Sec. School, Quresh Nagar, Idgah Road, Delhi.

Conditions for the validity of fire safety certificate

1. All the means of escape shall be kept free of all types of obstruction all the time.

2. All the fire safety arrangements provided there in shall be maintained in good working condition at all time.

3. Any loss of life or property due to non-functional fire safety measures shall be at the

responsibility of the management.

4. The compliance with regards to electrical installation, structural stability, set back area, occupancy and any deviation in construction etc. shall be verified from authority concerned.

5. Any deviation w.r.t construction etc. shall be verified by the concerned building sanctioning authority.

6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six months prior to its

8. Any flammable material for interior decoration shall strictly prohibited.

INSPECTION REPORT

1. Name & address of the building:- Govt. Girls Ser. Sec. School at Quresh

Nagar, Idgah Road, Delhi

2. Type of occupancy:-

Educational Group B-I, Gr.+03 Upper Floor

3. Type of case:-

Renewal

4. Details of previous NOC:-

F6/DFS/MS/2022/School/180 dated 17/02/22 Corrigendum letter no. F6/DFS/MSGH/NDZ/2020/789

dated 22.12.2020.

5. Fire safety directives No.-

N/A

6. Date of inspection:-

08/05/24.

7. Name of the inspecting officer:-

Sh. Ravinder Singh (ADO/CC)

8. Name & designation of officer

From the building side:-9. Year of construction:-

Seema Maini (Vice Principal) 2013-14 S(Co.Ed)VM/ON/2024/27 dated 25.04.24.

S.No.	Applicant's letter No:- Minimum Standards on fire	Requirement	Provided at site	Remarks MR/NMR		
	Prevention and fire safety U/R 33	Exiting				
1.	Access to Building		OCtm	MR		
	1) Road width	06 mtr.	06 mtr. 3.5 mtr.	NA		
	2) Gate width	NA		NA		
	avar: 14h of internal road	NA	NA	10.2		
2.	Number, Width Type & Arrangement of Exits					
۷.	A. Number of staircases			MR		
	1. Upper floors	02	02	N/A		
	2. Basements	N/A	N/A			
	B. Width of staircase		02 nos. of 1.50	MR		
	1. Upper floors	1.50 mtr	mtr.	100/11/00/		
	2 Pasaments	N/A	N/A	N/A		
	Basements C. Protection of exits			N/A		
	1. Fire check door	N/A	N/A	N/A		
1	Pressurization	N/A	N/A			
	D. No. of continuous	01	01	MR		
	staircase to terrace	2 mtr.	2.50 mtr.	N/A		
	E. Width of corridor	1 mtr.	1 mtr.	MR		
	F. Door size	1 11141.				
3.	Compartmentation	N/A	N/A	N/A		
	1) Fire check door	UNO -51-22-2	N/A	N/A		
	2) Sealing of electrical shafts	N/A	N/A	N/A		
	3) Fire rating of shaft door	N/A	N/A	N/A		
	4) Water curtain	N/A	N/A	N/A		
	5) Fire Dampers	N/A	TALL			
4.	Smoke Management System	DI/A	N/A	N/A		
	1) Basements	N/A	Natural	MR		
	2) Upper floors	12 ACPH	Ivatulai			
5.	Fire Extinguishers		08 Nos.	MR		
	1) Total numbers	06 Nos.	ABC, CO2 & W.CO2	MR		
ŀ	2) Types	ABC & CO2		MR		
ŀ	3) ISI marking	Required	Provided	IVIIC		
	First-Aid Hose Reel		00	MR		
-	1)Total number of each floor	02	02	IVIIC		

NIN

	2) I enoth of hose well						
	Length of hose reel hose Nozzle diameter	30 mtr.	30 mtr.	MR			
7.	Automatic Fire Detection 0. 4	05 mm	05 mm	MR			
les	Automatic Fire Detection & A						
	1) Type of detectors	N/A	N/A	N/A			
	2) Location of main panel	N/A	N/A	N/A			
	3) Location of repeater panel	N/A	N/A	N/A			
	4) Alternate source of power	N/A	N/A	N/A			
3.	5) Hooter's Location	N/A	N/A	N/A			
).	MOEFA	Required	Provided	MR			
10.	Public Address System	N/A	N/A	N/A			
ι υ.	Automatic Sprinkler System						
	1) Basement	N/A	N/A	N/A			
	2) Upper floors	N/A	N/A	N/A			
	3) Sprinkler above false	N/A	N/A	N/A			
-	ceiling		Shirt Walland	1 1 1 1 1 1 1			
11.	Internal Hydrants						
	1) Size of riser/down-comer	N/A	N/A	N/A			
	2) Number of hydrants per	N/A	N/A	N/A			
	floor		3// 25	I I'M			
	3) Hose box	N/A	N/A	N/A			
12.	Yard Hydrants		1-20-6	IVA			
	1) Total number of hydrants	N/A	N/A	N/A			
	2) Hose box	N/A	N/A	N/A			
13.	Pumping Arrangement		17771	IV/A			
	1) Ground level	N/A	N/A	N/A			
	a) Discharge of main	N/A	N/A	N/A			
	pump		IVA	N/A			
	b) Head of main pump	N/A	N/A	21/4			
	c) Number of main	N/A	N/A	N/A			
	pump		IN/A	N/A			
	d) Jockey pump out put	N/A	N/A	27/4			
	e) Jockey pump head	N/A	N/A	N/A			
	f) Stand by pump output	N/A		N/A			
	g) Stand by pump head	N/A	N/A	N/A			
	h) Auto starting/Manual	N/A	N/A	N/A			
	stopping	IV/A	N/A	N/A			
	2) Terrace level						
	a) Discharge of pump	450 LPM	450 T P) 4	1			
	b) Head of pump	30 mtr.	450 LPM	MR			
	c) Power supply		30 mtr.	MR			
	d) Auto starting of pump	Required	Provided	MR			
14.	Cantive Water Storage for El	Required	Provided	MR			
	Captive Water Storage for Fire						
	, amaria min	N/A	N/A	N/A			
	capacity	27/2					
	a) Draw-off connection	N/A	N/A	N/A			
1.0	b) Fire service inlet	N/A	N/A	N/A			
	c) Access to tank	Required	Provided	/ MR			
	d) Over head tank capacit		10,000 ltr.	MR			
15.	Exit Signage.	Required	Provided	MR			
16.	Provision of Lifts.						
	a) Pressurization of lift	N/A	N/A	N/A			

	 b) Pressurization of lift lobby 	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	N/A	N/A	N/A
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System f	1	of special Dick if any	N/A

The fire protection system provided in the school building were tested, checked at random and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, if approved, the FSC issued vide letter no. F6/DFS/MS/2022/School/180 dated 17/02/22, renewal under Rule 35 of the Delhi Fire Service rules 2010, is recommended.

Signature of the Inspecting Officer

Name:-Ravinder Singh Designation:-ADO (CC)

10/5/24

Dicto (DOS)

Ling or ha

In al sory

Director

Aggle

As approved pri pertupfroland perued and seg

Pleake

1618/24