

### GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No.F6/DFS/MS/School/SZ/2024/ 418

Dated: 14 05 2024

#### FIRE SAFETY CERTIFICATE

Issued on... 14/05/12024... at New Delhi by.

Delhi Fire Service

#### Copy to:-

1. The Directorate of Education, Govt. of NCT of Delhi, Old Secretariat, Delhi.

 The Principal, Govt. Girls Sr. Sec. School located at Sriniwas Puri, New Delhi-65, School ID no. 1924031 (General Shift), Building ID no. 19241638.

## Conditions for the validity of Fire Safety Certificate:-

- The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J'
  [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry
- 2. All the means of escape shall be kept free of all the type of obstruction all the time.
- All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
- This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>.

~/22

	<b>N</b> T		CTION REPORT				
	Nam	e and address of the building:		c. School located at Si	riniwas Pu		
		,	New Delhi-65.				
			School ID no. 1924	031 (General Shift)			
			Building ID no. 19	241638			
2	Building is comprised of		Comprised of Two	Comprised of Two Blocks:			
		<i>x</i> → :		1 <sup>st</sup> Block - Ground + 02 upper floors			
			2 <sup>nd</sup> Block - Ground				
	Type	e of occupancy		nal Building (School)	I.		
		e of case:	Renewal	, ,			
-		ils of previous FSC:	F6/DFS/MS/School/2021/SZ/235 dated 18.03.2021				
		The state of the s		016 for 1 <sup>st</sup> block (G+2)			
6	Fire safety directives no.:			e Safety/2011/3298 to			
			01.03.2011 for 2 <sup>nd</sup>		5570 0000		
	D-4	C	08.05.2024	Diock (G+1)			
		of inspection:		- Chulde (M. Poed)			
}		ne of the inspecting officer:		r Shukla (M. Road)			
)		ne and designation of the officer	Dr. Poonam Chawla	(HOS)			
		n the building side:					
10	,m.,x.e	r of construction:	1962 & 2014	75 1 . 124 04 2024			
11	112000	erence letter no.:		75 dated 24.04.2024	Remarks		
S,No		nimum Standards on fire	Requirements	Provide at site	MR/NMF		
	Pre	vention and fire safety					
	req	uirements U/R 33					
1	Ace	cess to Building	10 pt		T) (D)		
	A	Road width	6.0 mtrs.	Provided	MR		
	В	Gate width	4.5 m	Provided	MR		
	C	Width of internal roads	NA	NA	NA		
2	Nu	mber, Width, Type & Arrangem	ent of Exits				
	A	No. of staircase:		41.1			
	(9,57)	a) Upper floor	1 <sup>st</sup> Block - 2 nos.	1 <sup>st</sup> Block - 2 nos.	MR		
		а) оррегион	2 <sup>nd</sup> Block - 1 no.	2 <sup>nd</sup> Block - 1 no.			
		b) Basements	NA	NA	NA		
	В	Width of the staircase:					
	-	a) Upper floor	1.5 mtrs each block	1st Block - 1.64 m	MR		
		a) Opper Hoor		each			
		2-0-1		2 <sup>nd</sup> Block - 1.50 m			
	4	b) Basements	NA	NA	NA		
	C	Protection of exits					
		a) Fire check door	NA	NA	NA		
		b) Pressurization	NA .	NA	NA		
	D	No. of continuous staircase to	2 nos.	2 nos.	MR		
	ע	terrace:	2.1.55				
	177	Width of the corridor	1.5 mtrs	Provided	MR		
	F	Door size	1.0 mtrs. (for class	1.0 mtrs. (for class	MR		
	L	DOOL SIZE	room)	room)			
3		mpartmentation:	100111)				
3	A	Fire check doors	NA	NA	NA		
	B	Sealing of electrical shafts	NA	NA	NA		
		Fire rating of shaft doors	NA NA	NA	NA		
	C	Water curtain	NA NA	NA	NA		
1	D		NA NA	NA	NA		
	E	Fire dampers	11/1				
4	_	oke Management System:	LNIA	NA	NA		
_	A	Upper floors	NA		NA NA		
f	В	Basements	NA	NA	INA		
5	Fi	e Extinguishers		15 nos.	MR		
5	Fi	Total numbers	15 nos.		1000000		
5	_	The second secon	15 nos. CO <sub>2</sub> & ABC	CO <sub>2</sub> & ABC Provided	MR MR		

N/23

		st Aid Hose reel Total no. at each floor	1 <sup>st</sup> Block - 2 nos.	1 <sup>st</sup> Block - 2 no	s. MR
-	_	Length of hose reel	30 m	30 m	MR
-	c	Nozzle diameter	5 mm	5 mm	MR
7		tomatic Fire Detection and Ala	LEDACE MARKET	V mm	2,22
	Aut	Type of detectors	NA	NA	NA
-	B	Location of main panel	NA	NA	NA
1	_		NA	NA NA	NA
	C	Location of repeater panel	NA	NA	NA
	D	Alternate power source	NA	NA	NA
	E	Hooter's location	NA NA	NA NA	NA
8		DEFA	NA NA	Provided	NA
9		blic Address System	NA	Flovided	1473
10		tomatic Sprinkler System	LATA	NA	NA
	$\overline{}$	Basement	NA	NA NA	NA.
		Upper floor	NA	NA NA	NA
	C	Sprinklers above false ceiling	NA	INA	IM
11	_	ernal Hydrants	Tara	100 mm	NA
	A		NA	2 nos.	NA
		No. Of hydrants per floor	NA		NA NA
Super-	C	Hose box	NA	2 nos.	11/1
12		rd Hydrants	LNIA	NA	NA
	A	Total no. of hydrants	NA	NA NA	NA
		Hose box	NA	INA	INA
13		mping Arrangements		<del></del>	-
	A	Ground Level	INA	NA	NA
		a) Discharge of main pump	NA	NA NA	NA
	T by	b) Head of main pump	NA		NA
		c) Number of main pump	NA	NA	NA NA
	h:	d) Discharge of jockey pump	NA	NA	
		e) Head of jockey pump	NA	NA	NA
		f) Discharge of standby pump	NA	NA	NA
			NA	NA	NA
		h) Auto starting/ manual stopping	NA	NA	NA
	В	Terrace Level	has read to a	F TELA!	107
		a) Discharge of terrace pump	1 <sup>st</sup> Block – 450 LPM	1 <sup>st</sup> Block- 2 nos. of 450 LPM	MR
		b) Head of terrace pump	NA	NA	NA
	-	c) Alternate power supply	NA	NA .	NA
		d) Auto starting of pump	NA	NA	NA
14	Cs	aptive Water Storage for Fire Fi	ighting		
	A		NA	NA	NA
	В		NA	NA	NA
	C		NA	NA .	NA NA
	E	Access to tank	NA	NA Descrided	MR
	D		1 <sup>st</sup> Block- 10,000 ltrs	Provided Provided	MR
15	_	kit Signage	Required	Flovided	17111
16		rovision of lift	NA	NA	NA
	A		NA NA	NA	NA
		Pressurization of fift loody	4.74.4	The state of the s	NA
	B		NA	NA	
	D C B	Communication in lift car	NA NA	NA .	NA NA

Govt. Girls Sr. Sec. School located at Sriniwas Puri, New Delhi-65.



Govt. Girls Sr. Sec. School located at Sriniwas Puri, New Delhi-65.

18	Refuge Area					
	A	location	NA	NA	NA	
	В	Total area	NA	NA NA	NA NA	
19	Fire Control Room					
	A	Fire detection system panel	NA	NA	NA	
	В	Flow switch panel	NA	NA	NA NA	
	C	P A system panel	NA	NA	NA NA	
	D	Battery backup	NA	NA	NA	
	E	Building floor plan	NA	- NA	NA	
20						

# <u>LEGENDS:- Meeting Requirement (MR), Not Meeting Requirement (NMR), Not Applicable (NA), Provided But Not Functional (PNF).</u>

The fire protection systems provided in the building were tested checked and found properly functional at the time of inspection.

Keeping in view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter no. F6/DFS/MS/School/2021/SZ/235 dated 18.03.2021 is recommended to be renewed under Rule 37 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer
Name Rajesh Kumar Shukla
Designation ADO (M. Road)

DO (SØ)

Mills I

Denected My 5/1

M