

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F 6 / DFS / MS / 2024/ School/WZ/ 416

Dated: 14 05 2024

FIRE SAFETY CERTIFICATE

Certified that the HRM Global School located at PU-Block, Pitampura, Delhi-110034 comprised of Basement + Ground +Three upper floors was issued FSC by this department vide letter No F6/DFS/MS/WZ/2021/577 dated 03.08.2021. The premises was re-inspected by the officer concerned of this department on 08.05.2024 in the presence of Sh. Rahul Mangla, and observed that all the fire prevention and fire safety arrangements as provided in the premises found in good working condition. The premises have deemed complied with requirements under rule 33 of the Delhi Fire Service Rule, 2010 and that the building/ premise is fit for occupancy Group B Educational with effect from 14.05.12024.... for a period of three years, in accordance with the Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40, subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010 printed below.

Issued on ... 14 .05 ... 2024 ... at New Delhi, by

Director
Ph. 011-23414000

Ole 2

Copy to: -

1. The Director, Education, Old Secretariat, Delhi.

2. The Principal, HRM Global School, PU-Block, Pitampura, Delhi-110034.

Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.

2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.

5. This certificate cannot be treated in any case for regularizations of unauthorized construction.

6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <u>WWW.dfs.Delhigovt.nic.in</u>

INSPECTION REPORT Name & address of the building: HRM Global School (Gulshan Educational Society) located at PU Block, Pitampura, Delhi-110034. Type of Occupancy Educational **Building Comprised of** 3. : Basement + Ground + 3 upper floors) 4. Type of Case Renewal 5. Details of Previous NOC F6/DFS/MS/WZ/2021/577 Dated- 03/08/2021 6. Fire Safety directives letter No : F6/DFS/MS/BP/2019/2019/205 dated 29/05/2019 7. Date of inspection 08/05/2024 8. Name of Inspecting Officer R.K.Sinha, ADO (BW) 9. Name and designation of officers From the building side Sh. Rahul Mangla 10. Year of Construction 2019-20 11. Applicant's letter No. Form J dated 29/04/2024 Minimum Standards on fire S. NBC/ UBBL prevention and fire safety U/R 33 Provided at site No. Remarks Requirement/ Guideline MR/NMR letter dated 29/05/2019 1. Access to building Road width 6 m Provided MR Gate width 4.5 m Provided MR Width of internal road Required Provided 2. Number, Width, Type & Arrangement of Exits MR a. Number of staircases Upper Floors 04 Provided MR Basements 04 & 1 Ramp Provided MR b. Width of staircases • Jpper Floor 1.50 m 2 × 1.70 m & 2 × 1.5 m MR . Basements 1.5 m 1.70 m- 1.98 m, 1.70 m, 1.55 m & 1.54 m MR c. Protection of exits Fire check door Required Provided MR Pressurization NA NA NA d. No. of continuous staircases to 04 terrace Provided MR e. Width of Corridor 1.5 m Provided MR 1.20 m Door Size Provided MR 3. Compartmentation Fire check door Required Provided MR Sealing of electrical shafts Required Provided MR Fire Rating of shaft door NA NA NA Water Curtain NA NA NA Fire Dampers NA NA NA 4. Smoke Management System Basements Required Exhaust Fan Provided MR Upper floors Required Naturally Ventilated MR 5. Fire Extinguishers Total numbers • 36 Nos. Provided MR Types • ABC/ Co2 Type Provided MR IS marking Required Provided MR First-Aid Hose Reels Total numbers on each floor 04 Provided MR Length of hose reel hose 30 m Provided MR Nozzle diameter 5 mm Provided MR Automatic fire detection and alarming system Type of detectors NA NA NA Location of Main Panel NA NA NA Location of Repeater Panel NA NA NA Alternate source of power NA NA

NA

		N-10			
		NA	NA	NA	
	Hooters' Location	A778A	NA NA	NA	
	MOEFA	NA	NA NA	NA	
	Public Address System	NA	10.		
0.	Automatic Sprinkler System				
•		Required	Provided	MR	
	Basement	NA	NA	NA	
	Ground Floor	NA NA	NA	NA	
	 Sprinkler above false ceiling 	NA			
1.	Internal Hydrants	*			
		NA	Provided	NA	
	Size of riser/down-comer	NA NA	04	NA	
	Number of hydrants per floor	NA NA	Provided	NA	
	Hose Box	NA .		100	
12.	Yard Hydrants				
	Total number of hydrants	NA	04	NA	
	Hose Box	NA	Provided	NA	
13.	Pumping Arrangements	In the	p 385		
	reald -			-	
	Ground Level		Dooddad	MR	
	➤ Discharge of main Pump	2280 lpm 70 m	Provided Provided	MR	
	➤ Head of Main pump	70 m	riovided	1,124	
	> Number of main pumps	01	Provided	MR	
	> Jockey Pump out put	180 lpm	Provided	MR	
	> Jockey pump head	70 m	Provided	MR .	
	> Standby Pump out put	2280 lpm	Provided	MR	
	> Standby Pump Head	70 m	Provided	MR	
	➤ Auto Starting/Manual Stopping	Required	Provided	MR	
	> Pump House Access	Required	Provided	MR	
	Terrace level				
	➤ Discharge of pump	900 lpm	Provided	MR	
		70 m	Provided	MR	
	➤ Head of the pump		11011464	IVII.	
	➤ Power Supply	Required	Provided	MR	
Parrie	➤ Auto Starting of pump	Required	Provided	MR	
14.	Captive Water Storage for fire fighting	g		4.3	
	Underground tank capacity	2,00,000 ltrs	Provided	MR	
	> Draw-off connection	Required	Provided	MR	
	> Fire service inlet	NA	NA	NA	
10	> Access to tank	Required	Provided	MR	
	Overhead Tank capacity	15,000 ltrs	Provided	MR	
15.	Exit Signage.	Required	Provided	MR	
16.	Provision of Lifts.	1		9.1.1	
	Pressurization of Lift Shaft	NA	NA	NA	
	Pressurization of Lift lobby	NA	NA		
	Communication In lift Car	Required	Provided	NA MR	
	Fireman's Grounding Switch	Required	Provided	1.1-52-50	
	Lift Signage	Required	= 10 32000	MR	
17.	Standby power supply	NA	Provided	MR	
18.	Refuge Area.	· · · · · · ·	NA	NA	
	> Total Area				
	> Location	NA NA	NA	NA	
	No. of the last of	NA	NA	NA	

OV

	V		
Control Room			0.000
Detector System Panel	NA	NA	NA
Flow Switch Panel	NA	NA	NA
PA System Panel	NA .	NA	NA
Battery backup	NA	NA	NA
Building Floor Plans	NA	NA	NA
al Fire Protection System for ction of special Risks, if any:	Required 2 ABC type fire extinguishers near electrical panel	Provided	MR

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Note: Electrical panel and electric meter are not under the staircase.

Keeping in view of deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, it is recommended to renew the Fire Safety Certificate issued vide letter no. F6/DFS/MS/WZ/2021/577 dated 03/08/2021 under Rule 37 of the Delhi Fire Service Rules, 2010.

Signature of Inspecting Officer Name: Rajeev Kumar Sinha Designation: ADO/B.W.

301 January

20.

875

Durfolory

Director M)

Any of Wor FT letter pusp anson

Wreets (Of) My 2) 21

NW