## **GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE** NEW DELHI-110 001.

No.F.6/DFS/MS/School/2024/SZ 440

Dated: 17/05/2024

## **FIRE SAFETY CERTIFICATE**

Certified that the Mahima Children Valley Public School, A-29, Gali No.-2, Rajapuri, Uttam Nagar, New Delhi-110059, comprised of ground floor only owned/occupied by Mahima Children Valley Public School was issued Fire Safety Certificate by this department vide letter no. F.6/DFS/MS/School/2018/SZ/1174 dated 22.05.2018 was re-inspected by the officer concerned of this department on 13.05.2018 in the presence of Smt. Mahima (Principal) and found that Mahima Children Valley Public School have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises is fit for occupancy class "Educational Building" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed as below.

Issued on ....17. 05. 2024 at New Delhi.

Director

Delhi Fire Service

Copy to:-

1. The Principal, Mahima Children Valley Public School, A-29, Gali No.-2, Rajapuri, Uttam Nagar, New Delhi-110059

2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

## Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

## INSPECTION REPORT

Mahima Children Valley Public School, A-29, Gali No.-2, Rajapuri, 1. Name & address of the building:

Uttam Nagar, New Delhi-110059.

2. Type of Occupancy : Educational : Ground floor only 3. Building Comprised of

4. Type of Case Renewal

: F.6/DFS/MS/School/2018/SZ/1174 dated 22.05.2018 5. Details of Previous NOC

Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 6. Fire Safety directives letter No :

13.05.2024 7. Date of inspection

A.D.O. R.K. Yadav (JKP) 8. Name of Inspecting Officer

9. Name and designation of officers

: Smt. Mahima (Principal) From the building side

Before 2008 10. Year of Construction

. No.	Applicant's  Minimum fire safety	Standards on fire prevention and	Requirement as per FSC dt. 22.05.2018	Provided at site	Remarks MR/NMR			
	Access to building							
	• G	oad width ate width idth of internal road	Accessible (06 mtrs) 4.5 mtrs N/A	06 mtrs Directly accessible from road N/A	MR MR N/A			
2.	Number, Width, Type & Arrangement of Exits							
	Marks	r of staircases	8					
		I of staticases  Jpper Floors	N/A	N/A	Ground floor only			
		Basements	N/A	N/A	N/A			
		of staircases						
		Jpper Floor	N/A	N/A	Ground floor only			
	. I	Basements	N/A	N/A	N/A			
	c. Protect	ion of exits	TUTE	Ca utarra tes				
		Fire check door	N/A	N/A	N/A			
	• I	Pressurization	N/A	N/A	N/A			
			N/A	10.1				
	1 No o	f continuous staircases to	N/A	N/A	N/A			
	d. No. o			N/A	N/A			
	e. Width of Corridor		N/A	- Commen				
	f. Door		100 cms	90 cms (Double door)	M/R, being old case			
3.	Compar	tmentation			27/4			
		Fire check door	N/A	N/A	N/A			
		Sealing of electrical shafts	N/A	N/A	N/A			
1		Fire Rating of shaft door	N/A	N/A	N/A			
		Water Curtain	N/A	N/A	N/A			
		Fire Dampers	N/A	N/A	N/A			
	Smoke Management System							
4.	Basements		N/A	N/A	N/A			
		Upper floors	N/A	N/A	N/A			
5.	Fire Ex	tinguishers		- 24				
5.		- 1hare	02 no's	Provided	M/R			
	13447	Total numbers	ABC/CO <sub>2</sub> type	Provided	M/R			
	1 1	Types IS marking	ISI marked	ISI marked	M/R			
		19 mmgmg	, isi markeu	Western (1970)				

	Total numbers on each floor	N/A	N/A	N/A			
1	Length of hose reel hose	N/A	N/A	N/A			
	Nozzle diameter	N/A	N/A	N/A			
	Automatic fire detection and alarming system	25-21/2					
	Type of detectors     Location of Main Panel	N/A	N/A	N/A			
	Location of Nami Failer     Location of Repeater Panel	N/A	N/A	N/A			
	Alternate source of power	N/A	N/A	N/A			
	Hooters' Location	N/A	N/A	N/A			
	MOEFA	N/A N/A	N/A	N/A			
	Public Address System	T 955	N/A	N/A			
6		N/A	N/A	N/A			
.0.	Automatic Sprinkler System						
	Basement	N/A	N/A	N/A			
	Ground Floor	N/A	N/A	N/A			
	Sprinkler above false ceiling	N/A	N/A	N/A			
11.	Internal Hydrants						
	Size of riser/down-comer	N/A	N/A	N/A			
	Number of hydrants per floor	N/A	N/A	N/A N/A			
	Hose Box	N/A	N/A	N/A			
12.	Yard Hydrants		05/19/17/25				
	Total number of hydrants	NT/A	37/4				
	Hose Box	N/A N/A	N/A	N/A			
13.	Pumping Arrangements	IN/A	N/A	N/A			
	Ground Level		T T				
	> Discharge of main Pump	N/A	NT/A				
	> Head of Main pump	0.37.032	N/A	N/A			
	> Number of main pumps	N/A	N/A	N/A			
	> Jockey Pump out put	N/A	N/A	N/A			
	> Jockey pump head	N/A	N/A	N/A			
	Standby Pump out put	N/A	N/A	N/A			
	Standby Pump Head	N/A	N/A	N/A			
	> Auto Starting/Manual Stopping	N/A	N/A	N/A			
		N/A	N/A	N/A			
	Pump House Access	N/A	N/A	N/A			
	Terrace level		2.224	IVA			
	Discharge of pump	N/A	N/A	27/4			
	Head of the pump	N/A	N/A N/A	N/A			
	<ul><li>Power Supply</li></ul>	N/A	N/A N/A	N/A N/A			
	Auto Starting of pump	N/A	N/A	N/A N/A			
14.				IVA			
	Captive Water Storage for fire fighting						
	Underground tank capacity	N/A	N/A	37/4			
	<ul> <li>Draw-off connection</li> <li>Fire service inlet</li> </ul>	N/A	N/A	N/A			
	Access to tank	N/A		N/A			
	Overhead Tank capacity	N/A	N/A	N/A			
15.		N/A	N/A	N/A			
	Exit Signage.	N/A N/A	N/A	N/A			
16.	Provision of Lifts.		N/A	(No Lift)			
	Pressurigation CV to G						
	<ul> <li>Pressurization of Lift Shaft</li> <li>Pressurization of Lift lobby</li> </ul>	N/A	N/A	N/A			
	Communication In lift Car	N/A					
	• Fireman's Grounding Switch	N/A	N/A N/A	N/A			
	Lift Signage	N/A		N/A			
		N/A	N/A N/A	N/A			
1 3							

17.	Standby power supply	N/A	N/A	N/A		
18.	Refuge Area.					
	> Total Area > Location	N/A	N/A	N/A		
		N/A	N/A	N/A		
19.	Fire Control Room					
	Detector System Panel Flow Switch Panel PA System Panel Battery backup Building Floor Plans	N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F.6/DFS/MS/School/2018/SZ/1174 dated 22.05.2018, renewal in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Signature of Inspecting Officer Name:- R.K. Yadav

Designation:- ADO (JKP)

Divisional Officer (South West)

> 16/8/27

Dinecter

m