



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F.6/DFS/MS/School/SZ/2024/409

Dated: 10 105 12024

FIRE SAFETY CERTIFICATE

Certified that the Sanwal Das Memorial School located at Mahawar Nagar, Kotla Mubarakpur, New Delhi–110003, building comprised of ground plus three upper floors, was issued fire safety certificate by this department vide letter No. F6/DFS/MS/School/2018/SZ/2711 dated 24/12/2018. The said school was re-inspected by the officer concerned of this department on 04/05/2024 in the presence of Mr. Gopal Koli of the school and observed that the said premises have deemed complied with the fire prevention and fire safety requirements in according with Circular no. F.16/Estate/CC/Fire/Safety/2011/3298-3398 dated 01/03/2011 issued by Director of Education, Govt. of NCT of Delhi and that the building/premises is fit for occupancy class "Educational" (Group-B) with effect from the date of issuance of this certificate for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 10/05/2029 at New Delhi by

DIRECTOR DELMI FIRE SERVICE

Copy to: -

- The Manager, Sanwal Das Memorial School at Mahawar Nagar, Kotla Mubarakpur, New Delhi-110003
- 2. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054

Conditions for the validity of Fire Safety Certificate:

- 1. All the means of escape / entry / exit shall be kept free from any obstruction.
- All the fire safety arrangement provided there in shall be maintained in good working conditions at all times. Any loss of life or property due to non-functional fire safety measure shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3. of UBBL-2016), if any.
- 5. The owner/occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The foam is available on www.dfs.delhigovt.nic.in.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule37] along with a copy of this Certificate, six months prior to its expiry".

		N REPORT				
1	Name & Address of the Building Sanwal Das Memorial School, Mahawar Nagar, Kotla Mubarakpur, New Delhi-1 (Sahari ID: 1024157)					
		(School ID: 1924157) Educational "Group-B" (School)				
	1) po 01 01 1 1					
3	Building Comprised of	Ground + Three upper Floors.				
4	Type of Case	Renewal				
5	Details of Previous NOC	F6/DFS/MS/School/2018/SZ/2711 dt. 14/12/2018				
6	Fire Safety Directives Letter No F.16/Estate/CC/Fire Safety/2011/3298 to 3394 dated 01/03/2011					
7	Date of Inspection	04/05/2024	A DO/CD			
8	Name of the Inspecting Officers	Santosh Kumar (ADO/SJ) Mr. Gopal Koli (Manager)				
9	Name & Designation of Officers	Mr. Gopal Koli (I	vianager)			
	from the building side	2010				
10	Year of construction	2010 Email dated 29.04.2024				
11	Applicant letter No.	Requirement/	Provided at	Remarks		
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Existing Fire Protection System	Site	MR/NMR		
1	Access to Building.		Provided	MR		
-	Road width	6m		NA		
	Gate width	NA	NA			
	 Width of internal road 	NA	NA	NA		
2	Number, width, type & arrangeme	nt of exits.		4		
_	a) Number of Staircase	r man		T vm		
	> Upper floors.	Two	Two	MR		
4	> Basement floor.	NA	NA	NA		
Ĭ	b) Width of Staircase	1.5 / 0.75	1.10m & 1.05m	MR		
	> Upper floors	1.5m / 0.75m	1.1011 & 1.0511	(old case		
î -	Basement floor	NA	NA	NA		
	c) Protection of exits	annu May n				
Ě	> Fire check door	NA	NA	NA		
	> Pressurization	NA	NA	NA		
1	d) No. of continuous staircase to terrace	NA NA	NA	NA		
	e) Width of corridor	1.5m	Provided	MR		
)	f) Door size	1m	Provided	MR		
	Compartmentation.					
-	Fire check door.	NA	NA	NA		
	The same of the sa	NA	NA	NA		
	Sealing of electrical shafts. Figure 1 and	NA NA	NA	NA		
	• Fire rating of shaft door.	NA NA	NA NA	NA		
	Water curtain	2 2 2	NA NA	NA		
1_	• Fire dampers.	NA	INA	INA		
	4 Smoke Management system.		N7.4	NT.A		
	Basement	NA	NA	NA		
1	Upper floors	NA	NA	NA		
	5 Fire Extinguishers.					
	 Total numbers 		14 Nos	MR		
	Types	ISI marked	ABC & CO ₂	MR		
	ISI Marking	_	Provided	MR		
	6 First Aid Hose Reels.					
2	Total numbers on each floor	or.	02 Nos	MR		
	 Length of hose-reel hose. 	Hose-reel	30m	MR		
			5mm	MR		
	Nozzle Diameter		244444			

S

	Automatic fire detection & alarming s	NA NA	NA	N/
	Type of detectors	F West .	NA	N/
	 Location of Main Panel 	NA		NA NA
	 Location of Repeater Panel 	NA	NA	92/168-5
	 Alternate source of power 	NA	NA	NA
	 Hooter's location 	NA	NA	NA
8 N	MOEFA	NA	Provided NA	NA
9 I	Public Address System	NA		NA
	Automatic Sprinkler System			
	Basement	NA	NA	NA
	Upper floors	NA	NA	NA
	Sprinkler above false ceiling	NA	NA	NA
11 1	Internal Hydrants.			
	Size of Riser/Down-comer	NA	NA	NA
	Number of Hydrant per floor	NA	NA	NA
	Hose box.	NA NA	NA	NA
12	Yard Hydrants.	132	1412	
12	Total number of hydrants.	NA	NA	NA
	Hose box.	NA NA	NA	NA
10	77.70.70.70.70.70.70.70.70.70.70.70.70.7	INA	NA	IVA
13 1	Pumping arrangements.	July 1911		
	Ground Level	7000 Str. 1-16 A	wheel philosophical	I NA
	Discharge of main pump.	NA NA	NA NA	NA NA
	Head of main pump.Number of main pumps.	NA NA	NA NA	NA NA
	> Jockey Pump output.	NA NA	NA NA	NA
. 1	> Jockey Pump head.	NA	NA	NA
- 1	Standby Pump output.	NA	NA	NA
	> Standby Pump head.	NA	NA	NA
	 Auto Starting/Manual Stopping. Pump house access. 	NA	NA	NA
	rump nouse decess.	NA	NA	NA
	 Terrace Level Discharge of pump. 	450 LPM	Provided	MR
	Head of pump.	35m	Provided	MR
	> Power supply.	Required	Provided	MR
1	> Auto starting of pump.	Required	Provided	MR
14	Captive water storage for fire fighting.	required	11011404	
	Underground tank capacity.	NA	NA	NA
	Draw-off connection.	NA	NA	NA
	> Fire Service Inlet.	NA	NA	NA
	Access to tank.	NA	NA	NA
	Overhead tank capacity.	10,000 ltrs	Provided	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts. Pressurization of lift shaft.	NA	· NA	NA
	Pressurization of lift lobby.	NA NA	NA NA	NA
1/4	Communication in lift car.	NA	NA	NA
		NA	NA	NA
	 Fireman's switch. 	1421	1 1 2 2	
-	Lift signage.	NA	NA	NA
17 18	The state of the s	The second secon	A.000035	

19	Fire Control Room.			
	Detector system panel.Flow switch panel.	NA	NA	NA
	 PA system panel. Battery backup. Building floor plan. 	NA	NA	NA
		NA	NA	NA
		NA	NA	NA
20	Special Fire Protection System for the	NA	NA	NA
	Protection of Special Risk, if any.	NA	ABC type fire extinguisher provided near electrical panel	NA

The fire protection systems provided in the building were checked, tested at random and found functional at the time of inspection. The shortcomings earlier observed and communicated vide this department letter No. F.6/DFS/MS/School/SZ/2023/443 dated 04/10/2023 found complied.

Keeping in view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the Fire Safety Certificate ssued vide letter No. F.6/DFS/MS/School/2018/SZ/2711 dated 14/12/2018, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: Santosh Kumar Designation: ADO (SJ)

Jutes is protop for your sine