FORM 'H'

FORM FOR ISSUING FIRE SAFETY CERTIFICATE

[Refer sub - rule (1) of rule 35]
GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI

HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE
NEW DELHI

No. F6/DFS/MS/2024/9H 139

Dated: 13 /05/2024

FIRE SAFETY CERTIFICATE

Certified that the M/s Silver Stone guest house, Located at, Ground, 1st, 2nd, & 3rd floor, 13A/22, B.C, Marg, Karol Bagh, New Delhi-110005, in a building comprised of Basement + Ground + 4 Upper Floors using basement as (storage) Ground floor (office, reception, lobby & shops), 1st floor to 3rd floor (05 guest rooms each floor) (Total=15 rooms) 4th floor(vacant/sealed) was issued FSC vide Letter No. F6/DFS/MS/GH/SZ/2021/423, dated 24/09/2021. The premises was re inspected by the officer concerned of this department on 03/05/2024 in the presence of Sh. Ramesh Rawat (Manager) and observed that all the fire prevention and fire safety arrangements provided in the premises found in good working condition. The premises have therefore deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Residential" (guest house) at Ground floor = office, reception, lobby & shops, 1st floor to 3rd floor 05 guest rooms each floor (Total=15 rooms) with effect from 13 05/2024 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 13 05 120 24.. at New Delhi by.

Copy to:

 The Joint. Commissioner of Police (Lic), 1st Floor, Licensing Unit, Police Station, Defence Colony, New Delhi.

2. The Manager, M/s Silver Stone guest house, Located at, Ground, 1st, 2nd & 3rd floor, 13A/22, B.C, Marg, Karol Bagh, New Delhi-110005.

Following fire safety directives must be adhered to:-

1. 4th floor shall not be used as per undertaking given by owner/management.

- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. Basement strictly shall be kept vacant as seen during inspection.
- 8. The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.
- 9. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in

N25

INSPECTION REPORT

 Name & address of the building: M/s Silver Stone guest house, Located at, Ground, 1st, 2nd & 3rd floor, 13A/22, B.C, Marg, Karol Bagh, New Delhi-110005.

2. Type of Occupancy

:Lodging or rooming "A-1"

3. Type of Case: Renewal (Running at Ground, 1st, 2nd & 3rd floor in a building comprised of Basement, Ground + 3Upper Floor&4th floor (Sealed).

4. Details of previous NOC: F6/DFS/MS/GH/SZ/2021/423, dated 24/09/2021

5. Fire Safety directives Letter No.: Nil

6. Date of inspection

:03/05/2024

7. Name of the Inspecting Officer: ADO (DWK)

8. Name and designation of Officer

from the building side

: Sh. Ramesh Rawat (Manager)

9. Year of Construction

: Before 2010-11

10. Applicant's letter No.

: 202403300857, dated 18/04/2024

S No	Minimum standards on fire prevention and fire safety U/R:	33		per N 22 &		Pro	ovided a		arks NMR
1.	Access of building			1.1					
. •	Road width	06	mtr	S		Provi	ded		MR
	Gate width	N	A	1.3	Direct	acces	sible fro	om road	NA
i.	 Width of internal road 	N	Α.		NA		la		NA
2.	Number, width, Type & Arrang	gem	ents	of ex	cits			7	1
6 2 1	a. Number of staircases								
	Upper floors	01 No 01 No		01 No.		01		MR (Being old cas	
	Basements				02	2 Nos.	MR		
127	b. Width of staircases								
*	Upper floors	1.	25m		1.30 n	n .	ı	MR (Bein	g old case)
	Basements	0	ld ca	se	1.10m	D 50			g old case)
	c. Protection of exits		AI.			00.7	7 7 7		8
	Fire check door	N.	A		NA				NA
	 Pressurization 	NA		ottor il			NA		NA.
li i	d. No of continuous staircase to terrace	01				la ' r'	01		MR
•	e. Width Of Corridor	1	m		1.30n	1 :	<u>' </u>	MR (Beir	g old case)
	f. Door Size		1m		0.84 m			MR (Being old cas	
3.	Compartmentation ·							WIII (Dell	ig old case,
	Fire check door			NA		NA			NA
4	Sealing of electrical sha	ical shafts		Rec	uired	Sealed		III N	MR
	 Fire Rating of shaft do 		or NA		NA		VI ALL		
	Water Curtain			NA		NA			NA NA
	Fire Dampers			NA		NA			NA
4.	Smoke managements System								INA
	Basements 30 a		a/c per hour		Exl	Exhaust fan provided			MR
	• Upper floors 12 a	/c p				Provided			MR
	7							.,	



N/26.

5.	Fire Extinguishers	1		•	Provided	MR
	 Total numbers 	14 N		•	CO ₂ & ABC	MR
	 Types 		2 & C			MR
	IS marking	Req	uired	\$0.00	Provided	IVIIX
j	First - Aid Hose Reels		J. LA		Provided	MR
	Total numbers on	01			Flovided	
	each floor	20	. 4		Provided	MR
	Length of hose reel	30 n	nur		1101140	
	hose	5 M	M	140	Provided	MR
7	Nozzle diameter Automatic fire detection and a	- 28 S		em		
7	Type of detectors	CO	detect	ors .	Provided	MR
	Location of Main		uired		Provided	MR
	Panel	Keq	uneu		. 1101.000	× 1
9	Location of Repeater	NA	AL O. A.	·NA	to a constitute	NA.
	Panel	1,77	IM. C			
2.0	Alternate source of	Requ	uired.	Provid	ded	MR
	power				*	
	Hooters' Location	Requ	ired		Provided	MR
8.	MOEFA .	Requ	ired	Provid	ded	MR
9.	Public Address System	Requ	iired	Provid	ded ·	MR
10.	Automatic Sprinkler System	die in	Kir'i		r state of the last of the las	
ź	Basements	NA	Pro	vided	Area less than 20	
	Upper Floor	NA		e e	NA	NA
	Sprinkler above false	NA.			NA	NA
	ceiling				() Silving (Min + Aso)	يشيليه
11:	Internal Hydrants: • Size of riser/down- cor		NA		NA	NA
	Number of hydrants per					1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	Hose Box	1 11001	INA		· NA	NA
		4 bi i	NA	#PSetF	NA .	NA
12.	Yard Hydrants	LATA			A A SECOND	INTA
	Total number of	NA .			NA NA	NA NA
	hydrants • Hose Box	INA			NA	INA
3.	Pumping Arrangements:				e des arismane at	
٥.	• Ground Level					
	Discharge of main pum	n I	VA.	5 - 1 - 1	· NA	NA
	> Head of main pump	r _	VA.		NA	NA
	> Number of main pumps		NA.		NA	NA
	> Jockey pump out put		NA	100	NA	NA
	Jockey pump head	N	IA .	d of	NA	NA
, i	Standby Pump out put	N	NA	- Otto	NA	NA
	> Standby Pump Head		JA .	eta e	. NA	NA
	➤ Auto Staring/Manual	N	IA .		. NA	NA
					a Vandamilla	
	stopping .		IA ·	4.6	NA .	NA
•	> Pump House Access	I				or 10 1
	Pump House AccessTerrace level		50.1		[D	2.00
	 Pump House Access Terrace level Discharge of pump 	4	50 lpn		Provided	MR
	 Pump House Access Terrace level Discharge of pump Head of the pump 	4	0 mtrs	1	Provided	MR
	 Pump House Access Terrace level Discharge of pump 	4 4 R		1		

No. W

i. C	• Under ground tank capacity	NA				NA
		NA		NA		NA NA NA
		NA		Pro	vided	
	> Access to tank	NA.		NA		
1	Overhead Tank capacity	Old d	case .	4000 ltr		MR
15		Requ	iired	Pro	ovided	MR
	Provision of Lifts ·					
	 Pressurization of Lift Shaft Pressurization of lift lobby Communication in lift Car Fireman's Grounding Switch 		NA	N/	\	NA
,			NA	· NA	Α	NA
1			Car Required		ovided	MR
			Required		ovided	MR
0	➤ Lift Signage	age .		Pr	ovided	MR
17.			Required Required		ovided	MR
18.	Refuge Area					
10.	> Total area > Location		NA	NA		NA
			NA.	NA		NA
19.	Fire control room	5.45	•	157		NA
	> Detector system panel	l NA			<u>A</u>	NA NA
	 ➤ Flow Switch Panel ➤ PA System Panel ➤ Battery backup 				Α	NA NA
345			1	NA NA		NA NA
			1			NA NA
	Building Floor Plans	· ·NA	4	_ IN		NA.
20	> Building Floor Plans	ms for	r NA	. N	NA	

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of minimum standards on fire prevention and fire safety as required under the rules the NOC issued vide letter No. F6/DFS/MS/GH/SZ/2021/423, dated 24/09/2021 renewal under Rule 37 of the Delhi Fire Service Rules 2010 is recommended. If approved FSC may be issued.

Signature of the Inspecting Officer

Name: Sh. Udaivir Singh Designation: ADO (DWK)

D / States

10 (3) | mg/

Directary

Aor am