

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001**



No. F6/DFS/MS/2024/School/ 453

Dated: 22 /05 /2024

FIRE SAFETY CERTIFICATE

Certified that The Redwoods School located at Main Sant Nagar Marg, Burari, Delhi-110084 comprised of Ground floor only owned/ occupied by The Redwoods School was granted FSC by this department vide letter No. F6/DFS/MS/2017/School/WZ/1204 dated 14.08.2017. The premises was re-inspected by the officer concerned of this department on 13.05.2024 in the presence of Mrs. Savita Kalra (Principal) and observed that all the fire prevention and fire safety arrangements as provided in the premises found in good working condition. The premises have deemed complied with requirements of circular issued by Director of Education letter no 3298-3398 dated 01.03.2011 and the building/ premise is fit for occupancy Group B Educational with effect from .. 22 105. 12024... for a period of three years, subject to compliance of the conditions mentioned below:

Issued on 22 05 2024 at New Delhi

tul Garg) Director

Ph:-011-23414000

Copy to: -

1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi - 110054.

2. The Principal, The Redwoods School located at Main Sant Nagar Marg, Burari, Delhi-110084.

Conditions for the validity of Fire Safety Certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection.

3. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

4. All the staff members must know the correct method of operation of firefighting system.

5. The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule Delhi Fire Service Rules 2010. of The form http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms.

6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-

2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

INSPECTION REPORT

Name & address of the building

Type of Occupancy 2.

: The Redwoods School at Main Sant Nagar Marg, Burari, Delhi-110084.

: Educational

3. Type of Case

: Renewal

Composition of building

: Ground Floor Only

Details of previous NOC 5.

: F6/DFS/MS/2017/School/WZ/1204

Dated: 14.08.2017

Fire Safety directives letter No

: Director of Education Circular dated 01.03.2011

Date of inspection

: 13.05.2024

Name of the Inspecting Officers

: ADO (RN)

Name and designation of officers

from the building side

: Mrs. Savita Kalra (Principal)

10. Year of Construction

11. Applicant's letter No.

: Letter No. TRWS/Fire/NOC/2024/07 dated 30.04.2024

	Minimum Standards on fire prevention and fire safety U/R 33	Requirement as per Rule 35 (6)/ Inspection dated 03.07,2014	Provided at site	Remarks MR/NMR				
	Access to building							
	Road width	06m	06m	MR				
	Gate width Width of internal road	4.5m	4.5m	MR				
		NA	NA	NA				
	Number, Width, Type & Arrangement of Exits							
	a. Number of staircases	Lucius de la						
	Upper Floors	NΛ	NA	NA				
	Basements	NA	NA	NA				
	b. Width of staircases							
	Upper Floors	NA NA	NΛ	NA NA				
	Basements	INA	NA	NA				
	c. Protection of exits	N. 1	أم المرمولات الكراك					
	Fire check door	NA NA	NA NA	NA				
	Pressurization		NA	NA				
	d. No. of continuous staircases to terrace	NA	NΛ	NA				
	e. Width of Corridor	NA 1 m	NA Im double door	NA				
	f. Door Size		Till double door	MR				
	Compartmentation.							
	Fire check door	NA	NA	NA				
	• Sealing of electrical shafts	NA	NA	NA				
	Fire Rating of shaft door	NA	NΛ	NA				
	Water Curtain	NA	NΛ	NA				
	Fire Dampers	NA	NA	NA				
	Smoke Management System.							
	Basements	NA	NA	NA				
	Upper floors	NA	NA	NA				
	Fire Extinguishers							
	Total numbers	03nos	06nos	MR				
	gt.	Q		,,,,,,				

Autor MOE Public Autor Intern Yard I	Types	ABC/CO2				
Autor MOE Public Autor Intern Yard I	ISI marking		ABC-06			
Autor MOE Public Auton Intern Yard I	-Aid Hose Reels.	ISI Marked	Yes			
Autor MOE Public Auton Intern Yard I						
MOE Public Auton Auton Auton Intern Yard I	. oral mambers on each floor	NA	NA	N		
MOE Public O Auton Intern Yard I	Length of hose reel hose	NA	NA	N.		
MOE Public O Auton Intern Yard I	Nozzle diameter	NA				
MOE Public O Auton Intern Yard I	matic fire detection and alarming system	m.	NA	N.		
MOE Public Auton Intern Yard I	Type of detectors	NA	NA	NA NA		
MOE Public Auton Intern Yard I	Location of Main Panel	NA NA	NA	NA.		
MOE Public Auton Intern Yard I	Location of Repeater Panel	NA	NA	NA		
Public O Auton Intern Yard J	Alternate source of power	NA	NA	NA		
Public O Auton Intern Yard J	Hooters' Location	NA				
Public O Auton Intern Yard J	EA	NA NA	NA NA	NA NA		
O Auton Intern Yard I		83.020				
Intern Yard I	c Address System.	NΛ	NA	NA		
Intern Yard I	Automatic Sprinkler System.					
Intern Yard I	Basement	NA	NA	NA		
Intern Yard I	Upper Floor	NA	NA	NA		
Yard J	Sprinkler above false ceiling	NA	NA	NA		
Yard J	nal Hydrants		Later of the same			
Yard I	*	MA	NA	NA		
•	Size of riser/down-comer	NA NA	NA NA	NA		
•	Number of hydrants per floor Hose Box	NA NA	NA	. NA		
•						
Pumpi	Hydrants. Total number of hydrants	NA	NA	NA		
Pumpi	Hose Box	NA	NA	NA		
Pumpi						
	Pumping Arrangements.					
	Ground Level	NI/A	N/A	N/A		
	Discharge of main Pump	N/A	N/A	N/A		
	Head of Main pump Number of main pumps	N/A		N/A		
	D and but	N/A	N/A	N/A		
	Jockey pump head	N/A	N/A	N/A		
	Standby Pump out put	N/A	N/A N/A	N/A		
	Standby Pump Head	N/A N/A	N/A	N/A		
	Auto Starting/ Manual stopping	N/A	N/A	N/A		
	Pump House Access		714	NA		
	Terrace level Discharge of pump	NA	NA NA	NA		
	> Head of the pump	NA	NA NA	NA		
	> Power Supply	NA		NA		
	> Auto Starting of pump	NA	NA	NA		
Captive	e Water Storage for fire fighting.		NA	NA		
4	Underground tank capacity	NA	NA NA	NA		
×	Draw-off connection	NA	INA	1,41		

•	•						
	> Fire service inlet	NA	NA NA	NA			
	> Access to tank	NA	NA	NA			
	Overhead Tank capacity	NA	NA	N/			
5	Exit Signage.	NA	NΛ	NA			
6	Provision of Lifts.						
8	Pressurization of Lift Shaft	N/A	N/A	N/A			
	Pressurization of Lift lobby	N/A	N/A	N/A			
	Communication In lift Car	N/A	N/A	N/A			
	Fireman's Grounding Switch	N/A	N/A	≪ N/A			
	Lift Signage	N/A	N/A	N/A			
7	Standby power supply	N/A	N/A	N/A			
18	Refuge Area.						
	> Total Area	N/A	N/A	N/A			
	Total Area Location	N/A	N/A	N/A			
19	Fire Control Room	11					
D		N/A	N/A	N/A			
	Detector System Panel Flow Switch Panel	N/A	N/A	N/A			
	PA System Panel	N/A	N/A	N/A			
	Batter backup	N/A	N/A	N/A			
	Building Floor Plans		N/A	N/A			
		N/A	N/A	N/A			
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	10.00.00				

The fire protection systems provided in the building were tested/ checked randomly and found in

good working condition, at the time of inspection. Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in director of education Circular dated 01.03.2011, it is recommended to renewal of fire safety certificate issued vide this department letter of even F6/DFS/MS/2017/School/WZ/1204 dated 14.08.2017.

Dy. Chief Fire Officer (WZ)

Signature of the Inspecting Officer Name :-C.L. Meena

Designation:- ADO/RN

There is No file funding befor recived this file.