

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/2024/School/ 454

Dated: 22 / 05/2024

FIRE SAFETY CERTIFICATE

Certified that Ujjwal Public School located at 25 Futa Road, Kaushik Enclave, Burari, Delhi-110084 comprised of Ground floor only owned/occupied by Ujjwal Public School was issued FSC by this department vide letter no. F6/DFS/MS/School/2019/2289 dated 10.12.2019. The premises was inspected by the officer concerned of this department on 15.05.2024 in presence of Mr. Omesh Kumar (Manager) and observed that all the fire safety arrangements as provided in the premises found in good working condition. The premises have deemed complied with requirements of circular issued by Director of Education vide letter no 3298-3398 dated 01.03.2011 and the building/ premise is fit for occupancy class "Group B Educational" with effect from ...22.19.5.1202...... for a period of three years, subject to compliance of the conditions mentioned below:

Issued on ... 22/05/2024... at New Delhi by

(Atul Garg)
Director

Ph:-011-23414000

Copy to:-

- 1. The Director of Education, Government of N.C.T of Delhi. Old Sectt. Delhi 110054.
- 2. The Manager, Ujjwal Public School located at 25 Futa Road, Kaushik Enclave, Burari, Delhi-110084.

Conditions for the validity of Fire Safety Certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms.
- This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

INSPECTION REPORT

1. Name & address of the building Type of Occupancy

:Ujjwal Public School at 25 Futa Road, Kaushik Enclave, Burari, Delhi-110084. : Educational

Dated: 10.12.2019

Type of Case

: Renewal

Coposition of building 4.

: Ground floors only

Details of previous NOC

: F6/DFS/MS/School/2019/2289

Fire Safety directives letter No

: Director of Education Circular dated 01.03.2011

Date of inspection

6.

: 15.05.2024

Name of the Inspecting Officers 8.

: ADO (RN)

9. Name and designation of officers

from the building side

: Mr. Omesh Kumar, Manager : 2005

10. Year of Construction 11. Applicant's letter No.

: Online e-mail dated: 10.05.2024

	• Road width • Gate width • Width of internal road Number, Width, Type & Arrangement of Exits a. Number of staircases • Upper Floors	01.03.2011 06m Accessible NA	06m Accessible NA	MR MR				
	Gate width Width of internal road Number, Width, Type & Arrangement of Exits a. Number of staircases	Accessible NA	Accessible	MR				
	Width of internal road Number, Width, Type & Arrangement of Exits a. Number of staircases	NΛ	extends to					
	Number, Width, Type & Arrangement of Exits a. Number of staircases		NA	NA.				
	a. Number of staircases			1971				
	and the second s		Number, Width, Type & Arrangement of Exits					
	Upper Floors							
	7:27	NA	NA	NA				
	Basements	NA	NA	NA				
	b. Width of staircases			500				
-	Upper Floors	NA	NA	NΛ				
	Basements	NA NA	NA NA	NA				
2	c. Protection of exits			*****				
	Fire check door	NΛ	NΛ	NΛ				
	Pressurization	NΛ	NΛ	NΛ				
	d. No. of continuous staircases to terrace	NA	NΛ	NΛ				
	e. Width of Corridor	NΛ	NA	MR				
1	f. Door Size		metal a value	ivite				
		01m	01m	MR				
-	Compartmentation. • Fire check door	NA NA	NA	NΛ				
	######################################	NA NA	NA NA	NA				
	Sealing of electrical shafts							
	Fire Rating of shaft door	NA	NA	NΛ				
	Water Curtain	NA	NΛ	NΛ				
	Fire Dampers	NΛ	NΛ	NΛ				
S	Smoke Management System.							
	Basements	NA	NΛ	NΛ				
	Upper floors	NΛ	NA	NA				
	Fire Extinguishers							
	Total numbers	04 nos.	05 nos.	MR				
	• Types	ABC	ABC-05	MR				
	ISI marking	ISI Marked	Provided	MR				

		48		1	
	Total numbers on each floor	NA NA	NA	NA	
	Length of hose reel hose	NA	NA	NA	
	Nozzle diameter	NA	NA	NA	
7	Automatic fire detection and alarming systematic			1	
	Type of detectors	NA	NA	NA	
	 Location of Main Panel 	NA	NA .	NΛ	
	 Location of Repeater Panel 	NA	NA	NA	
	Alternate source of power	NA	NA NA	NA	
	Hooters' Location	NA	NA .	NA	
	MOEFA	NA	NA	NA	
8	Public Address System.				
	Automatic Sprinkler System.				
10		NA	NA	NA	
		NA	NA .	NA	
	Upper Floor Seriables above false ceiling	NA	NA	NA	
	Sprinklet above talse certing				
11	Internal Hydrants	NA	NA	NΛ	
	Size of riser/down-comerNumber of hydrants per floor	NA NA	NA .	NA	
	Hose Box	NA	NA	NΛ	
		TASTASS.			
12	Yard Hydrants.	NA	NA	NA	
	Total number of hydrants	NA	NA	NA	
	Hose Box	NA			
	Ground Level		322	N/A	
	 Discharge of main Pump 	N/A	N/A		
	> Head of Main pump	N/A	N/A	N/A	
	Number of main pumps	N/A	N/A	N/A	
	> Jockey Pump out put	NA	NA	NA	
	Jockey pump head	NA	NA	NA	
	Standby Pump out put	N/A	N/A	N/A	
	Standby Pump Head Auto Starting/ Manual stopping	vones.		N/A	
	> Pump House Access	N/A	N/A		
	Terrace level	N/A	N/A	N/A	
	> Discharge of pump				
	> Head of the pump	NA	NA	NA	
	> Power Supply	NA	NA -	NA	
	Auto Starting of pump	NA	NA -	NA	
		NA	NA	NA	
	Captive Water Storage for fire fighting.	TVA			
		NA	NA -	NA	
	Underground tank capacity Draw-off connection			NA	
	> Draw-off connection > Fire service inlet	NA	NA NA	NA NA	
	Access to tank	NA	NA NA	NA NA	
	S WY WASHINGTON WAS COMPANY	NA	NA	§	
	Overhead Tank capacity	NA)	NA	NA	
-	Exit Signage.	NA	NA	NA	

5	Decision of Life						
ks .	Provision of Lifts.						
	Pressurization of Lift Shaft	N/A	N/Λ.	N/A			
	Pressurization of Lift lobby	N/A	N/A	N/A			
	Communication In lift Car	N/A	N/A	N/A			
	Fireman's Grounding Switch	N/A	N/A	N/A			
	• Lift Signage	N/A	N/A	N/A			
17	Standby power supply	N/A	N/A	N/A			
18							
18	Refuge Area.	1111	N/A	N/A			
	Total Area	N/A		57/4			
	> Location	N/A	N/A	N/A			
19	Fire Control Room						
	Detector System Panel	N/A	N/A	N/A			
	Flow Switch Panel	N/A	N/A	N/A			
	PA System Panel	N/A	N/A	N/A			
	Batter backup	N/A	N/A	N/A			
	Building Floor Plans	N/A	N/A	N/A			
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A			

The fire protection systems provided in the building were tested/ checked randomly and found in good

working condition, at the time of inspection.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as supulated in director of education Circular dated 01.03.2011, it is recommended to renewal of fire safety certificate issued vide this department letter of even no. F6/DFS/MS/School/2019/2289 Dated: 10.12.2019.

Dy. Chief Fire Officer (WZ)

Signature of the Insp Name: 1 C.L. Meena Designation:- Asst. Div. Officer (RN)

There is 40 five pending before recive
This file.

P.T.O .