c-243

## QVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI-110001**

No.F.6/DFS/MS/Club/2024/SZ/322

Dated: 22/05/2024

## FIRE SAFETY CERTIFICATE

Certified that the Club Building in the Name & Style of M/s Vasant Vihar Club located at 88, Paschimi Marg, New Delhi 110057 comprised of Basement, ground plus Two upper floors owned/ Occupied by Govt. Servants Co-operative House building Society Ltd., was issued Fire Safety Certificate by this department vide letter No. F.6/DFS/MS/Club/ 2021/SZ/345 dated 23/07/2021. The premise was re-inspected by the officer concerned of this department on 14/05/2024 in the presence of Mr. Bhuvnesh Kashyap and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Assembly Building (Club) and validity upto 31/03/2027 in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010

Issued on 22 65 /2024 at New Delhi by

DELHI FIRE SERVICE

Copy to: -

1. The Addl. Commissioner of Police (Lic.), 1st Floor, P.S. Defence Colony, New Delhi-110049. (Ref. MHA Portal ID 2024042906362 dated 29/04/2024 & 2024040404243 dated 27/04/2024)

## Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of fire fighting

system.

4. The basement shall be used as per the provisions of UBBL-2016 /NBC Part- IV.

5. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of

UBBL-2016), if any.

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

	2 L M	(4/2+	7/			
1	INSPECTION	ON REPORT	<del>आज़ादी</del>	का।		
) I	Name & Address of the Building			त महोत्सव		
2	Type of Occupancy	Vasant Vihar Club, 88, Paschimi Marg, Vasan Vihar, New Delhi-110057				
3		Assembly Building "Group D"				
	Building Comprised of	Basement, Ground plus two upper floors.				
4	Type of Case	Renewal				
5	Details of Previous NOC	F.6/DFS/MS/Club/ 2021/SZ/345 dated 23/07/2021				
6 /	Fire Safety Directives Letter No	F.6/DFS/MS/BP/90/258 Dated 27/02/1990				
7	Date of Inspection	14/05/2024				
8	Name of the Inspecting Officers	DO (South) & ADO (BCD)				
9 M.M	Name & Designation of Officers from the building side	Mr. Bhuvnesh Kashyap				
10	Year of construction	1991 Blancount o				
11	Applicant letter No.	ASSAULT LINE CONTRACTOR OF THE PROPERTY OF THE				
		MHA Portal ID 2024042906362 dated 29/04/20				
S. No.	Minimum standards on Fire Prevention	& 2024040404243 dated 27/04/2024  Old FSC Provided at Site Page				
Shud.	and Fire Safety U/R 33	requirements	Provided at Site	Remarks		
1,	Access to Building.	- oquirements	additional a	MR/NMI		
	Road width	Required	9 mtr	1		
	Gate width	Required	5 mtr	MR		
	Width of internal road	N/A	N/A	M/R		
2	Number, width, type & arrangement of ex		N/A	N/A		
	3 Dumping armageners .					
	Number of Staircase	7	a Grand Level			
	Upper floors.	Required	03 Nos.	MR		
	Basement floor.	Required	03 Nos.	MR		
N.W	Width of Staircase	айт рынфэ.	m to usermay " K			
SIM	Upper floors	Required	1.46m, 1.47m, 0.98m,	MR(old cas		
	Basement floor		1.36m, 3.05m & 3.60m	MR(old cas		
3W	Protection of exits	hand q	Seenday Pon			
337	Fire check door	Required	Provided	M/R		
SE	Pressurization betterges/	N/A	N/A	N/A		
NE	No. of continuous staircase to terrace	Required	One	MR		
SERVI	Width of corridor	N/A	N/A	N/A		
Std.	Door size	Required	2m, 1.77m 1.90m	M/R		
3	Compartmentation.	7	Authors Williams			
	Start - Co. Market State of Other		वर्गानावर प्रशासक जातिक	M/R		
157	Fire check door.	Required	Provided	M/R M/R		
612	Sealing of electrical shafts.	Required	Provided	N/A		
DV.	Fire rating of shaft door.	N/A	N/A	N/A		
107	Water curtain	N/A	N/A			
13/4	Fire dampers.	N/A	N/A	N/A		
4	Smoke Management system.		agangir n			
-	Basement	Required	Exhaust fan Provided			
REAL	Upper floors	N/A	N/A	N/A		
5	Fire Extinguishers.	208 (5) this	purpar mayari 🤘	Ď.		
814	Total numbers	25 Nos.	25 Nos.	MR		
25.00	Total numbers		ABC-15 &	MR		
Shirt .	• Types	ABC/W.CO <sub>2</sub>	W.CO <sub>2</sub> -10	2050		
	ISI Marking	ISI marked	Provided 1	MR		
SPA	First Aid Hose Reels.		naty of a	18 14		
6			Provided	MR		
AWA	Total numbers on each floor.	One		MR		
	<ul> <li>Length of hose-reel hose.</li> </ul>	30m	30m	1.5		
	Nozzle Diameter	5mm	5mm	MR		



7	Automatic fire detection & alarming system		8 mir in memble. A smit	1
	• Time of detection & siarming system		N/A	N/A
	Type of detectors	N/A	N/A	N/A
	Location of Main Panel	N/A	N/A	N/A
78.5	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooter's location	N/A	Provided	MR
8	MOEFA	Required		MR
9	Public Address System	Required	Provided	10
10	Automatic Sprinkler System	ymoriii)	) la marante et et et	M/R
	Basement	Required	Provided Provided in restaurant	M/R
	Ground floor	Required		N/A
	Sprinkler above false ceiling	N/A	N/A	W
11	Internal Hydrants.			M/R
A Lucido	Size of Riser/Down-comer	100 mm	Provided	M/R
WA		One Provided		M/R
	Hose box.	One Provided		WIN
	The second secon		and w. cower	MR
12	Yard Hydrants.	Required	02 Nos.	MR
7	Total number of hydrants.	Required	02 Nos.	MIK
	Hose box.	A THEORY OF THE	AND THE STREET, STREET,	
13	Pumping arrangements.		Yearsher of Stateurs	MR
	Ground Level     Discharge of main pump.	1620 LPM	1620 LPM	MR
2877	and the Community of th	44m	.105.44m	MR
	Carain numns	One	associat One distance	MR
	Number of main pumps.  Jockey Pump output.	180 LPM	180 LPM	MR
	> Jockey Pump head.	60m	60m	MR
	> Standby Pump output.	1620 LPM	1620 LPM	MR
	Standby Pump head.	60m	60m Provided	MR
71-12	Auto Starting/Manual Stopping.	Required	Provided	MR
	> Pump house access.	Required	Provided	14114
Aw	Terrace Level	450 I D) 4	Provided	MR
18		450 LPM 60 m	Provided //	MR
15/9		Required	Provided	MR
56.8	> Power supply.	-	Provided	MR
	Auto starting or pump.	Required	contacto de recent	
14	Captive water storage for fire fighting.		D 41.1	MR
3),1	Underground tank capacity.	50,000 Ltrs	Provided Provided	MR
30.4	P Dian oil com	Required Required	Provided	MR
	Fire Service Inlet.	Required	Provided	MR
16	<ul> <li>Access to tank.</li> <li>Overhead tank capacity.</li> </ul>	10,000 Ltrs	Provided	MR
		Required	Provided Provided	MR
15			helicati •	1
16		Required	Provided	MR
1.	<ul> <li>Pressurization of lift shaft.</li> <li>Pressurization of lift lobby.</li> </ul>	N/A	N/A	N/A
	Communication in lift cor	Required	Provided	MR
. W	Fireman's switch.	Required	Provided	MR
展		Required	Provided	MR
17		Required	Provided	MR
18			Algeria and Market	IVIK
100	Total area	N/A	N/A	NT/ A
	Location	N/A	N/A	N/A
	Fire Control Room.	5 (20 A 7 A 1 A 1	17/7	N/A

N



20	Special Fire Protection System for the Protection of special Risk, if any.	N/A	ABC type fire extinguisher provided near electrical pane	s el N/A
20	Building floor plan.	N/A	N/A	N/A
	Battery backup.	N/A	N/A	N/A
		N/A	N/A	N/A
i.	PA system panel.	N/A	N/A	N/A
	<ul><li>Detector system panel.</li><li>Flow switch panel.</li></ul>	N/A	N/A	N/A

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F.6/DFS/MS/Club/ 2021/SZ/345 dated 23/07/2021, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

my

Signature of the Inspection Officer Name: Sh. Manoj Kumar Sharma

Design: DO (South)

Signature of the Inspecting Officer

Name: Sh. Rajesh Kumar Design: ADO (BCP)

CFO (HO)

18/51 20h

Director 905

appointed, fit Test

et el in

is protest

1

Dire

In start SMS MM

12/05/24

25/03/50