

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No.F.6/DFS/MS/GH/2024/SZ/144

Dated: ./4./.05./2024

FIRE SAFETY CERTIFICATE

Certified that the Guest House in the Name & Style of M/s Hotel Corporate Point located at A-2/7, Safdarjung Enclave, New Delhi-110029 comprised of basement and ground floor (other property) First, Second and Third floor only, but Guest house is running on 1st, 2nd & 3nd floor only having total 19 guest rooms owned/occupied by A Unit of Tribhuvan Hotels Pvt. Ltd. was issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/GH/2021/SZ/136 dated 12/03/2021. The premise was re-inspected by the officer concerned of this department on 07/05/2024 in the presence of Mr. Avinash (Manager) and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Residential Lodging, Group-A" (Guest House) and validity upto 31/03/2027 in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2011

(AMUL GARG) DIRECTOR DELHI FIRE SERVICE

Copy to: -

1. The Addl. Commissioner of Police (Lic.), 1st Floor, P.S. Defence Colony, New Delhi-110049 (Ref. MHA Portal ID 2024012200694 dated 19/04/2024)

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of fire fighting

system.

4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-

2016), if any.

6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."



		INSPECTION REPORT					
1	Name & Address of the Building	M/s Hotel Corporate Point (A Unit of Tribhuvan Hotels Pvt. Ltd.) located at A-2/7Africa Avenue Marg, Safdarjung Enclave, New Delhi-110029					
2	Type of Occupancy	Residential, "Group-A" (Guest House)					
3	Building Comprised of	Basement, Ground + 03 upper floors.					
4	Type of Case	Renewal					
5	Details of Previous NOC	F6/DFS/MS/GH/2021/SZ/136 dated 12/03/2021					
6	Fire Safety Directives Letter No	Nil					
7	Date of Inspection	07/05/2024					
8	Name of the Inspecting Officers	DO (South) & ADO (BCP)					
9	Name & Designation of Officers from the building side	Mr. Avinash (Manager)					
10	Year of construction	Guest House is running on 1st, 2nd & 3rd floor only having total 19 guest rooms (Basement & Ground floor is other's property)					
11	Applicant letter No.	MHA P	ortal ID 2	024012200694 dated 19/	04/2024		
No.	Minimum standards on Fire Prevention	Old.	NO.C.	Provided at Site	Remarks MR/NMR		
	and Fire Safety U/R 33	require	ments		MINITAL		
1	Access to Building.	n	: I	12 mtr	MR		
1	Road width	Requ		-NA-	-NA-		
A. 1	Gate width	-NA-		-NA-	-NA-		
	Width of internal road	-N.	A-	-IVA-	-1471		
2	Number, width, type & arrangement of exits.			the Mingrell and			
1	a) Number of Staircase			01 No	MR		
	➤ Upper floors.	01 No		mini tra i segui i i	90289-3074 		
T-1	➤ Basement floor.	-NA		the pelice-NA-d	-NA-		
	b) Width of Staircase		ppromi	gran Ferra (1901) - S	MR		
	> Upper floors	1.25 mtr		1:25 mtr	(old case)		
12	> Basement floor		MATHER DE	-NA-	-NA-		
			A- 7.2	1 of UBBL 2016	-1121		
. 1	c) Protection of exits	Required Required		Provided	MR		
7	➤ Fire check door			-NA-	-NA-		
	> Pressurization	-NA-		Transfer Tra) (SECANOLISE)		
5	d) No. of continuous staircase to terrace		ne	Provided	MR		
	e) Width of corridor		A-	-NA-	-NA-		
	n Door size	1	m	1.20 m (final exit)	MR		
3	Compartmentation.	presq Te product - Alize - C			3.7.1		
	Fire check door.	-NA-		-NA-system	-NA-		
	Sealing of electrical shafts.		A-	-NA-	-NA-		
. 4	Fire rating of shaft door.		A-	-NA-	-NA-		
0	Water curtain		IA-	-NA-	-NA-		
- 4	Fire dampers.		IA-	-NA-	-NA-		
4	Smoke Management system.	As per clause 7.31 of UBBL 2016					
	Resement	-NA-		-NA-	-NA-		
	Upper floors	12 A	PCH	Exhaust fan Provided	MR		
5	Fire Extinguishers.		(Letter 27)	centro openi +	3.40		
1	Total numbers		Nos	Provided	MR		
- P	Types		/ CO2	ABC & CO2	MR		
18	ISI Marking	ISI n	narked	Provided	MR		
6	First Aid Hose Reels.						
				Provided	MR		



			Provided	N
	Length of hose-reel hose.) 1 30 mtr	Provided	N
	Length of nose-reel nose. Nozzle Diameter	5 mm		
		As per clause 7.3	1 of UBBL 2016	N
7	Automatic fire detection & alarming system.	Co. Mo. Det.	Tiovides	M
	Type of detectors Shair Benefit	Required	Ground floor	-N
	Location of Main Panel Control Panel	-NA-	-NA-	M
	Location of Repeater Panel	Required	Battery backup	
	Alternate source of power	-NA-	-NA-	-N
	Hooter's location	Required	Provided	M
9	MOEFA	Required	Provided	M
10	Public Address System	Requires	127 9 4 1 1 1 2 2 2	46
10	Automatic Sprinkler System Basement	Required	Provided	M
		-NA-	-NA-	-NA
1000	Upper floors.	-NA-	-NA-	-NA
11	Sprinkler above false ceiling Internal Hadrands	-MA-	• • • •	19 14 14
100	Internal Hydrants. • Size of Riser/Down-comer	100 mm	Provided	MF
TERRY S		100 mm	Provided Provided	M
AVI SEDE	Number of Hydrant per floor Hose box.	01	Provided	MR
12		01 1	Tiovided	1 1/11
die .	Yard Hydrants.	-NA-	-NA-	-NA
	Total number of hydrants. Hose box.	-NA-	-NA-	-NA
13	Pumping arrangements.	-INA-	-INA-	-1471
- 10	Ground Level	and or chiminal for the	The state of the s	4
	Discharge of main pump.	-NA-	-NA-	-NA-
910	Head of main pump.	-NA-	-NA-	-NA-
	Number of main pumps.	-NA-	-NA-	-NA-
	> Jockey Pump output.	-NA-	-NA-Inf	-NA-
	Jockey Pump head.	-NA-	-NA-	-NA-
	Standby Pump output.	-NA-	-NA-	-NA-
	Standby Pump head.	-NA-	-NA-	-NA-
	> Auto Starting/Manual Stopping.	-NA-	-NA-	-NA-
	➤ Pump house access.	-NA-	-NA-	-NA-
	Terrace Level		THE PERSON OF	
66 -	Discharge of pump.	900 LPM	Provided 1	MR
Allega Allega	> Head of pump.	40m	Provided	MR
	Power supply.	Required	Provided	MR
	Auto starting of pump.	Required	Provided	MR
14	Captive water storage for fire fighting.	D 02 12 12 1	NE (2002) 21 . 4) î
	 Underground tank capacity. Draw-off connection. 	Required	20,000 ltr	MR
	Fire Service Inlet.	-NA-	-NA-	-NA-
	Access to tank.	Required	Provided	MR
	Overhead tank capacity.	-NA-	-NA-	-NA-
		Required	10,000 Ltr	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.	****	21 190ch 3	
	Pressurization of lift shaft.	-NA-	-NA-Viseri	-NA-
	Pressurization of lift lobby.	-NA-	-NA-	-NA-
	Communication in lift car.	-NA-	-NA-	-NA-
	• Fireman's switch.	Required NA	Provided	MR
17	Lift signage. Standby Power Sundy.	LOCALINE .	Provided	NA
1/	Standby Power Supply	Required	Provided	MR



18	Refuge Area		-,-	त महोत्सट
	Total area	-NA-	-NA-	
	Location	-NA-	The state of the s	-NA-
19	Fire Control Room.		-NA-	-NA-
	 Detector system panel. Flow switch panel. PA system panel. 	-NA-	-NA-	
		-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
	 Battery backup. 	-NA-	-NA-	-NA
	 Building floor plan. 	-NA-	Want	-NA
20	Special Fire Protection System for the Protection of special Risk, if any.		-NA	
	Total of special Risk, if any,			-NA-

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued &

communicated by this department vide letter of even no 84 dated 04/03/2024.

keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/GH/2021/SZ/136 dated 12/03/2021, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspection Officer Name: Sh. Manoj Kumar Sharma

Design DO (South)

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

Design: ADO (BCP)

CFO (HO)

Director

approved, F.T. fetter in Julity youlf sondier 11