

No. F6/DFS/MS/GH/NDZ/2024/BNOT 29

Dated: 17/05/2024

## FIRE SAFETY CERTIFICATE

Certified that the M/s Golden Petal Rooms located at 662/10, old C-2 Shivpuri Main Road, Krishan Nagar Extn, Delhi - 110051, building comprised of basement, stilt, ground plus three upper floors, (Total 15 Guest Rooms & 03 Store Rooms) owned/occupied by M/s Golden Petal Rooms was issued Fire Safety Certificate vide letter No. F6/DFS/MS/GH/2021/NDZ/456 dated 21.09.2021. The building was re-inspected by the officer concerned of this department on 10/05/2024 in presence of Mr. Vineet Arora (Owner) and found that the guest house deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Residential Building" for (1st floor: 05 Guest rooms plus store room, 2<sup>nd</sup> Floor: 05 Guest rooms plus one store & 3<sup>rd</sup> Floor: 05 Guest room plus one store room, total 15 rooms) valid up to 31/03/2027 for a period of in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rule 2010. Subject to conditions printed below.

Issued on \_\_\_17/05 | 2024 \_\_ at New Delhi by.

LHI FIRE SERVICE

Copy to:-

1. The Owner, Golden Petal Rooms located at 662/10, old C-2 Shivpuri Main Road, Krishan Nagar Extn, Delhi - 110051.

2. The Joint Commissioner of police (Lic.), Ist Floor, P.S Defence Colony, New Delhi-24 w.e.f. - MHA portal ID - 2024041905530 dated 19.04.2024.

## Conditions for the validity of Fire Safety Certificate

- 1. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry
- 2. All the means of escape shall be kept free of all the type of obstruction all the time.
- 3. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 4. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 5. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities
- 6. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

## MIZE

	Nan	na	& addrage of the building	Golden Detail	Dooms located at	((2)10 -11 0	
٠	Name & address of the building			Golden Petal Rooms located at 662/10, old C-			
				Shivpuri Main Road, Krishan Nagar Extn, Delhi			
				110051.			
2	Building is comprised of			B+S+G+3 (Guest house running at I, II & II floors, 05 Guest rooms plus one store room at each			
				floor			
3	Тут	e c	of occupancy	Residential Building			
4	Type of case			Renewal			
5	Details of previous FSC			F6/DFS/MS/GH/2021/NDZ/456 dated 21.09.2021.			
6	Fire safety directives letter no.			NBC Part - IV			
7	_		f inspection	08.05.2024.			
					Meena ADO/LAX	(MI NAGAR	
8			of the inspecting officers				
9			of the designation of	Mr. Vineet Arora (Owner)			
			from the building side	2009			
10			of construction	2008	tion No. 202109	2122143 dated	
11	Ap	pli	cant's letter no.		HOII 140. 202109.		
				30.04.2024	Provided at	Remarks	
			nimum standard of fire	Requirement NBC Part - IV		MR/NMR	
S.N	PI	rev	ention and fire safety U/R	NBC Part-1V	Site	MICHAE	
0			33				
1	Access to Building:		s to Building:		20 4	MR	
	A	R	oad width	06 mtrs.	30 mtrs.	N/A	
	В		ate width	N/A	N/A N/A	N/A	
	C Width of internal road		Vidth of internal road	N/A	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1071	
2	Nu		oer, Width, Type and Arran	igement of Exits:			
	A	N	lumber of staircases	01	03 nos.	MR	
		a	Upper floor	01 no.	(3.6 (C.5), 2.10)	MR	
		c	Basement	02 nos.	02 nos.	MIK	
	B	V	Vidth of staircases		125 610	MR /	
		a	Upper floor	1.25 mtrs.	1.25 mtrs. & 1.0 mtr.	(Accepted earlier)	
				1.25 mtrs.	1.25 mtrs. &	MR	
	-	Ь	Basement	1.23 mus.		(Accepted earlier)	
		D	Dusement	A 045-01/21/2-550-5	1.07 mtrs.	(receptor ====	
					1.07 mtrs. /	(racepas aller)	
p   14	C	P	rotection of exits		1.07 mtrs. <sup>7</sup> Provided	MR	
	C	P	rotection of exits Fire check door	Required N/A		MR N/A	
		P a b	rotection of exits Fire check door Pressurization	Required	Provided	MR	
	C	P a b N	rotection of exits Fire check door Pressurization o. of continuous staircases terrace	Required N/A 01 no.	Provided N/A 02 nos.	MR N/A MR	
		P a b N	rotection of exits Fire check door Pressurization To. of continuous staircases	Required N/A 01 no. N/A	Provided N/A 02 nos. N/A	MR N/A MR	
	D E F	P a b N to	rotection of exits  Fire check door  Pressurization  o. of continuous staircases terrace  Vidth of corridor  poor size	Required N/A 01 no.	Provided N/A 02 nos.	MR N/A MR	
3	D E F	P a b N to V	rotection of exits  Fire check door  Pressurization  To. of continuous staircases of terrace  Fire check door  Pressurization  To. of continuous staircases  To terrace  Fire check door  To continuous staircases  To terrace  Fire check door  To continuous staircases  To terrace  To continuous staircases  To terrace  To continuous staircases	Required N/A 01 no. N/A 2.0 mtrs.	Provided N/A 02 nos.  N/A 2.0 mtrs.	MR N/A MR N/A MR	
3	D E F	P a b N to W D D mp	rotection of exits  Fire check door  Pressurization  To. of continuous staircases of terrace  Fire check door  To corridor  Foor size  Foor siz	Required N/A 01 no. N/A 2.0 mtrs.	Provided N/A 02 nos.  N/A 2.0 mtrs.	MR N/A MR N/A MR	
3	D E F Co	P a b N to W D mp	rotection of exits  Fire check door  Pressurization  To. of continuous staircases of terrace  Fire check door	Required N/A 01 no. N/A 2.0 mtrs.  N/A Required	Provided N/A 02 nos.  N/A 2.0 mtrs.  N/A Provided	MR N/A MR N/A MR N/A MR	
3	D E F Co	P a b N tc W D mp F S	rotection of exits  Fire check door  Pressurization  o. of continuous staircases terrace  /idth of corridor  oor size  partmentation: ire check door ealing of electrical shafts ire rating of shaft door	Required N/A 01 no. N/A 2.0 mtrs.  N/A Required N/A	Provided N/A 02 nos.  N/A 2.0 mtrs.  N/A Provided N/A	MR N/A MR N/A MR N/A MR N/A MR N/A	
3	D E F Co A B C D	P a b N to V D mp	rotection of exits  Fire check door  Pressurization  To. of continuous staircases  terrace  Tidth of corridor  Toor size  The check door  Tire check door  Tire check door  Tire rating of shaft door  Tire curtain	Required N/A 01 no.  N/A 2.0 mtrs.  N/A Required N/A N/A	Provided N/A 02 nos.  N/A 2.0 mtrs.  N/A Provided N/A N/A N/A	MR N/A MR N/A MR N/A MR N/A MR N/A N/A	
	D E F Co A B C D E	P a b N to W D D mpF F S F F V V	rotection of exits  Fire check door  Pressurization  To. of continuous staircases of terrace  Fire check door	Required N/A 01 no. N/A 2.0 mtrs.  N/A Required N/A	Provided N/A 02 nos.  N/A 2.0 mtrs.  N/A Provided N/A	MR N/A MR N/A MR N/A MR N/A MR N/A	
3	D E F Co A B C D E	P a b N to W D D F S F V W F F mok	rotection of exits  Fire check door  Pressurization  To. of continuous staircases  terrace  Tidth of corridor  Toor size  The check door  Tire check door  Tire check door  Tire rating of shaft door  Tire curtain	Required N/A 01 no.  N/A 2.0 mtrs.  N/A Required N/A N/A	Provided N/A 02 nos.  N/A 2.0 mtrs.  N/A Provided N/A N/A N/A	MR N/A MR N/A MR N/A MR N/A MR N/A N/A	

	A	Total numbers	08 nos.	15 nos.	MR	
1	В	Types	CO <sub>2</sub> & ABC	CO <sub>2</sub> & ABC	MR	
	C	ISI marking	ISI Marked	Provided	MR	
5		st-Aid-Hose Reel:	131 Warkeu	Tiovided		
		Total numbers of each floors	01	01 no.	MR	
	B	Length of hose reel hose	01 no. 30 mtrs.	30 mtrs /	MR	
	C	Nozzle diameter	05 mm	05 mm	MR	
7		itomatic Fire Detection and Alan	APPEN MARKETA	/ /		
1			Co2 & Smoke	Co2 & Smoke	MR	
	A	Type of detectors  Location of main panel	N/A	N/A	N/A	
	B	Location of main panel  Location of repeater panel	N/A	N/A	N/A	
		Alternate source of power	N/A	N/A	N/A	
	D		N/A	N/A	N/A	
0	E	Hooters	Required	Provided	MR	
8		OEFA:	N/A	N/A	N/A	
9		blic Address System:	IN/A	N/A		
10	_	tomatic Sprinkler System:	Required	Provided	MR	
	A	Basement	N/A	N/A	N/A	
	В	Upper floor	38 (30,325,48)	N/A	N/A	
	C	Sprinkler above false ceiling	N/A	IN/A	14/21	
11	In	ternal Hydrants:		100	MR	
	A	Size of riser/down-comer	100 mm	100 mm (	MR	
	В	Number of hydrants per	01 nos.	01 nos. /	IVIIC	
		Branch	01 nos.	01 nos. /	MR	
12	C	Hose box	01 1103.	or nos.	45,957,123	
	_	ard Hydrants:	N/A	N/A	N/A	
	A	Total number of hydrants	N/A	N/A	N/A	
	В	Hose box	IN/A	IVA	1 1/1 1	
13		imping Arrangements:			-	
1	(	Ground level	NY/A	N/A	N/A	
	A	Discharge of main pump	N/A	N/A N/A	N/A	
	В	Head of main pump	N/A	N/A N/A	N/A	
	C	Number of main pumps	N/A	N/A N/A	N/A	
	D	Jockey pump out put	N/A	N/A N/A	N/A	
	E	Jockey pump head	N/A N/A	N/A	N/A	
	F	Standby pump out put		N/A	N/A	
	G	Standby pump head	N/A	N/A N/A	N/A	
	H	Auto starting /manual stopping	N/A	IVA	- 1/4 %	
2	Te	Terrace Level				
	A	Discharge of pump	450 LPM	450 LPM X 02	/ MR / MR	
	B	Head of the pump	40 mtrs	40 mtrs Provided	MR	
	C	Power supply	Required		MR	
	D	Auto starting of pump	Required	Provided	IVIIC	

50

M/38

Golden Petal Rooms located at 662/10, old C-2 Shivpuri Main Road, Krishan Nagar Extn, Delhi.

den 1	Petal	we Water Storage for Fire Fight	ing:	B-: Extil, [	veini.	
C	aptiv	inderground tank capacity	N/A	N/A	N/A	
A	Ų	nderground tank capus	Ñ/A	N/A	N/A	
B	D	raw-off connection	N/A	N/A	N/A	
1	7 F	Fire service inlet	N/A	N/A	N/A	
	-	Langes to tank	20,000 liters	20,000 liters	MR	
1	E	Overhead tank capacity	Required	Provided	MR	
15	Exit Signage:					
16	n deign of Lifts:		N/A	N/A	N/A	
10		D surization of lift shall	N/A	N/A	N/A	
+	_	n courization of IIII 1000	N/A	N/A	N/A	
-	_	Communication in lift car	N/A	N/A	N/A	
	Ď	Firemen's grounding switch	N/A	N/A	N/A	
	E	Lift signage	Required	Provided	MR	
17	Star	ndby Power Supply:	Required			
18						
10			N/A	N/A	N/A	
	A	Total area	N/A	N/A	N/A	
	B	Location	MA			
19	Fir	e Control Room:	N/A	N/A	N/A	
	A	Detector system panel	N/A N/A	N/A	N/A	
	В	Flow switch panel	N/A N/A	N/A	N/A	
1	C	PA system panel	N/A	N/A	N/A	
	D	Battery backup	N/A	N/A	N/A	
	E	Building floor plans		N/A	N/A	
20	0 Sp	pecial Fire Protection systems for rotection of special Risks, if any:	IVA	1,172		

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

Keeping In view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the rules of Directorate of Education the FSC issued vide letter no. F6/DFS/MS/GH/2021/NDZ/456 dated 21.09.2021, renewal under Rule 35 of the Delhi Fire Service rules 2010, is recommended to be renewed

No file is pending with me before disposal of this case.

Signature of the Inspecting Officer
Name- Yashwant Singh Meena
Designation- ADO (L.N)

DYCFOTNDZ

Kir fulos

15'51()20v

ANTIN