GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2024/164

Dated:20/95/2024

FIRE SAFETY CERTIFICATE

Certified that the Janta South Indian Lodge located at 4247, Tel Mandi, Pahar Ganj, New Delhi comprised of Ground + 03 Upper floors, Ground floor (Reception), 1st floor (04 guest rooms), 2nd floor (05 guest rooms), 3nd floor (05 guest rooms), total 14 guest rooms up to third floor only and terrace temporary tin shed for staff which is not to use, any floor above third floor as per an affidavit given by owner dated 30.10.2019, owned/occupied by Janta South Indian Lodge was earlier granted FSC by this department vide letter No.F6/DFS/MS/GH/NDZ/2021/351 dated 01/09/21 for 14 guest rooms up to third floor. Now, the premise was re-inspected by the officers concerned of this department on 10/05/24 in the presence of Manager and found that the said guest house building has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 Ground floor (Reception), 1st floor (04 guest rooms), 2nd floor (05 guest rooms), 3rd floor (05 guest rooms) total 14 guest rooms up to third floor only, and valid up to 31.03.2027 from the date of issue in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued 20/05/2024 at New Delhi by.

Delhi Fire Service

Copy to:-

 The Commissioner, North MCD, Civic Centre, and New Delhi: to ensure not to use any floor above third floor for any purpose and deviation if any.

2. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. Online id no.2024042205757 dated: 22/04/24.

3. The Manager, Janta South Indian Lodge 4247, Tel Mandi, Pahar Ganj, New Delhi.

Conditions for the validity of fire safety certificate

- All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

- The compliance with regards to electrical installation, structural stability, set back area, occupancy and any deviation in construction etc. shall be verified from authority concerned.
- This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

9. Any flammable material for interior decoration is prohibited.

INSPECTION REPORT

1. Name & address of the building Janta South Indian Lodge at 4247, Tel

2. Type of occupancy:- Mandi, Pahar Ganj, New Delhi. Residential, Sub Division-A-1

Gr. + 03 Upper floors (total 14 Guest rooms)
Ground floor (Reception), 1st floor (04 guest rooms),
2nd floor (05 guest rooms), 3rd floor (05 guest rooms)
and terrace temporary tin shed for staff & having
given affidavit dated 30.10.2019 regarding not

to use any floor above third floor,

3. Type of case:- Renewal

4. Details of previous FSC:- No.F6/DFS/MS/GH/NDZ/2021/351 dated

01/09/21.

5. Fire safety directives No.- N/A

6. Date of inspection:- 10/05/24

7. Name of the inspecting officer:- Sh. Ravinder Singh (ADO/CC) Sh. Rajinder Atwal (DO/CD)

 Name & designation of officer From the building side:-

Manager

9. Year of construction:- N/A
10. Applicant's letter No:- Onlin

Online id no.2024042205757 dated: 22/04/24.

S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement/ Existing fire safety arrangements	Provided at site	Remarks MR/NMR	
1.	Access to Building	180			
	1) Road width	N/A	2 mtr.	N/A	
	2) Gate width	N/A	N/A	N/A	
	3)Width of internal road	N/A	N/A	N/A	
2.	Number, Width Type & Arr	angement of Ex			
	A. Number of staircases				
	1. Upper floors	01	01	MR	
	2. Basements	N/A	N/A	N/A	
	B. Width of staircase				
	1. Upper floors	0.80 mtr.	0.87 mtr. /	MR	
	2. Basements	N/A	N/A	N/A	
	C. Protection of exits			_	
	1. Fire check door	N/A	N/A	N/A	
	2. Pressurization	N/A	N/A	N/A	
	D No. of continuous staircase to terrace	N/A	N/A	N/A	
	E. Width of corridor	N/A	N/A	N/A	
	F. Door size	01 mtr.	01 mtr.	MR	
3.	Compartmentation				
	1) Fire check door	N/A	N/A	N/A	
	2) Sealing of electrical shafts	N/A	N/A	N/A	
	3) Fire rating of shaft door	N/A	N/A	N/A	
	4) Water curtain	N/A	N/A	N/A	
	5) Fire Dampers	N/A	N/A	N/A	
4.	Smoke Management System				
	1) Basements	30 ACPH	N/A	N/A	
	2) Upper floors	Required	Provided	MR	
5.	Fire Extinguishers				
	1) Total numbers	10 Nos.	10 Nos.	MR	
	2) Types	ABC & CO2	ABC & CO2	MR	

MR Required Provided 3) ISI marking 6. First-Aid Hose Reel MR 1) Total number of eachfloor 01 01 MR 30 mtr. 30 mtr. 2) Length of hose reel hose MR 05 mm 05 mm 3) Nozzle diameter Automatic Fire Detection & Alarming System 7. 1) Type of detectors Co Type Required MR Provided 2) Location of main panel First floor Provided MR N/A N/A 3) Location of repeater panel N/A 4) Alternate source of power Provided MR Required Each floor Provided MR 5) Hooter's Location N/A N/A N/A **MOEFA** 8. **Public Address System** N/A N/A N/A 9. 10. **Automatic Sprinkler System** 1) Basement N/A N/A N/A 2) Upper floors N/A N/A N/A 3) Sprinkler above false N/A N/A N/A ceiling 11. Internal Hydrants 1) Size of riser/down-comer N/A N/A N/A 2) Number of hydrants per N/A N/A N/A floor 3) Hose box N/A N/A N/A 12. Yard Hydrants 1) Total number of hydrants N/A N/A N/A 2) Hose box N/A N/A N/A 13. **Pumping Arrangement** 1) Ground level N/A N/A N/A a) Discharge of main N/A N/A N/A pump b) Head of main pump N/A N/A N/A c) Number of main pump N/A N/A N/A d) Jockey pump out put N/A N/A N/A e) Jockey pump head N/A N/A N/A f) Stand by pump output N/A N/A N/A g) Stand by pump head N/A N/A h) Auto starting/Manual N/A N/A N/A N/A stopping 2) Terrace level a) Discharge of pump 180 LPM 180 LPM b) Head of pump MR 30 mtr 30 mtr. c) Power supply MR Required d) Auto starting of pump Provided MR Required 14. Captive Water Storage for Fire Fighting Provided MR 1) Under ground tank N/A N/A capacity N/A a) Draw-off connection N/A b) Fire service inlet N/A N/A N/A c) Access to tank N/A N/A N/A d) Over head tank N/A N/A 2500 ltr. 2500 ltr. capacity

MR

MIZZ

15.	Exit Signage.	Required	Provided (MR
16.	Provision of Lifts.			
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	NA	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection Sys Risk, if any:	N/A		

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, if agreed, we may renew the FSC issued vide letter no. F6/DFS/MS/GH/NDZ/2021/351 dated 01/09/21, under rule 35(6) of the Delhi Fire Service rules 2010 Accordingly, DFA is put up for kind perusal and signature please.

Signature of the Inspecting Officer

Signature of the Inspecting Officer

Name :- Rajinder Atwal Designation :- DO (CD)

Name:-Ravinder Singh Designation:-ADO (CC)

Dycho Cross

الم

6 5 SW 2000

1(15)1/1

MALL

Asseptive stripetupfor kur perned ansy

Pleas.

Director / 1/2/19

m

1015th