GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001.

No. F.6/DFS/MS/2024/SZ/ 331

Dated: 03/06/2024

FIRE SAFETY CERTIFICATE

Director

Delhi Fire Service

Copy to:-

Authorized Signatory, Reliance Prolific & Commercial Pvt. Ltd., A-3, Mohan Co-op Undustrial Estate, Mathura Road, New Delhi-110044.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape arrangements shall be kept unlocked & unobstructed for speedy evacuation of occupants in case of an emergency.
- Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. Basement shall be used as per the building bye laws.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

INSPECTION REPORT

1. Name & address of the building: Reliance Mall (A unit of Reliance Prolific & Commercial Pvt. Ltd.,

Plot No.-A, Block-A, Community Centre, Vikaspuri, New Delhi-18

Building is comprised of Three tier basement, ground plus five upper floors

Type of Occupancy Mercantile Type of Case Renewal

Details of Previous NOC F.6/DFS/MS/2021/SZ/260 dated 10.06.2021 6. Fire Safety directives letter No F.6/DFS/MS/BP/2012/1311 dated 13/04/2012

Date of inspection 24.05.2024

8. Name of Inspecting Officers Vedpal Chhikara, DO (SW) & R.K. Yadav, ADO (JKP)

9. Name and designation of officers

From the building side Sh. Sunil Sharma (AGM)

10. Year of Construction 2014

11. Applicant's letter No. Nil dated 15.05.2024

Basement (Parking), Ground floor (Shops), First, Second & Third Floor (Vacant), Fourth floor (Offices & partially Vacant) & Fifth floor (Offices & partially vaccant) & Terrace.

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	on Requirements	Provided at site	Remarks MR/NMR				
١.	Access to building							
	Road width	Accessible (09 m	n) 18 m	MR				
	Gate width	05 m	7.5 & 06 m	MR				
	Width of internal road	06 m	06 m	MR				
2.	Number, Width, Type & Arrangement of Exits							
	a. Number of staircases							
	Upper Floors	03 No.'s	03 No.'s	MR				
	Basements	10 No. A. S.	03 No.'s basement to terrace & 05 no.'s basement to ground & two ramps					
	b. Width of staircases		ground & two ramps					
	Upper Floor Basements	1.5 m each	1.95, 1.95 & 1.76 m	MR				
	Basements	1.5 m each	1.95, 1.94, 1.94, 1.53, 1.5, 1.5, 1.5 & 1.5 m	MR				
	c. Protection of exits	Required (2 hrs) Provided	100				
	Fire check door	Required	The state of the s	MR				
	 Pressurization 	Required	Provided	MR				
	d. No. of continuous staircases to	03 No.	03 No.'s	MR				
	terrace e. Width of Corridor	02 m	Provided	MR				
	f. Door Size	1.5 m	1.5 m	MR				
3.	Compartmentation							
	• Fire check door	Required (2 hrs)	Provided	MR				
	• Sealing of electrical shafts • Fire Rating of shaft door	Required	Sealed	MR				
	water Curtain	Required	Provided	MR				
_	Fire Dampers	N/A	Provided in basement	N/A				
	Smoke Management System	N/A	N/A	N/A				
F=====	Basements			41.00				
_		Required	Provided	MR				
	Upper floors	Required	Provided	MR				
	Fire Extinguishers			IVIK				
	• Total numbers							
	• Types	100 No.'s	121 no.'s Provided	MR				
	IS marking	ABC/CO ₂	Co2, Water Co2	MR				
1	S. Carlotte	ISI marked	ISI marked	MR				
W C /		markeu	marked	IVIK				

MIZ

5.	First-Aid Hose Reels					
	 Total numbers on each floor 04 no.'s & 09 		9 no.'s in Provided			
	 Length of hose reel hose 	basement	Provided	MR		
	Nozzle diameter	30 mtrs	Provided	MR		
7.	Automotic	5 mm	Tiovided			
	Automatic fire detection and alarming system Type of detectors Smoke & Heat Provided					
	Location of Main Panel	Smoke & Heat	Provided	MR		
	Location of Repeater Panel	Required	Provided at GF	MR		
	Alternate source of power	N/A	Main Gate	N/A		
	Hooters' Location	Required	UPS	MR		
8.	MOEFA	Corridor	Provided	MR		
^	* ACC	Required	Provided	MR		
9.	Public Address System	Required	Provided	MR		
10.	Automatic Sprinkler System					
	Basement	Required	Deceded	1.00		
	 Ground Floor 	Required	Provided Provided	MR MR		
	 Sprinkler above false ceiling 	Required	Provided	MR		
11.	Internal Hydrants		Tiovided	IVIK		
T T	Size of riser/down-comer	150 mm				
	 Number of hydrants 	04 No.'s	Provided	MR		
	Hose Box	Required	Provided Provided	MR		
12.	Yard Hydrants	quirou	Flovided	MR		
	Total number of hydrants Required 12 No 's Provided					
1.7	Hose Box	Required Required	12 No.'s Provided	MR		
13.	Pumping Arrangements	Roquited	12 No.'s Provided	MR		
	Ground Level					
	Discharge of main Pump	2850 LPM				
	Head of Main pump		Provided	MR		
	Number of main pumps	75 m	Provided	MR		
	Jockey Pump out put	02 No.'s 220 LPM	Provided	MR		
	Jockey pump head		Provided	MR		
	Standby Pump out put	75 m 2850 LPM	Provided	MR		
	Standby Pump Head	75 m	Provided	MR		
	➤ Auto Starting/Manual Stopping	Required	Provided Auto Mode	MR		
	Auto Mode		MR			
	 Pump House Access Terrace level 	Required	Provided	MR		
	Discharge of pump	N/A	N/A			
	 ➢ Head of the pump ➢ Power Supply 	N/A	N/A N/A	N/A		
	➤ Fower Supply ➤ Auto Starting of pump	N/A	N/A N/A	N/A		
	banting of pump	N/A	N/A	N/A		
4.	Captive Water Storage for fire fighting	= = =		N/A		
	Underground tank capacity 150 000 x					
	Draw-off connection	1,50,000 Ltrs	Provided	MR		
	Fire service inlet	Required	Provided	MR		
	 Access to tank Overhead Tank capacity 	Required	Provided	MR		
		Required	Provided	MR		
5.	Exit Signage.	20,000 ltrs	Provided	MR		
- 1		Required	Provided	TATE		

4

W

	Pressurization of Lift Shaft	Required	Provided	MR		
)	Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage	Required	Provided	MR		
1		Required	Provided	MR		
1		Required	Provided	MR		
		Required	Provided	MR		
17	7. Standby power supply	Required	Provided	MR		
18.	Refuge Area.					
	> Total Area > Location	N/A	N/A	N/A		
		N/A	N/A	N/A		
19.	Fire Control Room					
	Detector System Panel Flow Switch Panel	N/A	Provided	MR		
	PA System Panel	N/A	Provided	MR		
	 Battery backup 	N/A	Provided	MR		
	Building Floor Plans	N/A	Provided	MR		
		N/A	Provided	MR		
	Special Fire Protection System for	Required	Clean agent	MIK		

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F.6/DFS/MS/2021/SZ/260 dated 10.06.2021, renewal under Rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Signature of Inspecting Officer

Name: - R.K. Yadav

Designation: - ADO (JKP)

Signature of Inspecting Officer

Name: - Vedpal Chhikara Designation: - DO (SW)

C.F.O.(SZ)

20 soll

Directar

ADO SNEPORI

De rolly