GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001.

No. F.6/DFS/MS/EH/2024/SZ/ 14 8

Dated: 16/05/2024

FIRE SAFETY CERTIFICATE

Certified that the M/s Spinns Restaurant is running at ground floor only of a building comprised of ground plus two upper floors at G-2A & G-2B, Sonia PVR Complex, Vikas Puri, New Delhi-110018, owned/ occupied by M/s Spinns Restaurant. Sonia PVR Complex building was issued Fire Safety Certificate by this department vide letter no. F6/DFS/MS/EH/2021/SZ/88 dated 05.04.2021. The building was re-inspected by the officers concerned of this department on 09.05.2024 in the presence of Sh. Ramesh (Sr. Manager) and found that the building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises (at ground floor only) is fit for occupancy class Group "D" 'Assembly building' with effect from 16/05/2024 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010 printed below.

Issued on 16/05/2024 at New Delhi.

Director Delhi Fire Service

Online application Id 2024041605337 dated 16.04.2024

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

INSPECTION REPORT

1. Name & address of the building: M/s Spinns Restaurant, G-2A & G-2B, Ground Floor Only, Sonia

PVR Complex, Vikas Puri, New Delhi-110018.

G+2 upper floors but restaurant running at ground floor only Building comprised of Group D (Assembly Building)

3. Type of Occupancy 4. Type of Case Renewal

5. Details of Previous NOC F6/DFS/MS/EH/2021/SZ/88 dated 05.04.2021

6. Fire Safety directives letter No : N/A 7. Date of inspection 09.05.2024

8. Name of Inspecting Officers A.D.O. R.K. Yadav

9. Name and designation of officers

From the building side Sh. Ramesh (Sr.Manager)

10. Year of Construction 2011

	Minimum safety U/F	Standards on fire prevention and fire	Requirement	Provided at site	Remarks MR/NMR	
	Access to	building				
	• 6	oad width ate width /idth of internal road	Accessible (09 mtr 4.5 mtrs 06 mtrs	5) 09 mtrs Directly accessible from internal road Provided	MR MR MR	
	Number,	Width, Type & Arrangement of Exits	pop - 1 40 - 10 10	(Rest	aurant is at GF only	
	a Numbe	er of staircases				
		Upper Floors	N/A	N/A	N/A	
		Basements	N/A	N/A	N/A	
	10.					
	b. Width	of staircases	N/A	N/A	N/A	
	200	Upper Floor	N/A	N/A	N/A	
		Basements	14/A		The second second	
	c. Prote	ction of exits	N/A	N/A	N/A	
	•	Fire check door	N/A	N/A	N/A	
	•	Pressurization	IN/A	IVA		
	d No.	of continuous staircases to	N/A	N/A	N/A	
	terra	ce	N/A	Opening in	N/A	
	e. Wid	th of Corridor	N/A	hall		
			02 M	2.0, 1.25 & 1.25 M	MR being old	
	f. Doc	or Size		(including frames)	case	
3.	Compo	rtmentation			(Restaurant is a GF only)	
٠.	Сошра	Itmentation		N/A	N/A	
		Fire check door	N/A	49.784945	N/A	
		Sealing of electrical shafts	N/A	N/A	- However	
		Fire Rating of shaft door	N/A	N/A	N/A	
	•	Water Curtain	N/A	N/A	N/A	
	•	Fire Dampers	N/A	N/A	N/A	
4.	Smoke	Management System		(D)	staurant is at GF on	
٦.	SHOKE	Manuagement of area	N/A	N/A	N/A	
T		Basements	N/A			
			N/A	N/A	N/A	
	•	Upper floors		- 11	1	
	701 Y	xtinguishers		'P 11-1	MR	
5.	Fire	Total numbers	04 No.'s ABC/CO ₂		MR	
		Types	ABC/CO2		MR	
		IS marking	ISI marke	d ISI marked	- WANGE SEE	
6.	(Restaurant is at Groun					
0.	THSU		One	Provided	MR	
1		- t - t - t - co ground floor	-0000000V		MR	
-	•	Total numbers on ground floor Length of hose reel hose	30 mtrs	Provided	MR	

N	21

		•				
7.	Automatic fire detection and alarming syst	em				
	Type of detectors	N/A	N/A	N/A		
	 Location of Main Panel 	N/A	N/A	N/A		
	 Location of Repeater Panel 	N/A	N/A	N/A		
	 Alternate source of power 	N/A	N/A	N/A N/A		
	Hooters' Location	N/A	N/A	N/A N/A		
8.	MOEFA	Required	Provided	MR		
9.	Public Address System	Required	Provided	MR		
10.	Automatic Sprinkler System (Restaurant is a					
	Basement	N/A	N/A	N/A		
	Ground Floor	Required	Provided	MR		
	 Sprinkler above false ceiling 	N/A	N/A	N/A		
11.	Internal Hydrants (Restaurant is at GF o					
	Size of riser/down-comer	100 mm	Provided	MR		
	Number of hydrants	01 No.	Provided	MR		
	Hose Box	01 No.	Provided	MR		
12.	Yard Hydrants					
2	Total number of hydrants	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
13.	Pumping Arrangements	(cor	nmon with Sonia I			
- 4	Ground Level					
	 Discharge of main Pump 	2280 LPM	Provided	MR		
	Head of Main pump	70 mtrs	Provided	MR		
	Number of main pumps	One	Provided	MR		
	Jockey Pump out put	220 LPM	Provided	MR		
	Jockey pump head			(Allegania)		
		70 mtrs	Provided	MR		
	Standby Pump out put	2280 LPM	Provided	MR		
	> Standby Pump Head	70 mtrs	Provided	MR		
	> Auto Starting/Manual Stopping	Required	Provided	MR		
	> Pump House Access	Required	Provided	MR		
	Terrace level					
	Discharge of pump	N/A	N/A	N/A		
	➤ Head of the pump	N/A	N/A	N/A		
	> Power Supply	N/A	N/A	N/A		
	> Auto Starting of pump	N/A	N/A	N/A		
4.	Captive Water Storage for fire fighting (common with Sonia PVR Complex)					
	Underground tank capacity	1,30,000 ltrs	1,30,000 ltrs	MR		
	> Draw-off connection	Required	Provided	MR		
	> Fire service inlet	Required	Provided	MR		
	> Access to tank	Required	Provided	MR		
	Overhead Tank capacity	10,000 ltrs	10,000 ltrs	MR		
5.	Exit Signage.	Required	Provided	MR		
6.	Provision of Lifts.		APPREN -C -	is at GF only)		
	Pressurization of Lift Shaft	N/A	N/A	N/A		
	Pressurization of Lift Shart Pressurization of Lift lobby	2 1/823	FEA-FE	N/A		
	Communication In lift Car	N/A N/A	N/A N/A	N/A N/A		
	Fireman's Grounding Switch					
	Lift Signage	N/A	N/A	N/A		
	0 0	NI/A	N/A	N/A		
		N/A	1071			
7.	Standby power supply	Required	Provided	MR		
****			replacement of the control of the co	MR		
7. 8.	Standby power supply		replacement of the control of the co	MR N/A		

Fire Control Room Detector System Panel	N/A	N/A	N/A
Flow Switch Panel	N/A	N/A	N/A
	N/A	N/A	N/A
Battery backup Building Floor Plans	N/A	N/A	N/A
Building 1 lost 2	N/A	N/A	N/A
Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No.: F6/DFS/MS/EH/2021/SZ/88 dated 05.04.2021, renewal under rule 37 of the Delhi Fire Service rules 2010 is recommended.

Signature of Inspecting Officer

Name:-R.K.Yadav

Designation:- Asstt. Divisional Officer

Director March Saran March March Saran March March Saran March Saran March March Saran Mar