





## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F.6/DFS/MS/EH/2024/SZ/ 3 8

Dated: 10 /05 /2024.

## **FIRE SAFETY CERTIFICATE**

Certified that M/s T Lounge Restaurant (Devaryaa Hospitalities Pvt. Ltd.), Level-5, Terminal-3, International Wing, IGI Airport, New Delhi-110037, comprised of Two-Tier Basement, Ground & Five Upper Floors but the restaurant running at 5<sup>th</sup> Floor (International Wing) only was issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/SZ/2021/85 dated 05/04/2021. The said premise was re-inspected by the officers concerned of this department on 03/05/2024 in the presence of Mr. Satish (Asst. Manager) and observed that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/premises is fit for occupancy class "Assembly Group D" for a period up to 31/03/2027 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of conditions under 38 of the Delhi Fire Service Rules, 2010.

Issued on 10 05 2024 at New Delhi by

(ATUL GARG)
DIRECTOR
DELHI FIRE SERVICE

## Copy to: -

- 1. The Joint Commissioner of Police (Lic.), 1st Floor, Police Station Defence Colony, New Delhi-110049 (w.r.t. MHA ID No. 2023042207111 dated 16/04/2024)
- 2. Authorized Signatory M/s T Lounge Restaurant (Devaryaa Hospitalities Pvt. Ltd.), Level-5, Terminal-3, International Wing, IGI Airport, New Delhi-110037

## Conditions for the validity of Fire Safety Certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangement provided therein shall be maintained in good working conditions at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 5. The owner/occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule37] along with a copy of this Certificate, six months prior to its expiry".

. At	Name & address of the building	ON REPORT	- A (Description Horse	italities		
	realite & address of the building	T Lounge Restaurant (Devaryaa Hospitalities Pvt. Ltd.), Level-5, Terminal-3, International				
2.	Tune of O	Wing, IGI Airport	Airport New Delhi–110037			
2. 3.	Type of Occupancy	Assembly (Restt. at Level-5, International Wing)				
0.501	Building Comprised of	Two Tier Basement, Ground & 5 Upper Floors,				
١.	Type of Case	Renewal				
5.	Details of previous NOC	F6/DFS/MS/SZ/2021/85 dated 05/04/2021				
5.	Fire Safety directives letter No.	F6/DFS/MS/2007/1781 dated 05/07/2007				
7.	Date of inspection	03/05/2024				
3.	Name of Inspecting Officer	Manoj Kumar Sharma (DO/SD) & Santosh Kumar (ADO/SJ)				
9.	Name and designation of Officer from building side	Mr. Satish (Asst. Manager)				
0.	Year of Construction	2010				
1.	Applicant letter No.	MHA ID No. 2023042207111 dt. 16/04/2024				
S.	Minimum standards on fire	Old FSC	Provided at site	Remarks MR/NMR		
lo.		Requirements	7/2022/602 dated 19/1			
1.	Access of building T-3 Bldg. FSC	No. F6/DFS/MS/S2	Z/2023/602 dated 18/1 As above	MR		
	Road width	Restaurant	As above	MR		
	<ul> <li>Gate width</li> </ul>	within T-3	As above	MR		
	Width of internal road	Building	As above			
2.	Number, width, Type & Arrangements of exits  Number of staircases  Provided & Maintained by T-3 Bldg. Mgmt.					
	a. Number of staircases	Provided & Ivia	intained by 1-3 Bld	MR		
	Upper floors	Restt. within T-3	As above	NA NA		
	Basements	NA	NA	9005380400		
	b. Width of staircases	Provided & Maintained by T-3 Bldg. Mgmt.				
	Upper floors	Restt. within T-3	As above	MR		
	Basement	NA	NA	NA		
	c. Protection of exits		karagari ja x	I M		
	Fire check door	Restt. within T-3		MR		
	Pressurization	Restt. within T-3	As above	MR		
	d. No of continuous staircase to terrace	Restt. within T-3	As above	MR		
			As above	MR		
	e. Width of Corridor f. Door Size	0.91m F	rovided (final exit)	MR		
	The state of the s	Provided & Maintained by T-3 Bldg. Mgmt.				
3.	Compartmentation	Restt. within T-3	As above	MR		
	• Fire check door	Restt. within T-3	As above	MR		
	Sealing of electrical shafts  Sealing of electrical shafts  The state of the s	Restt. within T-3	As above	MR		
	Fire Rating of shaft door	Restt. within T-3	As above	NA		
	Water Curtain	Restt. within T-3	As above	MR		
	Fire Dampers	Provided & Maintained by T-3 Bldg. Mgmt.				
4.	Smoke managements System	NA NA N		NA		
	Basements	Restt. within T-3	As above	MR		
	Upper floors	Nesu. Within 1 3				
5.	Fire Extinguishers		15 Nos	MR		
	Total numbers	1 49 I	ABC, W.CO <sub>2</sub> /CC	5.05.5		
	• Types	ISI marked	Provided	MR		
	ISI marking			(A97670)		
_	First-Aid Hose Reels	Provided & M	aintained by T-3 Bl	ag. Mgmt.		
6.	Total numbers on each floor		3 Nos	MF		
	Length of hose reel hose	Hose-reel	30m	MF		
	I enoth of hose reel nose		5mm	MF		

	Automatic fire detection and alarming sy     Type of detector	Required	Smoke & Heat	MR
	Location of Main Panel	Required	Upper Basement MR	(Old case)
	Location of Repeater Panel	Required	Provided	MR
	Alternate source of power	Required	Provided	MR
	Hooters' Location	Required	All Areas	MR
8.	MOEFA	Required	Provided	MR
9	Public Address System	Required		
10	Automatic Sprinkler System		Provided & Maintained by T-3 Bldg. N	
-	Basements	NA		
	Upper floors	Required	Provided	MR
	Sprinkler above false ceiling	Required	Provided	MR
11_	Internal Hydrants		Maintained by T-3 Bldg	g. Mgmt.
	Size of riser/down- comer	150 mm	Provided	MR
	Number of hydrants per floor	3 Nos	Provided	MR
	Hose Box	3 Nos	Provided	MR
12	Yard Hydrants	Provided & Maintained by T-3 Bldg. Mgr		g. Mgmt.
	Total number of hydrants	Restt. within 7		MR
	Hose Box	Restt. within 7	7–3 As above	MR
13	Pumping Arrangements		Mary 1997 A	
	Ground Level		Maintained by T-3 Bld	g. Mgmt.
	<ul><li>Discharge of main pump</li></ul>	Restt. within	OL VI CHARLES SILV	MR
	> Head of main pump	Restt. within		MR
	> Number of main pumps	Restt. within		MR
	> Jockey pump out put	Restt. within	280987 RESPECT	MR
	> Jockey pump head	Restt. within		MR
	Standby Pump out put	Restt. within	T-3 As above	MR
	> Standby Pump Head	Restt. within		MR
	> Auto Staring/Manual stopping		BUSINESS NE	MR
	> Pump House Access	Restt. within	T-3 As above	MR
	Terrace level		to the same of	
	Discharge of pump	NA	NA	NA
	> Head of the pump	NA	NA	NA
	> Power supply	NA	NA	NA
	> Auto starting of pump	NA	NA	NA
14			Maintained by T-3 Bl	
	Underground tank capacity	Restt. within	1.00.00	MR
	<ul><li>Draw of connection</li><li>Fire service inlet</li></ul>	Restt. within		MR
	Access to tank	Restt. withir		MR MR
	Overhead Tank capacity	Restt. within	10.000	MR
15	. Exit Signage	Require		MR
16	(III) 100 (100 (100 (100 (100 (100 (100 (100	Provided a	& Maintained by T-3 B	
	Pressurization of Lift Shaft	Restt, within		MF
	Pressurization of lift lobby	Restt. withi		MF
	> Communication in lift Car	Restt. withi	- 1011000	MI
	Fireman's Grounding Switch	_ PATERING OF TAXABLE		MI
	> Lift Signage	Restt. withi	n T-3 Provided	MI
1	- A Providence	Requir		M
13	8. Refuge Area		& Maintained by T-3 B	ldg. Mgm
	> Total area	Restt. with		M
	Location	Restt, with	in T-3 As above	M



OT	Fire control room	Provided & Main	tained by 1-5 Die	MR
9.	> Detector system panel	Restt. within T-3	As above	MR
	<ul> <li>Flow Switch Panel</li> <li>PA System Panel</li> <li>Battery backup</li> <li>Building Floor Plans</li> </ul>	Restt. within T-3	As above	100000000000000000000000000000000000000
		Restt. within T-3	As above	MR
			As above	MR
		Restt. within T-3		MR
		Restt. within T-3	As above As above	MR
20.	Special Fire Protection Systems for	Restt. within T-3		

The fire protection systems provided in the building/premises were checked, tested at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the fire safety certificate issued vide letter No. F6/DFS/MS/SZ/2021/85 dated 05/04/2021, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer Name: Manoj Kumar Sharma

Designation: DO (SD)

Signature of the Inspecting Officer

Name: Santosh Kumar Designation: ADO (SJ)

CFO (HO)

Dinector

Many 8)

Sir, FT Jutter is puta

restor My

for your sing

uplanded 70/5