



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

F.6/DFS/MS/GH/2024/SZ/ 185 No.

Dated: .27/0:5-/2024

FIRE SAFETY CERTIFICATE

Certified that the Guest House in the Name & Style of M/s Bloom Boutique located at C-10, M Block Market, Hansraj Gupta Road, Greater Kailash Part -1, Delhi 110048 comprised of Basement, ground plus three upper floors with 24 guest rooms owned/occupied by (A Unit of Imperative Hospitality Pvt. Ltd.) was issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/2021/SZ/358 dated 03/09/2021. The premise was re-inspected by the officer concerned of this department on 17/05/2024 in the presence of Mr. Amit Gahlawat and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Group-A" (Residential & Lodging) and Validity upto 31/03/2027 in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 27 05./2024 at New Delhi by

DIRECTOR

Copy to: -

1. The Addl. Commissioner of Police (Lic.), 1st Floor, P.S. Defence Colony, New Delhi-110049 (Ref. MHA Portal Id 2024050106614 dated 01/05/2024)

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of fire fighting

system.

4. The basement shall be used as per the provisions of UBBL-2016 /NBC Part- IV.

5. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-

2016), if any.

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six



| 1 | Name & Address of the Building | N REPORT | Sauce (A This of Inc. | Alica | | | |
|--------|---|--|-----------------------|-------------------|--|--|--|
| | Hospitality Pvt. Ltd.) C-10, M Block Mark | | | | | | |
| 2 | Type of Occupancy | Greater Kailash Part -1, Delhi 110048 | | | | | |
| 3 | Building Comprised of | Residential, "Group-A" (Guest House) | | | | | |
| 4 | Type of Case | Basement, Ground + 03 upper floors | | | | | |
| 5 | Details of Previous NOC | Renewal | | | | | |
| 6 | Fire Safety Directives Letter No | F6/DFS/MS/2021/SZ/358 dated 03/09/2021 | | | | | |
| 7 | Date of Inspection | Nil | | | | | |
| 8 | Name of the Inspecting Officers | 17/05/2024 | | | | | |
| 9 | Name & Designation of Officers from the building side | DO (South) & ADO (BCP) Mr. Amit Gahlawat | | | | | |
| 10 | Year of construction | 1100000 | | | | | |
| 11 | Applicant letter No. | 2002 Total 24 Guest room | | | | | |
| S. No. | Minimum standards on Fire Prevention | MHA Portal Id 2024050106614 dated 01/05/2024 | | | | | |
| 1 | and Fire Safety U/R 33 | Old NOC requirements | Provided at Site | Remarks MR/NMR | | | |
| - | Access to Building. | | Zerlas II a | 100 | | | |
| | Road width | Required | 09 mtr | MR | | | |
| 4 | • Gate width | -NA- | ' I -NA- | -NA- | | | |
| 2 | • Width of internal road | Qr-NA- m/m)- | 22 mil - r -NA- | -NA- | | | |
| | Number, width, type & arrangement of exits. | | | | | | |
| | a) Number of Staircase | equipa diem | o entitled & | 1 .m | | | |
| | > Upper floors. | Required | 01 Nos | MR | | | |
| | > Basement floor. | Required | 02 Nos | MR | | | |
| | b) Width of Staircase | the state of the s | A TANAMACO A TANAMACO | | | | |
| | > Upper floors | 1.25 mtr | 1.25 mtr | MR (old case | | | |
| | ➤ Basement floor | 1.25 mtr | 1.25m each | MR (old case | | | |
| | c) Protection of exits | | -, | | | | |
| | Fire check door | -NA- | -NA- | -NA- | | | |
| | > Pressurization | -NA- | -NA- | -NA- | | | |
| | d) No. of continuous staircase to terrace | Required | in promy One | MR | | | |
| | e) Width of corridor | Required | make which 1.50 | MR | | | |
| -*- | f) Door size | ne for mi fighting | 1.20 m (final exit) | MR | | | |
| 3 | Compartmentation. | Virginia office | | IVIX | | | |
| 4 | Fire check door. | -NA- | -NA- | -NA- | | | |
| | Sealing of electrical shafts. | -NA-Inl.por | -NA- Fire Ser | -NA- | | | |
| | Fire rating of shaft door. | -NA- | -RESUSA -NA- | -NA- | | | |
| | Water curtain | -NA-am sh | at beerles -NA- | -NA- | | | |
| | Fire dampers. | -NA- | -NA- | -NA- | | | |
| | Smoke Management system. | As per clause 7.31 of UBBL 2016 | | | | | |
| | Basement | 30 ACPH | Exhaust fan Provided | MR | | | |
| | Upper floors | 12 ACPH | Exhaust fan Provided | | | | |
| _ 5 | Fire Extinguishers. | Mrs. Myl. no. n. | Tovided | MR | | | |
| | Total numbers | 10 Nos | Provided | | | | |
| | Types | ABC / CO2 | ABC & CO2 | MR | | | |
| | ISI Marking | ISI marked | | MR | | | |
| 9 | First Aid Hose Reels. | The state of the s | Provided | MR | | | |
| | Total numbers on each floor. Length of hose-reel hose. | One | Provided | MR | | | |
| | Nozzle Diameter | 30 mtr | Provided | | | | |
| 1 | Automatic fire detection & alarming system. | 5 mm | Provided | MR | | | |
| 4 | alarming system. | As per clause 7 | 31 of UBBL 2016. | MR | | | |



| | Type of detectors Type of July 2011 | Co. Mo. Detect | | MR |
|---------|--|---|--|---------|
| | CMain Donal | Required | Provided | MR |
| (FPER | and the second s | -NA- | -NA- | -NA- |
| toutre. | All the severe of nower | Required | Provided | MR |
| | ** . 1 1 | Required | Provided | MR |
| _ | THE SWITTER STORY COLOR | Required | Provided | MR |
| 8 | MOEFA Public Address System | -NA- | -NA- | -NA- |
| 9 | Automatic Sprinkler System | | 5-4 5/4/ 2- 1 | |
| 10 | | Required | Provided | MR |
| | Basement Upper floors. | -NA- | -NA- | -NA |
| | Sprinkler above false ceiling | -NA- | -NA- | -NA |
| 11 | Internal Hydrants. | 1000 | Survey I to I to I to I to I | |
| 11 | Size of Riser/Down-comer | -NA- | -NA- | -NA |
| | AT 1 CTT 1 Good | -NA- | -NA- | -NA |
| | Number of Hydrant per floor Hose box. | -NA- | -NA- | -NA |
| 12 | Yard Hydrants. | | The second secon | |
| 12 | Total number of hydrants. | -NA- | -NA- | -NA |
| | Hose box. | -NA- | -NA- | -NA |
| 13 | | 1477 | | |
| 19 | Pumping arrangements. Ground Level | | 10 L 27 | |
| | | -NA- | -NA- | -NA- |
| | Discharge of main pump. Head of main pump. | -NA- | -NA- | -NA- |
| | Number of main pumps. | -NA- | -NA- | -NA- |
| | > Jockey Pump output. | -NA- | -NA- | -NA- |
| | > Jockey Pump head. | -NA- | -NA- | -NA- |
| | Standby Pump output. | -NA- | -NA- | -NA- |
| | ➤ Standby Pump head. | -NA- | -NA- | -NA- |
| | Auto Starting/Manual Stopping. | -NA- | -NA- | -NA- |
| | Pump house access. | -NA- | -NA- | -NA- |
| | Terrace Level | | tza în waltereverii ea l | -11/1- |
| | Discharge of pump. | 450 LPM | Provided | MR |
| | > Head of pump. | 35 m | Provided | MR |
| | > Power supply. | Provided | Provided | MR |
| * | > Auto starting of pump. | Provided | Provided | MR |
| 14 | Captive water storage for fire fighting. | 210.1000 | A TOVICE | IVIK |
| | Underground tank capacity. | -NA- | NA. | NI A |
| | > Draw-off connection. | -NA- | -NA- | -NA- |
| | > Fire Service Inlet. | Provided | Provided | -NA- |
| | Access to tank. | -NA- | -NA- | Provide |
| | Overhead tank capacity. | 5,000 ltr | | -NA- |
| 15 | Exit Signage. | | 5,000 ltrs | MR |
| 16 | Provision of Lifts. | Required | Provided | MR |
| | Pressurization of lift shaft. | ATA | Smoke Managamen | h ii |
| | Pressurization of lift lobby. | -NA- | -NA- | -NA- |
| | Communication in lift car. | -NA- | -NA- | -NA- |
| | Fireman's switch. | 100000000000000000000000000000000000000 | -NA- | -NA- |
| 4. | Lift signage. | -NA- | -NA- | -NA- |
| 17 | Standby Power Supply | -NA- | -NA- | -NA- |
| 18 | Refuge Area | Required | Provided (DG Set) | MR |
| | Total area | - 10 | and the state of | - |
| | Location | -NA- | -NA- | -NA- |
| 19 | Fire Control Room. | -NA- | -NA- | -NA- |
| | Detector system panel. | _ | | 444 |
| | Delector system nonel | -NA- | and the second s | |

N



| | Flow switch | | -NA- | -NA- | -NA- |
|----|-------------------------------------|------------------|--|----------------------------------|------|
| | PA system | panel. | -NA- | -NA- | -NA- |
| | Battery backup. | | -NA- | -NA- | -NA- |
| | Building f | | -NA- | -NA- | -NA- |
| 20 | | | | tection of special Risk, if any. | |
| | s per MHA Portal . First Floor : | Application deta | ils per floor occupancy is 09 No of Bed | below mentioned. | |
| | Second Floor: | 08 Rooms | 09 No of Bed | | |
| 3. | Third Floor: | 08 Rooms | 00 No of Red | ce the FCD require | |

clause 7 31 of UBBL is not applicable.

The fire protection system provided in the building were randomly checked and found

functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued &

communicated by this department vide letter of even no 183 dated 30/04/2024.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/2021/SZ/358 dated 03/09/2021, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspection Officer Name: Sh. Manoj Kumar Sharma

Design DO (South)

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar Design: ADO (BCP)

CFO (HO)

approved, F-1. Letter in problép your synation Pl 1/14