

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE

NEW DELHI- 110001

No. F6/DFS/MS/School/2024/SZ/ 489

Dated: 03 06 2024

FIRE SAFETY CERTIFICATE

Certified that the Bal Bharti Jain Public School at B-47-48, Jeevan Park, Uttam Nagar, New Delhi-110059, is running at ground floor plus one upper floor in a three storied building, owned/occupied by Bal Bharti Jain Public School, was issued Fire Safety Certificate by this department vide letter No F.6/DFS/MS/School/2019/SZ/936 dated 03.05.2019. The school building was re-inspected by the officer concerned of this department on dated 20.05.2024 in the presence of Ms. Kiran Bhatia (Principal) and found that the school have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and found that the building (ground floor plus one upper floor only) is fit for occupancy Group B 'Educational Building' with effect from 03 06 2024 for a period of

(Atul Garg)

Director
Delhi Fire Service

Copy to:-

 The Principal, Bal Bharti Jain Public School at B-47-48, Jeevan Park, Uttam Nagar, New Delhi-110059.

2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

INSPECTION REPORT

1. Name & address of the building: Bal Bharti Jain Public School, B-47-48, Jeevan Park, Uttam Nagar,

New Delhi-110059

2. Type of Occupancy : Educational

3. Building Comprised of : School running at ground and 1st floor in a three storied building.

4. Type of Case : Renewal

5. Details of Previous NOC : F.6/DFS/MS/School/2019/SZ/936 dated 03.05.2019

6. Fire Safety directives letter No : Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011

7. Date of inspection : 20.05.2024

8. Name of Inspecting Officer : A.D.O. R.K. Yadav

9. Name and designation of officers

From the building side : Smt. Kiran Bhatia (Principal)

10. Year of Construction : Before 2018

11. Applicant's letter No. : BBJPS:2018-19/1008 dated 25.03.2019

| S. No. | | um Standards on fire prevention and Tety U/R 33 | Dir. Of Edu. Circular dt. 01.03.2011 Requirement | Provided at site | Remarks MR/NMR | | |
|--------|-------------------------|--|--|------------------------------|-------------------|--|--|
| 1. | Access to building | | | | | | |
| | — | Road width | Accessible 06 mtrs | Provided | MR | | |
| | | Gate width | N/A | N/A | N/A | | |
| | | Width of internal road | N/A | N/A | N/A | | |
| 2. | Numbe | er, Width, Type & Arrangement of Exits | | | 4 | | |
| | a. Num | iber of staircases | | | | | |
| | • | Upper Floors | 01No. | 01No. | MR | | |
| | • | Basements | N/A | N/A | N/A | | |
| | b. Wid | th of staircases | | | | | |
| | • | Upper Floor | 150 cms | 150 cms | MR | | |
| | | Basements | N/A | N/A | N/A | | |
| | c. Prote | ection of exits | | | 2 | | |
| | • | Fire check door | N/A | N/A | N/A | | |
| | • | Pressurization | N/A | N/A | N/A | | |
| | d. No. | of continuous staircases to terrace | N/A | N/A | N/A | | |
| | | th of Corridor | N/A | N/A | N/A | | |
| | f. Clas | ss room Door Size | 100 cms | 100 cms | MR | | |
| | Compa | rtmentation | | | | | |
| | • | Fire check door | N/A | N/A | N/A | | |
| | | Sealing of electrical shafts | N/A | N/A | N/A | | |
| | | Fire Rating of shaft door | N/A | N/A | N/A | | |
| | | Water Curtain | N/A | N/A | N/A | | |
| | • | Fire Dampers | N/A | N/A | N/A | | |
| •3 | Smoke Management System | | | | | | |
| | • | Basements | N/A | N/A | N/A | | |
| | • | Upper floors | Required | Natural ventilation provided | M/R | | |
| | Fire Ex | tinguishers | | | -1 | | |
| | • | Total numbers | 04 no's | Provided | M/R | | |
| | | Types | ABC/CO₂ type ISI marked | Provided | M/R | | |
| | • | IS marking | | Provided | M/R | | |

M12

| 5. | First-Aid Hose Reels | N/A | N/A | N/A |
|------------|--|---------------------------|---------------------|-----|
| | Total numbers on each floor | N/A | N/A | N/A |
| | Length of hose reel hose Nozzle diameter | N/A | N/A | N/A |
| | Automatic fire detection and alarming system | | | |
| | | N/A | N/A | N/A |
| | Type of detectors Location of Main Panel | N/A | N/A | N/A |
| | Location of Repeater Panel | N/A | N/A | N/A |
| | Alternate source of power | N/A | N/A | N/A |
| | Hooters' Location | N/A | N/A | N/A |
| | MOEFA | N/A | N/A | N/A |
| | Public Address System | N/A | N/A | N/A |
| 0. | Automatic Sprinkler System | him maren | | |
| <i>)</i> . | | N/A | N/A | N/A |
| | Basement Ground Floor | N/A | N/A | N/A |
| | Sprinkler above false ceiling | N/A | N/A | N/A |
| l. | Internal Hydrants | | | |
| | | N/A | N/A | N/A |
| | Number of hydrants per floor | N/A | N/A | N/A |
| | Hose Box | N/A | N/A | N/A |
| 2. | Yard Hydrants | | 7 | |
| | Total number of hydrants | N/A | N/A | N/A |
| | Hose Box | N/A | N/A | N/A |
| 3. | Pumping Arrangements | ACTION SECURIOR PRINCIPLE | M. Dall Parkers No. | _ |
| • | Ground Level | | | |
| | Discharge of main Pump | N/A | N/A | N/A |
| | > Head of Main pump | N/A | N/A | N/A |
| | > Number of main pumps | N/A | N/A | N/A |
| | > Jockey Pump out put | N/A | N/A | N/A |
| | > Jockey pump head | N/A | N/A | N/A |
| | > Standby Pump out put | N/A | N/A | N/A |
| | > Standby Pump Head | N/A | N/A | N/A |
| | > Auto Starting/Manual Stopping | N/A | N/A | N/A |
| | | N/A | N/A | N/A |
| | > Pump House Access | 17/24 | | |
| | Terrace level | N/A | N/A | N/A |
| | Discharge of pump | N/A | N/A | N/A |
| | > Head of the pump | N/A | N/A | N/A |
| | Power SupplyAuto Starting of pump | N/A | N/A | N/A |
| | Auto starting of pump | | | |
| 4. | Captive Water Storage for fire fighting | | | |
| | Underground tank capacity | N/A | N/A | N/A |
| | > Draw-off connection | N/A | N/A | N/A |
| | Fire service inlet | N/A | N/A | N/A |
| | Access to tank Overhead Tank capacity | N/A | N/A | N/A |
| | | N/A | N/A | N/A |
| 5. | Exit Signage. | N/A | N/A | N/A |
| 6. | Provision of Lifts. | | No Lift | |
| | Pressurization of Lift Shaft | NI/A | N/A | N/A |
| | The state of the s | N/A | No COSTONA | |
| | Pressurization of Lift lobby Communication In 1:6 Communication | N/A | N/A | N/A |
| | Communication In lift Car | N/A | N/A | N/A |
| | • Fireman's Grounding Switch | N/A | N/A | N/A |
| | Lift Signage | N/A | N/A | N/A |
| | | | | |

| 17. | Standby power supply | N/A | N/A | N/A | | |
|-----|---|-----|-----|-----|--|--|
| 18. | Refuge Area. | | | | | |
| | > Total Area | N/A | N/A | N/A | | |
| | > Location | N/A | N/A | N/A | | |
| 19. | Fire Control Room | | | | | |
| | Detector System Panel | N/A | N/A | N/A | | |
| | Flow Switch Panel | N/A | N/A | N/A | | |
| | PA System Panel | N/A | N/A | N/A | | |
| | Battery backup | N/A | N/A | N/A | | |
| | Building Floor Plans | N/A | N/A | N/A | | |
| 20. | Special Fire Protection System for Protection of special Risks, if any: | N/A | N/A | N/A | | |

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F.6/DFS/MS/School/2019/SZ/936 dated 03.05.2019, renewal under the Directorate of Education circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01-03-2011 is recommended.

Note: - As per the undertaking given by the Principal (placed at C-20), building is comprised of ground floor, first floor & second floor. Second floor is in tin shed having two rooms used for school guard residence. Second floor will not be used for schooling purpose.

Signature of Inspecting O

Name: - R.K. Yadav Designation: - ADO (JKP)

DO (South West)

30 5 Jon

AN.