GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001 10/06/2024 Dated:

No. F6/DFS/MS/GH/2024/SZ/219

FIRE SAFETY CERTIFICATE

Certified that the D' Presidente Guest House located at B2B/12, Janak Puri, Near Janak Puri East Metro Station, Metro Pillar No.-541, New Delhi-110058, comprised of basement, ground floor plus three upper floors using basement as Storage, ground floor as reception, office and lobby, 05 guest rooms on first floor, 05 rooms on second floor and 04 guest rooms on third floor (Total 14 guest rooms), owned/occupied by D' Presidente Guest House was issued FSC by this department vide letter no. F6/DFS/MS/GH/2021/SZ/145 dated 18.03.2021. The guest house building was re-inspected by the officer concerned of this department on 31.052024 in presence of Sh. Kulmohan Singh (Manager) and found that the Guest House have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi fire service Rules 2010 and that the building/premises (total 14 guest rooms at 1st, 2nd, & 3rd floor) is fit for occupancy class "Residential" (Guest house) w.e.f 10/66/2024 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010 printed below.

Issued on _______ at New Delhi.

Director Delhi Fire Service

Online application Id 2024051207393 dated 14.05.2024 Following fire safety directives must be adhered to:-

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.

2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.

3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.

4. The trained staff should be available round the clock.

5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.

6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.

8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

INSPECTION REPORT

1. Name & address of the building: D' Presidente Guest House, B2B/12, Janak Puri, Near Janak Puri

East Metro Station, Metro Pillar No.-541, New Delhi-110058

2. Type of Occupancy Residential (Guest House)

Building Comprised of basement, ground floor plus three upper floors using basement as Storage,

ground floor as reception, office and lobby, 1st & 2nd floor each having 05 guest rooms respectively and 3rd floor having 04 guest rooms (Total 14 guest rooms)

4. Type of Case

Renewal

5. Details of Previous NOC F6/DFS/MS/GH/2021/SZ/145 dated 18.03.2021. 6. Fire Safety directives letter No : F.6/DFS/MS/HQ/2012/GH/4504 dated 07.12.2012

7. Date of inspection 31.05.2024 8. Name of Inspecting Officer A.D.O. R.K. Yadav

9. Name and designation of officers

From the building side Sh. Kulmohan Singh (Manager)

10. Year of Construction

11. Applicant's letter No. ID No- 2024051207393 dated 14.05 2024

S. No.	Minin and f	num Standards on fire prevention re safety U/R 33	2024051207393 dated NBC/ BBL	Provided at	Remarks			
1.	Acces	s to building	Requirement	site	MR/NMR			
	•	Road width Gate width Width of internal road	Accessible 4.5 m N/A	09 m 4.5 m N/A	M/R MR N/A			
2.	Numb	er, Width, Type & Arrangement of Ex		1 7 12 11 1	N/A			
	a. Nu	mber of staircases	its					
	•	Upper Floors						
	•	Basements	Two	Two	M/R			
	b. Wie	dth of staircases	Two	01 staircase & 01 ram				
		Upper Floor	105 010	of the right of t				
	ı.	Basements	1.25 m & 1.0 m	1.0 & 1.25 to 1.35				
	a Dra		1.25 m & 1.0 m	1.0 m & 2.75 m ran	np M/R			
	c. Pro	tection of exits Fire check door	Required	Dec. 11.1	A STATE OF THE STA			
		Pressurization	N/A	Provided	MR			
		A 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	IVA	N/A	N/A			
	d. No. of continuous staircases to terrace e. Width of Corridor f. Door Size		Required	Provided	M/R			
			1.25m	3.0 m	M/R			
				0.79 m	Old			
	Compartmentation				accepted			
	•	Fire check door in basement Upper floors	Required	Provided	M/R			
-		Sealing of electrical shafts	N/A N/A	N/A	N/A			
	•	Fire Rating of shaft door		N/A	N/A			
	•	Water Curtain	N/A	N/A	N/A			
	•	Fire Dampers	N/A N/A	N/A	N/A			
_	Smoke	Management System	N/A	N/A	N/A			
	•	Basements	Required	Exhaust fans are provided				
	•	Upper floors	Required	Natural Ventilation	on M/R			
eş.	Fire Extinguishers							
	•	Total numbers	10 no.'s	Provided	M/R			
	• Types	W/CO ₂ / CO ₂ type ISI marked	Provided	M/R				
	IS marking		ISI marked	M/R				

	Fines Attack	10/52		,			
:	First-Aid Hose Reels						
	 Total numbers on each floor 	01 no.	01 no.	M/R			
	 Length of hose reel hose 	30 mtrs.	30 mtrs.	M/R			
	Nozzle diameter	5 mm	5 mm	M/R			
7.	Automatic fire detection and alarming system						
	Type of detectors	Required	Provided	MR			
	Location of Main Panel	N/A	N/A	N/A			
	Location of Repeater Panel Alternate services of	N/A N/A	N/A	N/A			
	Alternate source of power Hooters' Location	N/A N/A	N/A	N/A			
8.	MOEFA	n m sovemen	N/A	N/A			
	- 0.235 (This Art	Required	Provided	M/R			
9.	Public Address System	N/A	N/A	N/A			
10.	Automatic Sprinkler System basement less than 200 sq. r						
	Basement	N/A	N/A	N/A			
	Ground Floor	N/A	N/A	N/A			
	Sprinkler above false ceiling	N/A	N/A	N/A			
11.	Internal Hydrants						
i.	Size of riser/down-comer	Required	Provided	M/R			
	 Number of hydrants per floor 	Required	Provided	M/R			
	Hose Box	Required	Provided	M/R			
12.	Yard Hydrants						
	Total number of hydrants	N/A '	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
13.	Pumping Arrangements						
	Ground Level						
	Discharge of main Pump	N/A	N/A	N/A			
	Head of Main pump	N/A	N/A	N/A			
	Number of main pumps	N/A	N/A	N/A			
	Jockey Pump out put	N/A	N/A	N/A			
	Jockey pump head	N/A	N/A	N/A			
	Standby Pump out put	N/A	N/A	N/A			
	> Standby Pump Head	N/A	N/A	N/A			
	➤ Auto Starting/Manual Stopping	N/A	N/A	N/A N/A			
	> Pump House Access	N/A	N/A N/A				
	Terrace level	AVEX	IVA	N/A			
	➤ Discharge of pump	450 & 180 LPM	450 & 180 LPM	MR			
	➤ Head of the pump	30 M	30 M	MR			
	> Power Supply	Required	Provided	MR			
	> Auto Starting of pump	Required	Provided	MR			
14.	Captive Water Storage for fire fighting						
	Underground tank capacity	N/A	N/A	N/A			
	> Draw-off connection	N/A	N/A	N/A			
	Fire service inlet	N/A	N/A				
	> Access to tank	N/A N/A	500,000	N/A			
	Overhead Tank capacity		N/A	N/A			
		5000 Ltrs	5000 Ltrs	MR			
		Required	Provided	M/R			

16.	Provision of Lifts.	MES					
	Pressurization of Lift Shaft						
	riessurization of I in lake	N/A	N/A	N/A			
	Collimunication In 118 C	N/A	N/A	N/A			
	Fireman's Grounding Switch	N/A	N/A	N/A			
	Lift Signage	Required	Provided				
17.	Standby power supply	Required	Provided	M/R M/R			
	ominaby power supply	Required					
18.	Refuge Area.	required	Provided	M/R			
	> Total Area						
	> Total Area > Location	N/A	N/A				
	Location	N/A		N/A			
19.	Fire Control Room	I III I	N/A	N/A			
	Detector System Panel Flow Switch B.	N/A	N/A	N/A			
	• Flow Switch Panel	N/A	N/A	N/A			
	PA System Panel Pattern I I I I I I I I I I I I I I I I I I I	N/A	N/A	N/A			
	Battery backup	N/A	N/A	N/A			
20.	Building Floor Plans	N/A	N/A	N/A			
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A			

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the renewal under rules the FSC was issued vide letter no- F6/DFS/MS/GH/2021/SZ/145 dated 18.03.2021, renewal under the rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Note: - Obstruction to the second staircase at each floor level has been removed as affidavit (placed at C- 102) given that room No. 102, 202 & 302 will not be used for guest house purpose.

Signature of Inspecting Officer Name: - R.K. Yadav

Designation: - ADO (JKP)

D.O. (South West)

) nc.l

Director/

Asyok P