G126.

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE

NEW DELHI

Dated: 28/ 5/2024

FIRE SAFETY CERTIFICATE

Certified that the building of M/S Hotel Garden View Located at Ground, 1st,2nd & 3rd floors Plot No.5/12, WEA Saraswati Marg, Karol Bagh, New Delhi - 110005, in a building comprised of basement, ground plus three upper floors using basement as (storage /hall), ground floor (reception, office, pantry & 01staff room), first floor (10 guest rooms), second floor (10 guest rooms), third floor (09 guest rooms) (Total= 30 guest rooms) was issued FSC vide Letter No F6/DFS/MS/GH/SZ/2021/231, dated 19/07/2021. The premises was re inspected by the officer concerned of this department on 22/05/2024 in the presence of Sh. Narayan (Manager) and observed that all the fire prevention and fire safety arrangements provided in the premises found in good working condition. The premises have therefore deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Residential" (guest house) ground floor (reception, office, pantry & 01staff room), first floor (10 guest rooms), second floor (10 guest rooms), third floor (09 guest rooms), (Total=30 guest rooms), with effect from 28 05 2024 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 98 05 2024 at New Delhi by.

6. F6/DFS/MS/2024/ SZ Un (188

Delhi Fire Service

Copy to:

- 1. The Joint. Commissioner of Police (Lic), 1st Floor, Licensing Unit, Police Station, Defence Colony, New Delhi.
- 2. The Manager, M/S Hotel Garden View Located at Ground, 1st,2nd & 3rd floors Plot No.5/12, WEA Saraswati Marg, Karol Bagh, New Delhi - 110005.

Following fire safety directives must be adhered to:-

- 1. 4th floor shall not be used for any purpose as undertaking given by owner.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. Basement strictly shall be kept vacant as seen during inspection.
- The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.

9. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first

N/41

INSPECTION REPORT

 Name & address of the building: M/S Hotel Garden View Located at Ground, 1st,2nd & 3rd floors Plot No.5/12, WEA Saraswati Marg, Karol Bagh, New Delhi - 110005.

2. Type of Occupancy

:Lodging or rooming "A-1"

3. Type of Case: Renewal (Running at Ground, 1st,2nd & 3rd floors in a building comprised of Basement + G+3 UFs) (01 staff room & kitchen at terrace now sealed/closed).

4. Details of previous NOC: F6/DFS/MS/GH/SZ/2021/231, dated 19/07/2021

5. Fire Safety directives Letter No.: Nil

6. Date of inspection

:22/05/2024

7. Name of the Inspecting Officer: ADO (DWK)

8. Name and designation of Officer

from the building side

: Sh. Narayan (Manager)

9. Year of Construction

: Before 2001

10. Applicant's letter No.

: 2024050406840, dated 04/05/2024

S No	Minimum standards on fire prevention and fire safety U/R 3	I ab per I moo,		Provided site	Provided at Rema				
1.	Access of building								
	Road width	17.77.77.70.0		Provided					
	Gate width		Direct accessible from roa NA NA		from road	MR			
	Width of internal road	NA				NA			
2.	Number, width, Type & Arrangements of exits								
	a. Number of staircases		-			1 50000			
	 Upper floors 	01 No. 01 No.				MR			
	 Basements 	01 No. Provid		ovided	MR				
	b. Width of staircases	4 n							
	 Upper floors 	1.25m 1.2		m MR (Being		g old case)			
	Basements	1.25m 1.25 m			MR (Being old case				
	c. Protection of exits								
	Fire check door	Required Provid		led		MR			
	Pressurization	NA		NA		NA			
	d. No of continuous staircase to terrace	NA	N/			NA			
	e. Width Of Corridor	125 cm	1.52n	n	MR				
	f. Door Size	Old case	0.78n	n	MR	IR.			
3.	Compartmentation								
	Fire check door	Requ	ired	Pr	ovided	MR			
	 Sealing of electrical shafts 	NA	NA		NA				
	Fire Rating of shaft do		2, 20122		NA				
	Water Curtain	NA	NA		NA				
	Fire Dampers	NA	*	NA		NA			

N/42

4.	Smoke managements System Provided							MR
<u>+.</u>	D amounts 30 a		C DCI IIO CI		Provided		MR	
		Upper floors	12 a/	c per ho	ur	Provided		
5.	Fire F	xtinguishers		V.		D	rovided	MR
٥,	THEL	Total numbers			IO NOS.		O ₂ & ABC	MR
		 Types 		ABC & CO ₂				MR
		IS marking	Required P		rovided	1,12		
,	Direct	First – Aid Hose Reels					l n	MR
6		Total numbers on	e 30 mu			Provided	MR	
	•	 Length of hose reel hos 				Provided	MR	
	Nozzle diameter				J 141142		Provided	, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
	Auton	natic fire detection	and al	arming	system			MR
7	Auton	Type of detectors	CO detectors		S 1	rovided	760000	
	•	Location of Main		Required		P	rovided	MR
	•	Panel		Required			Y	274
		Location of Repeater		NA		1	١A	NA
	•	Panel	5880 E T	1324				\ \mathref{m}
		Alternate source	of	Requi	red	I	OG set 62 KVA	MR
		power	9657L		0.000 APA		A	1274
		Hooters' Locatio	n	NA		N	A	NA NA
0	MOE	MOEFA				Provided		MR
8. 9.				Troo war -		Provided		MR
	Automatic Sprinkler System							1.00
10	Autor	Basements		Required			Provided	MR
		Upper Floor		NA		T	NA	NA
		Sprinkler above					NA	NA
	•		iaise	132.5			1.5	
	Internal Hydrants:							
11	Intern	Size of riser/dov	m- coi	mer	NA NA		NA	
		 Number of hydrants per flo 			~		NA	NA
							NA NA	NA
	1777							1
12	Yard	Yard Hydrants					NA	NA
	•	Total number of	NA			NA NA	NA	
		hydrants	NA				INA .	
	•	Hose Box						
13	Pump	ing Arrangements	:	1			rus I ni n	Au T
	Ground Level				7.4		NA	NA
	•	 Discharge of main pur 		P	NA		NA NA	NA NA
		Head of main pump		NA		NA NA	NA NA	
		Number of main pumps			s NA		NA	NA NA
		 Jockey pump out put 			NA		NA	NA NA
		Jockey pump head		110	NA		NA	NA NA
	>	Standby Pump Head		1	NA		NA	NA NA
	>			NA		NA		
	>	Auto Staring/Manual		1	NA		NA	NA
		stopping Pump House Access			NA		NA	NA
		Terrace level		1412			A	
					450 lpm		Provided	MR
		Discharge of pump					Provided	MR
		> Head of the pump			40 mtrs		Provided	MR
		> Power supply			Requir		Provided	MR
	P	Auto starting of pump			Required		FIGNICE	IVIIC

1/ an

14	Captive water Storage for fire f Under ground tank capacity		g	NA	ŅA		
	Draw off connection	NA		NA	NA		
	Fire service inlet	NA		NA	NA NA		
	Access to tank	NA		NA			
	 Overhead Tank capacity 	Old	case	5000 ltr	MR		
15	Exit Signage	Required		Provided	MR		
16	Provision of Lifts						
	Pressurization of Lift S	haft	NA	NA	NA		
	Pressurization of lift lo	Pressurization of lift lobby		NA	NA		
		Communication in lift Car		Provided	MR		
	 Fireman's Grounding Switch 		Required Required	Provided	MR		
	➤ Lift Signage		Required	Provided	MR		
17	Standby power supply		Required	Provided	MR		
18	Refuge Area						
	> Total area		NA	NA'	NA		
	> Location		NA	NA	NA		
19	Fire control room						
	Detector system panel	NA		NA	NA NA		
	Flow Switch Panel	NA		NA .	NA NA		
	PA System Panel	NA		NA	MR		
	➤ Battery backup		uired	Provided	NA NA		
	Building Floor Plans	NA		NA	NA NA		
20	Special Fire Protection Systems for Protection of special Risks, if any;	NA	NA		INA		

The fire protection systems provided in the building were test checked and found

unctional at the time of inspection.

In view of the deemed compliance of minimum standards on fire prevention and fire safety as required under the rules the FSC issued vide letter No. F6/DFS/MS/GH/SZ/2021/231, lated 19/07/2021 renewal under Rule 37 of the Delhi Fire Service Rules 2010 is recommended. If approved FSC may be issued.

Signature of the Inspecting Officer

Name: Sh. Udaivir Singh Designation: ADO (DWK)