

00

No F 6 / DFS / MS / 2024 / School/WZ/ 49 |

Dated 03 06 2024

**FIRE SAFETY CERTIFICATE** 

Certified that the Nigam Pratibha Vidyalaya located at GP- Block, Pitampura, Delhi110034 comprised of 04 Blocks (3 Blocks- Ground floor only) & (01 Block- Ground + One
upper floor) owned/ occupied by Nigam Pratibha Vidyalaya have complied with the fire
prevention and fire safety requirements in accordance with DOE circular no. 3298-3398 dated
01.03.2011 and verified by the officers concerned of Fire Service on 22.05.2024 in the presence of
Smt. Vandana Kasturia (HOS) and found that the building/ premises is fit for occupancy
Group B Educational with effect from 03 06 2024 for a period of 03 (Three) years
subject to compliance of the conditions mentioned below:

Issued on .. 9.3 0.6 20.24.. at New Delhi by

Atul Garg)
Director
Ph. 011-23414000

## Copy to:-

- 1. The Director, Education, MCD Civic Centre.
- 2. The Principal, Nigam Pratibha Vidyalaya, GP-Block, Pitampura, Delhi-110034.

## Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="https://www.dfs.Delhigovt.nic.in"><u>WWW.dfs.Delhigovt.nic.in</u></a>
- 8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.
- 9. Electric Panel under the staircase must be removed within a period of three months from the date of issuance of the Fire Safety Certificate. Failing to do so the Fire Safety Certificate will be null and void.

INSPECTION REPORT

Nigam Pratibha Vidyalaya, GP- Block, Pitampura, Delhi- 110034. Name & address of the building:

Educational Type of Occupancy

04 Blocks (3 Blocks Ground floor) & (01 Block Ground plus First floor) 3. Building Comprised of

Addition/ Alteration

 Type of Case
 Details of Previous NOC F6/DFS/MS/School/2019/1988 dated 16/10/2019

(Previous FSC was for 04 Blocks of Ground floor only)

DOE circular No. 3298-3398 dated 01/03/2011 6. Fire Safety directives letter No :

22/05/2024 7. Date of inspection

R.K.Sinha, ADO (BW) 8. Name of Inspecting Officer

9. Name and designation of officers

Smt. Vandana Kasturia (HOS) From the building side 1984, 1991, 1995 & 2022 10. Year of Construction

	Minimum Standards on fire	DOE Paguirement	Provided at site	Remarks	
,.	prevention and fire safety U/R 33 Access to building	Requirement		MR/NMR	
	Road width	6 m	Provided	100	
	Gate width	Accessible	Accessible	MR	
	Width of internal road	NA	NA	MR	
		200-500,000	INA	NA	
	Number, Width, Type & Arrangement of Exits				
	a. Number of staircases				
	Upper Floors	01	01	MR	
	Basements	NA	NA	NA	
	b. Width of staircases				
	Upper Floor	1.50 m	Provided	MR	
	Basements	NA	NA	NA	
	c. Protection of exits			IVA	
	Fire check door	NA NA	NA	NA	
	Pressurization	NA NA	NA NA	5000000	
	d. No. of continuous staircases to	SP275-R3	IVA	NA	
	terrace	NA	01	NA	
	e. Width of Corridor	NA	NA	NA	
	f. Door Size	1 m old block 1.20 m new block	Provided with double door	MR	
3.	Compartmentation				
	Fire check door	NA	NA	NA	
	Sealing of electrical shafts	NA	NA	NA NA	
	Fire Rating of shaft door	NA	and the second s		
	Water Curtain	NA NA	NA NA	NA	
	Fire Dampers	NA NA	NA NA	NA	
1.	Smoke Management System	101	INA INA	NA	
	Basements	NA			
1	Upper floors		NA NA	NA	
	777.10013	Required	Naturally Ventilated	MR	
5.	Fire Extinguishers				
	Total numbers	10			
	<ul> <li>Types</li> </ul>		10	MR	
_	IS marking	ABC Type	Provided	MR	
6.	First-Aid Hose Reels	Required	Provided	MR	
	Total numbers on each floor	NA	N.		
	Length of hose reel hose	NA NA	NA NA	NA	
-	Nozzle diameter		NA	NA	
7.		NA	NA	NA	
Ť					
	ar of detectors	NA	NA		
	Location of Main Panel	NA	NA	NA	
	Location of Reports D	NA NA	NA	NA	
	Alternate source of power	NA NA	NA	NA	
	- 11	A.	NA	NA NA	

Ν	-	16
•		

				NA NA	
		NA	NA .	NA NA	
	Hooters' Location	NA	NA NA	NA	
	MOEFA	NA	NA	19 11 1	
	Public Address System				
0.	Automatic Sprinkler System	- 0 - 0	NA NA	NA	
υ.		NA	NA NA	NA	
	Basement	NA	NA NA	NA	
	Ground Floor     Glassiling	NA	INA	- 1	
	Sprinkler above false ceiling				
11.	Internal Hydrants	5.86.27	NA	NA	
	Size of riser/down-comer	NA	NA	NA	
	Number of hydrants per floor	NA NA	NA	NA	
	Hose Box	IVA 198			
12.	Yard Hydrants		NA	NA	
	Total number of hydrants	NA	NA NA	NA	
	Total number of flydrams     Hose Box	NA	NA	Eio F	
13.	Pumping Arrangements		, a 1, 10	S .	
13.					
	Ground Level     Grosin Rump	NA	NA	NA NA	
	> Discharge of main Pump	NA NA	NA	NA	
	> Head of Main pump		NA	NA	
	> Number of main pumps	NA	· NA	NA	
	> Jockey Pump out put	NA	NA NA	NA	
	> Jockey pump head	NA NA	NA NA	NA	
	> Standby Pump out put	NA NA	NA	NA	
	<ul> <li>Standby Pump Head</li> <li>Auto Starting/Manual</li> </ul>	NA NA	NA	NA	
	Stopping	NA	NA	NA NA	
	> Pump House Access	of of			
	Terrace level	a Calle			
	> Discharge of pump	NA	NA	NA	
		NA	NA	NA	
	> Head of the pump			- NA	
	> Power Supply	NA	NA NA	NA NA	
	> Auto Starting of pump	NA	NA	I NA	
14.	AND		NA	T NA	
	Underground tank capacity	NA	NA NA	NA NA	
	> Draw-off connection	NA	NA	NA	
	> Fire service inlet	NA	NA NA	NA NA	
	> Access to tank	NA NA	NA NA	NA	
15.	Overhead Tank capacity     Exit Signage.	NA Required	NA Provided	NA MR	
13.		Atoquilou	11071000	TATIC	
16.	Provision of Lifts.	, - Jii			
	Pressurization of Lift Shaft	NA	NA	NA	
	Pressurization of Lift lobby	NA	NA	NA NA	
	Communication In lift Car	NA	NA	NA NA	
	Fireman's Grounding Switch	NA	NA	NA NA	
		NA NA	NA NA		
17	Lift Signage  Standby power supply	NA NA	NA NA	NA	
17.	Standby power supply	INA	NA	NA	
18.	Refuge Area.		4- 3-34	-	
	> Total Area	NA	NA	NY4	
	> Location	NA	NA	NA NA	
		1/	414.4	INA	

W

Detector System Panel	NA	NA	NA
Flow Switch Panel	NA	NA	NA
PA System Panel	NA	NA	NA
Battery backup	NA	NA	NA
Building Floor Plans	NA	NA	, NA
Special Fire Protection System for Protection of special Risks, if any:	NA	NA	NA

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection. The management had rectified the shortcomings issued vide letter number F6/DFS/MS/School/2020/223 dated 13/04/2020. New block of Ground plus first floor is having one staircase of 1.5 m but it is meeting the requirement of minimum travel distance of 30 m.

Note: Electric meter found installed under the staircase which has to be removed to a safer place.

Keeping in view of substantial compliance of the minimum standards of fire prevention and fire safety measures as required under DOE circular no. 3298-3398 dated 01/03/2011, it is recommended to grant Fire Safety Certificate.

Signature of Inspecting Officer Name: Rajeev Kumar Sinha Designation: ADO/B.W.

1983-NW.

De CFO

0.24 ps/24

27 Mags 27 1 Sony

irola/

For Justin in Pro

, for again p

7 200

Director (1/6) 29/6) M

m