

c-186

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/EH/2024/SZ/ 165

Dated: 29/05/2024

FIRE SAFETY CERTIFICATE

Certified that the M/s Om Sweets Pvt. Ltd., GL-23, Shaheed Bhagat Singh Marg, Jail Road, Hari Nagar, New Delhi-110064 the building comprised of Basement, ground floor plus three upper floors, but restaurant is running at First floor only. The restaurant was issued FSC by this department vide letter no. F.6/DFS/MS/EH/2021/SZ/27 dated 04.02.2021. The building was re-inspected by the officers concerned of this department on 20.05.2024 in presence of Sh. Ajeem Khan (Unit Manager) and found that the management have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi fire service Rules 2010 and that the building/premises (First floor only) is fit for occupancy class **Group-D "Assembly Building"** w.e.f. 29/05/2024 for a period of **three years** in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed as below.

Issued on 29/05/2024 at New Delhi.


J. Gul Garg)
Director
Delhi Fire Service


Online application Id 2024032003290 dated 30.04.2024

Following fire safety directives must be adhered to:-

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
4. The trained staff should be available round the clock.
5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
7. Basement shall be used as per the building bye laws.
8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

N/25

INSPECTION REPORT

1. Name & address of the building : M/s Om Sweets Pvt. Ltd., GL-23, Shaheed Bhagat Singh Marg, Jail Road, Hari Nagar, New Delhi-110064
2. Building is comprised of : basement (store), ground floor (sweet shop), First floor (restaurant), second floor (kitchen), third floor (store) & terrace (two rooms sealed).
3. Type of Occupancy : Group D (Assembly Building)
4. Type of Case : Renewal
5. Details of Previous NOC : F.6/DFS/MS/EH/2021/SZ/27 dated 04.02.2021
6. Fire Safety directives letter No : N/A
7. Date of inspection : 20.05.2024
8. Name of Inspecting Officer : A.D.O. R.K.Yadav
9. Name and designation of officers :
From the building side : Sh. Azeem Khan (Unit Manager)
10. Year of Construction : 2009-10
11. Applicant's letter No. : Online application Id 2024032003290 dated 30.04.2024

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirement	Provided at site	Remarks MR/NM/R
1.	Access to building	09 mtrs	12 mtrs Provided	MR
	<ul style="list-style-type: none"> • Road width • Gate width • Width of internal road 	4.5 mtrs N/A	N/A	MR MR N/A
2.	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases	02 No.'s	02 No.'s	MR
	<ul style="list-style-type: none"> • Upper Floors • Basements 	02 No.'s	02 No.'s	MR
	b. Width of staircases	Two staircases	1.11 to 1.50 m & 85 cms	MR, old case
	<ul style="list-style-type: none"> • Upper Floor • Basements 	Two staircases	1.30 m & .85 m	MR, old case
	c. Protection of exits	Required	Provided	MR
	<ul style="list-style-type: none"> • Fire check door • Pressurization 	N/A	N/A	N/A
	d. No. of continuous staircases to terrace	Required	One	MR
	e. Width of Corridor	1.50 m	1.60 m	MR
	f. Door Size	Two exits	.92 & 1.15 m	MR, old case
3.	Compartmentation	Required	Provided	MR
	<ul style="list-style-type: none"> • Fire check door • Sealing of electrical shafts • Fire Rating of shaft door • Water Curtain • Fire Dampers 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
4.	Smoke Management System	Required	Exhaust fans are provided	MR
	<ul style="list-style-type: none"> • Basements 	Required	Natural Ventilation	MR
	<ul style="list-style-type: none"> • Upper floors 			
5.	Fire Extinguishers	03 No.'s/floor	Provided	MR
	<ul style="list-style-type: none"> • Total numbers • Types • IS marking 	ABC/CO ₂ ISI marked	Provided	MR
			ISI marked	MR
6.	First-Aid Hose Reels	One	Provided	MR
	<ul style="list-style-type: none"> • Total numbers on ground floor • Length of hose reel hose • Nozzle diameter 	30 mtrs 5 mm	Provided	MR
			Provided	MR

13

kn

7.	Automatic fire detection and alarming system			
	<ul style="list-style-type: none"> Type of detectors Location of Main Panel Location of Repeater Panel Alternate source of power Hooters' Location 	Smoke/Heat Required N/A Required Required	Provided G. Floor N/A Provided Provided Near exit	MR MR N/A MR MR MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System			
	<ul style="list-style-type: none"> Basement Ground Floor Sprinkler above false ceiling 	Required Required Required	Provided Provided Provided	MR MR MR
11.	Internal Hydrants			
	<ul style="list-style-type: none"> Size of riser/down-comer Number of hydrants Hose Box 	100 mm One One	Provided Provided Provided	MR MR MR
12.	Yard Hydrants			
	<ul style="list-style-type: none"> Total number of hydrants Hose Box 	N/A N/A	N/A N/A	N/A N/A
13.	Pumping Arrangements			
	<ul style="list-style-type: none"> Ground Level <ul style="list-style-type: none"> Discharge of main Pump Head of Main pump Number of main pumps Jockey Pump out put Jockey pump head Standby Pump out put Standby Pump Head Water Curtain Pump Auto Starting/Manual Stopping <ul style="list-style-type: none"> Pump House Access Terrace level <ul style="list-style-type: none"> Discharge of pump Head of the pump Power Supply Auto Starting of pump 	1620 LPM 70 mtrs One 180 LPM 40 mtrs 1620 LPM 70 mtrs Required Required Required 900 LPM 40 mtrs Required Required	1620 LPM 70 mtrs One 180 LPM 40 mtrs 1620 LPM 70 mtrs Provided Provided Provided 900 LPM 40 mtrs Provided Provided	MR MR MR MR MR MR MR MR MR MR MR MR MR MR MR MR MR MR MR
14.	Captive Water Storage for fire fighting			
	<ul style="list-style-type: none"> Underground tank capacity <ul style="list-style-type: none"> Draw-off connection Fire service inlet Access to tank Overhead Tank capacity 	70000 Ltrs Required Required Required 10000 ltrs Required	Provided Provided Provided Provided Provided Provided	MR MR MR MR MR MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts. (Lift is not in use)			
	<ul style="list-style-type: none"> Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage 	N/A N/A N/A N/A N/A	N/A N/A N/A N/A N/A	N/A N/A N/A N/A N/A
17.	Standby power supply	Required	Provided	MR

N/27

Refuge Area.			
	➤ Total Area	N/A	N/A
	➤ Location	N/A	N/A
19.	Fire Control Room	N/A	N/A
	• Detector System Panel	N/A	N/A
	• Flow Switch Panel	N/A	N/A
	• PA System Panel	N/A	N/A
	• Battery backup	N/A	N/A
	• Building Floor Plans	N/A	N/A
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A

The fire protection systems provided in the building were checked and found functional at the time of inspection. The shortcomings was already issued by this department vide letter no. F6/DFS/MS/EH/2024/SZ/140 dated 19.04.2024 has been rectified.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F.6/DFS/MS/EH/2021/SZ/27 dated 04.02.2021, renewal under rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Accordingly, reply letter is put up for approval & signature please.

R.K. Yadav
24/5/2024

Signature of the inspecting officer
Name- R.K. Yadav
Asstt. Div. Officer (JKP)

DO (SW)
[Signature]
22/5/24

Cfo (S2)
[Signature]
22/5/2024

Director (M)
[Signature]
22/5/24

[Signature]
ADG JKP