GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001

No.F6/DFS/MS/2024/ School/NDZ/ 484

Dated:31./.05/2024

FIRE SAFETY CERTIFICATE

Issued on ... 31/05/2024... at New Delhi by.

(Atul Garg)
DIRECTOR
Delhi Fire Service

Copy to:-

1. Director of Education, Old Secretariat, Delhi - 110054.

2. The Principal, Sarvodaya Kanya Vidyalaya at Ahata Kidera, Idgah Road, New Delhi.

Conditions for the validity of fire safety certificate

1. All the means of escape shall be kept free of all types of obstruction all the time.

2. All the fire safety arrangements provided there in shall be maintained in good working condition at all time.

3. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

4. The compliance with regards to electrical installation, structural stability, set back area, occupancy and any deviation in construction etc. shall be verified from authority concerned.

5. Any deviation w.r.t construction etc. shall be verified by the concerned building sanctioning authority.

6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

8. Any flammable material for interior decoration shall strictly prohibited.

	CTION REPOR	RT .		
			a	
K	edara. Iddah Re	oad, Delhi - 11000	6.	
			openik H	
			floor	
	Renewal			
		School/NDZ/1349	dated	
Details of provides 150.	24/07/2015.			
Fire safety directives No				
	17/05/24			
	Sh. Ravinder	r Singh ADO (CC)		
	Smt. Tara Ra	ni ,Principal		
	letter no. nil	dated nil		
		Provided at site	Remarks	
The state of the s			MR/NMR	
			A . T.	
) MESSEN SIVELEN NA	06 mtr	06 mtr	MR	
	100000000000000000000000000000000000000	177/201-00/20145	MR	
No. N. Control of the		100000000000000000000000000000000000000	N/A	
		N/A	IVA	
	gement of Exits			
	0.5	106	MR	
	(11950) Committee of the Committee of th	ANTE CONTRACTOR OF THE CONTRAC	N/A	
	A A M E A A A M E A A A A A A A A A A A	N/A	IN/A	
		1v2 0m 2v1 9m 8	MR	
1. Upper floors	1.0 mm		MIK	
2 Resements	N/A		N/A	
Company of the compan	AWZ			
	N/A	N/A	N/A	
		Exposition, Alexander	N/A	
			MR	
	3=			
The state of the s	NA	NA	NA	
			MR	
	1			
	N/A	N/A	N/A	
	1 7 St 1991 Millson	1247/2017/2017/2017	N/A	
		The second secon	N/A	
			N/A	
	The American Control of the Control		N/A	
	INIZE	LNIZA	17/11	
	30 ACPH	N/A	N/A	
			MR	
	12 ACFI	INALUIAI	IVIX	
	25 Nos	25 Nos	MR	
			IVILL	
	Required	Provided	MR	
1)Total number of each	03	03	MR	
	Type of occupancy:- Type of case:- Details of previous FSC:- Fire safety directives No Date of inspection:- Name of the inspecting officer:- Name & designation of officer From the building side:- Year of construction:- Applicant's letter No:- Minimum Standards on fire Prevention and fire safety U/R 33 Access to Building 1) Road width 2) Gate width 3) Width of internal road	Type of occupancy:- Type of occupancy:- Type of case:- Details of previous FSC:- Fire safety directives No Date of inspection:- Name of the inspecting officer:- Name & designation of officer From the building side:- Year of construction:- Applicant's letter No:- Minimum Standards on fire Prevention and fire safety U/R 33 Access to Building 1) Road width 2) Gate width 3) Width of internal road N/A Number, Width Type & Arrangement of Exits A. Number of staircases 1. Upper floors 2. Basements N/A B. Width of staircase 1. Upper floors 1. Fire check door 2. Pressurization D. No. of continuous staircase to terrace E. Width of corridor E. Width of corridor F. Door size Details of previous FSC:- Renewal F6/DFS/MS/S 24/07/2015. N/A Sm. Ravinder Smt. Tara Ravinder	ame & address of the building: Type of occupancy:- Type of case:- Details of previous FSC:- Details Deldat Mold Upper floor, New Block- Gr. + 5tilt 4 02 Upper flo	



		NG	30 mtr.	+
	Chase reel hose	30 mtr.		M
2) Length	of hose reel hose	05 mm	05 mm	M
3) Nozzle	Fire Detection &	Alarming System	m	1
Automatic	Fire Detection &	N/A	N/A	N
1) Type of	detectors	N/A	N/A	N
2) Locatio	n of main panel		N/A	N
3) Locatio	n of repeater panel	N/A	N/A	N
4) Alterna	te source of power	N/A	N/A	N
5) Hooter	s Location	N/A	N/A	N
8. MOEFA		N/A		N
	dress System	N/A	N/A	-
	Sprinkler System			N.
1) Basemo		N/A	N/A	
2) Upper		N/A	N/A	N/
	er above false	N/A	N/A	N/
	iei annac iaise	****		0
ceiling 11. Internal H	Sydnanta			
	riser/down-comer	N/A	N/A	N/
		N/A	N/A	N/
floor	er of hydrants per	11/21	1112	
		N/A	N/A	N/
3) Hose b		IN/A		
12. Yard Hyd		N/A	N/A	N/A
2) Hose b	number of hydrants	N/A	N/A	N/A
		IN/A	IVA	1 1
	rrangement	NT/A	N/A	N/A
	und level	N/A	N. 100000 1000	N/A
900	charge of main	N/A	N/A	I IN/E
pun		NT/A	NI/A	N/A
	nd of main pump	N/A	N/A	
	mber of main	N/A	N/A	N/A
pur d) Ioo		N/A	N/A	N/A
	key pump out put key pump head	N/A N/A	N/A N/A	N/A
	nd by pump	N/A	N/A	
out		IN/A	IVA	N/A
	nd by pump head	N/A	N/A	N/A
	to starting/Manual	N/A	N/A	N/A N/A
	pping		11/23	IWA
	race level			
ALC, VI. CONTROL OF	scharge of pump	2x450 LPM	2x450 LPM	MR
	ad of pump	40 mtr.	40 mtr.	MR
	wer supply	Required	Provided	MR
	to starting of	Required	Provided	MR
pui	THE PROPERTY OF PARTY OF THE PARTY.	Anazigiatora zazi	110114	IVIIC
	ater Storage for Fire	e Fighting		
	der ground tank	N/A	N/A	N/A
	pacity			A100-70-70
	aw-off connection	N/A	N/A	N/A
	e service inlet	N/A	N/A	N/A
	cess to tank	N/A	N/A	N/A
	er head tank	10,000 ltr.	10,000 ltr.	MR
	pacity			
15. Exit Signa		Required	Provided	MR

A.
 1 04
171

16.	Provision of Lifts.		- T	
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
U-2-	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
1	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
2 1 1	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risk, if any:			

The fire protection system provided in the school building were tested, checked at random and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the Rules, if agreed, we may renew the FSC issued vide letter no. F6/DFS/MS/2015/School/ NDZ/1349 dated 24/07/15, under Rule 35 of the Delhi Fire Service rules 2010. Accordingly, DFA is put up for kind perusal and signature please.

No fel i pendy refor autos this fil

Signature of the Inspecting Officer

Name: - Ravinder Singh Designation: - ADO (CC)

24/5/24 24/5/24 24/5/202)

27/05/2

Directer

Aoya