

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2024/200

Dated. 31. 0.5.../2024

FIRE SAFETY CERTIFICATE

Certified that the Surya Plaza Guest House located at 2471, Nalwa Gali, Pahar Ganj, New Delhi comprised of Basement + Ground + 03 Upper floors, Basement (Storage), Ground floor (03 guest rooms + Reception), 1st floor to 3rd floor (04 guest rooms at each floor), total 15 guest rooms up to third floor owned/occupied by Surya Plaza Guest House, was earlier granted FSC by this department vide letter No. /DFS/MS/GH/NDZ/2021/247 dated 26/07/21. Now, the premises was re-inspected by the officer concerned of this department on 20/05/24 in the presence of Manager and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 Ground floor (03 guest rooms) 1st floor to 3rd floor (04 guest rooms at each floor), total 15 guest rooms only up to third floor, 31.03.2027 from the date of issue in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued ...31 0.5 2024...New Delhi by.

DIRECTOR hi Fire Service

Copy to:-

- The Commissioner, North MCD, Civic Centre, New Delhi: to ensure not to use any floor above third floor.
- The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi. on line ID No. 2024043006503 dated 05/05/24
- 3. The Manager, Surya Plaza Guest House 2471, Nalwa Gali, Pahar Ganj, New Delhi.

Condition for the validity of fire safety certificate

- All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

1. Name & address of the building Surya Plaza Guest House at 2471, Nalwa Gali, Pahar Ganj, New Delhi. 2. Type of occupancy:-Residential, Sub Division-A-1 B + Ground + 03 Upper floors (total 15 guest rooms) Basement (Storage), Ground floor (03 guest rooms + Reception), 1st floor to 3rd floor (04 guest rooms at each floor) Type of case: Details of previous FSC:-Renewal No. F6/DFS/MS/GH/NDZ/2021/247 dated 26/07/21. N/A 5. Fire safety directives No.-6. Date of inspection:-20/05/24 7. Name of the inspecting officer:-Sh. Ravinder Singh (ADO/CC) 8. Name & designation of officer From the building side:-Manager 9. Year of construction:-2008 10. Applicant's letter No:on line ID No. 2024043006503 dated 05/05/24 Old Case Minimum Standards on fire Requirement/ S.No. Provided at site Remarks Existing fire safety Prevention and fire safety U/R 33 MR/NMR arrangements 1. Access to Building 1) Road width 06 mtr. MR 06 mtr. 2) Gate width N/A N/A N/A N/A 3) Width of internal road N/A N/A 2. Number, Width Type & Arrangement of Exits A. Number of staircases 1. Upper floors MR 01 Nos. 01 Nos. 2. Basements 01 Nos. 01 Nos. MR B. Width of staircase 1. Upper floors 1.25 mtr. MR 0.80 mtr. 2. Basements 0.80 mtr. 1.25 mtr. MR C. Protection of exits 1. Fire check door Required Provided MR 2. Pressurization N/A N/A N/A D. No. of continuous 01 01 MR staircase to terrace E. Width of corridor N/A N/A N/A F. Door size 01 mtr. 01 mtr. MR 3. Compartmentation 1) Fire check door N/A N/A N/A 2) Sealing of electrical shafts N/A N/A N/A 3) Fire rating of shaft door N/A N/A N/A 4) Water curtain N/A N/A N/A 5) Fire Dampers N/A N/A N/A **Smoke Management System** 4. 1) Basements 30 ACPH Provided MR 2) Upper floors 12 ACPH Natural MR 5. Fire Extinguishers 1) Total numbers 10 Nos. 10 Nos. MR

INSPECTION REPORT

1 1

.11	1.4
MI	DI
/	

	2) Types						
	3) ISI marking	ABC & CO2	ABC & CO	MR MR			
6.		Required	Provided	MR			
	THIST AID HOSE Real			IVIK			
	1) Total number of each	01	01	H-1			
	11001		01	MR			
	2) Length of hose reel hose	30 mtr.	30 mtr.	<u> </u>			
-	3) Nozzle diameter	O.C.		MR			
7.	Automatic Fire Detection 8	lomi- C	05 mm	MR			
	1 / 1 I ()COTION of	Required	Provided	MR			
	1 1 1 Ocation of	Required	Provided	MR			
	4) Alternate source of power	N/A	N/A	N/A			
	5) Hooter's Location	Required	Provided	MR			
8.	MOERA	Required	Provided	MR			
9.	MOEFA	Required	Provided				
10.	Public Address System	Required	Provided	MR			
10.	Automatic Sprinkler System			MR			
	1) Basement	Required	Drovidad	3.00			
	2) Upper floors	N/A	Provided /	MR			
	3) Sprinkler above false	N/A	N/A	N/A			
	ceiling	AND.	N/A	N/A			
11.	Internal Hydrants		1				
	1) Size of riser/down-comer	N/A	NT/A				
	2) Number of hydrants per	N/A	N/A	N/A			
	floor	IV/A	N/A	N/A			
_	3) Hose box	N/A	37/4	-			
12.	Yard Hydrants	IVA	N/A	N/A			
	11 70	1) Total number of hydroute N/4					
	2) Hose box	N/A	N/A	N/A			
13.	Pumping Arrangement	IVA	N/A	N/A			
	1) Ground level	NI/A	3-11				
	a) Discharge of main	N/A N/A	N/A	N/A			
	pump	1W/A	N/A	N/A			
	b) Head of main pump	N/A	NIA				
	c) Number of main pump	N/A	N/A	N/A			
	d) Jockey pump out put	N/A	N/A N/A	N/A			
	e) Jockey pump head	N/A	The second principle	N/A			
	f) Stand by pump output	N/A	N/A N/A	N/A			
	g) Stand by pump head	N/A	N/A	N/A			
	h) Auto starting/Manual	N/A	N/A	N/A			
14.	stopping	F. W. C.	IVA	N/A			
	2) Terrace level						
	a) Discharge of pump	450 LPM	450 LPM 4	MO			
	b) Head of pump	30 mtr.	30 mtr.	/ MR			
	c) Power supply	Required	Provided Provided	/ MR			
	d) Auto starting of pump	Required	Provided	MR			
	Captive Water Storage for F	ire Fighting	1-15/1404	MR			
	 Under ground tank 	N/A	N/A	N/A			
	capacity		1	IVA			

1	a) Draw-off connection	N/A	N/A	N/A	
	b) Fire service inlet	N/A	N/A	N/A	
	c) Access to tank	N/A	N/A	N/A	
	d) Over head tank capacity	5000 ltr.	5000 ltr.	MR	
15.	Exit Signage.	Required	Provided /	MR	
5. 6.	Provision of Lifts.			.,,,,,	
	a) Pressurization of lift shaft	N/A	N/A	N/A	
	b) Pressurization of lift lobby	N/A	N/A	N/A	
	c) Communication in lift car	N/A	N/A	N/A	
	d) Fireman's switch	N/A	N/A	N/A	
	e) Lift signage	N/A	N/A	N/A	
7.	Stand by Power Supply	Required	Provided	MR	
18.	Refuge Area	N/A	N/A	N/A	
	Total area location	N/A	N/A	N/A	
19.	Fire Control Room	N/A	N/A	N/A	
	a) Detector system panel	N/A	N/A	N/A	
	b) Flow switch panel	N/A	N/A	N/A	
	c) PA system panel	N/A	N/A	N/A	
	d) Battery backup	N/A	N/A	N/A	
	e) Building floor plan	N/A	N/A	N/A N/A	
20.	Special Fire Protection System for Protection of special Risk, if any:				

The fire protection systems provided in the building were randomly tested,

checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, if agreed, we may renew the FSC issued vide letter no. F6/DFS/MS/GH/NDZ/2021/247 dated 26/07/21, under rule 35(6) of the Delhi Fire Service rules 2010. Accordingly, DFA is put up for kind perusal and signature please.

Signature of the Inspecting Officer

Name: - Ravinder Singh

Designation: - ADO(CC)