GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI <u>HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001</u>



No F 6 / DFS / MS / 2024 /WZ/ 365

Dated 14/06/2004

FIRE SAFETY CERTIFICATE

Certified that M/s Bathla Motel Pvt. Ltd. located at Kh. No. 51/1 min, 51/10 min, 51/26 min, 52/6 min, Village Bakoli, Delhi- 110036 is comprised of Basement, Ground plus four upper floors have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of this department on 13.06.2024 in the presence of Sh. Devraj Chaudhary (A.E., MCD) & Sh. Amit Vashisht (J.E., MCD) and found that the building/ premises is fit for occupancy Mixed "Assembly & Residential" with effect from 14/56/2024 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010 printed below.

Issued on 14 06 2014 at New Delhi by

Pb-011-23414000

Copy to:-

1. The Executive Engineer (Bldg.) HQ, MCD, Civic Centre, New Delhi- 110002.

 M/s Bathla Motels Pvt. Ltd., Kh No. 51/1 min, 51/10 min, 51/26 min, 52/6 min, Village Bakoli, Delhi- 110036.

Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.

2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.

5. This certificate cannot be treated in any case for regularizations of unauthorized construction.

6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on WWW.dfs.Delhigovt.nic.in

8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

		N-50				
	1. Name & add	ress of the building: M	INSPECTION REPORT //s Bathla Motels Pvt. Ltd.	[located at Kh. No.51/1 min	, 51/10 min, 51/26	
	- ADE OF O		mi, sero min, v mage bak	on, Denn Troope.		
			Mixed (Assembly & Res			
			Basement, Ground plus For Addition/ Alteration	our upper moors.		
	5. Details of Pro	vious NOC		otel/193 Dated 05/05/2022	(For B+Gr+1)	
0	7. Date of inspe	rectives letter No	F6/DFS/MS/BP/2022/115		2 (101 D · 01.· 1)	
1 5	8. Name of Incr	ction :	13/06/2024	Date 15/ 05/ 2022		
	The and the	Florati - C	R.K.Sinha, ADO (BW)			
	IV. I car of Cone	mintin	Sh. Devraj Chaudhary (A.	E., MCD) & Sh. Amit Vas	hisht (J.E., MCD)	
	11. Applicant's L	ettor No	2018 & 2023-24	2012 1 . 1 02/04/05		
3.	Minimum Sta	ndords on C	MCD Portal ID No. 10099 As per directive issued		D	
No.	prevention an	d fire safety II/D 22	dated 15/03/2022	Provided at site	Remarks MR/NMR	
1.	recess to buil	ding			MICHINIK	
	Road		· 20 m	Provided	MR	
	Gate v		6 m	Provided	MR	
_	Width	of internal road	6 m & turning circle 9 r		MR	
2.	Number, Wid	th, Type & Arrangeme	ent of Exits			
-						
	a. Number of				A	
1	 Upper 	Floors	04	Provided	MR	
	Baser	nents	03	Provided	MR	
	b. Width of st		, 03	CONTRACTOR		
		Floor	1.5 m each	Provided	MR	
	Baser			Provided	MR	
	c. Protection		1.5 m each	Provided	IVIX	
		TANGE OF THE PARTY			1 10	
		heck door	Required	Provided	MR	
	Press	rization	NA	NA	NA	
	d. No. of cont terrace	inuous staircases to	02	Provided	MR	
	e. Width of Co	orridor	1.8 m	Provided	MR	
			1 m (Residential) &	Provided	MR	
	f. Door Size		2 m (assembly)	ACCOMMAND CONSISSION	354445648	
3.	Compartment	ation				
	Fire che	eck door	Required	Provided	MR	
	- I		Required	Provided	MR	
		of electrical shafts	1.00			
		ting of shaft door	Required	Provided	MR	
	Water (Required	Provided	MR	
	Fire Da		NA	NA	NA NA	
4.	Smoke Manage	ement System				
	Baseme	nts	Required	Provided	MR	
	Upper fi		Required	Provided	MR	
	- Opper	10015	Moquitou	Tiovided	IVIIX	
5.	Pine Fadin	*****				
J.	Fire Extinguish			104	1.00	
	Total nu	impers	60	124	MR	
(4°)	Types		ABC,Co2 & WCO2	Provided	MR	
	 IS mark 		Required	Provided	MR	
6.	First-Aid Hose		1.1			
	Total nu	imbers on each floor	02	Provided	MR	
4	• Length	of hose reel hose	30 m	Provided	MR	
	Nozzle	diameter	5 mm	Provided	MR	
7.	Automatic fire	detection and alarmin				
		detectors	CO & Smoke/ Heat	Provided	MR	
		n of Main Panel	G.F.	Provided	MR	
	The second state of the second	n of Repeater Panel	NA			
		te source of power		NA Dravidad	NA NA	
	Alterna	te source of power	Required	Provided	MR	
	Hooters	' Location	At all floors	Provided	MR	
	11001015	Location				
7 1	0	San Date of the San				

N-	<	ı

3.	MOEFA N-S					
9.	Public Address System	Required Provided		MR		
10.	Automatic Sprinkler System	Required	Provided	MR		
	Basement					
	Upper Floor	Required	Provided	MR		
		Required	Provided	MR		
11.	Sprinkler above false ceiling Internal II	NA	NA	NA		
	Internal Hydrants					
	Size of riser/down-comer Number of had a second community of had a second community of the se	100 mm	Provided	MR		
	realition of hydrants per floor	02	Provided	MR		
12.	Hose Box Yard Hydrants	02	Provided	MR		
	Total number of hydrants Hose Box	Required	Provided	MR		
13.	Pumping Arrangements	Required	Provided	MR		
	Ground Level					
		T		- 10		
	Discharge of main Pump	2850 lpm	Provided	MR		
	Head of Main pump	100 m	Provided	MR		
	Number of main pumps	1 electrical, 1 DG, 1 Jockey, 1 terrace pimp	Provided	MR		
	Jockey Pump out put	180 lpm	Provided	MR		
	Jockey pump head	40 m	Provided	MR		
	> Standby Pump out put	2850 lpm	Provided	MR		
	Standby Pump Head	100 m	Provided	MR		
	> Auto Starting/Manual Stopping	Required	Provided	MR		
	> Pump House Access	Required	Provided	MR		
	Terrace level					
	Discharge of pump	900 lpm	Provided	MR		
	> Head of the pump	40 m	Provided	MR		
	> Power Supply	Required	Provided	MR		
	➤ Auto Starting of pump	Required	Provided	MR		
14.	Captive Water Storage for fire fighting					
	Underground tank capacity 2,00,000 ltrs Provided					
	> Draw-off connection	Required	Provided	MR		
	The Control of the Co		810 910 0000 FEMORE CITE	MR		
	Fire service inlet	Required	Provided	MR		
	Access to tank	Required	Provided	MR		
15.	Overhead Tank capacity Exit Signage.	25,000 ltrs Required	Provided Provided	MR		
		Required	Provided	MR		
16.	Provision of Lifts					
	Pressurization of Lift Shaft	NA NA	NA	NA		
	Pressurization of Lift lobby	NA	NA	NA		
	Communication In lift Car	NA	NA	NA		
	Fireman's Grounding Switch	Required	Provided	MR		
	Lift Signage	Required	Provided	MR		
17.	Standby power supply	Required	Provided	MR		
18.	Refuge Area.					
	➤ Total Area	NA NA	N/			
	> Location	NA NA	NA NA	NA		
19.	Fire Control Room	INA	NA	NA		
	Detector System Panel Required Provided					
	Detector System Panel Flow Switch Panel	Required	Provided	MR		
	PA System Panel	Required Required	Provided	MR		
	17 System Panel	Required	Provided	MR		

Bartery backup	Required	Provided	MR
Building Floor Plans Special Fit Day	Required	Provided	MR
20. Special Fire Protection System for Protection of special Risks, if any:	Required	Provided	MR

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Keeping in view of satisfactory compliance of the minimum standards of fire prevention and fire safety measures as required under rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Signature of Inspecting Officer Name: Rajeev Kumar Sinha Designation: ADO/B.W.

Dycfo(Epw)

0×1916/24

CFD Mugh

Directer

Stoppen 1893

Letter is pur up for 1

Minathre p1

Dinipoluly

Mu