

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001



No F 6 / DFS / MS / 2024 /EH/WZ/ 186

Dated:

19/06/2024

## FIRE SAFETY CERTIFICATE

Certified that the M/s Imly (A Unit of Flashbolt Café Pvt. Ltd.) located at (Ground Floor), Property No. 3, Vaishali Enclave, Pitampura, Delhi-110088 in a building comprised of Basement, Ground plus Three upper floors was issued FSC by this department vide letter No F6/DFS/MS/EH/2021/WZ/51 dated 02.03.2021. The premise was re-inspected by the officer concerned of this department on 10.06.2024 in the presence of Sh. Alok Singh and observed that all the fire prevention and fire safety arrangements as provided in the premises found in good working condition. The premises have therefore deemed complied with fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premise is fit for occupancy "Assembly (Restaurant)" Group D (for Ground floor 36 unless renewed under Rule 37 or sooner cancelled under Rule 40, subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on ... 19.06.2024.. at New Delhi, by

Director

Delhi Fire Service

Copy to: -

- 1. M/s Imly (A Unit of Flashbolt Café Pvt. Ltd.) located at (Ground Floor), Property No. 3, Vaishali Enclave, Pitampura, Delhi-110088.
- MHA Portal, ID No. 202400108581.

Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate through MHA portal (https://www.delehlhlic.gov.in) along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on WWW.dfs.Delhigovt.nic.in
- 8. Basement shall be used as per building bye laws.

INSPECTION REPORT

1. Name & address of the building: M/s Imly (A Unit of Flashbolt Café Pvt. Ltd.) located at Property No. 3,

Ground Floor, Vaishali Enclave, Pitampura, New Delhi-110088.

: Assembly (Restaurant) at Ground Floor. 2. Type of Occupancy

: Basement, Ground floor plus three upper floors. Building Comprised of

Renewal

 Type of Case
 Details of Previous NOC F6/DFS/MS/EH/2021/WZ/51 Dated 02/03/2021

NBC/ UBBL 6. Fire Safety directives letter No : 7. Date of inspection 10/06/2024

8. Name of Inspecting Officer9. Name and designation of officers R.K.Sinha, ADO (BW)

From the building side Sh. Alok Singh

	10. Year of Construction : 11. Applicant's etter No. :	2015 as per MHA Port MHA Application ID 1	No. 2024060108581 dated 01	/06/2024		
S.	Minimum Standards on fire	fire As per Requirement Provided at site Re				
No.	prevention and fire safety U/R 33	letter dated 02/03/202	21	MR/NMR		
l	Access to building Road width					
	Gate width	6 m	Provided	MR		
	Width of internal road	4.5 m	Directly Accessible from Re			
2.	Width of internal road NA NA NA NA NA NA Number, Width, Type & Arrangement of Exits					
_	Number of staircases					
	Upper Floors	NA	NA	NA		
	Basements	NA	NA	NA		
	Width of staircases		TVX	IVA		
	Upper Floor	NA	NA	NA		
	Basements	NA NA	NA NA			
	Protection of exits	NA NA		NA		
	Fire check door	NA NA	- NA	NA		
	Pressurization Pressurization	NA NA	NA NA	NA		
		NA	NA	NA		
	No. of continuous staircases to terrace	NA	NA	NA		
	Width of Corridor	NA	NA	NA		
	Door Size	2 m & 1.5 m	Provided	MR		
	Compartmentation					
	Fire check door	NA	NA	N		
	Sealing of electrical shafts	NA NA		NA		
			NA	NA		
	Fire Rating of shaft door Water Curtain	NA	NA	NA		
	Fire Dampers	NA	NA	NA		
	Smoke Management System	NA	NA	NA		
-	The second constitution of the second constituti					
	Basements	NA	NA	NA		
	Ground floor	Required	Provided	MR		
5.	Fire Extinguishers					
	Total numbers	05 No.	07	MR		
	Types	ABC/Co2 Type	Provided			
	IS marking	Required	Provided	MR		
•	First-Aid Hose Reels Required Provided MR					
	Total numbers on each floor	01	Provided	100		
	Length of hose reel hose	30 m	Provided	MR		
	Nozzle diameter	5 mm	Provided	MR		
• 1	MR					
	Automatic fire detection and alarming system  Type of detectors  NA  Provided					
	Location of Main Panel		Provided	NA		
	Location of Repeater Panel	NA NA	GF	NA		
	Alternate source of power	NA	NA	NA		
	Hooters' Location	NA NA	Provided	NA		
3.	MOEFA	NA NA	Near Exit	NA		
		Required	Provided	MR		

		31	•
N	_	2	١

		N-21		<b>A</b>
•	Public Address System	NA	NA	<b>MA</b>
9. 10.	Automatic Sprinkler System	- V.		
10.	rational opening		NA	NA
	Basement	NA NA	NA NA	NA
	Upper Floor	NA NA	NA NA	NA
	Sprinkler above false ceiling	NA	IVA	
11.	Internal Hydrants			
	•	100 mm	Provided	MR
	Size of riser/down-comer	01	Provided	MR
	Number of hydrants per floor	01	Provided	MR
40	Hose Box		0.0000000000000000000000000000000000000	
12.	Yard Hydrants		P 9'	N/A
	Total number of hydrants	NA	NA NA	NA NA
	Hose Box	NA	NA	NA NA
13.	Pumping Arrangements			
	Ground Level	NA	· NA	NA
	Discharge of main Pump	NA NA	NA	NA
	Head of Main pump			NA
	Number of main pumps	NA	NA	
	Jockey Pump out put	NA	NA	NA NA
	Jockey pump head	NA	NA	NA NA
	Standby Pump out put	NA	NA	NA NA
	Standby Pump Head	NA	NA NA	NA NA
	Auto Starting/Manual Stopping	NA		NA NA
	Pump House Access	NA	NA	NA.
	Terrace level			
	Discharge of pump	450 lpm	Provided	MR
	Head of the pump	40 m	Provided	MR
	Power Supply	Required	Provided	MR
	Auto Starting of pump	Required	Provided	MR
14.	Captive Water Storage for fire fight	ing		1
	Underground tank capacity	NA	NA	NA
	Draw-off connection	NA	NA	NA
	Fire service inlet	NA NA	NA	NA NA
	Access to tank	Required	Provided	MR
	Overhead Tank capacity	20,000 ltrs	Provided	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			-
	Pressurization of Lift Shaft	NA	NA	NA
	ACTIVITY ADMINISTRATION OF CONTAINING WHICH IN THE STATE IN THE STATE OF CONTAINING AND ACTIVITY	NA NA	NA	NA
	Pressurization of Lift lobby  Communication In lift Car	NA NA	NA	NA
		NA NA	NA	NA
	Fireman's Grounding Switch	NA NA	NA	NA
	Lift Signage Standby power supply	Required	Provided	MR
17.		Required	1101.000	1
18.	Refuge Area.			
	Total Area	NA NA	NA NA	NA NA
9.	Location Fire Control Room	NA	. NA	NA
	The control of the co	NA NA	NA	NA
-	Detector System Panel Flow Switch Panel	NA NA	NA NA	NA NA
-	W. ACCOUNTAGE OF THE PROPERTY	, NA	NA NA	NA NA
	PA System Panel	<b>√</b>		204.5

	Battery backup	NA	NA	NA
20.	Building Floor Plans	NA	NA	NA
	Special Fire Protection System for Protection of special Risks, if any:	Required ABC type fire extinguisher near electrical panel	Provided	MR

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection. The management had rectified the shortcomings issued vide letter number F6/DFS/MS/EH/WZ/2024/155 dated 25/04/2024.

Keeping in view of deemed compliance of the minimum standards of fire prevention and fire safety measures as required under rules it is recommended to renew the Fire Safety Certificate issued vide letter number F6/DFS/MS/EH/2021/WZ/51 dated 02/03/2021 under rule 37 of Delhi Fire Service Rules, 2010.

Signature of Inspecting Officer Name: Rajeev Kumar Sinha Designation: ADO/B.W.

FOUFPW)

11612

Denectar M

For, For letter

th yn 8hm

12/6/24

restor May 106/2

Uploaded yours