्रिष्ठ आज़ादी का अमृत महोत्सव

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/EH/2024/SZ/ 179

Dated: 12 0 6 /2024

## FIRE SAFETY CERTIFICATE

Certified that the Eating House in the name & style of M/s Nukkad Café and Bar located at Shop no C-23 & C-24 SDA Market, Safdarjung Development Area, New Delhi-110016 comprised of Ground floor only owned/occupied by Unit of flying sparrow hospitality Pvt Ltd was issued FSC by this department vide letter no F6/DFS/MS/EH/2021/SZ/142 dated 19/07/2021. The restaurant premise was reinspected by the officers concerned of this department on 06/06/2024 in the presence of Mr. Sandeep Yadav (Manager) and found that the said restaurant premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rule, 2010 and that the building/premises is fit for occupancy Class- D " Assembly Building" (Restaurant) and validity upto 31/03/2027 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 12/06/2024 at New Delhi by

DIRECTOR

DELHI FIRE SERVICE

Copy to: -

1. The Joint Commissioner of Police (Lic/Branch), 1st Floor, MS. Defence Colony, New Delhi-110049 (Ref. MHA Portal ID 2024051507596 dated 19/05/2024)

## Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of fire-fighting

4. The owner/occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>

 This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.

 "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

| 1          | INSPECTION Name & Address of the Building                   |   | आज़ादी <del>।</del>   | नहोत्सव           |  |
|------------|---|---|-----------------------|-------------------|--|
| 1          | Issue or Address of the Diffiding                           | M/s Nukkad Café and Bar (A Unit of flying sparrow hospitality Pvt Ltd). Shop No C-23 & 24 SDA Market, Safdarjung Development Area, New Delhi- 110016. |                       |                   |  |
| 2          | Type of Occupancy   | Group-D Assembly Building.  |                       |                   |  |
| 3          | Building Comprised of                                       | Ground floor only   |                       |                   |  |
| 4          | Type of Case  | Renewal   |                       |                   |  |
| 5          | Details of Previous NOC                                     | F6/DFS/MS/EH/2021/SZ/142 dated 19/07/2021   |                       |                   |  |
| 6          | Fire Safety Directives Letter No                            | Nil   |                       |                   |  |
| 7          | Date of Inspection  | 06/06/2024  |                       |                   |  |
| 8          | Name of the Inspecting Officers                             | DO (South) & ADO (BCP)  |                       |                   |  |
| 9          | Name & Designation of Officers                              | Sh. Sandeep Yadav (Manager)   |                       |                   |  |
|            | from the building side                                      | om oundeep I aday (manager)   |                       |                   |  |
| 10         | Year of construction  | 1994  | THE PLANT R           |                   |  |
| 11         | Applicant letter No.  | MHA Portal ID 2024051507596 dated 19/05/2024  |                       |                   |  |
| S. No.     | Minimum standards on Fire Prevention and Fire Safety U/R 33 | UBBL/NBC<br>Requirement   | Provided at Site      | Remarks<br>MR/NMR |  |
| 1          | Access to Building.   |   | wide Suits of         |                   |  |
|            | Road width  | Required  | 9m                    | MR                |  |
| 74         | Gate width  | N/A   | N/A                   | N/A               |  |
|            | Width of internal road                                      | N/A   | N/A                   | N/A               |  |
| 2          | Number, width, type & arrangement of e                      | xits.   | succeeding the second |                   |  |
| 7.5        | a) Number of Staircase                                      | AGILET THE  | At Almet N            |                   |  |
|            | Upper floors.   | N/A   | N/A                   | N/A               |  |
| NIA<br>Ala | ➤ Basement floor.   | N/A   | N/A                   | N/A               |  |
|            | b) Width of Staircase                                       | resistant for   | Marin Sandard         |                   |  |
|            | ➤ Upper floors  | N/A   | N/A                   | N/A               |  |
|            | ➢ Basement floor  | N/A   | N/A                   | N/A               |  |
|            | c) Protection of exits                                      |   | See ka seed a         |                   |  |
|            | > Fire check door   | N/A   | N/A                   | N/A               |  |
| 20 14      | > Pressurization  | N/A   | N/A                   | N/A               |  |
| - 4        | d) No. of continuous staircase to terrace                   | e Required  | One                   | MR                |  |
|            | e) Width of corridor  | N/A   | N/A                   | N/A               |  |
| , ,        | f) Door size  | 02 exits  | 1.50 mtr each         | MR                |  |
| 3          | Compartmentation.   |   | and Design out to be  |                   |  |
|            | Fire check door.  | N/A   | N/A                   | N/A               |  |
|            | Sealing of electrical shafts.                               | N/A   | N/A                   | N/A               |  |
|            | Fire rating of shaft door.                                  | N/A   | N/A                   | N/A               |  |
| · 19 ·     | Water curtain   | N/A   | N/A                   | N/A               |  |
|            | Fire dampers.   | N/A   | N/A                   | N/A               |  |
| 4          | Smoke Management system.                                    |   |                       | ANA.              |  |
|            | Basement  | 30 ACPH   | N/A                   |                   |  |
|            | Upper floors  | 12 ACPH   |                       | N/A               |  |
| 5          | Fire Extinguishers.   | 12 ACIT   | N/A                   | N/A               |  |
|            | Total numbers   | 06 Nos 06 Nos M   |                       |                   |  |
|            | Types   | ABC/CO <sub>2</sub>   | 06 Nos                | MR                |  |
|            | ISI Marking   |   | ABC & CO <sub>2</sub> | MR                |  |
| 6          | First Aid Hose Reels.                                       | ISI marked  | Provided              | MR                |  |
| 0          | Total numbers on each floor.                                | 0-  |                       |                   |  |
|            | Length of hose-reel hose.                                   | One   | Provided              | MI                |  |
|            | Nozzle Diameter   | 30m   | Provided              | MI                |  |
| - 1        | - NOZZIE DIMINETET  | 5mm   | Provided              | MI                |  |
| 7          | Automatic fire detection & alarming s                       | 2000  | TIOVICE               | IVII              |  |

2 1

| _  | A Line of the last |                | अमृत              | releva |
|----|--|----------------|-------------------|--------|
|    | Location of Main Panel   | N/A            | N/A               | N/A    |
|    | Location of Repeater Panel   | N/A            | N/A               | N/A    |
|    | Alternate source of power  | N/A            | N/A               | N/A    |
| 0  | Hooter's location  | N/A            | N/A               | N/A    |
| 8  | MOEFA  | Required       | Provided          | MR     |
| 9  | Public Address System  | N/A            | NA                | N/A    |
| 10 | Automatic Sprinkler System   | Jan 1971       | t and a public of | 11     |
|    | Basement   | N/A            | N/A               | N/A    |
|    | Ground floor.  | N/A            | N/A               | N/A    |
|    | Sprinkler above false ceiling  | N/A            | N/A               | N/A    |
| 11 | Internal Hydrants.   |                | to all milker of  |        |
|    | Size of Riser/Down-comer   | 100 mm         | Provided          | MR     |
|    | Number of Hydrant per floor  | One            | Provided          | MR     |
|    | Hose box.  | One            | Provided          | MR     |
| 12 | Yard Hydrants.   | 25/4 1.1.1     |                   |        |
|    | Total number of hydrants.  | N/A            | N/A               | N/A    |
|    | Hose box.  | N/A            | N/A               | N/A    |
| 13 | Pumping arrangements.  | 1100           |                   |        |
|    | Ground Level   |                |                   |        |
|    | Discharge of main pump.  | N/A            | N/A               | N/A    |
|    | Head of main pump.   | N/A            | N/A               | N/A    |
|    | Number of main pumps.  | N/A            | N/A               | N/A    |
|    | > Jockey Pump output.  | N/A            | N/A               | N/A    |
|    | <ul> <li>▶ Jockey Pump head.</li> <li>▶ Standby Pump output</li> </ul>   | N/A            | N/A               | N/A    |
|    | <ul><li>Standby Pump output.</li><li>Standby Pump head.</li></ul>  | N/A            | N/A               | N/A    |
|    | <ul> <li>Auto Starting/Manual Stopping.</li> </ul>   | N/A            | N/A               | N/A    |
|    | > Pump house access.   | N/A            | N/A               |        |
|    | Terrace Level  | IVA            | N/A               | N/A    |
|    | Discharge of pump.   | 450 LPM        | Described 1       | \m_    |
|    | Head of pump.  | 40 m           | Provided          | MR     |
|    | ➤ Power supply.  | Required       | Provided          | MR     |
|    | Auto starting of pump.   |                | Provided          | MR     |
| 14 | Captive water storage for fire fighting.   | Required       | Provided          | MR     |
| ** |  | 37/4           |                   |        |
|    | <ul> <li>Underground tank capacity.</li> <li>Draw-off connection.</li> </ul>   | N/A            | N/A               | N/A    |
|    | Fire Service Inlet.  | N/A            | N/A               | N/A    |
|    | Access to tank.  | N/A            | N/A               | N/A    |
|    | Overhead tank capacity.  | N/A            | N/A               | N/A    |
| 1- |  | 20,000 Ltrs    | Provided          | MR     |
| 15 | Exit Signage.  | Required       | Provided          | MR     |
| 16 | Provision of Lifts.  | - minst        | And the state of  | 7      |
|    | Pressurization of lift shaft.  | N/A            | N/A               | N/A    |
|    | Pressurization of lift lobby.  | N/A            | N/A               | N/A    |
|    | Communication in lift car.   | N/A            | N/A               | N/A    |
|    | Fireman's switch.  | N/A            | N/A               | N/A    |
|    | Lift signage.  | N/A            | N/A               | N/A    |
| 7  | Standby Power Supply   | N/A            | N/A               | N/A    |
| 8  | Refuge Area  |                | - Rhat for Joseph |        |
|    | Total area   | N/A            | N/A               | N/A    |
|    | Location   | N/A            | N/A               | N/A    |
| 9  | Fire Control Room.   |                |                   |        |
|    | Detector system panel.   | N/A            |                   | Armoni |
|    | M2000000000000000000000000000000000000   | and the second | N/A               | N/A    |



|            | अमृतं महोत्सव     |      |  |
|------------|-------------------|------|--|
| N/A        | N/A               | N/A  |  |
| N/A        | N/A               | N/A  |  |
| N/A        | N/A               | 'N/A |  |
| N/A        | N/A               | N/A  |  |
| or the N/A | N/A               | N/A  |  |
|            | N/A<br>N/A<br>N/A | N/A  |  |

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/EH/2021/SZ/142 dated 19/07/2021, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

mul Signature of the Inspection Officer Name: Sh. Manoj Kumar Sharma

Design: DO (South)

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

Design: ADO (BCP)

CFO (HQ)

tetre in

)]

d

15