

## FIRE SAFETY CERTIFICATE

Certified that the M/s S. K. East End Party Hall located at Plot no. 1/A, Ground floor level, Star City Mall, Mayur Vihar Phase - 1, Delhi -110092 comprised of basement, ground plus two upper floors (S.K. East End Party Hall running at ground floor only) owned/occupied by M/s S.K. East End Party Hall was granted FSC by this department vide letter no. F6/DFS/MS/CGHS/NDZ/2021/62 dated 25/01/2021. The Premises was re-inspected by the officer concerned of this department of 08.06.2024 in the presence of Mr. Satish Kapoor (Owner) and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with the Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Group D "Assembly building" valid up to 31/03/2027 in accordance with Rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rule 2010, subject to conditions printed overleaf.

Issued 14/06/2029 at New Delhi by.

(ATUL GARG)
DIRECTOR
O/C DELHI FIRE SERVICE

Copy to:-

- 1. Sh. Satish Kapoor (Owner), M/s S.K. East End Party Hall located at Plot no. 1/A, Ground floor level, Star City Mall, Mayur Vihar Phase -1, Delhi -110092.
- 2. The Joint Commissioner of police (Lic.), Ist Floor, P.S Defence Colony, New Delhi-24 w.e.f. MHA portal ID . 2024053008466 dated 30/05/2024.

## Conditions for the validity of Fire Safety Certificate:

- 1. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry
- 2. All the means of escape shall be kept free of all the type of obstruction all the time.
- 3. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 4. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 5. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
- 6. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 7. Basement shall be used strictly as per Building By-Laws 1983.
- 8. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>.

				INS	SPECTION REPOR	T			
	- Januaria				M/s S.K. East End Party Hall located at Plot no. 1/A, Ground floor level, Star City Mall, Mayur Vihar Phase -1, Delhi -110092.				
2	Building is comprised of			comprised of	Basement, Ground plus two upper floors but banquet hall running on Ground floor only				
3	Type of occupancy			cupancy	Assembly Building (Community Hall)				
4	_	Type of case			Renewal				
5	-	Details of previous FSC			F6/DFS/MS/CGHS/NDZ/2021/62 dated 25/01/2021				
6	_	Fire safety direction letter no.							
7					F6/DFS/MS/2011/2167 dated 06/09/2011				
	Date of inspection				08/06/2024				
8	N	Name of the inspecting officers			Yashwant Singh Meena (ADO/LN)				
9	1	Name of the designation of officer From the building side			Mr. Satish Kapoor (Owner) 2006				
10	Y	Year of construction							
11	Applicant's letter no MHA Portal application No. 2024053008466 d				6 dated				
S.N	Vo.			evention and fire	NBC Part- IV/BBL	Provided at Site	Remarks MR/NM R		
•	safety requirements U/R 33 Access to building			Requirement					
1			_		0(	06	MR		
		a	5 30000	oad width	06 mtrs.	06 mtrs.	MR		
		b		ate width	N/A . N/A	06 mtrs. N/A	N/A		
2	c Width of internal road			200000000	IN/A	IVA			
	Number, Width, Type and A		lumber of staircases	Trangement of Exits					
		A	-		N/A	N/A	N/A		
			a	Upper floor Basement	N/A N/A	N/A	N/A		
		В	b	Width of staircases	IVA	IVA	IVA		
		D	a	Upper floor	N/A	N/A	N/A		
			b	Basement	N/A	N/A	N/A		
		C		otection of exits	3.33.5				
		-	a	Fire check door	Required	Provided	MR		
		1	b	Pressurization	N/A	N/A	N/A		
		D	No	o. of continuous ircases to terrace	N/A	N/A	N/A		
		Е		idth of corridor	2.0 mtrs	2.0 mtrs	MR		
		F	Do	oor size	2.0 mtrs.	2.0 mtrs	MR		
3			rtmentation						
	a Fire check door			Required	Provided	MR			
		b	Sealing of electrical shafts		Required	Sealed	MR		
		c	Fire rating of shaft door		02 hrs	02 hrs	MR		
1		d		ter curtain	N/A	N/A	N/A		
		е		e dampers	Required	Provided	MR		
4		Smoke Management System							
		a		sement	30 A/C Per hour	Provided	MR		
1		b	Up	per floor	12 A/C Per hour	Provided	MR		



N)3)
S.K. East End Part Hall located at Plot no. 1/A, Ground floor level, Star City Mall, Mayur Vihar Phase -1, Delhi -110092

5,	Fire Extinguisher							
	a	To	tal numbers	06 nos.	08 nos.	MR MR		
	b	Ty	pes	CO <sub>2</sub> & ABC	CO <sub>2</sub> & ABC			
	c	_	I marking	ISI marked	ISI marked	MR		
6		1000	aid-Hose Reels.			T		
	a Total numbers of each floor			01 nos.	01 nos.	MR		
	b		ngth of hose reel hose	30 mtrs.	30 mtrs.	MR		
	c		ozzle diameter	20 mm	20 mm	MR		
7	1000	0.45578	natic fire detection and ala	3 - 3 - 3 - 3 - 3 - 3 - 3 - 3 - 3 - 3 -				
<u>'</u>				Heat / Smoke	Provided	MR		
	a		ype of detectors	Control Room	Provided	MR		
		b Location of main panel		Security Room	Provided	MR		
	c	_	ocation of repeater panel	Battery & D.G Se		MR		
	d		Alternate source of power	Different Location		MR		
0	e		looter's location	Required	Provided	MR		
8	1855 CH	OE		Required	Provided	MR		
9			address System.	Required	11011111			
10	A	_	natic Sprinkler System.	Described	Provided in entire	MR		
	a	Ba	sement	Required	basement			
	<b>.</b>		2	Required	Provided	MR		
	b		oper floors	Required	Provided	MR		
1112-191		c Sprinkler above false ceiling		Required				
11	In		nal Hydrants	150	150 mm	MR		
	a		ze of riser	150 mm 01 no.	01 no.	MR		
	b	Number of hydrants per floor		TO REPORT OF THE PARTY OF THE P	01 no.	MR		
	С	Ho	ose Box	01 no.	Of no.	1,11		
12	Y		Hydrants.	1	T 02 = 0	MR		
	a	To	tal number of hydrants	01 no.	02 no.			
	b	Ho	se Box	01 no.	02 no.	MR		
13	Pu	ımp	ing Arrangements.	Provided for entir				
	A	Ė	Ground Level	Required	Provided	MR		
	-	a	Discharge of main Pump	2850 LPM	2850 LPM	MR		
		ь	Head of Main Pump	70 mtrs	70 mtrs /	MR		
		c	Number of main pumps	02 nos	02 nos.	MR		
		d	Jockey pump out put	180 LPM	180 LPM	MR		
		e	Jockey pump head	70 mtrs	70 mtrs	MR		
		f	Standby pump out put	2850 LPM	2850 LPM	MR		
		g	Standby pump head	70 mtrs	70 mtrs. /	MR		
		h	Auto starting /manual	Required	Provided	MR		
	stopping							
	В	Te	rrace Level	1	450 1 704	MR		
		а	Discharge of pump	450 LPM	450 LPM	MR		
		b	Head of the Pump	39 mtrs.	39 mtrs.	MR		
		С	Power supply	Required	Provided	MR		
	1	d	Auto Starting of pump	Required	Provided	IATIK		

S.K. East End Port Hall located at Plot no. 1/A, Ground floor level, Star City Mail, Mayur Vihar Phase -1, Delhi -110092

4	Captive Water Storage for Fire Fighting.							
	a Underground tank capacity 2		2,00,000 liters	2,00,000 liters	MR			
	bI	Draw-off connection	Provided	Provided	MR			
- 1	c Fire service inlet		Provided	Provided	MR			
	d	Access to tank	Provided	Provided	MR			
	e (	Overhead Tank capacity	2,50,000 liters	2,50,000 liters	MR			
15	Exi	t Signage.	Required	Provided	MR			
16	Provision of Lifts.							
_	a	Pressurization of Lift Shaft	NA	NA	NA			
- 1	ь	Pressurization of Lift lobby	NA	NA	NA			
- 1	c	Communication in lift car	NA	NA	NA			
- 1	d	Firemen's grounding switch	NA	NA	NA			
	ANTE	Lift Signage	NA	NA	NA			
17		andby power supply	Required	Provided	MR			
18	Refuge Area.							
	a	Total area	NA	NA	NA			
	b	Location	NA	NA	NA			
19	Fire Control Room							
	а	Detector system panel	Required	Provided	MR			
	b	Flow switch panel	Required	Provided	MR			
	c	PA system panel	Required	Provided	MF			
	d		Required	Provided	MI			
	e		Required	Provided	MI			
20	Special Fire Protection systems for		NA	NA and tested and	N/			

The fire protection system was randomly checked and tested and was found functional at the time of inspection. The earlier shortcomings issued vide letter no. F6/DFS/MS/BNQT/NDZ/2024/72 dated 24.05.2024 by this department have been

rectified by the management.

Keeping in view of above deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules. The NOC / FSC was issued vide letter no. F6/DFS/MS/CGHS/NDZ/2021/62 dated 25/01/2021 renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

10/6/2024

Signature of the Inspecting Officer Yashwant Singh Meena Name: -

ADO (L.N) Designation: -

DY. CFOANDZ