

No.F.6/DFS/MS/School/2024/SZ/563

Dated: 20/06/2024

## FIRE SAFETY CERTIFICATE

Certified that the Govt. Girls Sr. Sec. School, Dichaon Kalan, New Delhi-110043 comprised of Four blocks namely A-Block, B-Block, C-Block & D-Block. Each block is having ground plus one upper floor, owned/occupied by Govt. of NCT of Delhi was issued Fire Safety Certificate by this department vide letter No F.6/DFS/MS/School/SZ/2021/327 dated 16.04.2021. The school building was re- inspected by the officer concerned of this department on 13.06.2024 in the presence of Ms. Bimla Devi (HOS) and found that the Govt. Girls Sr. Sec. School have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises is fit for occupancy class "Educational Building" w.e.f. 20 06 2024 for a period of three years, subject to compliance of the conditions printed as under.

Issued on 2006/2024 at New Delhi.

Copy to:-

1. The HOS, Govt. Girls Sr. Sec. School, Dichaon Kalan, New Delhi-110043

2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi - 110054.

## Following fire safety directives must be adhered to: -

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.

2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of

occupants in case of emergency.

3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.

4. The trained staff should be available round the clock.

5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.

6. The certificate may not be treated in any case for the regularization of the unauthorized

construction, if any.

7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.

8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior

to its expiry.

## **INSPECTION REPORT**

1. Name & address of the building : 2. Building Comprised of Govt. Girls Sr. Sec. School, Dichaon Kalan, New Delhi-110043

Ground plus one upper floor only (Four Block)

3. Type of Occupancy 4. Type of Case Educational 5. Details of Previous FSC Renewal

6. Fire Safety directives letter No F.6/DFS/MS/School/SZ/2021/327 dated 16.04.2021

7. Date of inspection F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011

8. Name of Inspecting Officer 13.06.2024 A.D.O. R.K. Yadav

9. Name and designation of officers

From the building side

	Year of Construction : Ms. Bimla Applicant's letter No. : GGSSS/DI	014 K/2024/759 dated 15.05	2024			
No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirement as per FSC dt. 16.04.2021	Provided at	Remarks MR/NMR		
	Access to building	The second limited to	ware by File	Control of the		
	Road width     Gate width	Accessible 06 mtrs 4.5 mtrs	12 mtrs 4.70 mtrs	MR M/R		
	• Width of internal road	N/A	N/A	N/A		
-11	Number, Width, Type & Arrangement of E	xits	Same and the			
	a. Number of staircases		7-17 mail			
	• Upper Floors		01 no. in A, C & D bll	k MR		
	Basements	block N/A	and 02 no.'s in B Blk	N/A		
	b. Width of staircases	(juny)	of product			
	• Unper Floor	150 cms in A, C & & 150 cms/additio	blk, C-blk & and 140 &	D-blk case		
	Basements	staircase of 75 cms than 150 cms in B		blk		
	AM AM	N/A	N/A	N/A		
	c. Protection of exits	N/A	N/A	N/A		
	Fire check door     Pressurization	N/A	N/A	N/A		
			Indiana			
	d. No. of continuous staircases to	N/A 150 cms	N/A	N/A		
	e. Width of Corridor	100 cms	150 cms	MR		
	f. Door Size	100 cms	(Double door)	MR, Old case		
3.	Compartmentation	Arthdulberth so	A James States			
- 1	Fire check door	N/A	N/A	N/A		
	Sealing of electrical shafts	N/A	N/A	N/A		
1.75	Fire Rating of shaft door     Water Curtain	N/A	N/A	N/A		
1	• Fire Dampers	N/A N/A	N/A	N/A		
	Smoke Management System	N/A	N/A	N/A		
4.	Basements	N/A	N/A	N/A		
-	Upper floors	Required	Natural Ventilati	ion MR		
	Fire Extinguishers		provided			
5.	• Total numbers	100				
	Types	ABC/CO <sub>2</sub> tv	pe Provided Provided	MR		
	S marking	ISI marked	ISI marked	MR MR		
1		h		IVIX		

N/A Total numbers on each floor N/A NIA N/A N/A N/A N/A N/A N/A Automatic fire detection and alarming system N/A N/A N/A N/A N/A N/A Location of Repeater Panel N/A N/A N/A Alternate source of power N/A Provided N/A N/A N/A N/A N/A N/A N/A Sprinkler above false ceiling N/A N/A N/A N/A N/A N/A N/A N/A N/A Number of hydrants per floor N/A Discharge of main Pump N/A N/A N/A Number of main pumps N/A N/A N/A N/A N/A N/A N/A N/A Standby Pump out put N/A N/A N/A N/A Auto Starting/Manual Stopping N/A Auto Starting of pump N/A

14.	Captive Water Storage for fire fighting			
	Underground tank capacity	N/A	N/A	N/A
	> Draw-off connection	N/A	N/A	N/A
	Fire service inlet	N/A	N/A	N/A
	Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	N/A	N/A	N/A
15.	Exit Signage.	N/A	N/A	N/A
16.	Provision of Lifts.			(No Lift)
	<ul> <li>Pressurization of Lift Shaft</li> <li>Pressurization of Lift lobby</li> <li>Communication In lift Car</li> <li>Fireman's Grounding Switch</li> <li>Lift Signage</li> </ul> Standby power supply	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
17.		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A

N/A

N/A

N/A

First-Aid Hose Reels

Length of hose reel hose

Nozzle diameter

Type of detectors

Hooters' Location

**Public Address System** 

Basement

Hose Box

Hose Box **Pumping Arrangements** 

Ground Level

Internal Hydrants

Yard Hydrants

**Automatic Sprinkler System** 

Ground Floor

Size of riser/down-comer

Total number of hydrants

Head of Main pump

Jockey Pump out put

Jockey pump head

Standby Pump Head

Pump House Access

Discharge of pump

Head of the pump

Power Supply

Terrace level

MOEFA

Location of Main Panel

6.

7.

8.

9.

10.

11.

12.

13.

18.	Refuge Area.					
_	➤ Total Area	N/A	N/A	N/A		
	➤ Location	N/A	N/A	N/A		
19.	Fire Control Room					
	Detector System Panel	N/A	N/A	W-1024A-		
	Flow Switch Panel	N/A	N/A	N/A		
	PA System Panel	N/A	N/A	N/A		
			N/A	N/A		
	Battery backup	N/A		N/A		
	Building Floor Plans	N/A	N/A	14/14		
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F.6/DFS/MS/School/SZ/2021/327 dated 16.04.2021 renewal in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Signature of Inspecting Officer Name: - R.K. Yadav

Designation: - ADO (JKP)

DO (South West)

118/6/14

Dinector

M