

## GOVERNMENT OF NATIONAL CAP HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



.F6/DFS/MS/Hospital/SZ/202

Dated: 21 0 6

## FIRE SAFETY CERTIFICATE

Certified that the M/s Institute of Brain and Spine (IBS) located at 73, Ring Road, Lajpat Nagar-III, New Delhi-24, comprised of Basement + Ground + 03 upper floors, owned/occupied by Sri Neurocare Pvt. Ltd. have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and verified by a team of officers concerned of Delhi Fire Service on 13.06.2024 in the presence of Sh. Sahil Kandaria (Admin.) and found that the building/premises (Basement + Ground + 03 upper floors) is fit for occupancy of Group 'C' "Institutional Building" (Hospital) with effect from ...21\06\2014... for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire Service Rules, 2010 printed below.

Issued on. 2106 2014 at New Delhi by.

Director

Delhi Fire Service

## Copy to:-.

- 1. The Medical Superintendent Nursing Home, Directorate of General of Health Services, 3rd floor, DGD Building, S-1, School Block, Shakarpur, New Delhi-92.
- 2. The Medical Superintendent, M/s Institute of Brain and Spine (IBS), A Unit of Sri Neurocare Pvt. Ltd. located at 73, Ring Road, Lajpat Nagar-III, New Delhi-24.

## Conditions for the validity of Fire Safety Certificate:-

- 1. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry
- 2. All the means of escape shall be kept free of all the type of obstruction all the time.
- 3. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 4. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 5. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities
- 6. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized
- Basement shall be used as per NBC Part-IV/UBBL-2016.
- 8. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

1	Name	е & а	ddress of the building	M/s Institute of Bra Neurocare Pvt. Ltd. Nagar-III, New Delh	, located at 73, Ring ni-24.	A Unit of S Road, Lajp	
2	Building is comprised of			Basement + Ground + 03 upper floors			
3			ccupancy	Institutional Building	Group 'C' (Hospital)		
4		Type of case  Details of previous FSC		New Case			
5				Nil	<del></del>		
6		20.00 CO 10	direction letter no.	F6/DFS/MS/2024/BP	/35 dated 07 02 2024		
7	Date of inspection			13.06.2024			
8			e inspecting officers Manoj Kumar Sharma, DO (SD) & Rajesh Kumar Sh ADO (M. Road)		Kumar Shuk		
9	offic From	er n the	building side	Sh. Sahil Kandaria, A	dmin.		
10	Year	of c	onstruction	2014			
11	Applicant's letter no			Outdoor diary no. 2420 dated 04.06.2024			
S. No	Pre	venti	m Standards on fire on and fire safety nents U/R 33	Requirement as per guideline dated 07.02.2024	Provided at Site	Remarks MR/NMR	
1	Acc	ess t	o building				
	а	Ro	ad width	12.0 mtrs.	21.0 mtrs.	MR	
	b	Ga	te width	Directly accessible	Directly accessible	MR	
	c			NA ***	NA	NA	
2	Nur		, Width, Type and Arra	ingement of Exits			
toli it	A	N	lumber of staircases				
		a	Upper floor	02 nos.	02 nos.	MR	
		b	Basement	02 nos.	02 nos.	MR	
	В		Width of staircases			MD	
		a	Upper floor	2.0 mtrs & 1.5 mtrs	Provided	MR MR	
	-	b	Basement	2.0 mtrs & 1.5 mtrs	Provided	IVIN	
	C	-	otection of exits Fire check door	Required	Provided	MR	
		b	Pressurization	NA	NA	NA	
	D	No		02 nos.	02 nos.	MR	
	E		dth of corridor	2.4 mtrs	Provided	MR	
	F	Do	or size	-2.0 m (for more than 5 beds) -1.5 m (for less than equal to 5 beds) -1.25 m (for less than	Provided	MR	
				equal to 2 beds)			
3	Cor	1000	tmentation	D	Provided	MR	
	a		re check door	Required	Provided	MR	
	b		aling of electrical shafts	Required	Provided	MR	
	c			2 hours	NA	NA	
		d Water curtain		NA	NA NA	NA	
-	e		re dampers	NA	14/1		
4	-		Management System.	Required	Provided	MR	
	b		sement oper floor	Required	Provided	MR	

	Fir		inguisher	16	25 nos.	
	a Total numbers		numbers	15 nos.	CO <sub>2</sub> & ABC	MR
	b	Types		CO <sub>2</sub> & ABC	&WCO <sub>2</sub>	
4		-71		&WCO <sub>2</sub>	ISI marked	MR
	c	ISIn	narking	ISI marked	ISI marked	
	Til I Hago Dools					MR
6	-	Total	l numbers of each floor	01 no.	01 no.	MR
	a		gth of hose reel hose	30 mtrs.	30 mtrs.	2000
	b			5 mm	5 mm	MR
	c Nozzle diameter  Automatic fire detection and alarming		zie diametei	system.		
7	A	utoma	tic fire detection and alarming	Smoke	Smoke	MR
	a		pe of detectors	Ground	Provided	MR
	b	Lo	cation of main panel	NA	NÁ	NA
	c	Lo	cation of repeater panel	Required	Provided	MR
	d		ternate source of power	Audible in entire	Provided	MR
	e	Ho	ooters	building		1.00
8	TN/	10EF	Α -	Required	Provided	MR
9		ublic address System.		NA	NA	NA
10	Automatic Sprinkler System.					2002
	a			Required	Provided	MR
	b	35000000	per floors	Required	Provided	MR
				NA	NA	NA
	c Sprinkler above false ceiling NA Internal Hydrants					
11	-			100 mm	100 mm	MR
		a Size of riser b Number of hydrants per floor		01 nos.	01 nos.	MR
Ê	0		se Box	01 nos.	01 nos.	MR
12		0.5		1 3	M. C. Carrier	
12	_		lydrants. al number of hydrants	NA	NA	NA
	a			NA	NA	NA
-		b Hose Box		11/0		INA
13	_		ng Arrangements.  Ground Level			
	1	A a	Discharge of main Pump	1620 LPM	1620 LPM	MR
		b	Head of Main Pump	55 m	55 m	MR
		c	Number of main pumps	01 no.	01 no.	
		d	Jockey pump out put	180 LPM	AND TANK SERVICE AND THE SERVI	MR
		e	Jockey pump head	55 m	180 LPM	MR
		f	Standby pump out put	1620 LPM	55 m 1620 LPM	MR
		g	Standby pump head	55 m	55 m	MR
		h	Auto starting /manual stopping	Required	Provided Provided	MR
		i	Pump House Access	Required	Provided	MR
	I		errace Level		. TO TIUCU	MR
		a	Discharge of pump	NA	NA	<del></del>
		b	Head of the Pump	NA	NA	NA
		C	Power supply	NA	NA NA	NA
		d	Auto Starting of pump	NA		NA
	M/c I	etituta	of Brain and Spine (IBS), A Unit of Sri Ne	2/3	NA	NA

M/s Institute of Brain and Spine (IBS), A Unit of Sri Neurocare Pvt. Ltd., located at 73, Ring Road, Lajpat Nagar-III,

De

Mis Institute of Brain and Spine (IBS), A Unit of Sri Neurocare Pvt. Ltd., located at 73, Ring Road, Lajpat Nagar-III, New Delhi-24.

4	Çap	tive Water Storage for Fire Fightin	75,000 Liters	Provided	MR	
·	a l	Inderground tank capacity	Required	Provided	MR	
		Draw-off connection		Provided	MR	
		Fire service inlet	Required	Provided	MR	
	d	Access to tank	Required	Provided	MR	
	e	Overhead Tank capacity	10,000 ltrs	Provided	MR	
15		t Signage.	Required	Provided	1 1011	
16	Provision of Lifts.					
10	TE CITE Chaff		NA	NA	NA	
	a b	Pressurization of Lift lobby	NA	NA	NA	
	D	Communication in lift car	Required	Provided	MR	
	C	Firemen's grounding switch	Required	Provided	MR	
1			Required	Provided	MR	
<u> </u>	e Lift Signage		Required	DG Set	MR	
17		andby power supply				
18	Re	fuge Area.	NA	NA	NA	
	a	Total area	NA NA	NA	NA	
	b	Location	INA	1.77		
19	Fire Control Room NA NA					
	a	Detector system panel	NA	NA NA	NA NA	
	b	Flow switch panel	NA	NA	NA	
	C	PA system panel	NA	NA NA	NA	
	d	Battery backup	NA NA	NA NA	NA	
	е	Building Floor Plans	NA	NA NA	NA	
20	S	pecial Fire Protection systems for rotection of special Risks, if any:	NA	INA.		

LEGENDS - Meeting Requirement (MR), Not Meeting Requirement (NMR), Not Applicable (NA), Provided But Not Functional (PNF).

The width of the staircase as mentioned in the issued guidelines is 2 meters and 1.9 meters (alternate staircase) but requirements as per UBBL 2016 is 2 meters and 1.5 meters (alternate staircase) and the available staircases are well above these requirements.

The fire protection systems provided in the building were tested checked and found properly functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the Rules, it is recommended to grant Fire Safety Certificate under Rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer Manoj Kumar Sharma Name

Designation DO (SD) Signature of the Inspecting Officer Rajesh Kumar Shukla Name

ADO (M. Road) Designation