

# GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/2024/School/551

Dated: 19/06/2024

## FIRE SAFETY CERTIFICATE

Certified that the R.B. Ram Roop Vidya Mandir Sr. Sec. School located at Near Railway Under Bridge, Shakti Nagar, Delhi- 110007 comprised of Ground and first floors only owned/occupied by the R.B. Ram Roop Vidya Mandir was granted FSC by this department vide letter No. F6/DFS/MS/2021/WZ/450 Dated 07.07.2021. The premises was re-inspected by the officer concerned of this department on 11.06.2024 in the presence of Mr. Ajay Kumar (Incharge) and observed that all the fire prevention and fire safety arrangements as provided in the premises found in good working condition. The premises have deemed complied with requirements of circular issued by Director of Education letter no 3298-3398 dated 01.03.2011 and the building/premise is fit for occupancy Group B Educational with effect from ...1.9. \[ \alpha \frac{1}{20.2.9} \]... for a period of three years, subject to compliance of the conditions mentioned below:

Issued on .... 19 106 2024. at New Delhi

Director Pb.-011-23414000

### Copy to: -

- 1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi 110054.
- 2. The Manager, R.B. Ram Roop Vidya Mandir Sr. Sec. School at Near Railway Under Bridge, Shakti Nagar, Delhi-110007.

#### Conditions for the validity of Fire Safety Certificate:

- 1 All the means of escape/entry/exit shall be kept free from any obstruction.
- 2 All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3 All the staff members must know the correct method of operation of firefighting system.
- 4 The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="http://delhi.gov.in./wps/wcm/connect/doitfire/FIRE/Home/Forms">http://delhi.gov.in./wps/wcm/connect/doitfire/FIRE/Home/Forms</a>.
- 5 This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6 "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

#### INSPECTION REPORT

1. Name & address of the building : R.B. Ram Roop Vidya Mandir at Near Railway Under Bridge, Shakti Nagar,

Delhi-110007.

2. Type of Occupancy : Educational
3. Type of Case : Renewal

4. Coppsition of building : Ground & first floor only

Details of previous NOC : F6/DFS/MS/2021/WZ/450 Dated: 07.07.2021
 Fire Safety directives letter No : Director of Education Circular dated 01.03.2011

7. Date of inspection : 11.06.2024

8. Name of the Inspecting Officers : ADO (RN)

9. Name and designation of officers

from the building side : Mr. Ajay Kumar (Incharge)

10. Year of Construction : 1948

	Minimum Standards on fire prevention and fire safety U/R 33	Director of Educati Circular dated 01.03.2024	on Provided at site	Remarks MR/NMR		
1	Access to building.					
	Road width	06m	06m	MR		
	Gate width	Directly Accessible	Directly Accessible	MR		
	Width of internal road	NΛ	NA	NA		
2	Number, Width, Type & Arrangement of Exit	S				
	a. Number of staircases					
	Upper Floors	02	02	MR		
	Basements	NΛ	NA	NA		
	b. Width of staircases					
	• Upper Floors	1.50m	1.22m & 1.24m	MR( being old case)		
	Basements	NA	NA	NA		
	c. Protection of exits  Fire check door		1.51			
	Pressurization	NΛ	NA	NA		
	d. No. of continuous staircases to terrace	NΛ	NA·	NA		
	e. Width of Corridor	NΛ	NA .	NA		
	f. Door Size	NA	NA	NA		
		01m	01m	MR		
	Compartmentation.					
	Fire check door	NA	NA	NA		
	Sealing of electrical shafts	NA	NA	NA		
	Fire Rating of shaft door	NA	NA	NA		
	Water Curtain Fire Dampers	NA	NA	NA		
		NΛ	NA	NA		
	Smoke Management System.					
	Basements	NA	NA	NA		
	Upper floors	Required	Natural Ventilation	MR		
	Fire Extinguishers					
	Total numbers	06nos	12nos	MR		
	Types	ABC/CO2	ABC—12	MR		
	ISI marking First-Aid Hose Reels.	ISI Marked	Yes	MR		

	Total numbers on each floor	N 9 NA	NA	1	
	Length of hose reel hose	NA	NA	N	
	Nozzle diameter	NA	NΛ	5	
7	Automatic fire detection and alarming system			1	
	Type of detectors	NA NA	NA	NA	
	Location of Main Panel	NA	NA	NA	
	<ul> <li>Location of Repeater Panel</li> </ul>	NΛ	NΛ	NA	
	Alternate source of power	NΛ	NΛ	NΛ	
	<ul> <li>Hooters' Location</li> </ul>	NA	NΛ	NA	
	MOEFA	NA	NΛ	NΛ	
	Public Address System.	NA	NΛ	NA	
0	Automatic Sprinkler System.				
	Basement	NA	NΛ	NA	
	Upper Floor	NA	NΛ	NΛ	
	Sprinkler above false ceiling	NA	NA	NΛ	
	Internal Hydrants				
	Size of riser/down-comer	NA	NA	NA NA	
	<ul> <li>Number of hydrants per floor</li> </ul>	NA	NA	NA	
	Hose Box	NA	NA	NΛ	
	Yard Hydrants.				
	<ul> <li>Total number of hydrants</li> </ul>	NA		NA NA	
	Hose Box	NA	NA	NA.	
	Pumping Arrangements.				
	Ground Level		4 = 11		
	Discharge of main Pump	N/A	N/A	N/A	
	> Head of Main pump	N/A	N/A	N/A	
	Number of main pumps	N/A	N/A	N/A	
	> Jockey Pump out put			N/A	
	Jockey pump head	N/A	N/A	N/A	
	Standby Pump out put	N/A	N/A		
	Standby Pump Head	N/A	N/A	N/A N/A	
	➤ Auto Starting/ Manual stopping	N/A N/A	N/A N/A	N/A	
	> Pump House Access	IN/A	1072		
	Terrace level	N/A	N/A	N/A	
	Discharge of pump	N/A	N/A	N/A	
	➢ Head of the pump	N/A	N/A	N/A	
	Power Supply	N/A			
	Auto Starting of pump	N/A	N/A	N/A	
1	Captive Water Storage for fire fighting.				
	Underground tank capacity	NA	NA	NA	
	> Draw-off connection	NA	NA	NA	
	> Fire service inlet	NA NA	NA	NΛ	
	> Access to tank	NA NA	NA	NA	
	Overhead Tank capacity	SA17993.	3,000		
		N/A	N/A	N/A N/A	
	Exit Signage. N/A N/A Provision of Lifts.				
	• Pour i di serie				
	Pressurization of Lift lobby		N/A	N/A	
	Communication In lift Car	N/A	N/A	N/A	
	Communication in lift Car	N/A	N/A	N/A	

_	Fireman's Grounding Switch	N/A	N/A	N/A	
	Lift Signage	N/A	N/A	N/A	
17	Standby power supply	N/A	N/A	N/A	
18	Refuge Area				
	Total Area	N/A	N/A	N/A	
	> Location	N/A	N/A	N/A	
19	Fire Control Room				
	<ul> <li>Detector System Panel</li> <li>Flow Switch Panel</li> <li>PA System Panel</li> <li>Batter backup</li> <li>Building Floor Plans</li> </ul>	N/A	N/A	N/A	
		N/A	N/A	N/A	
		N/A	N/A	N/A	
		N/A	N/A	N/A	
		N/A	N/A	N/A	
20	Special Fire Protection Systems for	N/A	N/A	N/A	
20	Protection of special Risks, if any:				

The fire protection systems provided in the building were tested/ checked randomly and found in

working condition at the time of inspection. Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in director of education Circular dated 01.03.2011, it is recommended to renewal of fire safety certificate issued vide this department letter of even no. F6/DFS/MS/2021/WZ/450

Dated: 07.07.2021.

Signature of the Inspecting Name: - C.L. Meena Designation:- Asst. Div. Officer (RN)

Dy. Chief Fire Officer (WZ) - OH MIREST

approved F.T. letter is luxup for your signature for