

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/Business/2024/SZ/HTL 19

Dated: 25./.0.4./2024

FIRE SAFETY CERTIFICATE

Certified that the M/s Commercial Block at Radission Blu Plaza Delhi Airport, located at NH-8, Mahipalpur, New Delhi 110037 comprised of Basement, Ground Plus Five Upper Floor owned/occupied by Unit of A B Hotels Pvt Ltd was issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/2021/SZ/30 dated 01/10/2021. The premise was re-inspected by the officer concerned of this department on 15/06/2024 in the presence of Mr. Puneet Kumar & Mr. Ravinder (Head Fire Safety & Security) and found that the said Hotel building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Group "E" Business Occupancy and with effect from 25/06/2024 for a period of Three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued 25 | 06. /2024 at New Delhi by

(ATTL GARG)

DELHI FIRE SERVICE

Copy to: -

- 1. The Joint Commissioner of Police, (Lic) First Floor, P.S Defence Colony, New Delhi 110049.
- Mr. Ashwni Kumar Goela, The Commercial Block at Radission Blu Plaza, NH-8, New Delhi 110037.

Conditions for the validity of Fire Safety Certificate:

- All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to nonfunctional fire safety measures shall be at the responsibility of the management.
- The Building sanctioning authority may verify any deviation with regard to the construction/occupancy in the building. In case of any deviation, the fire safety certificate stands null and void.
- All the staff members must know the correct method of operation of fire fighting system.
- 4. The basement shall be used as per the provisions of UBBL-2016 /NBC Part- IV.
- 5. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry." The form is available on www.dfs.delhigovt.nic.in



RIP :	Name & Address of the Building	M/s Commercial Block at Radission Blu Plaza Delhi Airport, located at NH-8, Mahipalpur, New Delhi 110037			
2	The state of the s				
3	Type of Occupancy	Business Building			
4	Building Comprised of	Basement, Ground Plus Five Upper Floor			
5	Type of Case	Renewal			
6	Details of Previous NOC	F6/DFS/MS/2	021/SZ/30 dated 01/10/202	1	
	Fire Safety Directives Letter No	Nil	WHAT ENGLISH THE		
7	Date of Inspection	15/06/2024	I book I faith to		
8	Name of the Inspecting Officers	DO (South) &	ADO (BCP)	7 11	
9	Name & Designation of Officers from the building side	Mr. Puneet Kumar & Mr. Ravinder (Head Fire Safety & Security			
10	Year of construction	1995		21116	
11	Applicant letter No.	Outdoor diary no 2007 dated 24/05/2024			
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Old NOC Requirements	Provided at Site	Remarks MR/NMR	
1	Access to Building.		300 300 F		
	Road width	9 m	Answelling war and imple	MR	
	Gate width	6 m	Direct access from road	MR	
MV	Width of internal road	6 m	m to specifi-NA- %	-NA-	
2	Number, width, type & arrangement of ex	its. 11110	gome tectorici N		
Str.	a) Number of Staircase	equest/	nami te reomity A		
997.	> Upper floors.	Required	03 No Provided	MR (old case	
353 M	1 Lead Server 1 194 1 15581 1 1	Required	01 No Provided	MR	
5	b) Width of Staircase	build	Amely(bantz) S	1 100	
417	➤ Upper floors because A	Required	1.07 m, & 1.49 m & 1 m	(old case	
100	> Basement floor	Required	1.19 mtr	MIK	
100	c) Protection of exits		or Daywill of	1 200	
	> Fire check door	Required	Provided	MR	
Sund	> Pressurization	-NA-	Not provided in one staircase	-NA- MR	
200	d) No. of continuous staircase to terrace	Required	Provided Provided	MR	
- 4	e) Width of corridor	Required		MR	
AY.	f) Door size	Required	1 m (Final exit)	IVIK	
3	Compartmentation.		Thorne of the County	MR	
	Fire check door.	Required	Provided Provided	MR	
914	Sealing of electrical shafts.	Required	Provided	MR	
MME	Fire rating of shaft door.	Required	-NA-	-NA-	
3114	Water curtain	-NA-		MR	
	Fire dampers.	Required Provided		MIK	
4	Smoke Management system.	20 4 0017	M.V Provided	MR	
171	Basement	30 ACPH	M.V Provided M.V Provided	MR	
Part I	Upper floors	12 ACPH	IVI. V FIOVIUOU	IVIK	
5	Fire Extinguishers.	re Extinguishers.			
RAY.	Total numbers	ISI marked	ABC, CO2, M. Foam & W.CO2	MR MR	
114	Types ISI Marking		Provided	MR	
6	First Aid Hose Reels.		08 at each floor	MR	
	Total numbers on each floor. Length of hose-reel hose.	Hose-reels		MR	
			30m	200000	
110	Nozzle Diameter		5mm	MR	
-	Automatic fire detection & alarming system.				
7	Type of detectors	Required	Provided	MR	
1	 Location of Main Panel 	Required	B Level	MR	

11/2

TT.
नहोत्सव

	Location of Repeater Panel	Dominat I	B Level	-NA-
		Required Required	Provided	MR
	Alternate source of power Hooter's location			A CONTRACTOR
8	MOEFA	Required	Provided in all area	MR
9		Required	Provided	MR
10	Public Address System	Required	Provided	MR
	Automatic Sprinkler System Basement			
		Required	Provided	MR
	Upper floors	Required	Provided	MR
	Sprinkler above false ceiling	Required	Provided	MR
11	Internal Hydrants.	1 10	THE PROPERTY OF A AND A	1
	Size of Riser/Down-comer	100 mm	Provided	MR
	Number of Hydrant per floor	08 No's	Provided	MR
	Hose box.	08 No's	Provided	MR
12	Yard Hydrants.	08 NO S	Flovided	MIK
1	Total number of hydrants.	14 Page 1-14	mandrane and an arrival	S. See
	Hose box.	14 Required	Provided	MR
13	Pumping arrangements.	14 Required	Provided	MR
hist	Ground Level		Mars In Ch. A.	3
	Discharge of main pump.	2050 7 75 5	明 マガウ キ	(2)(1)
	Head of main pump.	2850 LPM	Provided	MR
	Number of main pumps.	70m	Provided	MR
25/4	Jockey Pump output.	02	Provided	MR
p No	Jockey Pump head.	1 x 180 LPM 70m	Provided	MR
	Standby Pump output.	2850 LPM	Provided	MR
	Standby Pump head.	70m	Provided	MR
	Auto Starting/Manual Stopping	Required	Provided	MR
	➤ Pump house access	Required	Provided Provided	MR
MIX	Terrace Level	required	Provided	MR
	Discharge of pump.	900 LPM	Provided	100
	➤ Head of pump.	40 m	Provided	MR
NY	➢ Power supply.	Required	Provided	MR
	Auto starting of pump.	Required	Provided	MR
14	Captive water storage for fire fighting.		Flovided	MR
816	 Underground tank capacity. 	2,25,000 ltrs	Provided	MD
	Draw-off connection.	Required	Provided	MR
	Fire Service Inlet.	Required	Provided	MR
3616	Access to tank.	Required	Provided	MR
WAX -	Overhead tank capacity.	20,000 ltrs	Provided	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.	10)	Tiovided	MR
	 Pressurization of lift shaft. 	NA	Provided	1
	 Pressurization of lift lobby. 	Required in		NA
	 Communication in lift car. 	basement lobby	Provided	MR
	 Fireman's switch. 	Required	Provided	MR
EJ.A	 Lift signage. 	Required	Provided	
	Den Acoustical and Market	Required	Provided	MR
17	Standby Power Supply	Required		MR
18	Refuge Area	- Junea	Provided	MR
	Total area	NA	- and a start pay half	ZA [] - 1
	Location		Provided	NA
-7 E 7	CONTRACTOR OF CASE	NA	1st floor	NA



19	Fire Control Room,			
	Detector system panel. Flow switch panel. PA system panel. Battery backup. Building floor plan	Required	Provided	MR
		Required	Provided	MR
		Required	Provided	ME
		Required	Provided	MI
20		Required	Provided	MI
	Special Fire Protection System for the Protection of special Risk, if any. The Fire protection systems	NA	Co2 Flooding system provided	N/

functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS MS/2021/SZ/30 dated 01/10/2021, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

my

Signature of the Inspection Officer Name: Sh. Manoj Kumar Sharma Design: DO (South)

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

Design: ADO (BCP)

CFO (HO)

Both case should be in one go.

clary.

19 61 20n

Turll

Ano(Bel)

The Hotel renewal case is received through MAA Portal and will be dealt separately. The occupancy of second blooks is mixed proviners occupancy, hence both & hie case can not be dealt in a single sec

20/6/20m

Ch lings

Directer My 2012

UM, plo