

NT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/NDZ/2024/ 416

Dated 28,06/2024

FIRE SAFETY CERTIFICATE

Certified that the Old Kalawati block at Lady Harding Medical College and associated Hospital, New Delhi comprised of Ground + 02 Upper floors, was inspected by the officers concerned of this department on 13/06/24 in the presence of Sh. Ranjeet (JE) and found that the said building has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Intuitional (Group C-1) with effect from 2.0.106.7024..... for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued .28 06 2024. at New Delhi by.

Copy to:-

1. The Chief Architect, NDMC Palika Kendra, New Delhi.

2. The Director, Lady Harding Medical College and Associated Hospital, Shaheed Bhagat Singh Marg, New Delhi.

Conditions for the validity of Fire Safety Certificate

1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. This FSC is valid for permanent structure only.

2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of

the management.

3. The trained fire fighting staff should be available round the clock.

4. The compliance with regards to electrical installation, structural stability, set back area, occupancy and any deviation in construction etc. shall be verified from authority concerned.

5. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule

of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

6. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an

7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.

8. Any flammable material for interior decoration shall be strictly prohibited.

MIL

INSPECTION REPORT

Name & address of the building : Old Kalawati block at Lady Harding Medical
 College and associated Hospital, New Delhi.

2. Type of occupancy : Hospital Building (Institutional)

(Gr. + 02 Upper floors)

Type of case:- : Fresh
 Details of previous FSC : NA
 Fire safety directives No. :NA
 Date of inspection:- : 13/06/24

7. Name of the inspecting officer : Sh. Ravinder Singh ADO/CC : Sh. Rajinder Atwal DO/CD

 Name & designation of officer From the building side

: Sh. Ranjeet (JE) : old-1970

9. Year of construction : old-1970
10. Applicant's letter No : E- mail (direcrorlhmc@gmail.com)dated

27/05/2024.

				Fresh			
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirements/ Existing arrangements	Provided at site	Remarks MR/NMR			
1.	Access to Building		1				
	1) Road width	06 mtr.	06 mtr.	MR			
	2) Gate width	N/A	N/A	N/A			
	3)Width of internal road	N/A	N/A	N/A			
2.	Number, Width Type & Arran						
2.	A Number of staircases						
	1. Upper floors	03 No.	03 no.	MR			
	2. Basements	N/A	N/A	N/A			
	B. Width of staircase						
	1. Upper floors	1.70m & 1.00 m .	1.70m & 1.00m	MR			
	2. Basements	N/A	N/A	N/A			
	C. Protection of exits						
	1. Fire check door	N/A	N/A	N/A			
	2. Pressurization	N/A	N/A	N/A			
	D. No. of continuous staircase to terrace	01 No.	Provided	MR			
	E. Width of corridor	1.50 mtr.		MR			
	F. Door size	N/A	N/A	N/A			
3.	Compartmentation						
	1) Fire check door	N/A	N/A	N/A			
	2) Sealing of electrical shafts	Required	Provided	MR			
	3) Fire rating of shaft door	N/A	N/A	N/A			
	4) Water curtain	N/A	N/A	N/A			
	5) Fire Dampers	N/A	N/A	N/A			
4.	Smoke Management System						
7.4	1) Basements	N/A	N/A	N/A			
	2) Upper floors	12 ACPH	Natural	MR			
5.	Fire Extinguishers						
	1) Total numbers	30Nos.	30 Nos.	MR			
	2) Types	ABC & CO2	ABC, CO2 & W.CO2	MR			
	3) ISI marking	Required	Provided	MR			
6.	First-Aid Hose Reel						
	1)Total number of each floor	03 No.	Provided	MR			

	~ \forall				
	2) Length of hose reel hose	30 m	Provided	M	
0.2	3) Nozzle diameter	5 mm	Provided	M	
7.	Automatic Fire Detection & Alarming System				
-	1) Type of detectors N/A Provided				
	2) Location of main panel	N/A	Provided	N/	
	3) Location of repeater panel	N/A	N/A	N/	
	4) Alternate source of power		Provided	N/	
	5) Hooter's Location	N/A	Provided	N/	
8.	MOEFA	Required	Provided	M	
9.	Public Address System	N/A	N/A	N/	
10.	Automatic Sprinkler System				
	1) Basement	N/A	N/A	N/	
	2) Upper floors	N/A	N/A	N/	
	Sprinkler above false ceiling	N/A	N/A	N/.	
11.	Internal Hydrants				
	1) Size of riser/down-comer	100 MM	Provided	MF	
	2) Number of hydrants per	03	Provided	MR	
	floor				
	3) Hose box each floor	03	Provided	MR	
12.	Yard Hydrants				
I aportis	1) Total number of hydrants	03	Provided	MR	
	2) Hose box	03	Provided	MR	
13.	Pumping Arrangement	Common pump house			
	3) Ground level		24		
	a) Discharge of main pump	2850 LPM	Provided	MR	
	b) Head of main pump	70 mtr.	Provided	MR	
	c) Number of main pump	02	Provided	MR	
	d) Jockey pump out put	180 LPM	Provided	MR	
	e) Jockey pump head	70 mtr.	Provided	MR	
	f) Stand by pump output	2850 LPM	Provided	MR	
	g) Stand by pump head	70 mtr.	Provided	MR	
	h) Auto starting/Manual stopping	Required	Provided	MR	
	4) Terrace level		57/1	37/4	
	a) Discharge of pump	N/A	N/A	N/A	
	b) Head of pump	N/A	N/A	N/A N/A	
	c) Power supply	N/A	N/A	N/A	
	d) Auto starting of pump	N/A	N/A		
14.	Captive Water Storage for Fire Fighting(combined pump house				
4.11	5) Under ground tank capacity	1,00,000 ltr.	Provided	MIK	
	a) Draw-off connection	Required	Provided	MR	
	b) Fire service inlet	Required	Provided	MR	
	c) Access to tank	Required	Provided	MR	
	d) Over head tank capacity	10,000 Ltrs.	Provided	MR	
		Required	Provided	MR	
15.	Exit Signage. Provision of Lifts.	Required	.10.100		
16.	LIOAIZION OF THES			N/A	

		/- (
	b) Pressurization of lift lobby	N/A	N/A	N/A	
	c) Communication in lift car	N/A	N/A	N/A	
	d) Fireman's switch	N/A	N/A	N/A	
	e) Lift signage	N/A	N/A	N/A	
17.	Stand by Power Supply	Required	Provided	MR	
18.	Refuge Area	N/A	N/A	N/A	
	Total area location	N/A	N/A	N/A	
19.	Fire Control Room	N/A	N/A	N/A	
	a) Detector system panel	N/A	N/A	N/A	
	b) Flow switch panel	N/A	N/A	N/A	
	c) PA system panel	N/A	N/A	N/A	
	d) Battery backup	N/A	N/A	N/A	
	e) Building floor plan	N/A	N/A	N/A MR	
20.	Special Fire Protection System for Protection of special Risk, if any: .				

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the substantial compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, if approved we may issued FSC to said premises. Accordingly, DFA is put up for kind perusal and signature please.

Signature of the Inspecting Officer

19/6/24 Name :- Rajinder Atwal Designation :- DO (CD)

Signature of the Inspecting Officer

Name :-Ravinder Singh Designation :- ADO (CC)

: As apporume please