GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE
NEW DELHI

No.F-6/DFS/MS/SZ/2024/EH / 197

Dated: 24 / 06/2024

FIRE SAFETY CERTIFICATE

Certified that the Mc Donalds Family Restaurant (A unit of M/s Connaught Plaza Restaurant Pvt. Ltd.) Located at Ground & Mezzanine floor Plot No. 01, Community Center, Naraina Industrial Area, Phase-1, New Delhi – 110028 in a building comprised of Basement, Ground & Mezzanine + 3 Upper Floors was issued FSC by this department vide letter No. F6/DFS/MS/EH/SZ/2021/26, dated 07/07/2021. The premises was re – inspected by the officer concerned of this department on 18/06/2024 in the presence of Sh. Sagar (Manager) and found that the premises have deemed complied with fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules 2010, and that the building is fit for occupancy class "Assembly" Group D (Ground & Mezzanine floor) with effect from 24/06/2024 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on ... 24106 12024 New Delhi by.

Deini Fire Service

Copy to:

- 1. The Joint Commissioner Police, Licensing, 1st Floor, PS, Defence Colony, N Delhi.
- 2. The Manager, Mc Donalds Family Restaurant (A unit of M/s Connaught Plaza Restaurant Pvt. Ltd.) Located at Basement, Ground & Mezzanine floor Plot No. 01, Community Center, Naraina Industrial Area, Phase-1, New Delhi 110028.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 6. Basement shall be used as per building bye laws.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.

えり INSPECTION REPORT

- .Name & address of the building: Mc Donalds Family Restaurant (A unit of M/s Connaught Plaza Restaurant Pvt. Ltd.) Located at Ground & Mezzanine floor Plot No. 01, Community Center, Naraina Industrial Area, Phase-1, New Delhi – 110028.
- Type of Occupancy: Class-D (Assembly)(At Ground & Mezzanine floor in a building comprised of Basement, Ground & Mezzanine + 3 UFs)

3. Type of Case : Renewal

Details of previous NOC: F6/DFS/MS/EH/SZ/2021/26, dated 07/07/2021

5. Fire Safety directives L. No.: NA

6. Date of inspection : 18/06/2024
7. Name of the Inspecting Officer ; ADO (DWK)

8. Name and designation of Officer

from the building side : Sh. Sagar (Manager)

9. Year of Construction. : Before 2005

10. Applicant's letter No.: 2024053008418, dated 30/05/2024

1	finimum standards on fire revention and fire safety U/R 33	As per N/21, N/22 & N/23	Prov	rided at site	Rema MR/N		
A	access of building						
	Road width	06 mtrs	Prov	Provided		MR	
	Gate width	4.5 m	Prov	Provided .		MR	
	Width of internal road	NA .	NA	4	NA	NA	
1	Number, width, Type & Arrangeme	ents of exits		44.75	-11		
	a. Number of staircases		AND CHAPTER			- M	
	 Upper floors Basements Width of staircases Upper floors 	02 No.		Provided		MR	
$\ $		02 No.	Pro	ovided	M		
11		Old case	1.17M	17M & 1.10 m MR(Bein		g old case)	
	Basements Protection of exits	Old case	1.17M	& 1.10 m		g old case)	
11	Fire check door		Army Intel				
	Pressurization No of continuous staircase to	Required			asement		
11		to NA	NA NA			NA	
	terrace	- 144	- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1		-		
	e. Width Of Corridor	1.5 m	P	Provided		MR	
1	f. Door Size	Old case	Old case 0.7		MR(Being	old case)	
3.	Compartmentation	he "			1 101 1		
	 Fire check door Sealing of electrical shafts Fire Rating of shaft door 				Provided in basement		
		1		NA		NA	
	Water Curtain	NA			The second	NA	
	Fire Dampers	NA			NA		
4.	Smoke managements System	NA	l	NA		NA	
-	Basements	30 0/2 7	n hour	Tri	<u> </u>	MR	
	Upper floors		30 a/c per hour 12 a/c per hour		Exhaust fans		
		12 ac pc	, Hour	Natural	Ventilation	MI	

1/26

i i	•	Total numbers	18 nos.	Provided			MR	
	•	Types	ABC, CO	O2 Pro	vided			
	: •	IS marking	ISI mark	ed Pro	vided			MR
i	First -	Aid Hose Reel				T		MR
	•	Total numbers on e		01 No		Provided		MR
	•	Length of hose ree	l hose	30 m		Provided		MR
7.		Nozzle diameter		5 mm		Provided		MR
, 		atic fire detection a						
	 Type of detectors Location of Main Panel Location of Repeater Panel Alternate source of power Hooters' Location 		Donal -	Required		Provided(smoke/heat)		MR
				In Office		Provided		MR
			ior -	NA		NA		NA
			fpower	Required		DG set (180 KVA)		MR
				Required		Near staircase		MR
8.	MOEF			Required		Provided		MR
9.		Address System		Required	17 11 12	Provided		MR
10.	Autom	atic Sprinkler Syste	m					
	•	Basements		Required		Provided	MR	
	•	Upper Floor	lee	Required	4	Provided in ent		MR
		Sprinkler above fa ceiling	ise	NA	11) 1	NA	NA	
11.	Interna	al Hydrants:			0.0			
	•	Size of riser/down- comer		100 mm		Provided MR		
	•	Number of hydran	ts per	01		Provided	MR	
		floor						
		Hose Box		01	1, 10, 1	Provided	MR	
12.	Yard I	Hydrants						
	•	Total number of h	ydrants	NA		NA	NA	- C
12	D	Hose Box		NA		NA ·	NA	
13.	Pump	ing Arrangements:	315	_				
		Ground Level		NA	NA	<u> </u>		NA
		Discharge of main	pump	15 TO		NA .		NA NA
	A	Head of main pum	ip			1		NA NA
1	A			NA	NA NA			NA NA
	A	Jockey pump out p		NA	NA NA			NA
	>	7 7		NA	N/			NA
	>	Standby Pump He	ad	NA	NA			NA
	>	➤ Auto Staring/Manual		NA	a promise and the second	NA		NA
	stopping Pump House Access Terrace level Discharge of pump Head of the pump Power supply Auto starting of pump		ess	NA	A NA		NA	
				11.				
				450 lpm & 240 lpm Provided				MR
			4	30 m		Provided		MR
			ump	Required		Provided		MR
			p	Required	Pro	ovided		MR
			7.0			Ĭž		
				3				
				- B	1	2 / 6		

N/27

14.	Captive water Storage for fire fighti	ng:					
+	 Under ground tank 	NA ·	NA	NA			
	capacity > Draw off connection	NA	NA	NA			
	Fire service inlet	NA	NA	NA			
	> Access to tank	NA	NA	NA			
	 Overhead Tank capacity 	Old case	10000 ltr	MR			
15	Exit Signage	Required	Provided	MR			
16.	Provision of Lifts	required	TTOVICEG				
	 Pressurization of Lift Shaft Pressurization of lift lobby Communication in No. Communication in	NA	NA	NA			
		NA	NA ·	NA			
11	Communication in lift Car	NA ,	NA	NA			
	Fireman's Grounding Switch	NA	NA	NA			
	➤ Lift Signage	NA	NA	NA			
17.	Standby power supply	Required	Provided	MR			
18.	Refuge Area	1,					
	> Total area > Location	NA	NA	NA			
		NA	NA	NA			
19.	Fire control room						
	 Detector system panel Flow Switch Panel PA System Panel Battery backup Building Floor Plans 	NA	NA	NA			
		NA	NA	NA			
		NA	NA .	NA			
		NA	NA	NA			
		NA	NA	NA			
20.	Special Fire Protection Systems for Protection of special Risks, if any;		01 ABC fire ext provided near el				

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of minimum standards on fire prevention and fire safety as required under the rules the FSC issued vide letter No. F6/DFS/MS/EH/SZ/2021/26, dated 07/07/2021 renewal under Rule 37 of the Delhi Fire Service Rules 2010 is recommended

Signature of the Inspecting Officer

Name UdaiVir Singh

Designation ADO/ DWK

30/6/29

20/6/2

10 (3) (1) 20m

ceter my 100

Appy com

uplanted 27/6/24