49 HI

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F6/DFS/MS/2024/WZ/EH/ 190

Dated: 19/06/2024

## FIRE SAFETY CERTIFICATE

Certified that the M/s Cue Culinary Urban Experience (A unit of Indispice Food Beverage Co, Shop No.131, FF, Manglam Paradise Mall, Manglam Place, Sector-3, Rohini, Delhi-110085, is running at 1<sup>st</sup> floor in a mall building comprised of Basement + Ground + 5 upper floors has already been issued FSC by this department vide letter No. F.6/DFS/MS/EH/2019/915 dated 30.04.2019. The premises was re-inspected by the officer concerned of this department on 06.06.2024 in the presence of Mr. Tarun Tar and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy Group D "Assembly" (Eating House) for Shop No.131, first floor only with effect from 19 66 2024 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subjected to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 19/06/2024 at New Delhi by

(Atul Garg) DIRECTOR Ph; 011-23414000

Copy to:-

MHA Portal ID. 2024052408106 dated 27.05.2024.

Ole Chy

Conditions for the validity of Fire Safety Certificate:

 All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.

 Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

 Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.

5. This certificate cannot be treated in any case for regularizations of unauthorized construction.

 The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

7. The owner / occupier shall submit a declaration every year in form "K" provided in the first

schedule of Delhi Fire Service Rules 2010. The form is available on

All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

http://www.delhi.gov.in/wps/wcm/connect/doit\_fire/FIRE/Home/Fire+Safety+Acts+and+Rules/http://www.delhi.gov.in/wps/wcm/connect/doit\_fire/FIRE/Home/Forms

1		INSPECTION REPORT						
18					vnerience (A unit	of Indispice Foo		
1. Name & ad		dress of the building	M/s Cue Culinary Urban Experience (A unit of In Beverage Co, Shop No.131, FF, Manglam P. Manglam Place, Sector-3, Rohini, Delhi-110085.			m Paradise Mal		
	Type of Oc	nunancy	Assemi	olv				
2. 7	Type of Ca	cupancy	Renewal (Restaurant running at Shop No.131, first floor)					
3.	ope of Ca	revious NOC	F.6/DFS/MS/EH/2019/915 dated 30.04.2019.					
4. I	Circ Safety	directives letter No	NBC Part-IV					
5. 1	Date of ins	nection	06.06.2	2024.				
6. Date of inspection 06.06.20 7. Name of Inspecting Officer Sh. Ajay				ay Kumar Sharma (ADO Rohini)				
8.	Name and	lesignation of officers uilding side	Mr. Tar	un Tar		Hiran A		
	Year of Co		2017-1	3				
3.00		letter No.	Online	application No.20240	52408106 dated 27	7.05.2024		
S.	Minimum	Standards on fire prev		NBC Requirement	Provided at site	Remarks MR/NMR		
No	and fire sa	fety U/R 33	nodice Me	Mall, Manglam Place, Sector-3, Rohini issued FSC vide				
1.	Access to	pullding liviangiam Pai	/202 data	d 24 06 20221				
		F.6/DFS/MS/2022/WZ	Zoz date	u 24.00.2022]				
		ad width	- heartesty	Restaurant within Mall	As Above	MR		
		e width	mymus still					
		dth of internal road						
2.	Number,	er, Width, Type & Arrangement of Exits						
	a. Numbe	er of staircases		IEM .		) MD		
-		Upper Floors		Restaurant within M		MR		
- 1		Basements		Restaurant within M	Iall As Above	MR		
	b. Width	of staircases		1777	edhrite, signifi	1 100		
	•	Upper Floor		Restaurant within Mall		MR		
		Basements		Restaurant within M	[all As Above	MR		
		ction of exits		and the same of th				
		Fire check door		Restaurant within M	Iall As Above	MR		
		Pressurization		Restaurant within M				
	d. No. of	continuous staircases to terrace		Restaurant within M				
	e. Width	of Corridor		Restaurant within M	2000HU			
	f. Door S			2.0m	2.0m x 2	MR		
3.	Compart	artmentation		517.33	" = -			
	a) Fi	ine check door		Restaurant within M	Iall As Above			
	b) Se	ealing of electrical shafts		Restaurant within N		(Alexander)		
		ire Rating of shaft door		Restaurant within N	COMPANY TO STATE OF THE PARTY.			
		Vater Curtain		Restaurant within N	As Above	MR		
	e) Fi	ire Dampers		Restaurant within N	Iall As Above	MR		
4.	-	anagement System	7 - V					
	VIOLET PROCES	Basements		Restaurant within N	Mall As Above	MR		
	9.50	Jpper floors		Restaurant within N	Mall As Above	MR		
5.		inguishers						
		I dtal numbers		05nos.	05nos.	MR		
		ypes		ABC/CO2	ABC/CO2	NOV.2384 903		
		S marking		ISI marked	Yes	MR		
6.		Hose Reels			1 100	IVIIC		
		Total numbers on each floor		01 near to restaura	ant As Above	e MR		
	100000	ength of hose reel hose	.01	30mm		2000		
	_ U) L	right of flose reel flose		Jumm	As Above	e MR		

Chy

	c) Nozzle diameter	5m	As Above	MR			
7.	Automatic fire detection and alarming system						
	a) Type of detectors	Required	Provided	MR			
8. 9. 10.	b) Location of Main Panel	-NA-	As above	-NA-			
	c) Location of Repeater Panel	-NA-	As above	-NA-			
	d) Alternate source of power	-NA-	As above	-NA-			
	e) Hooters' Location	-NA-	As above	-NA-			
8.	MOEFA	Required	Provided	MR			
9.	Public Address System	Required	Provided	MR			
10.	Automatic Sprinkler System	AND COMMON TO SERVICE AND ADDRESS OF THE PARTY OF THE PAR	ained by Mall man	agementl			
	a) Basement	-NA- As above		-NA-			
	b) Ground & Upper Floors	-NA-	As above	-NA-			
	c) Sprinkler above false ceiling	-NA-	As above	-NA-			
11.	Internal Hydrants	[Provided & Maintained by Mall n		V.Statiga.			
	a) Size of riser/down-comer	150mm As Above		MR			
	b) Number of hydrants per floor	One(near to restaurant)	THE STATE OF THE S	MR			
	c) Hose Box	One(near to restaurant)		MR			
12.	Yard Hydrants		tained by Mall man				
	a) Total number of hydrants	Restaurant within Mall	As Above	MR			
	b) Hose Box	Restaurant within Mall	As Above	MR			
13.	Pumping Arrangements	[Provided & Maint	10000000				
70200	Ground Level	Restaurant within Mall	As Above	MR			
	➤ Discharge of main Pump	Restaurant within Mall	As Above	MR			
	➤ Head of Main pump	Restaurant within Mall	As Above	MR			
	> Number of main pumps	Restaurant within Mall	As Above	MR			
	➤ Jockey Pump out put	Restaurant within Mall	As Above	MR			
	> Jockey pump head	Restaurant within Mall	As Above	MR			
	Standby Pump out put	Restaurant within Mall	As Above	MR			
	Standby Pump Head	Restaurant within Mall	As Above	MR			
	Auto Starting/Manual Stopping	Restaurant within Mall	As Above	MR			
	Pump House Access	Restaurant within Mall	As Above	MR			
	Terrace level	[Provided & Maint	agement]				
	Discharge of pump	Restaurant within Mall	As Above	MR			
	Head of the pump	Restaurant within Mall	As Above	MR			
	Power Supply	Restaurant within Mall	As Above	MR			
	Auto Starting of pump	Restaurant within Mall	As Above	MR			
14.	Captive Water Storage for fire fighting [Provided & Maintained by Mall management]						
	Underground tank capacity	Restaurant within Mall	As Above	MR			
	> Draw-off connection	Restaurant within Mall	As Above	MR			
	> Fire service inlet	Restaurant within Mall	As Above	MR			
	> Access to tank	Restaurant within Mall	As Above	MR			
	(2) Substitutional Nutrition	Restaurant within Mall	As Above	MR			
	Overhead Tank capacity	Required Required	Provided	MR			
15.	Exit Signage.	[Provided & Mainta					
16.	Provision of Lifts.	-NA-	-NA-	-NA-			
	a) Pressurization of Lift Shaft	47 GRI SIV	-NA-	-NA-			
	b) Pressurization of Lift lobby	-NA-	-NA-	-NA-			
	c) Communication In lift Car	-NA-	-NA-	-NA-			
	d) Fireman's Grounding Switch	-NA-	-NA-	-NA-			
	e) Lift Signage	-NA-	-11//-	4 W 4 2			

Standby p	wer supply	-NA-	-NA	-NA-		
Refuge Area.						
a) Tota	l Area	-NA	774			
b) Loc	ation			-NA-		
Fire Contr	ol Room	-NA-	-NA-	-NA-		
a) Det	ector System Panel	NA				
		100000000	A STATE OF THE PARTY OF THE PAR	-NA-		
				-NA-		
				-NA-		
	The second secon			-NA-		
		-NA-	-NA-	-NA-		
Protection	of special Risks, if any:	-NA-	-NA-	-NA-		
	a) Tota b) Loc Fire Contr a) Det b) Flor c) PA d) Bat e) Bui	a) Total Area b) Location Fire Control Room a) Detector System Panel b) Flow Switch Panel c) PA System Panel d) Bat ery backup	Refuge Area.  a) Total Area -NA- b) Location -NA- Fire Control Room  a) Detector System Panel -NA- b) Flow Switch Panel -NA- c) PA System Panel -NA- d) Battery backup -NA- e) Building Floor Plans -NA- Special Fire Protection System for -NA-	Refuge Area		

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of the fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F.6/DFS/MS/EH/2019/915 dated 30.04.2019 is recommended for renewal under rule 37 of the Delhi Fire Service rules 2010.

Signature of the Inspecting Officer
Name Ajay Kumar Sharma
Designation ADO(Rohini)

Dy. CFO(WZ) -on MR

11612 (1612)

Dinecter

Fi dettu'o fout up

for kind

bemsel and

Dignature please

106/21

ufloated