

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No.F6/DFS/MS/2024/GH/ 240

Dated 19/06/2024

## FIRE SAFETY CERTIFICATE

Certified that the M/s Hotel D2 located at Property No-14, Panchwati, Azadpur, Delhi110033. comprised of basement, Stilt, upper ground & 03 upper floors but (guest house proposed at first, second & third floors with 24 guest rooms only) owned/occupied by M/s Hotel D2 have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Fire Service on 10.06.2024 in the presence of Sh. Devender (Manager) and that the building/premise is fit for occupancy Class A-1 Residential (Rooming & Lodging) for first, second & third floors with 24 guest rooms only with effect from 19/06/2024 for a period of three years, in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on ...19.10.6.12024 at New Delhi by

Ph: 011-23414000

Copy to:-

1. M/s Hotel D2 located at Property No-14, Panchwati, Azadpur, Delhi-110033.

## Conditions for the validity of Fire Safety Certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection.

3. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

4. All the staff members must know the correct method of operation of firefighting system.

5. The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="http://delhi.gov.in./wps/wcm/connect/doit">http://delhi.gov.in./wps/wcm/connect/doit</a> fire/FIRE/Home/Forms.

 This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

## INSPECTION REPORT

1. Name & address of the building: M/s Hotel D2 at Property No-14, Panchwati, Azadpur, Delhi-110033.

2. Type of Occupancy : Residential (Lodging house)

3. Composition of building : Basement, Stilt, upper ground & 03upper floors, basement-other property, stilt-

Parking/ reception, upper ground- other property, guest house running at

First, second & third floor with 24 guest rooms only

4. Type of Case : New Case

5. Details of previous NOC : Nil6. Fire Safety directives letter No : Nil

6. Fire Safety directives letter No : Nil7. Data of inspection : 10.06.2024

8. Name of the Inspecting Officers : ADO (RN)

9. Name and designation of officers

from the building side : Sh. Devender (Manager)

10. Year of Construction : 2023 as per MHA Portal

11. App icant's letter No. : Online MHA Portal I'd No-2024052608165 dated: 28.05.2024

	Min	mum Standards on fire prevention and fire safety U/R 33	NBC Part- IV Requirements	Provided at site	Remarks MR/NMR			
	Acces	ess to building						
	•	Road width	06m	06m	MR			
T <sub>y</sub>	•	Gate width	4.5m	4.5m	MR			
	•	Width of internal road	NA	NA	NA			
	Number, Width, Type & Arrangement of Exits							
	a. Nun	ber of staircases	Alexander					
	•	Upper Floors	02	02	MR			
	•	Basements	NΛ	Other property	NA			
	b. Width of staircases							
	J. WILL	Upper Floors	1.50m cach	1.70m &1.50m (iron)	MR			
		Basements	NA	NA	NA			
	c. Prote	ction of exits	Required	Provided	MR			
	•	Fire check door	NΛ	NA	NA			
	•	Pressurization		- x	A004904.V			
	d. No.	of continuous staircases to terrace	02	02	MR			
	e. Widt	of Corridor	1.80m	Provided	MR			
	f. Door	Size	lm	Provided	MR			
	Compa	rtmentation.			714			
	•	Fire check door	NA	NA	NA			
		Sealing of electrical shafts	NΛ	NA	NA			
		Fire Rating of shaft door	NΛ	NA	NA			
		Water Curtain	NΛ	NA	NA			
		Fire Dampers	NΛ	NA	NA			

4	Smoke Management System.				
	Basements	NA NA	Other property .	1	
	Upper floors	Required	Natural ventilation	× D	
	Fire Extinguishers				
	Total numbers	08nos	10nos	MR	
	Types	ABC & WCo2	ABC -10	MR	
	ISI marking		Yes	MR	
	First-Aid Hose Reels.	Yes	100		
	Total numbers on each floor	01	Provided	MR	
			Provided	MR	
	Length of hose reel hose	30m			
	Nozzle diameter	5mm	Provided	MR	
y.	Automatic fire detection and alarming system.				
	Type of detectors	Smoke/Heat	Smoke/Heat	MR	
	Location of Main Panel	(carbon monoxide)	(carbon monoxide)		
	Location of Repeater Panel	Required	Provided	MR	
	Alternate source of power	NA	NA	NA	
	Hooters' Location	NA	NA	NA	
T	MOEFA	NA	NA	NΛ	
	Public Address System.	Required	Provided	MR	
0	Automatic Sprinkler System.	NA	NA	NA	
•	Basement				
	Upper Floor	Required	Provided	MR	
	20 1	NA	NA	NA	
	Sprinkler above false ceiling	NA .	NA	NA	
1	Internal Hydrants	1.54. 37.			
	Size of riser/down-comer	100mm	Provided	MR	
	<ul> <li>Number of hydrants per floor</li> <li>Hose Box</li> </ul>	01	Provided	MR	
		01	Provided	MR	
2	Yard Hydrants.				
	Total number of hydrants     Hose Personal Total number of hydrants	NA	NA	NA	
-	Hose Box	NA	NA	NA	
	Pumping Arrangements.	***			
	Ground Level				
	Discharge of main Pump	N/A	N/A	N/A	
	<ul><li>Head of Main pump</li><li>Number of main pumps</li></ul>	N/A	N/A	N/A	
	Jockey Pump out put	N/A	N/A	N/A	
	Jockey pump head	N/A	N/A	N/A	
	<ul><li>Standby Pump out put</li><li>Standby Pump Head</li></ul>	N/A	N/A	N/A	
	> Auto Starting/ Manual stopping	N/A N/A	N/A N/A	N/A N/A	
	> Pump House Access	N/A	N/A	N/A	
				202.03	
	Terrace level	450 LPM	450 LPM	MD	
	Discharge of pump	430 EFW		MR	
	Head of the pump		40m	MR	
	Power Supply	Required	Provided	MR	
	➤ Auto Starting of pump	* Required	Provided	MR	
	Captive Water Storage for firefighting.	12			

	Underground tank capacity	NA	- NA	NA		
	> Draw-off connection	NΛ	NA	NA		
	> Fire service inlet	NΛ	NA NA	NA		
	> Access to tank	NΛ	NA	NA		
	Overhead Tank capacity	10,000 LTR	Provided	MR		
15	Exit Signage.	Required	Provided	MR		
1.5			To California			
16	Provision of Lifts.  Pressurization of Lift Shaft	N/A	N/A	N/A		
	Pressurization of Lift lobby	N/A	N/A	N/A		
	Communication In lift Car	Required	Provided	MR		
	Fireman's Grounding Switch	Required	Provided	MR		
	Lift Signage	Required	Provided	MR		
	Standby power supply	Required	Provided	MR		
17	3 1 1 3					
18	Refuge Area.					
		N/A	N/A	1440-475-474		
	Total Area					
	Total Area	N/A	N/A	N/A		
10	Location	N/A	N/A			
19	Location Fire Control Room	N/A	N/A	N/A		
19	Fire Control Room  • Detector System Panel	790.	N. R.			
19	Location  Fire Control Room  Detector System Panel Flow Switch Panel	N/A	N/A	N/A N/A N/A		
19	Location  Fire Control Room      Detector System Panel     Flow Switch Panel  Page 18 System Panel	N/A N/A	N/A N/A	N/A N/A N/A		
19	Location  Fire Control Room  Detector System Panel Flow Switch Panel PA System Panel	N/A N/A N/A N/A	N/A N/A N/A	N/A N/A N/A N/A		
19	Location  Fire Control Room      Detector System Panel     Flow Switch Panel     PA System Panel     Batter backup	N/A N/A N/A	N/A N/A N/A	N/A N/A N/A		

The fire protection systems provided in the building were tested/ checked and found in working order at the

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety time of inspection. required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010

Signature of the Inspecting Officer

Name: - C.L. Meena

Designation: Asst. Div. Officer (RN)

Dy. Chief Fire Officer (WZ) - ON Leave

ADO LAN)