

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/2024/GH/ 252

Dated 24/06/2024

FIRE SAFETY CERTIFICATE

Certified that the M/s Hotel Seven Seas located at A-2 & 3, Sarai Pipal Thala Extn., G.T. Karnal Road, Adarsh Nagar, Delhi-110033 comprised of basement, ground & 02 upper floors (Ground floor reception + Two room, 1st floor- 15 rooms & 2nd floor- 14 rooms only) owned/occupied by Sh. Puran Chand was issued fire safety certificate vide letter no. F6/DFS/MS/2021/WZ/GH/188 dated 03.05.2021. The premises was inspected by the officer concerned of Fire Service on 14.06.2024 in the presence of Sh. Ramesh (Manager) and observed that all the fire prevention & fire safety arrangements as provided in the premises found in good working condition The premises have therefore, deemed complied with the requirement under rule 33 of Delhi Fire Service Rules, 2010 and the building is fit for occupancy Class -A-1 Residential (Rooming & Lodging) for 31 guest rooms only with effect from -24 106 1024 for a period of 03 (Three) years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 24 06 2024 at New Delhi by

Director Ph-011-23414000

Copy to:-

 The Manager, Hotel Seven Seas at A-2 & 3, Sarai Pipal Thala Extn., G.T. Karnal Road, Adarsh Nagar, Delhi- 110033...

Conditions for the validity of Fire Safety Certificate:

- 1 All the means of escape/entry/exit shall be kept free from any obstruction.
- 2 All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3 All the staff members must know the correct method of operation of firefighting system.
- 4 The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms.
- 5 This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6 "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

INSPECTION REPORT

1. Name & address of the building

: Hotel Seven Seas A-2&3, Sarai Pipal Thala Extn. Adarsh Nagar, Delhi.

Type of Occupancy

: Residential (Lodging house)

3. Composition of building

: Basement, Ground & 02 upper floors only

4. Type of Case

: Renewal

5. Details of previous NOC

: F6/DFS/MS/2021/WZ/GH/188 dated 03.05.2021

6. Fire Safety directives letter No

:Nil

Basement-Vacant

Date of inspection

: 14.06.2024 : ADO (RN)

Ground- Reception & Two rooms

8. Name of the Inspecting Officers

First floor- 15 rooms

9. Name and designation of officers

Second floor-14 rooms

from the building side

: Sh. Ramesh (Manager)

10. Year of Construction

11. Applicant's letter No.

: Online MHA Portal ID No. 2024053008444 dated 03.06.2024

	Minim	um Standards on fire prevention and fire safety U/R 33	NBC/ BBL Requirements	Provided at site	Remarks MR/NMR			
	Access to building							
_		Road width	06m	9m	MR			
_		Gate width	Directly Accessible	Directly Accessible	MR			
	•	Width of internal road	NA	NA .	NA			
2 -	Number, Width, Type & Arrangement of Exits							
	a. Numb	per of staircases	1-1-15-1-1					
		Upper Floors	- 02	02	MR			
ž.		Basements	Required	01	MR (being old case)			
	b. Width of staircases							
	•	Upper Floors	lm	1.26m & 1.00m	MR (being old case)			
	•	Basement	Required	01m	MR (being old case)			
	c. Prote	ction of exits						
	T.	Fire check door	Required	Provided	MR			
	•	Pressurization	NA	NA	NA			
	d. No.	of continuous staircases to terrace	01	01	MR			
	e. Widt	h of Corridor	NA	NA	NA			
	f. Door	Size	01m	1.02m	MR (being old case)			
3	Compartmentation.							
		Fire check door	NA	NA	NA			
		Sealing of electrical shafts	NA	NA	NA			
	1	Fire Rating of shaft door	NA	NA	NA			
		Water Curtain	NA	NA	NA			
	•	Fire Dampers	NA	. NA	NA			
4	Smoke Management System.							
	4 .	Basements	NA	NA	NA			
		Upper floors	Required	Provided	MR			
L_		Q _q						

	Fire Extinguishers	,	, 100			
+	Total	13nos	15	MR		
	Total numbersTypes	ABC & Co2	W. Co2 - (9ltr Cap) ABC type—one at each	MR		
	ISI marking	Yes	floor	MR		
	First-Aid Hose Reels.					
	Television of the control of the con	01	01	MR		
	Total numbers on each floor	mir saa	30m	MR		
	Length of hose reel hose	30m	5mm	MR		
	Nozzle diameter	5mm	Smin			
7	Automatic fire detection and alarming system.					
	Type of detectors	Smoke/Heat (carbon monoxide)	Smoke/Heat (carbon monoxide)	MR		
	Location of Main Panel	Required	Provided	MR		
	Location of Repeater Panel	NA	NA	NA		
	Alternate source of power	NA	NA T	NA		
	Hooters' Location	NA	NA	NA		
		Required	Provided	MR		
8	MOEFA	NA	NA	NA		
9	Public Address System. Automatic Sprinkler System.					
10	Automatic Sprinkler System.	NA NA	NA NA	NA		
	Basement	NA NA	NA	NA		
	Upper Floor		NA	NA		
	Sprinkler above false ceiling	NA	INA			
11	Internal Hydrants	THE PARTY	Edical Local Lie	374		
	Size of riser/down-comer	NA	NA	NA NA		
	Number of hydrants per floor	NA	NA	NA NA		
	Hose Box	NA NA	NA	NA		
12	Yard Hydrants.					
	Total number of hydrants	NA	NA	NA		
	Hose Box	NA	NA	NA		
13	Pumping Arrangements.					
13						
	Ground Level	N/A	N/A	N/A		
	Discharge of main Pump		N/A	N/A		
	➤ Head of Main pump	N/A N/A	N/A N/A	N/A		
	Number of main pumps	N/A	N/A	N/A		
	> Jockey Pump out put	N/A N/A	N/A	N/A		
	 Jockey pump head Standby Pump out put 			N/A		
	➤ Standby Pump out put ➤ Standby Pump Head	N/A	N/A			
	> Auto Starting/ Manual stopping	N/A	N/A	N/A		
	> Pump House Access	N/A	N/A	N/A		
	Terrace level		H 4 . 49			
	➤ Discharge of pump	450 LPM	450 LPM	MR		
	➤ Head of the pump	40m	40m	MR		
	> Power Supply	Required	Provided	MR		
	> Auto Starting of pump	Required	Provided	MR		
		(y				

1	Captive Water Storage for fire fig	hting.		
14	d tonk canacity	NIA NIA	NA	NA
	Underground tank capacity Draw-off connection	NA NA	NA	NA
	> Fire service inlet	7 NA	NA	NA
	> Access to tank	NA	NA	NA
	Overhead Tank capacity	10,000 LTR	10,000 LTR	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.	N/A	N/A	N/A
	 Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage 	N/A	N/A	N/A
			Provided	MR
		itch Required	Provided	MR
		Required	Provided	MR.
17	Standby power supply	Required	Provided	MR
18	Refuge Area.		N/A	N/A
	> Total Area	N/A	N/A N/A	N/A
	> Location	N/A	N/A	8301.5
19	Fire Control Room.	N/A	N/A	
	Detector System Panel		N/A	N/A
	Flow Switch Panel	N/A	In V. (1947), 244	N/A
	PA System Panel	N/A	N/A	
	Batter backup	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
20	Special Fire Protection Systems for Protection of special Risks, if any	or NA	NA	NA

The fire protection systems provided in the building were tested/ checked and found in working order at the time of inspection.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to renew Fire Safety Certificate issued vide this department letter of even no. F6/DFS/MS/2021/WZ/GH/188 dated 03.05.2021 under rule 37 of the Delhi Fire Service Rules 2010.

Dy. Chief Fire Officer (WZ)

Signature of the Inspecting Officer Name: - C.L. Meena Designation: Asst. Div. Officer (RN)

MR