Dated: 20/06/2024

(a Garg)



## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI

No. F6/DFS/MS/2024/9H 244

## FIRE SAFETY CERTIFICATE

Certified that the building of M/s Hotel Star Palace Located at 1<sup>st</sup>, 2<sup>nd</sup> & 3<sup>rd</sup> floor 15A/17, WEA Karol Bagh, New Delhi-110005, comprised of, Basement, ground + 03 upper floors using Basement (storage) ground floor (reception & shops), first & second floor (10 guest rooms each floor) third floor (09 rooms) (Total=29 guest rooms) & 02 staff room on terrace (now sealed/closed) was issued FSC vide letter No F6/DFS/MS/GH/SZ/2021/196, dated 02/07/21. The premises was re inspected by the officer concerned of this department on 18/06/2024 in the presence of Sh. Ashwani Singh (Manager) and observed that all the fire prevention and fire safety arrangements provided in the premises found in good working condition. The premises have therefore deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Residential" (guest house) at first & second floor (10 guest rooms each floor) third floor (09 rooms) (Total=29 guest rooms) with effect from 20/06/2024 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 20, 06, 2024... at New Delhi by.

Copy to:

 The Joint. Commissioner of Police (Lic), 1<sup>st</sup> Floor, Licensing Unit, Police Station, Defence Colony, New Delhi.

 The Manager, M/s Hotel Star Palace Located at 1<sup>st</sup>, 2<sup>nd</sup> & 3<sup>rd</sup> floor 15A/17, WEA Karol Bagh, New Delhi-110005.

## Following fire safety directives must be adhered to:-

1. 4th floor shall not be used for any purpose as undertaking given by owner.

- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.

4. The trained staff should be available round the clock.

- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

7. Basement strictly shall be kept vacant as seen during inspection.

- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.
- 9. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>

## **INSPECTION REPORT**

1. Name & address of the building: M/s Hotel Star Palace Located at 1<sup>st</sup>, 2<sup>nd</sup> & 3<sup>rd</sup> floor 15A/17, WEA Karol Bagh, New Delhi-110005.

2. Type of Occupancy

:Lodging or rooming "A-1"

3. Type of Case: Renewal (Running at 1<sup>st</sup>, 2<sup>nd</sup> & 3<sup>rd</sup> floor in a building comprised of Basement, Ground + 3 Upper Floor & 02 staff room at terrace now sealed/closed)

4. Details of previous NOC: F6/DFS/MS/GH/SZ/2021/196, dated 02/07/21

5. Fire Safety directives Letter No.: Nil

6. Date of inspection

: 18/06/2024

7. Name of the Inspecting Officer: ADO (DWK)

8. Name and designation of Officer

from the building side

: Sh. Ashwani Singh (Manager)

9. Year of Construction

: 1990-91

10. Applicant's letter No.

: 2024052708209, dated 28/05/2024

	Minimum standards on fire prevention and fire safety U/R 3	33	As per N N/31 &				ed at	Remar MR/N		
1.	Access of building			191	1 1		W		1 m	
	<ul> <li>Road width</li> </ul>	6	mtr		Prov	rided			MR	
	Gate width	4.	5m	Prov	ided				MR	
			A	NA					NA	
2.	Number, width, Type & Arran	gen	nents of e	xits	ME TH		V			
	a. Number of staircases		14 70							
	Upper floors	0	1		01			Being ol		
	Basements	0	1	1111	Provi	ded	MR (	Being ol	d case)	
	b. Width of staircases				L K		4			
	Upper floors		Old case	1.0	5m			(Being		
	Basements	(	Old case	1.37m MR (Being					old case	
	c. Protection of exits		3 1"						ليسال	
	Fire check door	1	Required Provided				MR			
	Pressurization		NA			N	IA		NA	
	d. No of continuous staircase to terrace		01		W	0	1		MR	
1	e. Width Of Corridor	H	1.5m	1.115	1.5m		MR			
1	f. Door Size	1	Old case		0.79		MR	(Being o	ld case)	
3.	. Compartmentation		-14	U I			10	4	MR	
	Fire check door		Required	.   P	rovide		TA		NA	
	Sealing of electrical shafts		NA				NA			
	<ul> <li>Fire Rating of shaft</li> </ul>		NA		45/4	I C	NA		NA	
1	door	Н	NA				NA		NA	
	<ul><li>Water Curtain</li><li>Fire Dampers</li></ul>	ì	NA		174	_	NA		NA	

			100	109	1/38					
-40					0128	T			14	
5	Smoke r	managements System	20 -/-	per ho	ır Pro	vide	d		MR	
		Basements	12 a/c	per ho	ur Pr	ovide	d	1.07.1.	MR	
	• 1	Upper floors	12 a/C	per no	ui	ALCOHARD.				
]		tinguishers	15 No	0		Pro	vided		MR	
		Total numbers		ABC & CO <sub>2</sub>		CO <sub>2</sub> & ABC			MR	
		Types	Requi			Pro	vided		MR	
		IS marking								
	First -	Aid Hose Reels	1	01		Provided			MR	
	•	Total numbers on each		01					MR	
	<ul> <li>floor</li> <li>Length of hose reel hose</li> <li>Nozzle diameter</li> </ul> Automatic fire detection and also		se -	e 30 mtr		Provided Provided			MR MR	
			J IVIIVI						IVIK	
			larming	arming system					MR	
	Autom	Type of detectors	CO	CO detectors Provided			ovided		A2 (A2) DE	
	•	Location of Main	Requ	ired	red Provi		ided		MR	
		Panel	10040				de also de la		NA	
		Location of Repeater	NA		NA				INA	
	3 <del>30</del> 7.	Panel			بياري	e la la minera de 124			MR	
	•	Alternate source of	Requ	Required DG set 62.5 KVA		SKVA		4144		
		power	1		NA			NA		
	•	Hooters' Location	NA					MR		
	MOEI	FA		nired Provide					MR	
:	Public	Address System	System Required Provided			7	1,123			
0.	Auton	Automatic Sprinkler System			-		Provided		MR	
	•	Basements		Required NA NA		NA		5.	NA	
	•	Upper Floor				- 1	NA		NA	
		Sprinkler above false	INA							
	B c==	ceiling								
1.		Internal Hydrants:  • Size of riser/down-com			mer NA		NA		NA	
	•	Number of hydrants	per floo	iller		. NA			NA	
	•	Hose Box	per mee				NA		NA	
	•		-	19.	A	- 11	1112			
2.	Yard	Yard Hydrants			nts NA		NA		NA	
	•	Total number of hyd	rants	N	111111111111111111111111111111111111111		NA		NA	
	•	Hose Box		11		- 1	TAMPOS!			
3.	Pump	oing Arrangements:								
	•	Oloure -	umn	NA			NA		NA NA	
	•	Discharge of main pu	ump	NA			NA	Α		
		Head of main pump	nne	NA	N I		NA		NA	
	4000	Number of main pur Jockey pump out pur	t PS	NA NA		NA			NA	
		Jockey pump out pur Jockey pump head					NA NA		NA	
		Standby Pump out p	ut			30/1			NA	
		Standby Pump Head		NA		NA		NA		
		<ul> <li>Auto Staring/Manua</li> </ul>	d	NA NA		NA NA			NA	
	>	stopping Pump House Access	3						NA	
	•	Terrace level				Provided M		D		
	3	Discharge of pump					110,100		MR	
	>			40 mtrs Required				MR		
	-	Power supply	nn				The State of the S			
	>	Auto starting of pur	пþ	Required			Provided			



	Under ground tank capacity	NA		NA	NA				
		NA		NA	NA NA NA				
- 1	Fire service inlet	NA		NA NA					
- 1	Access to tank	NA		NA					
	Overhead Tank capacity	Old	case	5000 ltr	MR				
	Exit Signage	Requ	uired	Provided	MR				
10.	Provision of Lifts								
	> Pressurization of Lift Sh		NA	NA	NA				
1	> Pressurization of lift lob	by	NA	NA	NA				
- 1	Communication in lift C	ar	Required	Provided	MR				
	<ul><li>Fireman's Grounding Switch</li></ul>	Required		Provided	MR				
	▶ Lift Signage		Required	Provided	MR				
17.	Standby power supply		Required	Provided	MR				
18.	Refuge Area	3							
	➤ Total area		NA	NA	NA				
10	> Location		NA	NA	NA				
19.									
	Detector system panel	NA		NA	NA				
	Flow Switch Panel	NA NA		NA ·	NA				
	> PA System Panel > Battery backup > Building Floor Plans			NA	NA				
			8	NA	NA				
20				NA	NA				
20.	Protection of special Risks, if	is for	NA	.NA	NA				

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of minimum standards on fire prevention and fire safety as required under the rules the FSC issued vide letter No. F6/DFS/MS/GH/SZ/2021/196, dated 02/07/21 renewal under Rule 37 of the Delhi Fire Service Rules 2010 is recommended. If approved, the FSC may be issued

Signature of the Inspecting Officer

Name: Sh. Udaivir Singh Designation: ADO (DWK)

18/2/19

19 61 20M

n ADJA

4) loaded