



No. F6/DFS/MS/School/NDZ/2024/ 596

Dated: 28/06/2024

FIRE SAFETY CERTIFICATE

Certified that the St. Eknath Govt. Sarvodaya Kanya Vidyalaya located at, J & K Block, Dilshad Garden, Delhi-110095, comprised of ground plus three upper floors (New Building, one block) owned/occupied by St. Eknath Govt. Sarvodaya Kanya Vidyalaya was issued FSC vide letter No. F6/DFS/MS/School/2021/NDZ/998 dated 09/12/2021 (New Building, one block). The School building was re-inspected by the officer concerned of this department on 25/06/2024 in presence of Mrs. Parvati Nautiyal (Principal) of the school and found that school building have deemed complied with the fire prevention and fire safety requirements accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and observed that the school building is fit for occupancy class "Educational Building" (Group - B) for ground plus three upper floor with effect from 28/06/2024 for a period of three years in accordance with rule 36 unless renewal under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010 subject to conditions printed overleaf.

Issued on 28/06/2024 at New Delhi by.

(ATUL GARG)
DIRECTOR

o/c DELHI FIRE SERVICE

Copy to: -

1. The Dy. Director of Education, B - Block, Yamuna Vihar, Delhi - 110053.
2. The Principal, St. Eknath Govt. Sarvodaya Kanya Vidyalaya located at, J & K Block, Dilshad Garden, Delhi-110095.

Conditions for the validity of Fire Safety Certificate

1. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry
2. All the means of escape shall be kept free of all the type of obstruction all the time.
3. All the employees shall be acquainted with the use and maintenance of all fire equipment's and method of smooth and speedy safe evacuation of occupants in case of emergency.
4. All the firefighting equipment's shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
5. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc. may be got verified from the authorities concerned.
6. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

N/30

INSPECTION REPORT

1	Name & address of the building	St. Eknath Govt. Sarvodaya Kanya Vidyalaya located at, J & K Block, Dilshad Garden, Delhi-110095.		
2	Building is comprised of	Ground plus three upper floors (New Building, one block)		
3	Type of occupancy	Educational Building		
4	Type of case	Renewal		
5	Details of previous FSC	F6/DFS/MS/School/2021/NDZ/998 dated 09/12/2021		
6	Fire safety directives letter no.	NBC Part-IV		
7	Date of inspection	25/06/2024		
8	Name of the inspecting officers	Yashwant Singh Meena ADO (L.N)		
9	Name of the designation of officer from the building side	Mrs. Parvati Nautiyal (Principal)		
10	Year of construction	2017		
11	Applicant's letter no.	Email dated 27/05/2024		
S.No	Minimum standard of fire prevention and fire safety U/R 33	NBC Part-IV Requirement	Provided at site	Remarks MR/NMR
1	Access to Building:			
	A	Road width	6.0 mtrs. / 6.0 mtrs	MR
	B	Gate width	4.50 mtrs / 4.50 mtrs	MR
	C	Width of internal road	N/A / N/A	N/A
2	Number, Width, Type and Arrangement of Exits:			
	A	Number of staircases		
	a	Upper floor	02 no / 03 nos.	MR
	b	Basement	N/A / N/A	N/A
	B	Width of staircases		
	a	Upper floor	1.5 mtrs. / 1.66 mtrs, 1.72 mtrs & 1.85 mtrs	MR
	b	Basement	N/A / N/A	N/A
	C	Protection of exits		
	a	Fire check door	N/A / N/A	N/A
	b	Pressurization	N/A / N/A	N/A
	D	No. of continuous staircases to terrace	01 no. / 03 nos.	MR
	E	Width of corridor	1.50 mtrs. / 1.71 mtrs.	MR
	F	Door size	1.0 mtr. / 1.12 mtr.	MR
3	Compartmentation:			
	A	Fire check door	NA / NA	NA
	B	Sealing of electrical shafts	N/A / N/A	N/A
	C	Fire rating of shaft door	N/A / N/A	N/A
	D	Water curtain	N/A / N/A	N/A
	E	Fire dampers	N/A / N/A	N/A
4	Smoke Management System:			
	A	Basement	N/A / N/A	N/A
	B	Upper floor	N/A / N/A	N/A

W

5. Fire Extinguisher:					
	A	Total numbers	10 nos.	10 nos. ✓	MR
	B	Types	CO ₂ & ABC	CO ₂ & ABC	MR
	C	ISI marking	ISI Marked	ISI Marked	MR
6 First-Aid-Hose Reel:					
	A	Total numbers of each floor	02 nos.	02 nos. ✓	MR
	B	Length of hose reel hose	30 mtrs.	30 mtrs.	MR
	C	Nozzle diameter	05 mm	05 mm	MR
7 Automatic Fire Detection and Alarming System:					
	A	Type of detectors	N/A	N/A	N/A
	B	Location of main panel	N/A	N/A	N/A
	C	Location of repeater panel	N/A	N/A	N/A
	D	Alternate source of power	N/A	N/A	N/A
	E	Hooters	N/A	N/A	N/A
8 MOEFA:					
9 Public Address System:					
10 Automatic Sprinkler System:					
	A	Basement	N/A	N/A	N/A
	B	Upper floor	N/A	N/A	N/A
	C	Sprinkler above false ceiling	N/A	N/A	N/A
11 Internal Hydrants:					
	A	Size of riser/down-comer	N/A	N/A	N/A
	B	Number of hydrants per floor	N/A	N/A	N/A
	C	Hose box	N/A	N/A	N/A
12 Yard Hydrants:					
	A	Total number of hydrants	N/A	N/A	N/A
	B	Hose box	N/A	N/A	N/A
13 Pumping Arrangements:					
1 Ground level					
	A	Discharge of main pump	N/A	N/A	N/A
	B	Head of main pump	N/A	N/A	N/A
	C	Number of main pumps	N/A	N/A	N/A
	D	Jockey pump out put	N/A	N/A	N/A
	E	Jockey pump head	N/A	N/A	N/A
	F	Standby pump out put	N/A	N/A	N/A
	G	Standby pump head	N/A	N/A	N/A
	H	Auto starting /manual stopping	N/A	N/A	N/A
	I	Pump house access	N/A	N/A	N/A
2 Terrace Level					
	A	Discharge of pump	450 LPM	450 LPM ✓	MR
	B	Head of the pump	40 mtrs.	40 mtrs. ✓	MR
	C	Power supply	Required	Provided	MR
	D	Auto starting of pump	Required	Provided	MR


(w)

N

14 Captive Water Storage for Fire Fighting:				
A	Underground tank capacity	N/A	N/A	N/A
B	Draw-off connection	N/A	N/A	N/A
C	Fire service inlet	N/A	N/A	N/A
D	Access to tank	N/A	N/A	N/A
E	Overhead tank capacity	10,000 liters.	10,000 liters	MR
15 Exit Signage:		Required	Provided	MR
16 Provision of Lifts:				
A	Pressurization of lift shaft	N/A	N/A	N/A
B	Pressurization of lift lobby	N/A	N/A	N/A
C	Communication in lift car	N/A	N/A	N/A
D	Firemen's grounding switch	N/A	N/A	N/A
E	Lift signage	N/A	N/A	N/A
17 Standby Power Supply:		N/A	N/A	N/A
18 Refuge Area:				
A	Total area	N/A	N/A	N/A
B	Location	N/A	N/A	N/A
19 Fire Control Room:				
A	Detector system panel	N/A	N/A	N/A
B	Flow switch panel	N/A	N/A	N/A
C	PA system panel	N/A	N/A	N/A
D	Battery backup	N/A	N/A	N/A
E	Building floor plans	N/A	N/A	N/A
20 Special Fire Protection systems for protection of special Risks, if any:		N/A	N/A	N/A

The fire protection system was randomly checked and tested and was found functional at the time of inspection. The earlier shortcomings issued vide letter no. F6/DFS/MS/School/NDZ/2024/149 dated 28/03/2024 by this department has been rectified by the management.

Keeping in view of above deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules. The NOC / FSC was issued vide letter no. F6/DFS/MS/School/2021/NDZ/998 dated 09/12/2021 renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.
No file is pending with me before disposal of this case.


 26/6/2024
 Signature of the Inspecting Officer
 Name - Yashwant Singh Meena
 Designation ADO (L.N)

DY. CFO/NDZ

Rivp
27/06/24

C.F.O. — On leave

Director
27/06/24

Any/LN

Sir, F.T. letter is put up for sign. Please

Director
27/6/24


 28/6/2024