7 अंग्राजादी ब अमृत महोत्सव ८ ३२

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/EH/WZ/2024/207

Dated: 281 06 /2024

Director

FIRE SAFETY CERTIFICATE

Certified that the The Yellow Chilli (A unit of NKCR Ventures Pvt. Ltd.) located at Property No. Z 10, Right Side, First Floor, Rajouri Garden, New Delhi-110027, running at Right Side, First Floor in a building comprised of Basement + Stilt + Upper Ground + 03 Upper Floor, Owned/Occupied by The Yellow Chilli (A unit of NKCR Ventures Pvt. Ltd.) was inspected by the officer concerned of this department on 27/06/2024 in the presence of Sh. Sunil Kumar (Manager) and found that the owner have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Assembly" Group - D (Restaurant Only) and valid upto 31/03/2027 in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010, conditions mentioned below.

Issued on 28/06/2029 at New Delhi by.

Copy to: -

1. The owner/occupier, The Yellow Chilli (A unit of NKCR Ventures Pvt. Ltd.) 1st Floor Property No. Z 10, Right Side, First Floor, Rajouri Garden, New Delhi-110027.

2. The Joint Commissioner of Police, Licensing Unit, 1st floor, Police Station, Defence Colony, New Delhi. (addlcp.lic-dl@nic.in.)

3. The Dy. Health Officer, MCD, West Zone, Vishal Enclave, Rajouri Garden, New Delhi 110027. (dhowest zone@gmail.com)

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.

3. The trained staff should be available round the clock.

- 4. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

6. Basement shall be used as per Building Bye Laws.

- 7. The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 9. The FSC is valid for The Yellow Chilli Restaurant, Right Side First Floor only.

2110

_							
			NSPECTIC	ON REPORT			
	1. N	Name & address of the building	located at		nit of NKCR Ventures P Z 10, Right Side, First F 1027.		
	2. 7	ype of Occupancy	Assembly	/ Restaurant (Eating House)	BY T	
3. 7		ype of Case	New				
	4. I	etails of previous NOC	Nil		encer's transfer		
		re Safety directives letter No	Nil				
		ate of inspection	27/06/202	24	The second of		
7. N 8. N		ame of the Inspecting Officers	Sarabjeet Singh ADO (MN)				
	9. Ye	ar of Construction	2023 (As	per MHA Por	tal)		
	10. A	pplicant's letter No.	Online Ar	oplication ID	No. 2024052808258		
The	e Said	Restaurant is running at firs	st floor (Ri			of Basement	
S.		Minimum Standards on fire		BL /NBC-IV	Provided at site	Remarks	
No.		revention and fire safety U/R 3	Re	quirement		MR/NMR	
1	A	ccess to building		10	Provided	1/D	
		Road width		12 m	On Main Road	MR MR	
		Gate width Width of internal road		4.5 m NA	NA NA	NA NA	
_	NT.		- Anz		NA .	INA	
2		mber, Width, Type & Arrang Number of staircases	gement of E	LXITS	ATT WATER TO STAN	61. 19	
	a.	Upper Floors		2	Provided	MR	
		Basements		N/A	N/A	MR	
L/A	ь.	Width of staircases	0. 7				
STP.		Upper Floors	2	2 x 1.5 m	Provided	MR	
		Basements	Mr.	NA	NA	NA	
	c. I	rotection of exits		T bu	Standard .		
	1	Fire check door	F	Required	Provided	MR	
		 Pressurization 		N/A	N/A	N/A	
	200	No. of continuous staircases to ter	rrace	01	Provided	MR	
		Vidth of Corridor		N/A	N/A	N/A	
		Door Size	2	X 1.5 m	Provided 2 X 1.5 m	MR	
3	Co	mpartmentation.		100	The Control of the		
		Fire check door		NA NA	NA	NA	
		 Sealing of electrical shafts 		NA	NA	NA	
		 Fire Rating of shaft door 	History	NA	NA	NA	
		Water Curtain		NA	NA	NA	
		Fire Dampers		NA	NA	NA	
4	Sm	oke Management System.		NIA I	377	***	
		Basements		NA Paguinad	NA Provided	NA NA	
	-	Upper floors	r	Required	Provided	MR	
5 .	Fire	Extinguishers					
		Total numbers	1 - h	05 Nos.	Provided	MR	
		Types	CO	, ABC type	Provided	MR	
	1	IS marking	IS	I marked	Provided	MR	
	First	-Aid Hose Reels.			Sala a morello e d'alle		
				MY.			

2	13
-	1

	ν,	13	of and	1		
	Total numbers on each floor	01	Provided	MR		
	Length of hose reel hose	30 m	Provided	MR		
	Nozzle diameter	5mm	Provided	MR		
7	Automatic fire detection and alarming system.					
	Type of detectors	NA	NA	NA		
	Location of Main Panel	NA	NA	NA		
	Location of Repeater Panel	NA	NA	NA		
	Alternate source of power	NA	NA	NA		
	Hooters' Location	NA	NA	NA		
8	MOEFA	Required	Provided	MR		
9	Public Address System.	NA	NA	NA		
10	Automatic Sprinkler System.					
	Basement	NA	NA	NA		
	Upper Floor	NA	NA	NA		
	Sprinkler above false ceiling	NA	NA	NA		
11	Internal Hydrants		14 18 A 14	71 × 41		
48	Size of riser/down-comer	100 mm	Provided	MR		
	Number of hydrants per floor	1	Provided	MR		
	Hose Box	1	Provided	MR		
12	Yard Hydrants.		1,7 1111			
	Total number of hydrants	NA	NA	NA		
	Hose Box	NA NA	NA	NA		
13	Pumping Arrangements.	THE RESIDENCE OF THE PARTY OF T	HER BEY JUL			
-	Ground Level					
	➤ Discharge of main Pump	NR	NR	NR		
	> Head of Main pump	NR NR	NR	NR		
	> Number of main pumps	NR	NR	NR		
	➤ Jockey Pump out put	NR	NR	NR		
	> Jockey pump head	NR	NR	NR		
	> Standby Pump out put	NR	NR	NR		
	> Standby Pump Head	NR	NR	NR		
	> Auto Starting/ Manual stopping	NR	NR	NR		
	➤ Pump House Access	NR	NR	NR		
	Terrace level	ł	and the second			
	Discharge of pump	450 lpm	Provided	MR		
	➤ Head of the pump	40 m	Provided	MR		
	> Power Supply	Required	Provided	MR		
	> Auto Starting of pump	Required	Provided	MR		
14	Captive Water Storage for fire fighting.					
	Underground tank capacity	NR	NR	NR		
	> Draw-off connection	NR	NR	NR		
	> Fire service inlet	NR	NR	NR		
	> Access to tank	NR	NR	NR		
	Overhead Tank capacity	20,000 ltrs	Provided	MR		
15	Exit Signage.	Required	Provided	MR		
-1-7.			· Pa			
6	Provision of Lifts.	N/A	NA	NA		
	 Pressurization of Lift Shaft 	NA	and the same of th	1		
	Pressurization of Lift lobby	NA	NA	NA		

A METERS	PIIA	1411	MIG	
a unding Switch	NA	NA	NA	
• Fireman's Grounding Switch	NA	NA	NA	
Lift Signage	Required	Provided	MR	
Standby power supply	 			
Refuge Area.	NA	NA	NA	
> Total Area	NA NA	NA	NA	
> Location	1			
Fire Control Room	NA	NA	NA	
Detector System Panel		NA	NA	
Flow Switch Panel	NA NA	NA	NA	
PA System Panel	NA	NA	NA	
Batter backup	NA	NA	NA	
Building Floor Plans	NA	NA	NA	
Special Fire Protection Systems for Protection of special Risks, if any:	NA			

The fire protection systems provided in the building were checked and found functional at the time of inspection. All the shortcomings issued by this department has been complied by the managements.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

Dycho Kuiz)

Signature of the Inspecting Officer

Name: Sarabjeet Singh Designation: ADO (MN)

540/05/2

CFo- on leave

Direc 6

80/100

15 loaded 28/6/2024