GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/EH/2024/196

Dated:-24/04/2024

FIRE SAFETY CERTIFICATE

Certified that the DDCA Eating House Restaurant And Bar located at Arun Jaitley Stadium, Ferozshah Kotla Ground, New Delhi comprised of Ground floor only was earlier granted FSC by this department vide letter No.F6/DFS/MS/EH/2021/NDZ/101dated 13/04/21 Now, the premises was re-inspected by the officer concerned of this department on 14/06/24 in the presence of Mr A.K. Chaurasia and found that the said restaurant premises has deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the restaurant premises is fit for occupancy class Assembly Building (Group D) and valid up to 31.03.2027 from the date of issue in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued. 24.06.12024...at New Delhi by.

Delhi Fire Service

Copy to:-

- 1. The Commissioner of MCD, Civic Centre, New Delhi to ensure the occupancy in the building
- 2. The Dy. Commissioner of Police (Lic), Ist floor, PS Defence Colony, New Delhi Online ID no. 2024060108609 dated 01.06.2024.
- 3. The Manager, DDCA Eating House Restaurant And Bar located at Arun Jaitley Stadium, Ferozshah Kotla Ground, New Delhi.

Conditions for the validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of

3. The trained fire fighting staff should be available round the clock.

4. The compliance with regards to electrical installation, structural stability, set back area, occupancy and any deviation in construction etc. shall be verified from authority concerned.

5. This fire safety certificate may not be treated in any case for regularization of unauthorized

6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an

8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry". 9. Any flammable material for interior decoration is prohibited

NIZZ

INSPECTION REPORT

DDCA Eating House Restaurant and Bar 1. Name & address of the building:-

located at Arun Jaitley Stadium Ferozshah Kotla Ground, New Delhi

Group - D Assembly Building 2. Type of occupancy:-

Ground floor only

Renewal 3. Type of case:-

F6/DFS/MS/EH/2021/NDZ/101dated 13/04/21 4. Details of previous FSC:-

5. Fire safety directives No .-N/A 14/06/24 6. Date of inspection:-

Sh. Ravinder Singh (ADO/CC) 7. Name of the inspecting officer:-

8. Name & designation of officer

From the building side:-

Mr. A.K. Chaurasia

2010 9. Year of construction:-

Id No. 2024060108609 dated 01.06.2024. 10. Applicant's letter No:-

S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirements/ Existing	Provided at site	Remarks MR/NMR	
1.	Access to Building				
	1) Road width	4.5 mtr.	4.5 mtr.	MR	
	2) Gate width	4.5 mtr.	6.0 mtr.	MR	
	3)Width of internal road	N/A	·N/A	N/A	
2.	Number, Width Type & Arr	angement of Exi	ts		
	A. Number of staircases				
	1. Upper floors	N/A	N/A	N/A	
	2. Basements	N/A	N/A	N/A	
	B. Width of staircase				
	1. Upper floors	N/A	N/A	N/A	
	2. Basements	N/A	N/A	N/A	
	C. Protection of exits				
	1. Fire check door	N/A	N/A	N/A	
	2. Pressurization	N/A	N/A	N/A	
	D. No. of continuous staircase to terrace	N/A	N/A	N/A	
	E. Width of corridor	N/A	N/A	N/A	
	F. Door size	2 mtr.	2 mtr.	MR	
3.	Compartmentation				
	1) Fire check door	N/A	N/A	N/A	
	2) Sealing of electrical shafts	N/A	N/A	N/A	
	3) Fire rating of shaft door	N/A	N/A	N/A	
	4) Water curtain	N/A	N/A	N/A	
	5) Fire Dampers	N/A	N/A	N/A	
4.	Smoke Management System				
	1) Basements	N/A	N/A	N/A	
	2) Upper floors	12 a/c per hour	Natural	MR	
5.	Fire Extinguishers				
	1) Total numbers	10 Nos.	12 Nos.	MR	

	2) Type	1/23	ABC & CO2	MR 💣
	2) Types	ABC & CO2	Provided	MR
6.	3) ISI marking	Required	Provided	
	First-Aid Hose Reel			MR
	1) Total number	02	02	MR
	2) Length of hose reel hose	30 m	30 m	MR
7.	3) Nozzle diameter	5 mm	5 mm	Invite
<u>'</u> -	Automatic Fire Detection &	Alarming Syst	em	MR
	1) Type of detectors Co type	N/A	Provided	
	2) Location of main panel	N/A	N/A	N/A
	3) Location of repeater panel	N/A	N/A	N/A
	4) Alternate source of power	N/A	N/A	N/A
	5) Hooter's Location	N/A	N/A	N/A
8.	MOEFA	Required	Provided	MR
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System			
	1) Basement	N/A	N/A	N/A
	2) Gr. floor	N/A	provided	N/A
	3) Sprinkler above false	N/A	N/A	N/A
	ceiling			le .
11.	Internal Hydrants		_	
	1) Size of riser/down-comer	100 MM	100 MM	MR
	2) Number of hydrants per	02	02	MR ·
	floor	1000 100	***************************************	1
	3) Hose box	02	02	MR
12.	Yard Hydrants			
	1) Total number of hydrants	N/A	Provided	N/A
	2) Hose box	N/A	Provided	N/A
13.	Pumping Arrangement			
	Ground level		100	
	a) Discharge of main	2250 LPM	2250 LPM	MR
	pump			
	b) Head of main pump	40 mtr.	40 mtr.	MR
	c) Number of main	01	01	MR
	pump		HI .	
	d) Jockey pump out put	180 LPM	180 LPM	MR
	e) Jockey pump head	40 mtr.	40 mtr.	MR
	f) Stand by pump	N/A	N/A	N/A
	output			
	g) Stand by pump head	Required	Provided .	MR
	h) Auto starting/Manual	Required	Provided	MR
	stopping			
	2) Terrace level			
	a) Discharge of pump	N/A	N/A	N/A
	b) Head of pump	N/A	N/A	N/A
	c) Power supply	N/A	N/A	N/A
	d) Auto starting of	N/A	N/A	N/A
	pump			- CO

		10101		(4)
	Under ground tank capacity	2,00,000 ltr.	2,00,000 ltr.	MR
	a) Draw-off connection	Required	Provided	MR
	 b) Fire service inlet 	Required	Provided	MR
	c) Access to tank	Required	Provided	MR
	 d) Over head tank capacity 	N/A	N/A	N/A
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.	1	Tiovided	IVIIC
	 a) Pressurization of lift shaft 	N/A	N/A	N/A
	 b) Pressurization of lift lobby 	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	· N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System Risk, if any:	for Protection	on of special	N/A

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, if agreed, we may renew the FSC issued vide letter no. F6/DFS/MS/EH/2021/NDZ/101dated 13/04/21, under rule 35(6) of the Delhi Fire Service Rules 2010. Accordingly, DFA is put up for kind perusal and signature please.

Signature of the Inspecting Officer

Name: - Ravinder Singh Designation: - ADO (CC)

18/6/24

Dycho (Moz) - on leave

Inda Wang

Antes