

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001



No F 6 / DFS / MS / 2024 /WZ/ 3 0 4

_ Dated 28/06/2014

FIRE SAFETY CERTIFICATE

Certified that Invitation Restaurant located at Plot No. 3, local Shopping Center, Near SBI Bank, Ashok Vihar, Delhi-110052 is running at Ground & Mezzanine Floor in a building comprised of Basement, Ground, Mezzanine plus Three Upper Floors have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of this department on 24.06.2024 in the presence of Sh. Tarun and found that the building/ premises is fit for occupancy "Assembly" (Group D) Eating House with effect from 28 06 2024 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010 printed below.

Issued on 28 06 224 at New Delhi by

Ph- 011-23414000

Copy to:-

- 1. M/s Invitation Restaurant located at Plot No. 3, local Shopping Center, Near SBI Bank, Ashok Vihar, Delhi-110052.
- 2. MHA Portal ID No. 2024060408750.

Conditions for the validity of Fire Safety Certificate:

1. Fire Safety Certificate is valid for Ground and Mezzanine Floor only.

2. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.

3. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.

4. The trained fire fighting staff should be available round the clock.

5. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.

6. This certificate cannot be treated in any case for regularizations of unauthorized construction.

The owner/occupier shall apply for renewal of this Fire Safety Certificate through MHA
portal (https://www.delehlhlic.gov.in) along with a copy of this Certificate, six months
prior to its expiry".

8. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <u>WWW.dfs.Delhigovt.nic.in</u>

9. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

INSPECTION REPORT

M/s Invitation Restaurant located at Plot No. 3, local Shopping Centre, 1. Name & address of the building:

Near SBI Bank, Ashok Vihar, Delhi- 110052.

2. Type of Occupancy

: Assembly

: Basement (Storage), Ground & Mezzanine (Restaurant) and Three upper 3. Building Comprised of

Floors(other Property used as Nursing Home)

Type of Case

New Case Nil

5. Details of Previous NOC

NBC Part- IV/ UBBL

6. Fire Safety directives letter No 7. Date of inspection

24/06/2024

8. Name of Inspecting Officer

R.K.Sinha, ADO (BW)

9. Name and designation of officers

From the building side

Sh. Tarun

1985 as per MHA portal

<u> </u>	Applicant's letter No. Minimum Standards on fire	NBC Part IV/	060408750 dated 04/06/20 Provided at site	Kemarks		
No.	prevention and fire safety U/R 33	UBBL		MR/NMR		
1.	Access to building		n !1-1	MR		
	Road width	6 m	Provided	MR		
	Gate width	5 m	Directly Accessible NA	NA		
	 Width of internal road 	NA NA	NA	100		
2.	Number, Width, Type & Arrangeme	nt of Exits				
	a. Number of staircases		20	MR		
	Upper F oors	02	02	NA NA		
	Basements	NA	. NA	NA		
	b. Width of staircases					
	Upper F oor	1.5 m each	Provided	MR		
	Basements	NA	· NA	NA		
	c. Protection of exits					
	Fire check door	Required	Provided	MR		
	Pressurization	NA NA	NA	NA		
	d. No. of continuous staircases to terrace	01	01	MR		
	e. Width of Corridor	NA	NA	NA		
	f. Door Size	2 m & 1.5 m	Provided	MR		
3.	Compartmentation					
3.	Fire check door	Required	Provided	MR		
	Sealing of electrical shafts	NA	NA	NA		
	20 2 0 7 7 7 7	NA	NA	NA ·		
	Fire Rating of shaft door Water Curtain	NA NA	NA NA	NA NA		
	Fire Dampers	NA NA	NA	NA NA		
4.	Smoke Management System		IM			
7.				1 277		
	Basements	NA	NA	NA		
	Upper fldor	Required	Provided	MR		
5.	Fire Extinguishers					
	Total numbers	6	10	MR		
	Types	ABC/Co2 Type	Provided	MR		
	IS marking	Required	Provided	MR		
6.	First-Aid Hose Reels					
	Total numbers on each floor	01	Provided	MR		
	 Length of hose reel hose 	30 m	Provided	MR		
	Nozzle d ameter	5 mm	Provided	MR		
7.	Automatic fire detection and alarm	ing system	Tiovided	IVIR		
	Type of detectors	NA NA	Provided	NA		
	Location of Main Panel	NA	NA	NA		
	 Location of Repeater Panel 	NA NA	NA NA	- Children		
	Alternate source of power	NA NA	NA NA	NA NA		
	- David	INA	NA NA	NA NA		
	Hooters' Location	NA	\$1.6	NA		

	11
-	1
-	- ('

		N 11			
8.	MOEFA	Required	Provided	MR	
9. 10.	Public Address System	NA	NA	NA	
10.	. Automatic Sprinkler System				
	Basement	NA	NA	NA	
	Upper Floors	NA	NA	NA	
	Sprinkler above false ceiling	NA	NA	NA	
11.	Internal Hydrants				
	Size of riser/down-comer	100 mm	Provided	MR	
	Number of hydrants per floor	01	Provided	MR	
	Hose Box	01	Provided	MR	
12.	Yard Hydrants		11011000		
	Total number of hydrants	NA	NA	NA	
	Hose Box	NA	NA NA	NA NA	
13.	Pumping Arrangements		TVA	IVA	
	Ground Level				
	Discharge of main Pump	NA	NIA	NIA	
		NA NA	NA NA	NA NA	
	➤ Head of Main pump		INA	INA	
	Number of main pumps	NA	NA	NA	
^	Jockey Pump out put	NA	NA	NA	
	Jockey pump head	NA	NA	NA	
	> Standby Pump out put	NA	NA	NA	
	Standby Pump Head	NA	NA	NA	
	➤ Auto Starting/Manual Stopping	NA	NA	NA	
	➤ Power Supply	NA	NA	NA	
	Terrace level				
ŀ	➢ Discharge of pump	450 lpm	Provided	MR	
	➤ Head of the pump	40 m	Provided	MR	
, F			<u> </u>		
	Power Supply	Required	Provided	MR	
4.	➤ Auto Starting of pump Captive Water Storage for fire fighting	Required	Provided	MR	
-	Underground tank capacity	NA	NA	NA	
-	> Draw-off connection	NA	NA	NA	
_	> Fire service inlet	NA	NA	NA	
-	Access to tank	NA	NA	NA	
	Overhead Tank capacity	20,000 ltrs	Provided	MR	
5.	Exit Signage.	Required	Provided	MR	
5.]	Provision of Lifts.				
	Pressurization of Lift Shaft	NA	NIA		
	Pressurization of Lift lobby	NA NA	NA	NA	
	Communication In lift Car	NA NA	NA	NA	
	Fireman's Grounding Switch	NA NA	NA	NA	
-	Lift Signage	0.000.00	NA	NA	
S	tandby power supply	NA .	NA	NA	
	7	Required	Provided	MR	
R	efuge Area.				
1	> Total Area	NA	NA	NA	
4	> Location	NA	NA	NA NA	
Fi	re Control Room			, Arr	
	Detector System Panel	NA	NA	NA NA	
			13/4	INA	

1	Flow Switch Panel			
20.		NA	NA	NA
	PA System Panel	NA	- NA	NA NA
	Battery backup	NA		92.6Viii
	Building Floor Plans	NA	NA	NA
	Special Fire Protection System for		NA	NA
	Protection of special Risks, if any:	NA	NA	NA

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection. The management had rectified the shortcomings issued vide letter number F6/DFS/MS/EH/WZ/2024/206 dated 27/05/2024.

Keeping in view satisfactory compliance of the minimum standards of fire prevention and fire safety measures as required under rules it is recommended grant Fire Safety Certificate under rule 35 of the Delhi Fire Service, Rules 2010.

Rycfollog

Signature of Inspecting Officer Name : Rajeev Kumar Sinha

Designation : ADO/B.W.

Director My de 2

1.

uploaded by