

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-1 10001

No.F.6 DFS/MS/School/2024/SZ/S94

Dated: 27/66/2024

## FIRE SAFETY CERTIFICATE

Certified that the MCD Pratibha Co-ed Vidyalaya, located at Pushp Vihar, Sector-7, New Delhi – 110017 comprised of ground plus floor only owner/occupied by Municipal Corporation of Delhi was issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/School/2021/SZ/150 dated 23/02/2021. The said premises was re-inspected by officer concerned of this department on 19/06/2024 in presence of Mr. Rajbeer Singh (Principal) of the school and found that the said school building have deemed complied with the fire prevention and fire safety requirements in accordance with Directorate of Education Circular No F.16//Estate/CC/Fire Safety/2011/3298 to 3398 dated 01/03/2011 issued by Director of Education, Govt. of NCT of Delhi and that the building is fit for occupancy class "Educational Building Group - B" with effect from 10 miles of 10 miles approached under rule 20 miles renewed under rule 20 miles renewed under rule 20 miles fire Service Rules 2010.

Issued on 27/06/2024 at New Delhi by

ATUL GARG)
DIRECTOR
LHI FIRE SERVICE

Copy to: -

- The Principal, MCD Pratibha Co-ed Vidyalaya, located at Pushp Vihar, Sector-7, New Delhi - 110017
- 2. The Director of Education, MCD, Civic Centre, Minto Road, New Delhi-110002

## Conditions for the validity of Fire Safety Certificate:-

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.
- 3. This certificate cannot be treated as regularization of unauthorized construction, if any.
- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."



1	Name & Address of the Building	ON REPORT  Dakshin Nigam  Pushn Viber Sector	Pratibha Co-ed, Prim r-7, New Delhi - 11002	ary School	
2	Type of Occupancy	Educational Grow	-7, New Delni - 11002	.7	
3	Building Comprised of	Educational, Group-B (School) Ground Floor only			
4	Type of Case	Renewal			
5	Details of Previous NOC				
6	Fire Safety Directives Letter No	F6/DFS/MS/School/2021/SZ/150 dt. 23/02/2021			
7	Date of Inspection	F.16//Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 19-06-2024			
8	Name of the Inspecting Officers	Sh. Rajesh Kumar ADO (BCP)			
9	Name & Designation of Officers from the building side	Sh. Rajbeer Singh (Principal)			
10	Year of construction	1997			
11	Applicant letter No.	Outdoor diary no 2596 Dated 06/06/2024			
S. No	Minimum standards on Fire Prevention and Fire Safety U/R 33	Circular dt 01/03/2011	Remarks MR/NMR		
1	Access to Building.	01/00/2011		MINIMIN	
第一	Road width	Required	6 mtr	MR	
N d	Gate width	4.5 mtr	Direct accessible	MR	
-	Width of internal road	-NA-	-NA-	-NA-	
2	Number, width, type & arrangement of exits.			-NA-	
	a) Number of Staircase	1997			
	> Upper floors.	-NA-	-NA-	-NA-	
b. 7	➤ Basement floor.	-NA-	-NA-	-NA-	
	b) Width of Staircase	222		-11/1-	
66	➤ Upper floors	-NA-	-NA-	-NA-	
	➤ Basement floor	-NA-	-NA-	-NA-	
	c) Protection of exits	Landon & Complete	5611 V -0.0A	141	
	> Fire check door	-NA-	-NA-	-NA-	
	➤ Pressurization	-NA-	NA-	-NA-	
	d) No. of continuous staircase to terrace	-NA-	-NA-	26195961	
12."	e) Width of corridor	-NA-	-NA-	-NA-	
1	f) Door size	1 mtr		-NA-	
3	Compartmentation.	Same	1 mtr	MR	
10/-	Fire check door.	-NA-	-NA-	-NA-	
	Sealing of electrical shafts.	-NA-	-NA-	-NA-	
17	Fire rating of shaft door.	-NA-	-NA-	-NA-	
a de	Water curtain	-NA-	-NA-	-NA-	
	Fire dampers.	-NA-	-NA-	-NA-	
4.	Smoke Management system.				
	Basement	-NA-	-NA-	-NA-	
	Upper floors	12 a/c per hour	Open corridor	MR	
5.		All a Martin at a	EMPLEY.		
15	Total numbers	Required	10 Nos	MR	
	Types	ABC	ABC Type	MR	
	ISI Marking	ISI mark	Provided	MR	
6.	First Aid Hose Reels.		4-4-5		
	Total numbers on each floor.	-NA-	-NA-	-NA-	
1	Length of hose-reel hose.	-NA-	-NA-	-NA-	
	Nozzle Diameter	-NA-	-NA-	-NA-	
7		10 <sup>2</sup> -75-72	434.5	-14/4-	

0



		-		
	Type of detectors Type	-NA-	-NA-	-NA-
	Location of Main Panel	-NA-	-NA-	-NA-
	Location of Repeater Panel	-NA-	-NA-	-NA-
	Alternate source of power	-NA-	-NA-	-NA-
	Hooter's location	-NA-	-NA-	-NA-
8.	MOEFA	-NA-	-NA-	-NA-
9.	Public Address System	-NA-	-NA-	-NA-
10,	Automatic Sprinkler System	979-1	Section Section 18	
	Basement	-NA-	-NA-	-NA-
	Upper floors	-NA-	-NA-	-NA-
	Sprinkler above false ceiling	-NA-	-NA-	-NA-
11.	Internal Hydrants.		ordinals in 1919	
	<ul> <li>Size of Riser/Down-comer</li> </ul>	-NA-	-NA-	-NA-
	Number of Hydrant per floor	-NA-	-NA-	-NA-
	Hose box.	-NA-	-NA-	-NA-
12.	Yard Hydrants.			
	Total number of hydrants.	-NA-	-NA-	-NA-
	Hose box.	-NA-	-NA-	-NA-
13.	Pumping arrangements.			
	Ground Level	J		
	Discharge of main pump.	-NA-	-NA-	-NA-
	➤ Head of main pump.	-NA-	-NA-	-NA-
	Number of main pumps.	-NA-	-NA-	-NA-
	➢ Jockey Pump output.	-NA-	-NA-	-NA-
	Jockey Pump head.	-NA-	-NA-	-NA-
	➤ Standby Pump output.	-NA-	-NA-	-NA-
	Standby Pump head.	-NA-	-NA-	-NA-
	➤ Auto Starting / Manual Stopping.	-NA-	-NA-	-NA-
	Pump house access.	-NA-	-NA-	-NA-
	Terrace Level		WHITE A LEED TO BE	
	Discharge of pump.	-NA-	-NA-	-NA-
	➤ Head of pump.	-NA-	-NA-	-NA-
	➤ Power supply.	-NA-	-NA-	-NA-
	Auto starting of pump.	-NA-	-NA-	-NA-
14.	Captive water storage for fire fighting.			V V
	Underground tank capacity.	-NA-	-NA-	-NA-
	> Draw-off connection.	-NA-	-NA-	-NA-
	> Fire Service Inlet.	-NA-	-NA-	-NA-
	➤ Access to tank.	-NA-	-NA-	-NA-
	Overhead tank capacity.	-NA-	-NA-	-NA-
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.		The make a	
	Pressurization of lift shaft.	-NA-	-NA-	-NA-
	Pressurization of lift lobby.	-NA-	-NA-	-NA-
	Communication in lift car.	-NA-	-NA-	-NA-
	Fireman's switch.	-NA-	-NA-	-NA-
	Lift signage.	-NA-	-NA-	-NA-
17.	Standby Power Supply	-NA-	-NA-	-NA-
18.	Refuge Area	****	there were the same	
10.		-NA-	-NA-	-NA-
	Total area	EVACE I	-NA-	-NA-
	Location	-NA-	-11/1-	-11/4-
	Fire Control Room.	1		
19.	FII C COULT OF ROOM.	-NA-		



	Flow switch panel.	-NA-	-NA-	-NA-
- 1	PA system panel.	-NA-	-NA-	-NA-
- 1	Battery backup.	-NA-	-NA-	-NA-
1	Building floor plan.	-NA-	-NA-	-NA-
20.	Special Fire Protection System for the Protection of special Risk, if any.	-NA-	-NA-	-NA-

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the PSC issued vide letter no F6/DFS/MS/School/2021/SZ/150 dt. 23/02/2021, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: Sh. Rajesh Kumar

Design: ADO (BCP)

As approved, F.T. I that is fortry for your synature of