

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI-110001**

No.F.6 DFS/MS/Audi/2024/SZ/School) 582

Dated: 27/06 / 2024

FIRE SAFETY CERTIFICATE

Certified that the **Auditorium / MP Hall** at Mothers International School at Sri Aurobindo Marg, New Delhi 110016 comprised of Basement, Ground, Mezzanine & Two upper floors owned/occupied by Sri Aurobindo Education Society was issued Fire Safety Certificate by this department vide letter No. F.6/DFS/MS/Audi/2021/SZ/540 dated 27-07-2021. The said premise was re-inspected by officer concerned of this department on 20/06/2024 in presence of Mr. Pranjal and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010 and that the building is fit for occupancy class "**Group - D**" **Assembly Building (Auditorium)** with effect from 27/06 / 2024 for a period of **Three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of Delhi Fire Service Rules 2010.

Issued on 27/06, 2024 at New Delhi by

(ATUL GARG)
DIRECTOR
DELHI FIRE SERVICE

Copy to: -

1. The Chairman, Auditorium / MP Hall at Mothers International School at Sri Aurobindo Marg, New Delhi 110016.
2. The Joint Commissioner of Police, Lic/Branch, 1st Floor, PS Defence colony, New Delhi 110049
3. The Executive Engineer (Bldg Department) MCD, Green Park, New Delhi 110016.

Conditions for the validity of Fire Safety Certificate

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
2. All the staff members must know the correct method of operation of firefighting system.
3. This certificate cannot be treated as regularization of unauthorized construction, if any.
4. The basement shall be used as per the provisions of BBL /NBC Part- IV.
5. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

14/25

INSPECTION REPORT

1	Name & Address of the Building	Auditorium / MP Hall at Mothers International School at Sri Aurobindo Marg, New Delhi-16		
2	Type of Occupancy	Assembly (Auditorium), Group-D		
3	Building Comprised of	Basement, Ground Mezzanine plus 02 upper floors		
4	Type of Case	Renewal		
5	Details of Previous NOC	F.6/DFS/MS/Audi/2021/SZ/540 dated 27-07-2021		
6	Fire Safety Directives Letter No	F6/DFS/MS/BP/2006/3487 dated 01/12/2006		
7	Date of Inspection	20-06-2024		
8	Name of the Inspecting Officers	DO (South) & ADO (BCP)		
9	Name & Designation of Officers from the building side	Mr. Pranjal		
10	Year of construction	2006		
11	Applicant letter No.	MIS/A17-3/2004 dated 04-06-2024		
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	As per old NOC	Provided at Site	Remarks MR/NMR
1	Access to Building.			
	• Road width	06 mtr	Provided	MR
	• Gate width	5 mtr	Provided	MR
	• Width of internal road	Accessible	Provided	MR
2	Number, width, type & arrangement of exits.			
	a) Number of Staircase			
	➤ Upper floors.	03 No + 01 ramp	Provided	MR
	➤ Basement floor.	04 No + 2 ramp	Provided	Old case
	b) Width of Staircase			
	➤ Upper floors	1.5m each	1.78m, 1.80m, 1.97m & ramp 1.85m	MR
	➤ Basement floor	1.5m each	1.50m, 1.50m, 1.70m & ramp 2 x 6m & 1.85m	MR
	c) Protection of exits			
	➤ Fire check door	Required	Provided	MR
	➤ Pressurization	N/A	N/A	N/A
	d) No. of continuous staircase to terrace	Required	03 Nos	MR
	e) Width of corridor	N/A	N/A	N/A
	f) Door size	1.50 mtr	Provided	MR
3	Compartmentation.			
	• Fire check door.	Required	Provided	MR
	• Sealing of electrical shafts.	Required	Provided	MR
	• Fire rating of shaft door.	N/A	N/A	N/A
	• Water curtain	N/A	N/A	N/A
	• Fire dampers.	N/A	N/A	N/A
4	Smoke Management system.			
	• Basement	30 ACPH	Provided	MR
	• Upper floors	12 ACPH	Provided	MR
5	Fire Extinguishers.			
	• Total numbers	ISI marked	20 Nos	MR
	• Types		ABC & W.CO ₂	MR
	• ISI Marking		Provided	MR
6	First Aid Hose Reels.			
	• Total numbers on each floor.	Hose Reel	BF-4, GF-4, FF-2, & 2 nd Floor -01 No	MR
	• Length of hose-reel hose.		30m	MR
	• Nozzle Diameter		5mm	MR
7	Automatic fire detection & alarming system.			
	• Type of detectors	Smoke & Heat	Provided	MR
	• Location of Main Panel	Required	Ground floor	MR
	• Location of Repeater Panel	N/A	N/A	N/A
	• Alternate source of power	Required	Provided	MR
	• Hooter's location	Required	Provided	MR



8	MOEFA			MR
9	Public Address System	Required	Provided	MR
10	Automatic Sprinkler System			
	• Basement	Required	Provided	MR
	• Upper floors	N/A	N/A	N/A
	• Sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants.			
	• Size of Riser/Down-comer	100mm	100mm	MR
	• Number of Hydrant per floor	BP-4, GP-4, VP-2, & 2 nd Floor -01 No	BP-4, GP-4, VP-2, & 2 nd Floor -01 No	MR
	• Hose box.	BP-4, GP-4, VP-2, & 2 nd Floor -01 No	BP-4, GP-4, VP-2, & 2 nd Floor -01 No	MR
12	Yard Hydrants.			
	• Total number of hydrants.	N/A	N/A	N/A
	• Hose box.	N/A	N/A	N/A
13	Pumping arrangements.			
	• Ground Level			
	➤ Discharge of main pump.	N/A	N/A	N/A
	➤ Head of main pump.	N/A	N/A	N/A
	➤ Number of main pumps.	N/A	N/A	N/A
	➤ Jockey Pump output.	N/A	N/A	N/A
	➤ Jockey Pump head.	N/A	N/A	N/A
	➤ Standby Pump output.	N/A	N/A	N/A
	➤ Standby Pump head.	N/A	N/A	N/A
	➤ Auto Starting/Manual Stopping.	N/A	N/A	N/A
	➤ Pump house access.	N/A	N/A	N/A
	• Terrace Level			
	➤ Discharge of pump.	900 & 450 LPM	450 & 900 LPM	MR
	➤ Head of pump.	40 mtr each	Provided	MR
	➤ Power supply.	Required	Provided	MR
	➤ Auto starting of pump.	Required	Provided	MR
14	Captive water storage for fire fighting.			
	• Underground tank capacity.	50,000 ltrs	Provided	MR
	➤ Draw-off connection.	Required	Provided	MR
	➤ Fire Service Inlet.	Required	Provided	MR
	➤ Access to tank.	Required	Provided	MR
	• Overhead tank capacity.	20,000 ltrs	Provided	MR
		Required	Provided	MR
15	Exit Signage.			
16	Provision of Lifts.			
	• Pressurization of lift shaft.	N/A	N/A	N/A
	• Pressurization of lift lobby.	N/A	N/A	N/A
	• Communication in lift car.	N/A	N/A	N/A
	• Fireman's switch.	N/A	N/A	N/A
	• Lift signage.	N/A	N/A	N/A
17	Standby Power Supply	Required	Provided	MR
18	Refuge Area			
	• Total area	N/A	N/A	N/A
	• Location	N/A	N/A	N/A
19	Fire Control Room.			
	• Detector system panel.	N/A	N/A	N/A
	• Flow switch panel.	N/A	N/A	N/A
	• PA system panel.	N/A	N/A	N/A
	• Battery backup.	N/A	N/A	N/A
	• Building floor plan.	N/A	N/A	N/A
20	Special Fire Protection System for the Protection of special Risk, if any.	N/A	N/A	N/A

N/27

The Mother's International School located at Sri Aurobindo Marg, New Delhi-110016

The fire protection systems provided in the premises were test checked at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No F.6/DFS/MS/Audi/2021/SZ/540 dated 27-07-2021, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

[Handwritten signature]

Signature of the Inspection Officer
Name: Sh. Manoj Kumar Sharma
Design: DO (South)

[Handwritten signature]
20/8/2024

Signature of the Inspecting Officer
Name: Sh. Rajesh Kumar
Design: ADO (BCP)

CFO (HQ)

[Handwritten signature]
21/6/2024

Director

[Large handwritten signature]
21/06/24

[Handwritten signature]

As approved, F.T. letter is put up
for your signature pl

[Handwritten signature]
24/6/24

Director *[Handwritten signature]*
21/06/24

[Handwritten signature]