

# GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/2024/School/ 580

Dated: 27 /06 /2024

#### **FIRE SAFETY CERTIFICATE**

Certified that the St. Ramjas Convent School located at 342 & 693, Bhalswa Village, Near K-Block, Delhi-110042 comprised of Ground & first floors with hall owned/occupied by the St. Ramjas Convent School was issued fire safety certificate vide this office letter no. F6/DFS/MS/2020/234 dated 17.07.2020. The premises was inspected by the officer concerned of this department on 14.06.2024 in the presence of Sh. Dushyant Gupta (Manager) and observed that all the fire prevention and fire safety arrangements as provided in the premises found in good working condition. The premises have deemed complied with requirements of circular issued by Director of Education letter no 3298-3398 dated 01.03.2011 and the building/premise is fit for occupancy Group B Educational with effect from ... 27/106/21.29.. for a period of three years, subject to compliance of the conditions mentioned below:

Issued on .. 27. 6. 12.224. at New Delhi by.

(Affal Garg)
Director
Ph:-011-23414000

### Copy to:-

1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi - 54.

2. The Manager, St. Ramjas Convent School at 342 & 693, Bhalswa Village, Delhi-110042.

## Conditions for the validity of Fire Safety Certificate:

1 All the means of escape/entry/exit shall be kept free from any obstruction.

2 All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

3 All the staff members must know the correct method of operation of firefighting system.

4 The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="http://delhi.gov.in/wps/wcm/connect/doit">http://delhi.gov.in/wps/wcm/connect/doit</a> fire/FIRE/Home/Forms.

5 This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.

6 "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

#### **INSPECTION REPORT**

1. Name & address of the building : St. Ramjas Convent School at 342 & 693, Bhalswa Village, Delhi-110042.

2. Type of Occupancy : Educational

3. Composition of Building : Ground & First floors with one hall at ground floor

4. Type of Case : Renewal

5. Details of previous NOC : F6/DFS/MS/2020/234 Dated: 17.07.2020

6. Fire Safety directives letter No : Director of Education Circular dated 01.03.2011

7. Date of inspection : 14.06.2024
8. Name of the Inspecting Officers : ADO (RN)

9. Name and designation of officers

from the building side : Mr. Dushtant Gupta (Manager)

10. Year of Construction : 2009

11. Applicant's letter No. : SRCS/FSC/2024/564 Dated 03.05.2024

	Minimum Standards on fire prevention and fire safety U/R 33	Requirement as per Rule 35 (6)/ Inspection dated 24.09.2013		Remarks MR/NMR		
	Access to building					
	Road width	Accessible	Accessible	MR		
	Gate width	Accessible	Accessible	MR		
	Width of internal road	NA	NA	NA		
	Number, Width, Type & Arrangement of Exits					
	a. Number of staircases					
	Upper Floors	01	02	MR		
	Basements	NA	NA	NA		
	b. Width of staircases					
	Upper Floors	1.50m	1.30m & 1.0m	MR (being old case)		
12.19	Basements  c. Protection of exits	NA	NA	NA NA		
	Fire check door	NA I	NA	NA		
	Pressurization	NA	NA	NA NA		
	d. No. of continuous staircases to terrace	NA	NA	NA		
	e. Width of Corridor	01m	02m	MR		
	f. Door Size	1m & hall 02 exits	1m & hall exits 02m	MR		
	Compartmentation.					
	Fire check door	NA NA	NA	NA		
	Sealing of electrical shafts	NA	NA	NA		
	Fire Rating of shaft door	NA	NA	NA		
	Water Curtain	NA	NA -	NA		
	Fire Dampers	NA	NA	NA		
	Smoke Management System.					
	Basements	NA	NA	NA		
	Upper floors	Required	Natural Ventilated	MR		
	Fire Extinguishers					
	Total numbers	05nos	12nos	MR		



		ABC/CO2	ABC—12	3
	• Types	ISI Marked	Yes	MI
	ISI marking	ISI Marked		
6	First-Aid Hose Reels.		NA NA	NA
	Total numbers on each floor	NA	NA	NA
	Length of hose reel hose	NA	3.71	NA NA
	Nozzle diameter	NA	NA	1,7.
_	Automatic fire detection and alarming system		I NA	
7		T NA	NA	NA NA
	Type of detectors	NA	NA	
	Location of Main Panel	NA	NA	NA
	Location of Repeater Panel	NA	NA	NA
	Alternate source of power	17.07	NA	NA
	Hooters' Location	NA NA	NA	NA
8	MOEFA	NA	NA NA	NA
9	Public Address System.	NA	NA .	
10	Automatic Sprinkler System.		NA	NA
	Basement	NA NA	NA NA	NA
	Upper Floor	NA		NA
	Sprinkler above false ceiling	NA	NA	INA
11	Internal Hydrants.		. NA	NA
	Size of riser/down-comer	NA NA	NA NA	NA
	Number of hydrants per floor     Hose Box	NA NA	NA NA	NA
		INA		
12	Yard Hydrants.     Total number of hydrants	NA	NA	NA
	Hose Box	NA	NA	NA
3	Pumping Arrangements.			
	Ground Level			
	➤ Discharge of main Pump	N/A	N/A	N/A
	➤ Head of Main pump	N/A	N/A	N/A
	➤ Number of main pumps	N/A	N/A	N/A
	➤ Jockey Pump out put	N/A	N/A	N/A
	➤ Jockey pump head  ➤ Standby Pump out put	N/A N/A	N/A	N/A
	> Standby Pump Head	- 1"	N/A	N/A
	> Auto Starting/ Manual stopping	N/A	44.	17555743.1
	➤ Pump House Access	N/A	N/A	N/A
	Terrace level     Discharge of pump	N/A	N/A	N/A
	➤ Head of the pump	,,,, — T		
	➤ Power Supply	NA NA	NA NA	NA
	Auto Starting of pump	NA N/A	NA NA	NA
		N/A	NA	N/A
	Captive Water Storage for fire fighting.	N/A	NA	N/A
-				
	<ul> <li>Underground tank capacity</li> </ul>	NA	NA	NA



1	> Draw-off connection	NA	NA NA	NA		
- 60	<ul> <li>Fire service inlet</li> <li>Access to tank</li> <li>Overhead Tank capacity</li> </ul>	NA	NA	NA		
		NA.	NA NA	NA		
		NA	NA	NA		
111		N/A	N/A	N/A		
5	Exit Signage.					
6	Provision of Lifts.  Pressurization of Lift Shaft  Pressurization of Lift lobby  Communication In lift Car  Fireman's Grounding Switch  Lift Signage	N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
17	Standby power supply	N/A	N/A	N/A		
i i	Pri 3741	-	***	-		
18	Refuge Area.  > Total Area	N/A	N/A	N/A		
	> Location	N/A	N/A	N/A		
19	Fire Control Room.					
200	Detector System Panel	N/A	N/A	N/A		
	Flow Switch Panel	N/A	N/A	N/A		
0	PA System Panel     Batter backup	N/A	N/A	N/A		
		N/A	N/A	N/A		
	Building Floor Plans	N/A	N/A	N/A		
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were tested/ checked randomly and found in working condition at the time of inspection.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in director of education Circular dated 01.03.2011, it is recommended to renewal of fire safety certificate issued vide this department letter of even no. F6/DFS/MS/2020/234 dated: 17.07.2020.

Dy. Chief Fire Officer (WZ)

Signature of the Inspecting Name: C.L. Meena

Designation:- Asst. Div. Officer (RN)