

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001



No F 6 / DFS / MS / 2024/WZ/ 425

Dated 02/07/2024

## FIRE SAFETY CERTIFICATE

Certified that the Pearls PGF Limited located at Plot No. B-1, Netaji Subhash Place, Pitampura, Delhi-110034 comprised of 3 Basements, Ground plus 12 upper floors owned/ occupied by Pearls PGF Limited was issued fire safety certificate vide letter no. F6./DFS/MS/WZ/2020/387 dated 25.09.2020. The building was re-inspected by the officer concerned of this department on 07.06.2024 in the presence of Sh. Kapil Kumar and found that ,all the fire prevention and fire safety arrangements provided in the building in good working condition. The building have therefore deemed complied with the requirements under Rule 33 of the Delhi Fire Service Rules, 2010 and the building premise is fit for occupancy under Mixed (Mercantile & Business) with effect from ...02/07/2029... for a period of three years in accordance with the Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40, subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010. Issued on .. 02/07/2024. at New Delhi, by

Copy to:-

1. Sh. Kapil Kumar (Manager), Pearls PGF Ltd., Plot No. B-1, Netaji Subhash Place, Pitampura, Delhi- 110034.

Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided there-in shall be maintained in good working conditions

2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.

5. This certificate cannot be treated in any case for regularizations of unauthorized construction.

6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on **WWW.dfs.Delhigovt.nic.in** 

8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

18-47

## INSPECTION REPORT

Name & address of the building : Pearl PGF Limited, located at Plot No. B-1, Netaji Subhash

Place, Pitampura, Delhi- 110034.

Remarks

MR/NMR

2. Type of Occupancy : Mixed(Mercantile + Business), (03 Basements + Ground + 12 upper floors).

3. Type of Case : Renewal

4. Details of previous NOC : F6/DFS/MS/WZ/2020/387 dated 25/09/2020

5. Fire Safety directives letter No : F6/DFS/MS/BP/2006/824 dated 04/04/2006

: 07/06/2024 6. Date of inspection

7. Name of the Inspecting Officers: R.K. Sinha, ADO (BW)

8. Name and designation of officers

: Sh. Kapil Kumar from the building side

: 2009 (As per pre. Insp. report dated 15/09/2020) 9. Year of Construction

: Form J dated 30/05/2024 10. Applicant's letter No. Provided at site As per Rule 35 (6) Minimum Standards on fire S. prevention and fire safety U/R 33 DFS Rule 2010

No. Access to building MR Provided 22 mtr Road width MR Provided 06 mtr Gate width MR As per DDA controlled drawing Width of internal road 06 mtr

Number, Width, Type & Arrangement of Exits

a. Number of staircases	6 up to 3 <sup>rd</sup> , 4 up to 12 <sup>th</sup> floor	Provided	MR
Upper Floors	6 + 2 ramp Provided		MR
Basements     b. Width of staircases		1 = 131cm,140cm	MR (old
Tile one	4 x 1.5 m & Tower-	a 121am 140cm	

Tower-2 = 131cm, 140cmUpper Floors Up to 4th Floor = 1x114cm & case) 2 x 1.25 m 1x120cm MR (old 4 x 1.5 m &

3x131cm,1x140cm & 2x120cm case) Basements 2 x 1.25 m c. Protection of exits

MR Provided Required Fire check door MR Provided Required Pressurization MR Provided

e. No. of continuous staircases to terrace 04 MR Provided f. Width of Corridor 1.5m

MR Provided g. Door Size 1m

3 Compartmentation. MR Provided Required Fire check door MR

Provided Required Sealing of electrical shafts MR Provided Fire Rating of shaft door Required MR Provided Water Curtain Required

MR Provided Fire Dampers Required 4

Smoke Management System. MR Provided Basements (LGF) Required MR Provided Upper floors Required

5 Fire Extinguishers Provided MR Total numbers 114 nos. Provided MR. Types CO2, ABC type IS marking MR Provided ISI marked

n

	N-48		-	Ja L
F	First-Aid Hose Reels.	16 E		
	Total numbers on each floor	4 for upper floors	Provided	M
	Length of hose reel hose	30m	Provided	MR
	Nozzle diameter	5mm	Provided	1411
1	Automatic fire detection and alarming			100
	Type of detectors	Smoke & Heat	Provided Provided	MR MR
	Location of Main Panel	Required	Provided	MR
	<ul> <li>Location of Repeater Panel</li> </ul>	Required	Provided	MR
	Alternate source of power	Required	Provided	MR
	Hooters' Location	Required	Provided	MR
	MOEFA	Required	Met Roll Helines	
	Public Address System.	Required	Provided	MR
0	Automatic Sprinkler System.			
	Basement	Required	Provided	MR
	Upper Floor	Required	Provided	MR
	Sprinkler above false ceiling	Required	Provided	MR
11	Internal Hydrants			
	Size of riser/down-comer	150 mm	Provided	MR
	Number of hydrants per floor	4 for upper floors	Provided	MR
	Hose Box	Required	Provided	MR
12	Yard Hydrants.	<del> </del>		
	Total number of hydrants	Required	Provided	MR
	Hose Box	Required	Provided	MR
13	Pumping Arrangements.	1	C422-127-15	*****
	Ground Level			
	Discharge of main Pump	2850 lpm	Provided	MR
	> Head of Main pump	110 m	Provided	MR
	> Number of main pumps	02	Provided	MR
	> Jockey Pump out put	180 lpm	Provided	MR
	Jockey pump head	110 m	Provided	MR
	Standby Pump out put	2850 lpm	Provided	MR
	> Standby Pump Head	110 m	Provided	MR
	Auto Starting/ Manual stopping	Required	Provided	MR
	➤ Pump House Access	Required	Provided	MR
	Terrace level			
	Discharge of pump	NA	NA	NA
	> Head of the pump	NA	NA	NA
	> Power Supply	NA	NA	NA
	> Auto Starting of pump	NA	NA	NA
14	Captive Water Storage for fire fight	ing.		
	Underground tank capacity	2,00,000 ltrs	Provided	MR
	> Draw-off connection	Required	Provided	MR
	➤ Fire service inlet	Required	Provided	MR
1	> Access to tank	Required	Provided	MR
	Overhead Tank capacity	20,000 ltrs	Provided	MR
	• Overhead rank capacity	20,000 105		

1	1.	Pressurization of Lift Shaft	Required	Provided	MR	
1 1		Pressurization of Lift lobby	Required	Provided	MR	
		Communication In lift Car	Required	Provided	MR	
		<ul> <li>Fireman's Grounding Switch</li> </ul>	Required	Provided	MR	
		Lift Signage	Required	Provided	MR	
17	Stand	by power supply	Required	Provided	MR	
18	Refuge Area.					
	4	Total Area	Required	Provided	MR	
	>	Location	4 <sup>th</sup> , 6 <sup>th</sup> , 9 <sup>th</sup> , Terrace floor	Provided	MR	
19 F	Fire Control Room					
		Detector System Panel	Required	Provided	MR	
		Flow Switch Panel	Required	Provided	MR	
		PA System Panel	Required	Provided	MR	
		Batter backup	Required	Provided	MR	
		Building Floor Plans	Required	Provided	MR	
20	100000000000000000000000000000000000000	Fire Protection Systems for tion of special Risks, if any:	Co2 flooding system for HT & LT panel	Provided	MR	

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection. The management had rectified the shortcomings issued vide letter number F6/DFS/MS/WZ/2023/4526 dated 29/12/2023.

Keeping in view of deemed compliance of the minimum standards of fire prevention and fire safety measures as required under rules it is recommended to renew the fire safety certificate issued vide letter number F6/DFS/MS/WZ/2020/387 dated 25/09/2020 under rule 37 of the Delhi Fire Service Rules, 2010.

Signature of the Inspecting Officer Name: - Rajeev Kumar Sinha

Designation: - ADO (BW)

The inspection is already easter Low-by

ADD (Bairana) & the Same is Checked by DCFO (FPH)

It is a renewal case.

Enbruito plens.

Cfo- on leave