

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/2024/School/ 635

Dated:08 67 /2024

FIRE SAFETY CERTIFICATE

Certified that Sunmax Public School located at A-Block, Pradhan Enclave, Burari, Delhi-110084. comprised of ground & 02 upper floors but school is running at ground & first floor only owned/ occupied by the Sunmax Public School have complied with the fire prevention and safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and verified by the officer concerned of Fire Service on 25.06.2024 in the presence of Smt. Tanu Shree Singh (Principal) and observed that all the fire safety arrangements as provided in the premises found in good working condition. The premises have complied with requirements of circular issued by Director of Education vide letter no 3298-3398 dated 01.03.2011 and the building/ premise is fit for occupancy class 'Group B Educational' for ground & first floor only with effect from08/07/2024 for a period of three years, subject to compliance of the conditions mentioned below:

Issued on ... 08 07 2024 ... at New Delhi

Director Ph:-011-23414000

Copy to: -

1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi - 110054.

2. The Manager, Sunmax Public School located at A-Block, Pradhan Enclave, Burari, Delhi-110084.

Conditions for the validity of Fire Safety Certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection.

3. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

4. All the staff members must know the correct method of operation of firefighting system.

5. The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms.

6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-

2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

INSPECTION REPORT

1. Name & address of the building

:Sunmax Public School at A-Block, Pradhan Enclave, Burari, Delhi-110084.

Composition of building

: Ground & 02 upper floors only but school is running at ground + first floor

Only & 2nd floor use for residance purpose.

3. Type of Occupancy

: Educational

4. Type of Case

: New

.....

5. Details of previous NOC

Nil

6. Fire Safety directives letter No

: Director of education circular dated 01.03.2011

Date of inspection

:25.06.2024

8. Name of the Inspecting Officers

: ADO (RN)

9. Name and designation of officers

from the building side

: Smt. Tanushri Singh (Principal)

10. Year of Construction

		m Standards on fire prevention and fire safety U/R 33	Director of education circular dated 01.03.2011 Requirements	Provided at site	Remarks MR/NMR			
	Access to	Access to building						
	•]	Road width	06m	06m	MR			
		Gate width Width of internal road	Directly Accessible	Directly Accessible	MR			
			NΛ	NA	NA			
	Number, Width, Type & Arrangement of Exits							
	a. Number of staircases							
	•	Upper Floors	02	03	MR			
	•	Basements	NA	NA	NA			
	b. Width	of staircases			INA			
		Upper Floors	1.50m or less and 75cm	1.50m (iron) 90cm & 88cm	MR			
		Basements tion of exits	NA	NA	NA			
		Fire check door	NA	NA	NA			
		Pressurization	NΛ	NA	NA			
	d. No. o	f continuous staircases to terrace	02	02	MR			
	e. Width	of Corridor	NA	NA	NA			
	f. Door S	ize	01m	01m	MR			
3	Compartmentation.							
	•	Fire check door	NA	NΛ				
		Sealing of electrical shafts	NA	792	NA			
	1 00	Fire Rating of shaft door		NA	NA			
		Water Curtain	NA	NA	NA			
		Fire Dampers	NA	NA	NA			
4	Smoke	Aanagement System.	NA	NA	NA			
: 241		gement System,						
	•	Basements	NA	NA				
	•	Upper floors			NA			
5	L.	Petinguisham	NA	NA	NΛ			
		Fire Extinguishers						
	•	Total numbers	04nos					

		NIE		N. A.		
	• Types	ABC/CO2	ABC—04	1		
	ISI marking	ISI Marked	Yes	M		
	First-Aid Hose Reels.			-		
	Total numbers on each floor	NA NA	NA	NA"		
	Length of hose reel hose	NA	NΛ	NA		
	Nozzle diameter	NA	NA	NΛ		
	Automatic fire detection and alarming system.					
	Type of detectors	NA	NΛ	NΛ		
	Location of Main Panel	NA NA	NA	NA		
	Location of Repeater Panel	NA	NA	NA		
	Alternate source of power	NA	NA	NΛ		
	Hooters' Location	NA	NΛ	NΛ		
	MOEFA	NA	NA	NA		
	Public Address System.	NA	NA	NA		
)	Automatic Sprinkler System.					
	Basement	NA	NA	NΛ		
	Upper Floor	NA	NA	NA		
	Sprinkler above false ceiling	NA	NA	NA		
	Internal Hydrants					
	Size of riser/down-comer	NA	NA	NA		
	Number of hydrants per floor	NA	NA	NA		
	Hose Box	NA	NA	NA		
	Yard Hydrants.					
	Total number of hydrants	NA I	NA	NA NA		
	Hose Box	NA				
	Pumping Arrangements.	1	NA .	NA		
	Ground Level		Tell and the			
	➤ Discharge of main Pump					
	► Head of Main pump	N/A	N/A	N/A		
	 Number of main pumps 	N/A	N/A	N/A		
	Jockey Pump out put	N/A	N/A	N/A		
	Jockey pump head	N/A	N/A	N/A		
	Standby Pump out put	N/A	N/A	N/A		
	> Standby Pump Head	N/A	N/A			
	 Auto Starting/ Manual stopping 	N/A	N/A	N/A N/A		
	Pump House Access	N/A	N/A	N/A		
	Terrace level					
	 Discharge of pump 	NA	NA .	NA		
	 Head of the pump 	NA NA	NA NA	NA NA		
	Power Supply	NA NA	NA NA			
	Auto Starting of pump	NA	NA NA	NA NA		
	Captive Water Storage for fire fighting.					
	Underground tank capacity					
	 Draw-off connection 	NA NA	NA	· NA		
	 Fire service inlet 	NA NA	NA	NA		
	- Access to tank		NA	NA		
		NA	NA	NA		

-	Overhead Tank capacity	NA	NA	NA			
15	Exit Signage.	NA	NA	NA			
16	Provision of Lifts.						
	Pressurization of Lift Shaft	N/Λ	N/A	N/A			
	Pressurization of Lift lobby	N/A	N/A	N/A			
	Communication In lift Car	N/A	N/A	N/A			
	 Fireman's Grounding Switch Lift Signage 	N/A	N/A	N/A			
	Lan Signage	N/A	N/A	N/A			
17	Standby power supply	N/A	N/A	N/A			
18	Refuge Area.						
	➤ Total Area	N/A	N/A	N/A			
	Location	N/A	N/A	N/A			
19	Fire Cantrol Room						
	Detector System Panel	N/A	N/A	N/A			
	Flow Switch Panel	N/A	N/A	N/A			
	PA System Panel	N/A	N/A	N/A			
	Batter backup Duilding Floor Plans	N/A	N/A	N/A			
	Building Floor Plans	N/A	N/A	N/A			
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A			

The fire protection systems provided in the building were tested/ checked randomly and found in working condition at the time of inspection. The management has complied all the shortcomings issued and communicated by this department vide letter of even no. F6/DFS/MS/2024/School/165 dated 16.04.2024.

Keeping in view the satisfactory compliance of the minimum standard on fire prevention and fire safety requirements as stipulated under the circular issued by Director of Education dated 01.03.2011, it is recommended to grant Fire Safety Certificate

Signature of the Inspecting Officer

Name :-C.L. Meena

Designation:- ADO/RN

D= 26 06 24

Cfo- on leave

Anyen

conf. P.T.O -