

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001

८-३५ ग्राजादी व अमृत महोत्स्रय

No. F6/DFS/MS/School/NDZ/2024/ 652

Dated:09 /07/2024

FIRE SAFETY CERTIFICATE

Certified that the Hindon Public Senior Sec. School located at B – 3/411, 33 Foota Road, Harsh Vihar, Delhi – 110093, building comprised of ground plus two upper floors and ground plus one upper floor (Interconnected) owned/occupied by Hindon Public Senior Sec. School was issued FSC vide letter No. F6/DFS/MS/School/2021/NDZ/530 dated 26/07/2021. The School building was reinspected by the officer concerned of this department on 02/07/2024 in presence of Mrs. Rajni Singh (Prinicipal of the school and found that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with rules 33 of the Delhi Fire Service Rules, 2010 and circular letter No. F 16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01/03/2011 issued by Director of Education and observed that the school building is fit for G+2 & G+1 occupancy class "Educational Building" (Group - B) with effect from 6 9 /07/2024 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010 printed overleaf.

Issued on 6 9 0 7 12024 at New Delhi by.

sued on 8 1 104 170 at New Della by

DIRECTOR

O C DELHI FIRE SERVICE

Copy to: -

- 1. The Dy. Director of Education, B- Block, Yamuna Vihar, Delhi 110053.
- 2. The Principal, Hindon Public Senior Sec. School located at B-3/411, 33 Foota Road, Harsh Vihar, Delhi-110093.

Conditions for the validity of Fire Safety Certificate

- 1. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry
- 2. All the means of escape shall be kept free of all the type of obstruction all the time.
- 3. All the employees shall be acquainted with the use and maintenance of all fire equipment's and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 4. All the firefighting equipment's shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc. may be got verified from the authorities concerned.
- 6. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

Į.	1		INSPE	CTION REPOR	<u> </u>				
	Na	ame	& address of the building	Hindon Public Senior Sec. School located at B 3/411, 33 Foota Road, Harsh Vihar, Delhi					
2	Bı	ildi	ng is comprised of	- Najevnevane	110093.				
3	Ty	/pe	of occupancy		(G+2) & (G+1) Interconnected				
4	Ty	/pe	of case	Educational Building Renewal					
5	Details of previous FSC F6/DFS/MS/School/2021/NDZ/530 dated					dated			
6	Fire safety directives letter no.			26/07/2021 NBC Part-IV & DOE Circular 2011					
7			of inspection						
8	_		of the inspecting officers		02/07/2024				
9			of the designation of office		Yashwant Singh Meena ADO (L.N)				
			he building side	iviis. Rajiii Sii	Mrs. Rajni Singh (Prinicipal)				
10			of construction	(G+2) = 2010	0 & (G + 1) = 2016				
11	1 Applicant's letter no. Outdoor dairy no. 525 dated Minimum standard of fire NBC Part-IV Provided a				024				
S.N o				NBC Part-IV	Provided at site	Remarks MR/NMR			
1	A	ces	s to Building:	•					
	A	R	oad width	06 mtrs.	06 mtrs.	MR			
	В	G	ate width	N/A	N/A	N/A			
	C	2000	idth of internal road	N/A	N/A	N/A			
2	Number, Width, Type and Arrangement of Exits:								
4									
	A			02 nos.	04 nos. /	MR			
	_	-	Upper floor	N/A	N/A	N/A			
		b	Basement	IWA	- 1100				
	В		idth of staircases	1.50 mtrs 1.22 mtrs, 1.36 mtrs,		MR			
		a	Upper floor	1.50 mus	1.38 & 1.56 mtrs.				
		lhl	Basement	N/A	/ N/A/	N/A			
	C	b Pi	Basement rotection of exits		C N/A				
	C	1.77		N/A N/A	N/A	N/A			
	C	Pi a b	rotection of exits Fire check door Pressurization	N/A N/A	N/A N/A N/A	N/A N/A			
	C D	Pr a b	rotection of exits Fire check door Pressurization o. of continuous staircases	N/A	N/A	N/A			
	D	Pi a b No to	rotection of exits Fire check door Pressurization o. of continuous staircases terrace	N/A N/A 01 no.	N/A N/A 01 no.	N/A N/A MR			
	D E	Pra a b No to W	Protection of exits Fire check door Pressurization o. of continuous staircases terrace fidth of corridor	N/A N/A 01 no.	N/A N/A 01 no. (N/A N/A MR MR			
	D E F	Pra a b No to W	Protection of exits Fire check door Pressurization o. of continuous staircases terrace fidth of corridor oor size class room	N/A N/A 01 no.	N/A N/A 01 no.	N/A N/A MR			
3	D E F	Pra a b No to W Do	Protection of exits Fire check door Pressurization o. of continuous staircases terrace fidth of corridor oor size class room artmentation:	N/A N/A 01 no. 1.50 mtrs. 1.0 mtr.	N/A N/A N/A 01 no. 3.0 mtrs. 1.0 mtr.	N/A N/A MR MR			
3	D E F	Pra a b No to W Dompa	Protection of exits Fire check door Pressurization o. of continuous staircases terrace fidth of corridor oor size class room artmentation: re check door	N/A N/A 01 no. 1.50 mtrs. 1.0 mtr.	N/A N/A N/A 01 no. 3.0 mtrs. 1.0 mtr.	N/A N/A MR MR MR			
3	D E F	Pra a b No to W Dompa	Protection of exits Fire check door Pressurization o. of continuous staircases terrace fidth of corridor oor size class room artmentation:	N/A N/A 01 no. 1.50 mtrs. 1.0 mtr. NA N/A	N/A N/A N/A 01 no. 3.0 mtrs. 1.0 mtr. NA N/A	N/A N/A MR MR MR N/A			
3	D E F Co	Pra a b No to W Do mpa Fii	Pressurization o. of continuous staircases terrace fidth of corridor oor size class room artmentation: re check door aling of electrical shafts re rating of shaft door	N/A N/A 01 no. 1.50 mtrs. 1.0 mtr. NA N/A N/A	N/A N/A N/A 01 no. 3.0 mtrs. 1.0 mtr. NA N/A N/A N/A	N/A N/A MR MR MR N/A N/A N/A			
3	D E F Co	Pra a b No to W Do mpa Fii	Pressurization On of continuous staircases terrace Fidth of corridor Foor size class room Formentation: For check door For aling of electrical shafts	N/A N/A 01 no. 1.50 mtrs. 1.0 mtr. NA N/A N/A N/A N/A	N/A N/A N/A 01 no. 3.0 mtrs. 1.0 mtr. NA N/A N/A N/A N/A N/A	N/A N/A MR MR MR NA N/A N/A N/A			
3	D E F Co	Pra a b Noto to W Do mpa Fin See Fin W	Pressurization o. of continuous staircases terrace fidth of corridor oor size class room artmentation: re check door aling of electrical shafts re rating of shaft door	N/A N/A 01 no. 1.50 mtrs. 1.0 mtr. NA N/A N/A	N/A N/A N/A 01 no. 3.0 mtrs. 1.0 mtr. NA N/A N/A N/A	N/A N/A MR MR MR N/A N/A N/A			
	D E F Coo A B C D E	Pra b No to W Do mpa Fin W Fin	Pressurization On of continuous staircases terrace Fidth of corridor For size class room For the check door For size class room F	N/A N/A 01 no. 1.50 mtrs. 1.0 mtr. NA N/A N/A N/A N/A	N/A N/A N/A 01 no. 3.0 mtrs. 1.0 mtr. NA N/A N/A N/A N/A N/A	N/A N/A MR MR MR N/A N/A N/A N/A			
-	D E F Coo A B C D E	Pra b No to W Do mpa Fin W Fin oke	Pressurization o. of continuous staircases terrace fidth of corridor oor size class room artmentation: re check door aling of electrical shafts re rating of shaft door atter curtain re dampers	N/A N/A 01 no. 1.50 mtrs. 1.0 mtr. NA N/A N/A N/A N/A	N/A N/A N/A 01 no. 3.0 mtrs. 1.0 mtr. NA N/A N/A N/A N/A N/A	N/A N/A MR MR MR N/A N/A N/A N/A			

l

Hindon Public Senior Sec. School located at B - 3/411, 33 Foota Road, Harsh Vihar, Delhi - 110093

	Fire Extinguisher: 14 nos.						
	A	Total numbers	14 nos. <	CO ₂ & ABC	MR MR		
1	В	Types	CO ₂ & ABC	ISI Marked	MR		
	C	ISI marking	ISI Marked	ISI Marked	IVII		
_	Ein	st-Aid-Hose Reel:			MR		
6	lang of each floor		02 no.	02 no.	MR		
	A	Length of hose reel hose	30 mtrs	30 mtrs /	MR		
	B	1. diameter	05 mm	05 mm	IVIIC		
	C	tomatic Fire Detection and Ala	rming System:		27/4		
7	Automatic Fire Detection and		N/A	N/A	N/A		
	A	Type of detectors	N/A	N/A	N/A		
	B	Location of main panel Location of repeater panel	N/A	N/A	N/A		
	C	Location of repeater purer	N/A	N/A	N/A		
	D	Alternate source of power	N/A	N/A	N/A		
	E	Hooters	N/A	N/A	N/A		
8	M	OEFA:	N/A	N/A	N/A		
9	Pu	blic Address System:					
10	Au	tomatic Sprinkler System:	N/A	N/A	N/A		
_	A	Basement	N/A	N/A	N/A		
	В	Upper floor	57/31	N/A	N/A		
	C	Sprinkler above false ceiling	N/A	14/21			
11	Internal Hydrants:			100	MR		
11	A	Size of riser/down-comer	N/A	100 mm /	MR		
	B	Number of hydrants per floor	N/A	14 100 1000	MR		
	C	Hose box	N/A	01 no	IVII		
105				11 11 Mpr	N/A		
12	_	rd Hydrants: Total number of hydrants	N/A	N/A	2000000		
	A		N/A	N/A	N/A		
	В	Hose box					
13	Pumping Arrangements:						
1	G	Ground level	N/A	N/A	N/A		
	A	Discharge of main pump	N/A	N/A	N/A		
	В	Head of main pump	N/A	N/A	N/A		
	C	Number of main pumps	N/A N/A	N/A	N/A		
	D	Jockey pump out put	THE STATE OF THE S	N/A	N/A		
	E	Jockey pump head	N/A N/A	N/A	N/A		
	F	Standby pump out put	55454500 5853	N/A	N/A		
	G	Standby pump head	N/A	N/A N/A	N/A		
	H	Auto starting /manual	N/A	19/73			
		stopping	NI/A	N/A	N/A		
	I Pump house access		N/A	11/12			
2	Terrace Level		450 I DM	450 LPM	MR		
	A	Discharge of pump	450 LPM	40 mtrs.	MR		
	B	Head of the pump	40 mtrs.	Provided	MR		
	C	Power supply	Required	Provided	MR		
	D	Auto starting of pump	Required	Flovided	1411		



	NIS
Hindon Public Senior Sec. School located at B - 3/4	Delhi - 110093
14 Cantive Water Second 18 - 3/4	11, 33 Foota Road, Harsh Vihar, Deut

4	Cap	dic Senior Sec. School located at B - 3/411, tive Water Storage for Fire Fightin	or	u/3/1 / 1		
	A	Underground tank capacity	N/A	N/A	N/A	
	B	Draw-off connection	N/A	N/A	N/A	
. [C	Fire service inlet	N/A	N/A	N/A	
	D	Access to tank	N/A	N/A	N/A	
	E	Overhead tank capacity	10,000 liters	10,000 liters	MR	
15	Exi	t Signage:	Required	Provided	MR	
16	Provision of Lifts:					
	A	Pressurization of lift shaft	N/A	N/A	N/A	
	B	Pressurization of lift lobby	N/A	N/A	N/A	
	C	Communication in lift car	N/A	N/A	N/A	
	D	Firemen's grounding switch	N/A	N/A	N/A	
	E	Lift signage	N/A	N/A	N/A	
17	_	andby Power Supply:	N/A	N/A	N/A	
18		fuge Area:				
10	-		N/A	N/A	N/A	
	A	Total area Location	N/A	N/A	N/A	
10	1-	re Control Room:				
19	-		N/A	N/A	N/A	
1	A	Detector system panel	N/A	N/A	N/A	
	B		N/A	N/A	N/A	
	C		N/A	N/A	N/A	
	D		N/A	N/A	N/A	
2	0 S	Building floor plans pecial Fire Protection systems for rotection of special Risks, if any:	N/A	N/A	N/A	

The fire protection system was randomly checked and tested and was found functional at the time of inspection.

Keeping In view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the rules of Directorate of Education the FSC issued vide letter no. F6/DFS/MS/School/2021/NDZ/530 dated 26/07/2021, renewal under Rule 35 of the Delhi Fire Service rules 2010, is recommended to be

No file is pending with me before disposal of this case.

Signature of the Inspecting Officer
Name Yashwant Singh Meena

Designation ADO (L.N)

DY. CFO/NDZ

aom

enuted M

1/3/01

efter is a

p for Sign. f

8/7/2024