

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/GH/2024/SZ/279

Dated: .09./.07./2024

## FIRE SAFETY CERTIFICATE

Certified that the Lodging House in the Name & Style M/s Hotel Africa Avenue located at B-104 Greater Kalash-1 Delhi 110048 comprised of Basement (Storage), Ground plus three upper floors (Total- 39 Guest Room) owner/occupied by A Unit of Sanskriti Hospitality was issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/GH/2018/SZ/921 dated 04/05/2018. The premise was re-inspected by the officer concerned of this department on 07/01/2024 in the presence of Mr. Sudhir Chadha and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Residential, Group-A" (Guest House with 39 Guest rooms) and validity upto 31/03/2027 in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 20

(AFUL GARG) DIRECTOR TIRE SERVICE

Copy to: -

 The Addl. Commissioner of Police (Lic.), 1st Floor, P.S. Defence Colony, New Delhi-110049 (Ref. MHA Portal ID 2024061409380 dated 14/06/2024 & MHA Portal ID 2024062009697 and 20/06/2024)

## Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of fire fighting

system.

4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

5. The basement shall be used as per the provisions of UBBL-2016 /NBC Part- IV.

6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."



	INSPECTION REPORT  M/s Hotel Africa Avenue (A Unit of Sanskri						
1	Name & Address of the Building	Hospitality) at B-104 Greater Kalash-1 Delhi 110048					
2	Type of Occupancy	Residential, "Group-A" (Guest House)  Basement, Ground + 03 upper floors					
3	Building Comprised of						
4	Type of Case	Renewal F6/DFS/MS/GH/2018/SZ/921 dated 04/05/2018					
5	Details of Previous NOC	The state of the s	2016/32/921 dated 04/03	72010			
6	Fire Safety Directives Letter No	Nil					
7	Date of Inspection	01/07/2024					
8	Name of the Inspecting Officers	DO (South) & ADO (BCP)					
9	Name & Designation of Officers from the building side	Mr. Sudhir Chadha					
10	Year of construction	2013 Total 39 Guest room					
11	Applicant letter No.	MHA Portal ID 2024061409380 dated 14/06/2024					
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Old NOC requirements	Provided at Site	Remarks MR/NMR			
1	Access to Building.		06	MR			
	Road width	Required	06 mtr	-NA-			
197	Gate width	-NA-	-NA-	-NA-			
	Width of internal road	-NA-	-NA-	-IVA-			
2	Number, width, type & arrangement of exits.			-			
	a) Number of Staircase		0027	MR			
	> Upper floors.	Required	02 Nos	77-27-12-5			
.00	Basement floor.	Required	02 Nos	MR			
1	b) Width of Staircase	#01.00ML(0.0	n religiolistics w				
S.	> Upper floors	1.32 & 0.92 m	1.32 & 0.92 m	MR (old case)			
, O	> Basement floor	1.33 & 0.60 m	1.33 & 0.60 m	MR (old case)			
A plant	c) Protection of exits	0.000		MR			
A Pro	Fire check door (As per clause 7.31 of UBBL 2016)	Required -NA-	Provided -NA-	· -NA-			
RE I	> Pressurization		-	MR			
217	d) No. of continuous staircase to terrace	Required	Two	-NA-			
417	e) Width of corridor	-NA-	-NA-	MR			
N. Y	f) Door size	1m	1.0 m (Final Exit)	IVIIC			
3	Compartmentation.	100	-NA-	-NA-			
-	Fire check door.	-NA-		-NA-			
	Sealing of electrical shafts.	-NA-	-NA-	-NA-			
	Fire rating of shaft door.	-NA-		MR			
	Water ourtain	Required	Provided	-NA-			
107	Fire dampers	-NA-	-NA-	-1447-			
4	Smoke Management system.		31 of UBBL 2016.	MR			
4	Basement	30 ACPH	Exhaust fan provided				
	Upper floors	12 APCH	Exhaust fan provided	MR			
5	Fire Extinguishers.	12 Nos	Provided	MR			
	Total numbers	ABC / CO2	ABC & CO2	MR			
	Types     ISI Marking	ISI marked	-NA-	-NA-			
6	First Aid Hose Reels.	7		MR			
0	Total numbers on each floor.	One	Provided				
	Length of hose-reel hose.	30 mtr	Provided	MR			
	Nozzle Diameter	5 mm	Provided	MR			

आज़ादीक	
अमृत म	होत्सव

	Automatic fire detection & alarming system.	As per clause 7.31	01 OBBT 5019	
	Type of detectors	Co. Mo. Det.	Provided	MR
	Location of Main Panel	Required	Provided	MR
	<ul> <li>Location of Repeater Panel</li> </ul>	-NA-	-NA-	-NA-
	Alternate source of power	Required	Provided	MR
	Hooter's location	Required	Provided	MR
3	MOEFA	Required	Provided	MR
9	Public Address System	-NA-	NA	-NA-
0	Automatic Sprinkler System	-1475	220 11 12 12 10 10 10	7.12
	Basement	Required	Provided	MR
	Upper floors.	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
1	Sprinkler above false ceiling     Internal Hydrants.	-IVA-	-IVA-	1171
		Decided	150 mm	MR
	Size of Riser/Down-comer	Required	01 Nos	MR
	Number of Hydrant per floor	Required		MR
10	Hose box.	Required	01 Nos	IVIK
12	Yard Hydrants.		D 11.1	MD
	Total number of hydrants.	Required	Provided	MR
d	Hose box.	Required	Provided	MR
13	Pumping arrangements.			
	Ground Level		The second second	
	Discharge of main pump.	-NA-	-NA-	-NA-
	Head of main pump.	-NA-	-NA-	-NA-
	Number of main pumps.	-NA-	-NA-	-NA-
	> Jockey Pump output.	-NA-	-NA-	-NA-
	> Jockey Pump head.	-NA-	-NA-	-NA-
	Standby Pump output.	-NA-	-NA-	-NA-
	Standby Pump head.	-NA-	-NA-	-NA-
	> Auto Starting/Manual Stopping.	*35.5	-NA-	-NA-
	Pump house access.	-NA-	-NA-	-NA-
	Terrace Level			1 100
	Discharge of pump.	900 LPM	Provided	MR
	> Head of pump.	35 m	Provided	MR
	> Power supply.	Required	Provided	MR
	> Auto starting of pump.	Required	Provided	MR
14	Captive water storage for fire fighting.	2	THE STREET	774
7	<ul> <li>Underground tank capacity.</li> </ul>	-NA-	· NA	-NA-
	> Draw-off connection.	-NA-	-NA	-NA-
	> Fire Service Inlet.	-NA-	-NA-	-NA-
	> Access to tank.	-NA-	-NA-	-NA-
	<ul> <li>Overhead tank capacity.</li> </ul>	10,000 ltrs	10,000 ltrs	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.		The second second	
10	Pressurization of lift shaft.	-NA-	-NA-	-NA-
	Pressurization of lift lobby.	-NA-	-NA-	-NA-
	Communication in lift car.	Required	Provided	MR
	• Fireman's switch.	Required	Provided	MR
		Required	Provided	MR
	Lift signage.  Standard Research  Company Standard  Company S	Required	Provided	MR
17	Standby Power Supply	- Alequates		
18	Refuge Area	-NA-	-NA-	-NA
	Total area	-NA-	-NA-	-NA
	Location	-NA-	-11/1	

1

~



20	Special Fire Protection System for the Protection of special Risk, if any.		Co2 flooding system provided	-NA-
20	Special Fire Protection Co.	-NA-	-NA-	
- 1	<ul> <li>Building floor plan.</li> </ul>		-NA-	-NA-
	Battery backup.	-NA-	-NA-	-NA-
- 1	<ul> <li>PA system panel.</li> </ul>	-NA-	-NA-	-NA-
1	<ul> <li>Flow switch panel.</li> </ul>	-NA-	-NA-	-NA-
	<ul> <li>Detector system panel.</li> </ul>	-NA-	111	

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Further, the party has complied all the observation / Shortcoming already issued & communicated by this department vide letter of even no 767 dated 09/09/2022.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/GH/2018/SZ/921 dated 04/05/2018, renewal under rule 37 of the Delhi Fire Service

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspection Officer Name: Sh. Manoj Kumar Sharma

Design DO (South)

सव

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

Design: ADO (BCP)

Any Any Byll
As approved, F-1- (-etter in
your syndrice o)